

DeKalb County School District/Elementary Schools

Briar Vista Elementary

Final

School Assessment Report

May 19, 2016



Table of Contents

School Executive Summary	4
School Condition Summary	6
<u>1955, 1957, 1970 Building</u>	8
Executive Summary	8
Condition Summary	9
Photo Album	10
Condition Detail	11
System Listing	12
Renewal Schedule	14
Forecasted Sustainment Requirement	17
Deficiency Summary By System	18
Deficiency Summary By Priority	19
Deficiency By Priority Investment	20
Deficiency Summary By Category	21
Deficiency Details By Priority	22
<u>1970 Storage</u>	37
Executive Summary	37
Condition Summary	38
Photo Album	39
Condition Detail	40
System Listing	41
Renewal Schedule	42
Forecasted Sustainment Requirement	45
Deficiency Summary By System	46
Deficiency Summary By Priority	47
Deficiency By Priority Investment	48
Deficiency Summary By Category	49
Deficiency Details By Priority	50
<u>2000 Gym</u>	51

School Assessment Report

Executive Summary	51
Condition Summary	52
Photo Album	53
Condition Detail	54
System Listing	55
Renewal Schedule	56
Forecasted Sustainment Requirement	58
Deficiency Summary By System	59
Deficiency Summary By Priority	60
Deficiency By Priority Investment	61
Deficiency Summary By Category	62
Deficiency Details By Priority	63
<u>Site</u>	67
Executive Summary	67
Condition Summary	68
Photo Album	69
Condition Detail	70
System Listing	71
Renewal Schedule	72
Forecasted Sustainment Requirement	74
Deficiency Summary By System	75
Deficiency Summary By Priority	76
Deficiency By Priority Investment	77
Deficiency Summary By Category	78
Deficiency Details By Priority	79
Glossary	86

School Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	64,142
Year Built:	1955
Last Renovation:	2009
Replacement Value:	\$14,588,652
Repair Cost:	\$10,880,580.73
Total FCI:	74.58 %
Total RSLI:	12.64 %
FCA Score:	25.42



Description:

The Briar Vista Elementary School campus consists of two buildings located at 1131 Briar Vista Terrace N.E. in Atlanta, Georgia. The original campus was constructed in 1955, additions to the main school building were constructed in 1957 and 1970, and a gymnasium building was constructed in 2000. In addition to these buildings, the campus contains a covered walkway, storage building, hard surface play area, playground, and playing field. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for each building and site improvement on the campus.

School Assessment Report - Briar Vista Elementary

Attributes:

General Attributes:

Assigned Region:	Region 2	Board District:	District 2
DOE Facility:	4051	Geographic Region:	Region 2
HS Attendance Area:	Druid Hills HS	Jurisdictional City:	DeKalb County (Unincorporated)
Site Acreage:	10.8		

School Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	44.36 %	0.00 %	\$0.00
A20 - Basement Construction	40.00 %	0.00 %	\$0.00
B10 - Superstructure	52.27 %	0.00 %	\$0.00
B20 - Exterior Enclosure	31.40 %	32.93 %	\$498,552.30
B30 - Roofing	4.02 %	104.35 %	\$1,366,534.00
C10 - Interior Construction	29.41 %	35.31 %	\$291,608.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	2.90 %	67.99 %	\$1,285,494.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	4.21 %	88.20 %	\$1,446,388.00
D30 - HVAC	10.07 %	94.42 %	\$2,233,342.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	1.61 %	105.43 %	\$1,628,893.00
E10 - Equipment	0.00 %	110.00 %	\$530,642.00
E20 - Furnishings	0.00 %	110.00 %	\$345,819.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
G20 - Site Improvements	8.51 %	75.32 %	\$559,035.42
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$515,765.83
G40 - Site Electrical Utilities	0.00 %	110.00 %	\$178,507.18
Totals:	12.64 %	74.58 %	\$10,880,580.73

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 Priority	2 Priority	3 Priority	4 Priority	5 Priority
1955, 1957, 1970 Building	58,544	76.84	\$0.00	\$0.00	\$9,448,867.00	\$0.00	\$0.00
1970 Storage	120	21.11	\$0.00	\$0.00	\$2,040.30	\$0.00	\$0.00
2000 Gym	5,478	19.40	\$0.00	\$0.00	\$176,365.00	\$0.00	\$0.00
Site	64,142	91.26	\$0.00	\$250,474.51	\$1,002,833.92	\$0.00	\$0.00
Total:		74.58	\$0.00	\$250,474.51	\$10,630,106.22	\$0.00	\$0.00

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	58,544
Year Built:	1955
Last Renovation:	2009
Replacement Value:	\$12,296,650
Repair Cost:	\$9,448,867.00
Total FCI:	76.84 %
Total RSLI:	10.28 %
FCA Score:	23.16



Description:

The main building at Briar Vista Elementary School is a one-story building located at 1131 Briar Vista Terrace N.E. in Atlanta, Georgia. Originally built in 1955, there have been additions in 1957 and 1970, and renovations in 2008 and 2009. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2010, 2011, 2012	Fire Sprinkler System:	No
-----------------	------------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	40.00 %	0.00 %	\$0.00
A20 - Basement Construction	40.00 %	0.00 %	\$0.00
B10 - Superstructure	40.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.00 %	35.74 %	\$496,512.00
B30 - Roofing	0.00 %	110.00 %	\$1,366,534.00
C10 - Interior Construction	23.00 %	40.86 %	\$291,608.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	2.67 %	67.19 %	\$1,202,771.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	1.51 %	93.41 %	\$1,446,388.00
D30 - HVAC	9.15 %	96.88 %	\$2,163,141.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	110.00 %	\$1,605,452.00
E10 - Equipment	0.00 %	110.00 %	\$530,642.00
E20 - Furnishings	0.00 %	110.00 %	\$345,819.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
Totals:	10.28 %	76.84 %	\$9,448,867.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). North Elevation - Jun 28, 2015



2). West Elevation - Jun 28, 2015



3). South Elevation - Jun 28, 2015



4). East Elevation - Jun 28, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1955, 1957, 1970 Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	58,544	100	1955	2055		40.00 %	0.00 %	40			\$379,951
A1020	Special Foundations	\$0.00	S.F.	0	100	1955	2055		40.00 %	0.00 %	40			\$0
A1030	Slab on Grade	\$7.09	S.F.	58,544	100	1955	2055		40.00 %	0.00 %	40			\$415,077
A2010	Basement Excavation	\$0.26	S.F.	2,500	100	1955	2055		40.00 %	0.00 %	40			\$650
A2020	Basement Walls	\$6.13	S.F.	2,500	100	1955	2055		40.00 %	0.00 %	40			\$15,325
B1010	Floor Construction	\$0.00	S.F.	58,544	100	1955	2055		40.00 %	0.00 %	40			\$0
B1020	Roof Construction	\$5.34	S.F.	58,544	100	1955	2055		40.00 %	0.00 %	40			\$312,625
B2010	Exterior Walls	\$16.02	S.F.	58,544	100	1955	2055		40.00 %	0.00 %	40			\$937,875
B2020	Exterior Windows	\$6.79	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$437,265.00	\$397,514
B2030	Exterior Doors	\$0.92	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$59,247.00	\$53,860
B3010	Roof Coverings - Asphal Shingles	\$0.00	S.F.	0	10	1955	1965		0.00 %	0.00 %	-50			\$0
B3010	Roof Coverings - BUR	\$20.70	S.F.	58,544	25	1980	2005		0.00 %	110.00 %	-10		\$1,333,047.00	\$1,211,861
B3010	Roof Coverings - EPDM	\$0.00	S.F.	0	15	1955	1970		0.00 %	0.00 %	-45			\$0
B3010	Roof Coverings - Preformed Metal	\$0.00	S.F.	0	30	1955	1985		0.00 %	0.00 %	-30			\$0
B3010	Roof Coverings - Standing Seam Metal	\$0.00	S.F.	0	75	1955	2030		20.00 %	0.00 %	15			\$0
B3020	Roof Openings	\$0.52	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$33,487.00	\$30,443
C1010	Partitions	\$7.01	S.F.	58,544	100	1955	2055		40.00 %	0.00 %	40			\$410,393
C1020	Interior Doors	\$2.39	S.F.	58,544	30	1955	1985		0.00 %	80.00 %	-30		\$111,936.00	\$139,920
C1030	Fittings	\$2.79	S.F.	58,544	20	1955	1975		0.00 %	110.00 %	-40		\$179,672.00	\$163,338
C2010	Stair Construction	\$0.00	S.F.	0	100	1955	2055		40.00 %	0.00 %	40			\$0
C3010	Wall Finishes - Ceramic & Glazed	\$10.27	S.F.	29,272	30	1955	1985		0.00 %	0.00 %	-30			\$300,623
C3010	Wall Finishes - Paint	\$1.93	S.F.	29,272	10	1955	1965		0.00 %	110.00 %	-50		\$62,144.00	\$56,495
C3010	Wall Finishes - Wall Coverings	\$0.00	S.F.	0	10	1955	1965		0.00 %	0.00 %	-50			\$0
C3020	Floor Finishes - Carpet	\$8.50	S.F.	6,440	8	2009	2017		25.00 %	0.00 %	2			\$54,740
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	3,220	50	1955	2005		0.00 %	110.00 %	-10		\$51,324.00	\$46,658
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	6,440	50	1970	2020		10.00 %	0.00 %	5			\$341,384
C3020	Floor Finishes - VCT	\$9.54	S.F.	41,566	20	1977	1997		0.00 %	110.00 %	-18		\$436,194.00	\$396,540
C3020	Floor Finishes - Wood	\$14.70	S.F.	644	20	1955	1975		0.00 %	109.99 %	-40		\$10,413.00	\$9,467
C3030	Ceiling Finishes	\$9.98	S.F.	58,544	20	1977	1997		0.00 %	110.00 %	-18		\$642,696.00	\$584,269
D1010	Elevators and Lifts	\$1.17	S.F.	0	30	2004	2034		63.33 %	0.00 %	19			\$0
D2010	Plumbing Fixtures	\$17.66	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$1,137,276.00	\$1,033,887
D2020	Domestic Water Distribution	\$3.99	S.F.	58,544	30	1988	2018		10.00 %	0.00 %	3			\$233,591
D2030	Sanitary Waste	\$3.41	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$219,599.00	\$199,635
D2040	Rain Water Drainage	\$0.98	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$63,110.00	\$57,373

School Assessment Report - 1955, 1957, 1970 Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	58,544	30	1984	2014		0.00 %	110.00 %	-1		\$26,403.00	\$24,003
D3020	Heat Generating Systems	\$4.55	S.F.	58,544	30	2008	2038		76.67 %	0.00 %	23			\$266,375
D3030	Cooling Generating Systems	\$4.73	S.F.	58,544	30	1984	2014		0.00 %	110.00 %	-1		\$304,604.00	\$276,913
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	58,544	30	1984	2014		0.00 %	110.00 %	-1		\$354,835.00	\$322,577
D3050	Terminal & Package Units	\$18.52	S.F.	58,544	15	2008	2023	2015	0.00 %	110.00 %	0		\$1,192,658.00	\$1,084,235
D3060	Controls & Instrumentation	\$3.60	S.F.	58,544	20	1984	2004		0.00 %	110.00 %	-11		\$231,834.00	\$210,758
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$79,210.00	\$72,009
D4010	Sprinklers	\$4.75	S.F.	0	30	1955	1985		0.00 %	0.00 %	-30			\$0
D4020	Standpipes	\$0.51	S.F.	0	30	1955	1985		0.00 %	0.00 %	-30			\$0
D5010	Electrical Service/Distribution	\$1.81	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$116,561.00	\$105,965
D5020	Branch Wiring	\$6.78	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$436,621.00	\$396,928
D5020	Lighting	\$8.90	S.F.	58,544	30	1955	1985		0.00 %	110.00 %	-30		\$573,146.00	\$521,042
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	58,544	10	2005	2015		0.00 %	110.00 %	0		\$360,631.00	\$327,846
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	58,544	10	2005	2015		0.00 %	110.00 %	0		\$79,210.00	\$72,009
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	58,544	10	2005	2015		0.00 %	110.00 %	0		\$39,283.00	\$35,712
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	0	15	1955	1970		0.00 %	0.00 %	-45			\$0
E1010	Commercial Equipment	\$0.00	S.F.	0	20	1955	1975		0.00 %	0.00 %	-40			\$0
E1020	Institutional Equipment	\$0.40	S.F.	58,544	20	1955	1975		0.00 %	110.00 %	-40		\$25,759.00	\$23,418
E1090	Other Equipment (Kitchen Equipment)	\$7.84	S.F.	58,544	20	1955	1975		0.00 %	110.00 %	-40		\$504,883.00	\$458,985
E2010	Fixed Furnishings	\$5.37	S.F.	58,544	20	1955	1975		0.00 %	110.00 %	-40		\$345,819.00	\$314,381
F1010	Special Structures - Canopies	\$1.61	S.F.	0	25	1955	1980		0.00 %	0.00 %	-35			\$0
Total									10.28 %	76.84 %			\$9,448,867.00	\$12,296,650

School Assessment Report - 1955, 1957, 1970 Building

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$9,448,867	\$0	\$63,881	\$280,776	\$0	\$435,334	\$0	\$0	\$0	\$0	\$808,342	\$11,037,200
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1020 - Special Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$437,265	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$437,265
B2030 - Exterior Doors	\$59,247	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$59,247
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Asphal Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$1,333,047	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,333,047
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Preformed Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$33,487	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$33,487
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1955, 1957, 1970 Building

C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$111,936	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$111,936
C1030 - Fittings	\$179,672	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$179,672
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic & Glazed	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$62,144	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$83,516	\$145,660
C3010 - Wall Finishes - Wall Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Carpet	\$0	\$0	\$63,881	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$80,923	\$144,804
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$51,324	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$51,324
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$435,334	\$0	\$0	\$0	\$0	\$0	\$435,334
C3020 - Floor Finishes - VCT	\$436,194	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$436,194
C3020 - Floor Finishes - Wood	\$10,413	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$10,413
C3030 - Ceiling Finishes	\$642,696	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$642,696
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$1,137,276	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,137,276
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$280,776	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$280,776
D2030 - Sanitary Waste	\$219,599	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$219,599
D2040 - Rain Water Drainage	\$63,110	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$63,110
D2090 - Other Plumbing Systems - Natural Gas	\$26,403	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,403
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$304,604	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$304,604
D3040 - Distribution & Exhaust Systems	\$354,835	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$354,835
D3050 - Terminal & Package Units	\$1,192,658	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,192,658
D3060 - Controls & Instrumentation	\$231,834	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$231,834
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$79,210	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,210
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1955, 1957, 1970 Building

D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$116,561	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$116,561
D5020 - Branch Wiring	\$436,621	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$436,621
D5020 - Lighting	\$573,146	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$573,146
D5030 - Communications and Security - Clock & PA Systems	\$360,631	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$484,658	\$845,289
D5030 - Communications and Security - Fire Alarm	\$79,210	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$106,452	\$185,662
D5030 - Communications and Security - Security & CCTV	\$39,283	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$52,793	\$92,076
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$25,759	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$25,759
E1090 - Other Equipment (Kitchen Equipment)	\$504,883	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$504,883
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$345,819	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$345,819
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$9,448,867.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$437,265.00	\$0.00	\$0.00	\$437,265.00
B2030	Exterior Doors	\$0.00	\$0.00	\$59,247.00	\$0.00	\$0.00	\$59,247.00
B3010	Roof Coverings - BUR	\$0.00	\$0.00	\$1,333,047.00	\$0.00	\$0.00	\$1,333,047.00
B3020	Roof Openings	\$0.00	\$0.00	\$33,487.00	\$0.00	\$0.00	\$33,487.00
C1020	Interior Doors	\$0.00	\$0.00	\$111,936.00	\$0.00	\$0.00	\$111,936.00
C1030	Fittings	\$0.00	\$0.00	\$179,672.00	\$0.00	\$0.00	\$179,672.00
C3010	Wall Finishes - Paint	\$0.00	\$0.00	\$62,144.00	\$0.00	\$0.00	\$62,144.00
C3020	Floor Finishes - Ceramic & Quarry Tile	\$0.00	\$0.00	\$51,324.00	\$0.00	\$0.00	\$51,324.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$436,194.00	\$0.00	\$0.00	\$436,194.00
C3020	Floor Finishes - Wood	\$0.00	\$0.00	\$10,413.00	\$0.00	\$0.00	\$10,413.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$642,696.00	\$0.00	\$0.00	\$642,696.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$1,137,276.00	\$0.00	\$0.00	\$1,137,276.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$219,599.00	\$0.00	\$0.00	\$219,599.00
D2040	Rain Water Drainage	\$0.00	\$0.00	\$63,110.00	\$0.00	\$0.00	\$63,110.00
D2090	Other Plumbing Systems - Natural Gas	\$0.00	\$0.00	\$26,403.00	\$0.00	\$0.00	\$26,403.00
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$304,604.00	\$0.00	\$0.00	\$304,604.00
D3040	Distribution & Exhaust Systems	\$0.00	\$0.00	\$354,835.00	\$0.00	\$0.00	\$354,835.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$1,192,658.00	\$0.00	\$0.00	\$1,192,658.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$231,834.00	\$0.00	\$0.00	\$231,834.00
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$0.00	\$0.00	\$79,210.00	\$0.00	\$0.00	\$79,210.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$116,561.00	\$0.00	\$0.00	\$116,561.00
D5020	Branch Wiring	\$0.00	\$0.00	\$436,621.00	\$0.00	\$0.00	\$436,621.00
D5020	Lighting	\$0.00	\$0.00	\$573,146.00	\$0.00	\$0.00	\$573,146.00
D5030	Communications and Security - Clock & PA Systems	\$0.00	\$0.00	\$360,631.00	\$0.00	\$0.00	\$360,631.00
D5030	Communications and Security - Fire Alarm	\$0.00	\$0.00	\$79,210.00	\$0.00	\$0.00	\$79,210.00
D5030	Communications and Security - Security & CCTV	\$0.00	\$0.00	\$39,283.00	\$0.00	\$0.00	\$39,283.00
E1020	Institutional Equipment	\$0.00	\$0.00	\$25,759.00	\$0.00	\$0.00	\$25,759.00
E1090	Other Equipment (Kitchen Equipment)	\$0.00	\$0.00	\$504,883.00	\$0.00	\$0.00	\$504,883.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$345,819.00	\$0.00	\$0.00	\$345,819.00
	Total:	\$0.00	\$0.00	\$9,448,867.00	\$0.00	\$0.00	\$9,448,867.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$9,448,867.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B2020 - Exterior Windows



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$437,265.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The exterior window system is original construction, beyond its expected service life, damaged, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$59,247.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The exterior door system is beyond its expected service life, not ADA compliant, and should be replaced. SPLOST IV project 101-422 to replace exterior and interior doors.

System: B3010 - Roof Coverings - BUR



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$1,333,047.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The roof covering is leaking, beyond its expected service life, and should be replaced.

System: B3020 - Roof Openings



Location: Roof

Distress: Missing

Category: Safety

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$33,487.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: There is no roof hatch/ladder system installed at this school. Multi-level roofs require safe access for maintenance personnel. Recommend adding three roof hatches for multi-level roofs, or install one hatch/ladder system and wall mount ladders to the other levels. Identified as a SPLOST project 101-422 to replace/repair roof openings in the 1955, 1957, and 1970 buildings.

System: C1020 - Interior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Building Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$111,936.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Some interior doors had improvements made to them in 2014 for ADA compliance. The remaining interior doors are original construction, not ADA and building code compliant, and should be replaced. SPLOST IV project 101-422 to replace exterior and interior doors.

System: C1030 - Fittings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$179,672.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Fittings, such as toilet partitions, signage and lockers, are beyond their expected service life, inadequate, not ADA compliant, and should be replaced. Many, but not all, of the toilet partitions and accessories were replaced in 2014.

System: C3010 - Wall Finishes - Paint



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 29,272.00

Unit of Measure: S.F.

Estimate: \$62,144.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The painted wall finishes are beyond their expected service life, dirty, and should be replaced. SPLOST IV project 101-422 to paint interior walls.

System: C3020 - Floor Finishes - Ceramic & Quarry Tile



Location: Kitchen and Restrooms

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 3,220.00

Unit of Measure: S.F.

Estimate: \$51,324.00

Assessor Name: Ben Nixon

Date Created: 06/28/2015

Notes: The tile floor covering is beyond its expected service life and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 41,566.00

Unit of Measure: S.F.

Estimate: \$436,194.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: VCT floor finishes are beyond their service life, in some cases original construction, and should be scheduled for replacement.

System: C3020 - Floor Finishes - Wood



Location: Stage

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 644.00

Unit of Measure: S.F.

Estimate: \$10,413.00

Assessor Name: Ben Nixon

Date Created: 06/28/2015

Notes: The wood floor is original construction, worn, deteriorated, beyond its expected service life, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$642,696.00

Assessor Name: Ben Nixon

Date Created: 08/12/2015

Notes: The ceiling tiles have been replaced as needed; however, the system is beyond its expected service life and should be replaced. The tiles in the kitchen and the stage area are original.

System: D2010 - Plumbing Fixtures



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$1,137,276.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Some, but not all of the plumbing fixtures were replaced in 2014. The remaining plumbing fixtures are beyond their expected service life; not ADA compliant, including protrusions into the hallway more than four inches; and should be scheduled for replacement. SPLOST IV project 101-422 to renovate hall restroom for ADA compliance.

System: D2030 - Sanitary Waste



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$219,599.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The sanitary waste system is beyond its expected service life and should be scheduled for replacement. School staff reports odors in the building.

System: D2040 - Rain Water Drainage



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$63,110.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The roof rain water drainage system is beyond its expected service life, not functioning, and should be replaced. SPLOST IV project 101-422 to replace/repair roof water drainage system.

System: D2090 - Other Plumbing Systems - Natural Gas



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$26,403.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The natural gas system is beyond its expected service life and should be scheduled for replacement. SPLOST IV project 101-422 to replace grease trap and backflow preventer.

System: D3030 - Cooling Generating Systems



Location: East Side of Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$304,604.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The cooling generating system is beyond its expected service life and should be scheduled for replacement.

System: D3040 - Distribution & Exhaust Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$354,835.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The distribution and exhaust systems are beyond their expected service life, inadequate, and should be scheduled for replacement. School staff reports indoor air-quality problems.

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$1,192,658.00

Assessor Name: Ben Nixon

Date Created: 07/01/2015

Notes: The terminal and package units are beyond their expected service life and should be scheduled for replacement. SPLOST IV project 126-422 to replace the water source heat pumps in the 1955, 1957, and 1970 buildings.

System: D3060 - Controls & Instrumentation



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$231,834.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The controls and instrumentation system is beyond its expected service life, inadequate, and should be scheduled for replacement.

System: D3090 - Other HVAC Systems/Equip - Kitchen Hood



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$79,210.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The kitchen hood system is beyond its expected service life and should be scheduled for replacement. SPLOST IV project 101 -422 to replace kitchen hood and associated equipment.

System: D5010 - Electrical Service/Distribution



Location: Main Switch Room/Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$116,561.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The electrical service/distribution system is beyond its expected service life, inadequate, and should be scheduled for replacement.

System: D5020 - Branch Wiring



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$436,621.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The branch wiring system is beyond its expected service life, inadequate, and should be scheduled for replacement. There are not enough outlets to serve current needs.

System: D5020 - Lighting



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$573,146.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The lighting system is beyond its expected service life, inadequate in classrooms and hallways, and should be scheduled for replacement.

System: D5030 - Communications and Security - Clock & PA Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$360,631.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The clock and PA systems are beyond their expected service life, missing in the hallways, and should be scheduled for replacement.

System: D5030 - Communications and Security - Fire Alarm



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Building Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$79,210.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The fire alarm system is beyond its expected service life, not code compliant, and should be scheduled for replacement.

System: D5030 - Communications and Security - Security & CCTV



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$39,283.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The security and CCTV systems are beyond their expected service life and should be scheduled for replacement.

System: E1020 - Institutional Equipment



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$25,759.00

Assessor Name: Ben Nixon

Date Created: 08/12/2015

Notes: Institutional equipment, such as theater and stage equipment and audio-visual equipment, is beyond its expected service life and should be scheduled for replacement.

System: E1090 - Other Equipment (Kitchen Equipment)



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$504,883.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Kitchen equipment is beyond its expected service life and should be scheduled for replacement. SPLOST IV project 101-422 to replace kitchen hood and associated equipment.

System: E2010 - Fixed Furnishings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 58,544.00

Unit of Measure: S.F.

Estimate: \$345,819.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Fixed furnishings, such as built-in cabinets, are beyond their expected service life and worn, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	120
Year Built:	1970
Last Renovation:	
Replacement Value:	\$9,664
Repair Cost:	\$2,040.30
Total FCI:	21.11 %
Total RSLI:	45.22 %
FCA Score:	78.89



Description:

The storage building at Briar Vista Elementary School is a one-story building located at 1131 Briar Vista Terrace N.E. in Atlanta, Georgia. Originally built in 1970, there have been no additions or major renovations. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	Fire Sprinkler System:	No
-----------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	55.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	55.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	48.52 %	38.81 %	\$2,040.30
B30 - Roofing	25.00 %	0.00 %	\$0.00
C10 - Interior Construction	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	0.00 %	0.00 %	\$0.00
D20 - Plumbing	0.00 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	0.00 %	\$0.00
Totals:	45.22 %	21.11 %	\$2,040.30

Photo Album

The photo album consists of the various cardinal directions of the building.

1). East Elevation - Jun 28, 2015



2). North Elevation - Jun 28, 2015



3). West Elevation - Jun 28, 2015



4). South Elevation - Jun 28, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$0.00	S.F.	120	100	1970	2070		55.00 %	0.00 %	55			\$0
A1030	Slab on Grade	\$3.60	S.F.	120	100	1970	2070		55.00 %	0.00 %	55			\$432
A2010	Basement Excavation	\$0.00	S.F.	120	100	1970	2070		55.00 %	0.00 %	55			\$0
A2020	Basement Walls	\$0.00	S.F.	120	100	1970	2070		55.00 %	0.00 %	55			\$0
B1020	Roof Construction	\$16.33	S.F.	120	100	1970	2070		55.00 %	0.00 %	55			\$1,960
B2010	Exterior Walls	\$38.65	S.F.	120	100	1970	2070		55.00 %	29.31 %	55		\$1,359.30	\$4,638
B2020	Exterior Windows	\$0.00	S.F.	120	30	1970	2000		0.00 %	0.00 %	-15			\$0
B2030	Exterior Doors	\$5.16	S.F.	120	30	1970	2000		0.00 %	110.02 %	-15		\$681.00	\$619
B3010	Roof Coverings	\$16.79	S.F.	120	20	1970	1990	2020	25.00 %	0.00 %	5			\$2,015
C1010	Partitions	\$0.00	S.F.	120	40	1970	2010		0.00 %	0.00 %	-5			\$0
C1020	Interior Doors	\$0.00	S.F.	120	30	1970	2000		0.00 %	0.00 %	-15			\$0
C1030	Fittings	\$0.00	S.F.	120	20	1970	1990		0.00 %	0.00 %	-25			\$0
C3010	Wall Finishes	\$0.00	S.F.	120	20	1970	1990		0.00 %	0.00 %	-25			\$0
C3020	Floor Finishes	\$0.00	S.F.	120	20	1970	1990		0.00 %	0.00 %	-25			\$0
C3030	Ceiling Finishes	\$0.00	S.F.	120	20	1970	1990		0.00 %	0.00 %	-25			\$0
D2040	Rain Water Drainage	\$0.00	S.F.	120	30	1970	2000		0.00 %	0.00 %	-15			\$0
D5010	Electrical Service/Distribution	\$0.00	S.F.	120	30	1970	2000		0.00 %	0.00 %	-15			\$0
D5020	Lighting and Branch Wiring	\$0.00	S.F.	120	30	1970	2000		0.00 %	0.00 %	-15			\$0
Total									45.22 %	21.11 %			\$2,040.30	\$9,664

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%


School Assessment Report - 1970 Storage

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$2,040	\$0	\$0	\$0	\$0	\$2,569	\$0	\$0	\$0	\$0	\$0	\$4,609
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$1,359	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,359
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$681	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$681
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$2,569	\$0	\$0	\$0	\$0	\$0	\$2,569
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting and Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards. .
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2010	Exterior Walls	\$0.00	\$0.00	\$1,359.30	\$0.00	\$0.00	\$1,359.30
B2030	Exterior Doors	\$0.00	\$0.00	\$681.00	\$0.00	\$0.00	\$681.00
	Total:	\$0.00	\$0.00	\$2,040.30	\$0.00	\$0.00	\$2,040.30

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B2010 - Exterior Walls



Location: Exterior Wall

Distress: Damaged

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Point and refinish painted concrete block wall, 1st floor

Qty: 100.00

Unit of Measure: C.S.F.


Estimate: \$1,359.30

Assessor Name: Sam Mandola

Date Created: 08/13/2015

Notes: The painted exterior wall finish is damaged and needs to be replaced.

System: B2030 - Exterior Doors



Location: Exterior Wall

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 120.00

Unit of Measure: S.F.

Estimate: \$681.00

Assessor Name: Dave Cunningham

Date Created: 04/11/2015

Notes: The exterior door is beyond its expected service life, damaged, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	5,478
Year Built:	2000
Last Renovation:	
Replacement Value:	\$908,946
Repair Cost:	\$176,365.00
Total FCI:	19.40 %
Total RSLI:	56.35 %
FCA Score:	80.60



Description:

The 2000 gymnasium building at Briar Vista Elementary School is a one-story building located at 1131 Briar Vista Terrace N.E. in Atlanta, Georgia. There have been no additions or major renovations to this building. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2020	Fire Sprinkler System:	No
-----------------	------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	85.00 %	0.00 %	\$0.00
B10 - Superstructure	85.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	81.77 %	0.00 %	\$0.00
B30 - Roofing	80.00 %	0.00 %	\$0.00
C10 - Interior Construction	70.21 %	0.00 %	\$0.00
C30 - Interior Finishes	7.05 %	82.31 %	\$82,723.00
D20 - Plumbing	50.00 %	0.00 %	\$0.00
D30 - HVAC	25.62 %	53.04 %	\$70,201.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	29.15 %	27.41 %	\$23,441.00
Totals:	56.35 %	19.40 %	\$176,365.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). North Elevation - Jun 28, 2015



2). West Elevation - Jun 28, 2015



3). South Elevation - Jun 28, 2015



4). East Elevation - Jun 28, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 2000 Gym

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$9.34	S.F.	5,478	100	2000	2100		85.00 %	0.00 %	85			\$51,165
A1030	Slab on Grade	\$6.21	S.F.	5,478	100	2000	2100		85.00 %	0.00 %	85			\$34,018
B1020	Roof Construction	\$21.36	S.F.	5,478	100	2000	2100		85.00 %	0.00 %	85			\$117,010
B2010	Exterior Walls	\$19.80	S.F.	5,478	100	2000	2100		85.00 %	0.00 %	85			\$108,464
B2030	Exterior Doors	\$2.01	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$11,011
B3010	Roof Coverings - Standing Seam Metal	\$11.91	S.F.	5,478	75	2000	2075		80.00 %	0.00 %	60			\$65,243
C1010	Partitions	\$12.78	S.F.	5,478	100	2000	2100		85.00 %	0.00 %	85			\$70,009
C1020	Interior Doors	\$4.24	S.F.	5,478	40	2000	2040		62.50 %	0.00 %	25			\$23,227
C1030	Fittings	\$3.46	S.F.	5,478	20	2000	2020		25.00 %	0.00 %	5			\$18,954
C3010	Wall Finishes - Ceramic	\$6.65	S.F.		30	2000	2030		50.00 %	0.00 %	15			\$0
C3010	Wall Finishes - Paint	\$1.41	S.F.	5,478	10	2000	2010	2015	0.00 %	109.99 %	0		\$8,496.00	\$7,724
C3020	Floor Finishes - Ceramic Tile	\$6.67	S.F.	253	50	2000	2050		70.00 %	0.00 %	35			\$1,688
C3020	Floor Finishes - Neoprene	\$14.46	S.F.	4,554	15	2000	2015		0.00 %	110.00 %	0		\$72,436.00	\$65,851
C3020	Floor Finishes - VCT	\$5.01	S.F.	325	15	2000	2015		0.00 %	110.01 %	0		\$1,791.00	\$1,628
C3030	Ceiling Finishes	\$4.31	S.F.	5,478	20	2000	2020		25.00 %	0.00 %	5			\$23,610
D2010	Plumbing Fixtures	\$9.66	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$52,917
D2020	Domestic Water Distribution	\$5.85	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$32,046
D2030	Sanitary Waste	\$0.87	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$4,766
D2040	Rain Water Drainage	\$0.22	S.F.	0	30	2000	2030		50.00 %	0.00 %	15			\$0
D2090	Other Plumbing Systems - Natural Gas	\$0.32	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$1,753
D3040	Distribution Systems & Exhaust Systems	\$12.25	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$67,106
D3050	Terminal & Package Units	\$11.65	S.F.	5,478	15	2000	2015	2015	0.00 %	110.00 %	0		\$70,201.00	\$63,819
D3060	Controls & Instrumentation	\$0.26	S.F.	5,478	20	2000	2020		25.00 %	0.00 %	5			\$1,424
D4010	Sprinklers	\$3.84	S.F.	0	30				0.00 %	0.00 %				\$0
D5010	Electrical Service/Distribution	\$1.24	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$6,793
D5020	Branch Wiring	\$5.24	S.F.	5,478	30	2000	2030		50.00 %	0.00 %	15			\$28,705
D5020	Lighting	\$5.24	S.F.	5,478	20	2000	2020		25.00 %	0.00 %	5			\$28,705
D5030	Communications and Security - Fire Alarm	\$2.13	S.F.	5,478	10	2000	2010	2015	0.00 %	110.00 %	0		\$12,835.00	\$11,668
D5030	Communications and Security - Public Address & Clock System	\$0.88	S.F.	5,478	20	2000	2020	2015	0.00 %	110.00 %	0		\$5,303.00	\$4,821
D5030	Communications and Security - Security & CCTV	\$0.88	S.F.	5,478	10	2000	2010	2015	0.00 %	110.00 %	0		\$5,303.00	\$4,821
Total									56.35 %	19.40 %			\$176,365.00	\$908,946

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$176,365	\$0	\$0	\$0	\$0	\$92,698	\$0	\$0	\$0	\$0	\$35,794	\$304,857
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$24,170	\$0	\$0	\$0	\$0	\$0	\$24,170
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$8,496	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,418	\$19,914
C3020 - Floor Finishes - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Neoprene	\$72,436	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$72,436
C3020 - Floor Finishes - VCT	\$1,791	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,791
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$30,108	\$0	\$0	\$0	\$0	\$0	\$30,108
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 2000 Gym

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$70,201	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,201
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$1,817	\$0	\$0	\$0	\$0	\$0	\$1,817
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$36,604	\$0	\$0	\$0	\$0	\$0	\$36,604
D5030 - Communications and Security - Fire Alarm	\$12,835	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,249	\$30,084
D5030 - Communications and Security - Public Address & Clock System	\$5,303	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,303
D5030 - Communications and Security - Security & CCTV	\$5,303	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,127	\$12,430

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$176,365.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
C3010	Wall Finishes - Paint	\$0.00	\$0.00	\$8,496.00	\$0.00	\$0.00	\$8,496.00
C3020	Floor Finishes - Neoprene	\$0.00	\$0.00	\$72,436.00	\$0.00	\$0.00	\$72,436.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$1,791.00	\$0.00	\$0.00	\$1,791.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00	\$70,201.00
D5030	Communications and Security - Fire Alarm	\$0.00	\$0.00	\$12,835.00	\$0.00	\$0.00	\$12,835.00
D5030	Communications and Security - Public Address & Clock System	\$0.00	\$0.00	\$5,303.00	\$0.00	\$0.00	\$5,303.00
D5030	Communications and Security - Security & CCTV	\$0.00	\$0.00	\$5,303.00	\$0.00	\$0.00	\$5,303.00
Total:		\$0.00	\$0.00	\$176,365.00	\$0.00	\$0.00	\$176,365.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$176,365.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: C3010 - Wall Finishes - Paint



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$8,496.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The painted wall finishes are beyond their expected service life, dirty, and should be replaced. SPLOST IV project 101-422 to paint interior walls.

System: C3020 - Floor Finishes - Neoprene



Location: Gym

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 4,554.00

Unit of Measure: S.F.

Estimate: \$72,436.00

Assessor Name: Eduardo Lopez

Date Created: 12/16/2015

Notes: The flooring is stained, showing signs of early failure and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Office and Main Entrance

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 325.00

Unit of Measure: S.F.

Estimate: \$1,791.00

Assessor Name: Eduardo Lopez

Date Created: 12/16/2015

Notes: The VCT flooring is aged, stained, worn, and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Inadequate

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$70,201.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: One PTAC AC unit is located in the office area of the gym. It is beyond its expected service life. The main gym area does not have air conditioning and it should be provided.

System: D5030 - Communications and Security - Fire Alarm



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$12,835.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The fire alarm system is beyond its expected service life and should be scheduled for replacement.

System: D5030 - Communications and Security - Public Address & Clock System



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$5,303.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The public address and clock system is beyond its expected service life and should be scheduled for replacement.

System: D5030 - Communications and Security - Security & CCTV



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$5,303.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The security and CCTV systems are beyond their expected service life and should be scheduled for replacement.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	64,142
Year Built:	1955
Last Renovation:	
Replacement Value:	\$1,373,392
Repair Cost:	\$1,253,308.43
Total FCI:	91.26 %
Total RSLI:	4.60 %
FCA Score:	8.74



Description:

The Briar Vista Elementary School site was originally constructed in 1955, has a total area of 10.8 acres, and is occupied by approximately 64,142 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and electrical distribution. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site features.

Attributes:

General Attributes:

Site Code: 1070

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	8.51 %	75.32 %	\$559,035.42
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$515,765.83
G40 - Site Electrical Utilities	0.00 %	110.00 %	\$178,507.18
Totals:	4.60 %	91.26 %	\$1,253,308.43

Photo Album

The photo album consists of the various cardinal directions of the building.

- 1). Aerial Image of Briar Vista Elementary School - Oct 20, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$5.17	S.F.	30,324	25	1955	1980		0.00 %	110.00 %	-35		\$172,452.59	\$156,775
G2020	Parking Lots	\$4.56	S.F.	12,087	25	1955	1980		0.00 %	110.00 %	-35		\$60,628.39	\$55,117
G2030	Pedestrian Paving	\$1.50	S.F.	64,142	30	1955	1985		0.00 %	110.00 %	-30		\$105,834.30	\$96,213
G2040	Baseball Field	\$8.35	S.F.		20	1955	1975		0.00 %	0.00 %	-40			\$0
G2040	Canopies	\$0.29	S.F.		25	1955	1980		0.00 %	0.00 %	-35			\$0
G2040	Covered Walkways	\$48.72	S.F.	640	25	2000	2025		40.00 %	0.00 %	10			\$31,181
G2040	Fencing & Guardrails	\$0.91	S.F.	64,142	30	1955	1985		0.00 %	110.00 %	-30		\$64,206.14	\$58,369
G2040	Football Field	\$5.85	S.F.		20	1955	1975		0.00 %	0.00 %	-40			\$0
G2040	Hard Surface Play Area	\$6.26	S.F.	7,785	20	1955	1975		0.00 %	110.00 %	-40		\$53,607.51	\$48,734
G2040	Playing Field	\$3.92	S.F.	51,745	20	1955	1975	2020	25.00 %	0.00 %	5			\$202,840
G2040	Soccer/Lacross Field	\$5.00	S.F.		20	1955	1975		0.00 %	0.00 %	-40			\$0
G2040	Softball Field	\$8.86	S.F.		20	1955	1975		0.00 %	0.00 %	-40			\$0
G2040	Tennis Courts	\$18.47	S.F.		20	1955	1975		0.00 %	0.00 %	-40			\$0
G2040	Track	\$7.04	S.F.		10	1955	1965		0.00 %	0.00 %	-50			\$0
G2050	Landscaping	\$1.45	S.F.	64,142	15	1955	1970		0.00 %	110.00 %	-45		\$102,306.49	\$93,006
G3010	Water Supply	\$1.83	S.F.	64,142	50	1955	2005		0.00 %	110.00 %	-10		\$129,117.85	\$117,380
G3020	Sanitary Sewer	\$1.15	S.F.	64,142	50	1955	2005		0.00 %	110.00 %	-10		\$81,139.63	\$73,763
G3030	Storm Sewer	\$3.55	S.F.	64,142	50	1955	2005		0.00 %	110.00 %	-10		\$250,474.51	\$227,704
G3060	Fuel Distribution	\$0.78	S.F.	64,142	40	1955	1995		0.00 %	110.00 %	-20		\$55,033.84	\$50,031
G4010	Electrical Distribution	\$1.86	S.F.	64,142	50	1955	2005		0.00 %	110.00 %	-10		\$131,234.53	\$119,304
G4020	Site Lighting	\$1.15	S.F.	0	30				0.00 %	0.00 %				\$0
G4030	Site Communications & Security	\$0.67	S.F.	64,142	10	1955	1965		0.00 %	110.00 %	-50		\$47,272.65	\$42,975
Total									4.60 %	91.26 %			\$1,253,308.43	\$1,373,392

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

School Assessment Report - Site


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,253,308	\$0	\$0	\$0	\$0	\$258,662	\$0	\$0	\$0	\$0	\$109,626	\$1,621,596
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$172,453	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$172,453
G2020 - Parking Lots	\$60,628	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$60,628
G2030 - Pedestrian Paving	\$105,834	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$105,834
G2040 - Baseball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$46,095	\$46,095
G2040 - Fencing & Guardrails	\$64,206	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$64,206
G2040 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Hard Surface Play Area	\$53,608	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$53,608
G2040 - Playing Field	\$0	\$0	\$0	\$0	\$0	\$258,662	\$0	\$0	\$0	\$0	\$0	\$258,662
G2040 - Soccer/Lacross Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Softball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Tennis Courts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping	\$102,306	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$102,306
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$129,118	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$129,118
G3020 - Sanitary Sewer	\$81,140	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$81,140
G3030 - Storm Sewer	\$250,475	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$250,475
G3060 - Fuel Distribution	\$55,034	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,034
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$131,235	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$131,235
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$47,273	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$63,531	\$110,804

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$1,253,308.43

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
G2010	Roadways	\$0.00	\$0.00	\$172,452.59	\$0.00	\$0.00	\$172,452.59
G2020	Parking Lots	\$0.00	\$0.00	\$60,628.39	\$0.00	\$0.00	\$60,628.39
G2030	Pedestrian Paving	\$0.00	\$0.00	\$105,834.30	\$0.00	\$0.00	\$105,834.30
G2040	Fencing & Guardrails	\$0.00	\$0.00	\$64,206.14	\$0.00	\$0.00	\$64,206.14
G2040	Hard Surface Play Area	\$0.00	\$0.00	\$53,607.51	\$0.00	\$0.00	\$53,607.51
G2050	Landscaping	\$0.00	\$0.00	\$102,306.49	\$0.00	\$0.00	\$102,306.49
G3010	Water Supply	\$0.00	\$0.00	\$129,117.85	\$0.00	\$0.00	\$129,117.85
G3020	Sanitary Sewer	\$0.00	\$0.00	\$81,139.63	\$0.00	\$0.00	\$81,139.63
G3030	Storm Sewer	\$0.00	\$250,474.51	\$0.00	\$0.00	\$0.00	\$250,474.51
G3060	Fuel Distribution	\$0.00	\$0.00	\$55,033.84	\$0.00	\$0.00	\$55,033.84
G4010	Electrical Distribution	\$0.00	\$0.00	\$131,234.53	\$0.00	\$0.00	\$131,234.53
G4030	Site Communications & Security	\$0.00	\$0.00	\$47,272.65	\$0.00	\$0.00	\$47,272.65
Total:		\$0.00	\$250,474.51	\$1,002,833.92	\$0.00	\$0.00	\$1,253,308.43

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,253,308.43

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 Priority:

System: G3030 - Storm Sewer



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 2 Priority

Correction: Renew System

Qty: 64,142.00

Unit of Measure: S.F.

Estimate: \$250,474.51

Assessor Name: Eduardo Lopez

Date Created: 06/28/2015

Notes: The storm sewer system is beyond its expected service life and should be scheduled for replacement. Storm water runoff funnels into a depression in front of the 1979 addition, causing flooding of the building's classrooms.

Priority 3 Priority:

System: G2010 - Roadways



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 30,324.00

Unit of Measure: S.F.

Estimate: \$172,452.59

Assessor Name: Eduardo Lopez

Date Created: 06/28/2015

Notes: Roadways are beyond their expected service life, damaged with many cracks and potholes, worn, and should be replaced.

System: G2020 - Parking Lots



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 12,087.00

Unit of Measure: S.F.

Estimate: \$60,628.39

Assessor Name: Sam Mandola

Date Created: 06/28/2015

Notes: The parking lot is beyond its expected service life, inadequate, deteriorating, not fully ADA compliant, and should be replaced.

System: G2030 - Pedestrian Paving



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 64,142.00

Unit of Measure: S.F.

Estimate: \$105,834.30

Assessor Name: Sam Mandola

Date Created: 06/28/2015

Notes: Pedestrian paving is beyond its expected service life, damaged, not fully ADA compliant, and should be replaced.

System: G2040 - Fencing & Guardrails



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 64,142.00

Unit of Measure: S.F.

Estimate: \$64,206.14

Assessor Name: Eduardo Lopez

Date Created: 06/28/2015

Notes: Fencing is damaged from overgrown vines and brush, and should be replaced. Handrails in front of campus and at lower field are damaged and in need of repair.

System: G2040 - Hard Surface Play Area



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 7,785.00

Unit of Measure: S.F.

Estimate: \$53,607.51

Assessor Name: Eduardo Lopez

Date Created: 06/28/2015

Notes: The hard surface play area is beyond its expected service life, damaged with cracks, and should be replaced. Basketball goals are also damaged and should be replaced.

System: G2050 - Landscaping



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 64,142.00

Unit of Measure: S.F.

Estimate: \$102,306.49

Assessor Name: Eduardo Lopez

Date Created: 06/28/2015

Notes: Landscaping is beyond its expected service life, overgrown, and should be replaced.

System: G3010 - Water Supply



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 64,142.00
Unit of Measure: S.F.
Estimate: \$129,117.85
Assessor Name: Eduardo Lopez
Date Created: 06/28/2015

Notes: The site water supply system is beyond its expected service life and should be scheduled for replacement. SPLOST IV project 101-422 to replace the backflow preventer.

System: G3020 - Sanitary Sewer



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 64,142.00
Unit of Measure: S.F.
Estimate: \$81,139.63
Assessor Name: Eduardo Lopez
Date Created: 06/28/2015

Notes: The site sanitary sewer system is beyond its expected service life and should be scheduled for replacement. SPLOST IV project 101-422 to replace grease trap and backflow preventer.

System: G3060 - Fuel Distribution



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 64,142.00
Unit of Measure: S.F.
Estimate: \$55,033.84
Assessor Name: Eduardo Lopez
Date Created: 06/28/2015

Notes: The site fuel distribution system is beyond its expected service life and should be scheduled for replacement.

System: G4010 - Electrical Distribution



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 64,142.00
Unit of Measure: S.F.
Estimate: \$131,234.53
Assessor Name: Eduardo Lopez
Date Created: 06/28/2015

Notes: The site electrical distribution system is beyond its expected service life and should be scheduled for replacement.

System: G4030 - Site Communications & Security



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 64,142.00

Unit of Measure: S.F.

Estimate: \$47,272.65

Assessor Name: Eduardo Lopez

Date Created: 06/28/2015

Notes: The site communications and security systems are beyond their expected service life and should be scheduled for replacement.

Glossary

Abandoned	A facility owned by a district that is not occupied and not maintained. See Vacant.
Additional Cost	Total project cost is composed of hard and soft costs. Additional costs or soft expenses are costs that are necessary to accomplish the corrective work but are not directly attributable to the deficient systems direct construction cost, which are often referred to as hard cost. The components included in the soft costs vary by owner but usually include architect and contractor fees, contingencies and other owner-incurred costs necessary to fully develop and build a facility. These soft cost factors can be adjusted anytime within the eCOMET® database at the owner's discretion.
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems, reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ASTM	ASTM International (ASTM): Originally known as the American Society for Testing and Materials, ASTM is an international standards organization that develops and publishes voluntary consensus technical standards for a wide range of materials, products, systems, and services.
BOMA	Building Owners Managers of America (BOMA): National organization of public and private facility owners focused on building management tools and maintenance techniques. eCOMET® reference: Building and component system effective economic life expectancies.
Building	A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior.
Building Addition	An area, space or component of a building added to a building after the original building's year built date. NOTE: As a convention in the database, "Main" was used to designate the original building. Additions built prior to 1983 (30 years) were included in the main building area calculations to reflect their predicted system depreciation characteristics and remaining service life.
Building Systems	eCOMET® uses UNIFORMAT II to organize building data. UNIFORMAT II was originally developed by the federal General Services Administration to delineate building costs by systems rather than by material. UNIFORMAT II was formalized by an NIST standard, NISTIR 6389 in 1999. It has been further quantified and updated by ASTM standard 2005, E1557-05. The Construction Specifications Institute, CSI, has taken over the standard as part of their MasterFormat / MasterSpec system.
Calculated Next Renewal	The year a system or building element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal refers to the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life. It is not normally included in an annual operating/maintenance budget. See calculated next renewal and next renewal.
City Cost Index (CCI)	RS Means provides building system, equipment, and construction costs at a national level. The City Cost Index (also provided by RS Means) localizes those costs to a geographic region of the United States. In eCOMET®, each building or site is assigned a City Cost Index, which adjusts all of the associated costs for systems, deficiencies and inventory to the local value.
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
Condition Budget	The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work.

School Assessment Report - Briar Vista Elementary

Condition Index (CI) %	The Condition Index (CI) also known as the Remaining Service Life Index (RSLI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude soft cost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).
Construction Specifications Institute	Construction Specifications Institute: Primary national organization specializing in construction materials data and data location in construction documents. eCOMET® reference: UNIFORMAT II materials classification.
Correction	Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a UNIFORMAT II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction.
Cost Model	A cost model is a list of facility systems which could represent the installed systems a given facility. Included in the cost model are standard unit cost estimates, gross areas, life cycles and installed dates. Also represented is the repair cost for deficient systems, replacement values. See eCOMET® cost models.
Criteria	Criteria refer to the set of requirements, guidelines or standards that are assessed and rated to develop a score.
Current Period	The Current Period is the current year plus a user defined number of forward years.
Current Replacement Value (CRV)	The Current Replacement Value (CRV) of a facility, building or system represents the hypothetical cost of rebuilding or replacing an existing facility under today's codes and construction standards, using its current configuration. It is calculated by multiplying the gross area of the facility by a square foot cost developed in that facility's cost model. Replacement cost includes construction costs and owner's additional or soft costs for fees, permits and other expenses to reflect a total project cost.
Deferred Maintenance	Deferred maintenance is condition work deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose.
Deficiency Category	Deficiency Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions include, but are not limited to: Accessibility Code Compliance, Appearance, Building Code Compliance, Deferred Maintenance, Energy, Environmental, Life Safety Code Compliance, and Safety.
Deficiency Distress	Deficiency Distress refers to a user-defined root cause of a deficiency. Distress descriptions are: Beyond Service Life, Damaged, Inadequate, Needs Remediation, and Missing.
Deficiency Priority	Deficiency Priority refers to a deficiency's urgency for repair as determined by the assessment team. Deficiencies were assigned a priority of 1 through 5, with Priority 1 deficiencies being the most urgent.
eCOMET®	Energy and Condition Management Estimation Technology (eCOMET®) is Parsons proprietary facility asset management software developed to provide facility managers with a state of the art, web-based tool to develop and maintain a comprehensive database of FCA data and information used for facility asset management, maintenance and repair, and capital renewal planning. eCOMET® is used by Parsons and its clients as the primary tool for collecting FCA data, preparing cost estimates, generating individual facility reports and cost estimates, and developing the overall capital renewal program.

School Assessment Report - Briar Vista Elementary

eCOMET® Cost Models	eCOMET® cost models are derived from RS Means Square Foot Cost Data cost models and these models are used to develop the current replacement value (CRV) and assign life cycle costs to the various systems within a building. Cost models are assigned current costs-per-square-foot to establish replacement values. The Cost models are designed to represent a client specific facility that meets local standards cost trends.
Element	Elements are the major components that comprise building systems as defined by UNIFORMAT II.
Expected Life	Also referred to as Useful Life. See Useful Life definition.
Facility	A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose.
Facility Attributes	Customizable eCOMET® fields to identify attributes specific to a facility. These fields are part of the eCOMET® database set-up with the owner.
Facility Condition Assessment (FCA)	A facility condition assessment (FCA) is a visual inspection of buildings and grounds at a facility to identify and estimate current and future needed repairs or replacements of major systems for planning and budgeting purposes. It is typically performed for organizations that are tasked with the day to day maintenance, operation, and capital renewal (replacement) of building systems and components of a large inventory of facilities. The primary goal of an FCA is to objectively and quantifiably identify, inspect, and prioritize the repair and replacement needs of the building and ground systems (e.g., roofs, windows, doors, floor finishes, plumbing fixtures, parking lot, and sidewalks) within facilities that have either failed or have surpassed their service life, and to identify and forecast future capital replacement needs for systems that have not yet failed, but planned replacement of those systems is needed to ensure that the facilities will continue to meet the mission of the organization.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition expressed as a percentage from 0.00% to 100.00% that is derived by dividing the cost to correct a facility's deficiencies by its Current Replacement Value (CRV). The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio, a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.
Forecast Period	The Forecast Period refers to a user defined number of years forward of the Current Period.
Gen (Generate)	The Cost Model has a Gen box for each system line item. By checking the box, eCOMET® will generate life cycle deficiencies based on the Year Installed and the Life for that system. Systems that typically do not re-generate (foundations, floor construction, roof construction, basement walls, etc.) would not have the Gen box checked as those systems would not re-generate at the end of a life cycle. In those instances, it would be more practical and cost effective to demolish the entire facility than renew those systems.
Gross Square Feet (GSF)	The area of the enclosed floor space of a building or building addition in square feet measured to the outside face of the enclosing wall.
Life cycle	Life cycle refers to the period of time that a building or site system or element can be expected to adequately serve its intended function. Parsons assigns expected life cycles to all building systems based on Building Operators and Managers of America (BOMA) recommended life cycles, manufacturers suggested life, and RS Means cost data, and client-provided historical data. BOMA standards are a nationally recognized source of life cycle data for various components and/or systems associated with facilities. RS Means is a national company specializing in construction estimating and costs.
Next Renewal	Next Renewal refers to a manually-adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately reflect current conditions.

School Assessment Report - Briar Vista Elementary

Order of Magnitude	Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.
Remaining Service Life (RSL)	RSL is the number of years of service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the Calculated Next Renewal date or the Next Renewal date whichever one is the later date.
Renewal Factors	Renewal factors represent the difference in cost of renovating or replacing an existing system, rather than new construction of a building system. For example, installing a new built-up roof on an existing building would include removing and disposing of the old roof, a cost not associated with new construction. Using a renewal premium to account for demolition and other difficulty costs, Parsons typically assigns a renewal factor of 110%.
Renewal Schedule	A timeline by year that indicates when the systems will need to be renewed and the estimated price of the renewal.
Repair Cost	Repair cost is the sum of all the deficiencies associated with a building or multiple buildings/facilities. It will include any applied soft costs or City Cost Indexes.
Replacement Value	See Current Replacement Value.
Site	A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.
Soft Costs	Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user-defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses.
Sustainability	Sustainability refers to the collection of policies and strategies that meet society's present needs without compromising the ability of future generations to meet their own needs.
System	System refers to building and related site work elements as described by ASTM UNIFORMAT II Classification for Building Elements (E1557-97), a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also UNIFORMAT II.
System Generated Deficiency	eCOMET® automatically generates system deficiencies based on system life cycles using the systems installation dates as the base year. By adjusting the Next Renewal date ahead or behind the predicted or stated life cycle date, a system cost will come due earlier or later than the originally installed life cycle date. This utility accounts for good maintenance conditions and a longer life, or early expiration of a system life due to any number of adverse factors such as poor installation, acts of god, material defects, poor design applications and other factors that may shorten the life of a material or system. It is important to mention that the condition of the systems is not necessarily a reflection of maintenance practices, but a combination of system usage and age.
UNIFORMAT	ASTM UNIFORMAT II, Classification for Building Elements (E1557-97), a publication of the Construction Specification Institute (CSI), is a format used to classify major facility components common to most buildings. The format is based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies.
Unit Price	The Unit Price (Raw) x (100% + the Additional Cost Template percentage).
Unit Price (Raw)	The actual \$/sq. ft cost being used for the building and systems. It will include adjustments for the City Cost Index applied to the facility.

School Assessment Report - Briar Vista Elementary

Useful Life	Also known as Expected Life, Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in the database are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from client- defined historical experience.
Vacant	Vacant refers to a facility that is not occupied but is a maintained facility by a district. See Abandoned.
Year Built	The year that a building or addition was originally built based on its date of substantial completion or occupancy.
Year Installed	The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.