

DeKalb County School District/Elementary Schools

Dresden Elementary

Final

School Assessment Report

May 19, 2016



Table of Contents

School Executive Summary	5
School Condition Summary	7
<u>1963, 1965, 1967 Building</u>	9
Executive Summary	9
Condition Summary	10
Photo Album	11
Condition Detail	12
System Listing	13
Renewal Schedule	15
Forecasted Sustainment Requirement	18
Deficiency Summary By System	19
Deficiency Summary By Priority	20
Deficiency By Priority Investment	21
Deficiency Summary By Category	22
Deficiency Details By Priority	23
<u>1980 Storage</u>	36
Executive Summary	36
Condition Summary	37
Photo Album	38
Condition Detail	39
System Listing	40
Renewal Schedule	41
Forecasted Sustainment Requirement	44
Deficiency Summary By System	45
Deficiency Summary By Priority	46
Deficiency By Priority Investment	47
Deficiency Summary By Category	48
Deficiency Details By Priority	49
<u>1998 Addition</u>	50

School Assessment Report

Executive Summary	50
Condition Summary	51
Photo Album	52
Condition Detail	53
System Listing	54
Renewal Schedule	56
Forecasted Sustainment Requirement	59
Deficiency Summary By System	60
Deficiency Summary By Priority	61
Deficiency By Priority Investment	62
Deficiency Summary By Category	63
Deficiency Details By Priority	64
<u>1998 Gym</u>	65
Executive Summary	65
Condition Summary	66
Photo Album	67
Condition Detail	68
System Listing	69
Renewal Schedule	70
Forecasted Sustainment Requirement	72
Deficiency Summary By System	73
Deficiency Summary By Priority	74
Deficiency By Priority Investment	75
Deficiency Summary By Category	76
Deficiency Details By Priority	77
<u>Site</u>	80
Executive Summary	80
Condition Summary	81
Photo Album	82
Condition Detail	83
System Listing	84

School Assessment Report

Renewal Schedule	85
Forecasted Sustainment Requirement	87
Deficiency Summary By System	88
Deficiency Summary By Priority	89
Deficiency By Priority Investment	90
Deficiency Summary By Category	91
Deficiency Details By Priority	92
Glossary	99

School Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	69,880
Year Built:	1963
Last Renovation:	
Replacement Value:	\$16,147,557
Repair Cost:	\$9,651,394.00
Total FCI:	59.77 %
Total RSLI:	21.65 %
FCA Score:	40.23



Description:

The Dresden Elementary School campus consists of two buildings located at 2449 Dresden Drive in Chamblee, Georgia. The original campus was constructed in 1963, additions to the main school building were constructed in 1965, 1967, and 1998, and a gymnasium building was constructed in 1998. In addition to these buildings, the campus contains a storage building, covered walkway, hard surface play area, playground, and playfield. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for each building and site improvement on the campus.

School Assessment Report - Dresden Elementary

Attributes:

General Attributes:

Assigned Region:	Region 1	Board District:	District 4
DOE Facility:	1055	Geographic Region:	Region 1
HS Attendance Area:	Cross Keys HS	Jurisdictional City:	City of Chamblee
Site Acreage:	9.1		

School Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	58.88 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	63.26 %	0.00 %	\$0.00
B20 - Exterior Enclosure	44.37 %	25.04 %	\$413,126.00
B30 - Roofing	11.01 %	79.48 %	\$1,143,245.00
C10 - Interior Construction	51.39 %	10.38 %	\$92,982.00
C20 - Stairs	83.00 %	0.00 %	\$0.00
C30 - Interior Finishes	23.44 %	31.16 %	\$650,487.00
D10 - Conveying	90.00 %	0.00 %	\$0.00
D20 - Plumbing	12.29 %	78.97 %	\$1,414,919.00
D30 - HVAC	2.93 %	100.95 %	\$2,589,246.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	18.71 %	55.91 %	\$953,749.00
E10 - Equipment	0.19 %	108.60 %	\$536,011.00
E20 - Furnishings	3.65 %	83.22 %	\$287,263.00
F10 - Special Construction	7.79 %	75.65 %	\$78,296.00
G20 - Site Improvements	4.20 %	95.55 %	\$850,223.00
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$501,947.00
G40 - Site Electrical Utilities	33.36 %	54.40 %	\$139,900.00
Totals:	21.65 %	59.77 %	\$9,651,394.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 Priority	2 Priority	3 Priority	4 Priority	5 Priority
1963, 1965, 1967 Building	48,631	72.59	\$0.00	\$0.00	\$7,579,302.00	\$0.00	\$0.00
1980 Storage	120	30.01	\$0.00	\$0.00	\$2,902.00	\$0.00	\$0.00
1998 Addition	15,651	15.04	\$0.00	\$0.00	\$478,780.00	\$0.00	\$0.00
1998 Gym	5,478	10.81	\$0.00	\$0.00	\$98,340.00	\$0.00	\$0.00
Site	69,880	93.06	\$0.00	\$88,398.00	\$1,193,208.00	\$210,464.00	\$0.00
Total:		59.77	\$0.00	\$88,398.00	\$9,352,532.00	\$210,464.00	\$0.00

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	48,631
Year Built:	1963
Last Renovation:	
Replacement Value:	\$10,441,560
Repair Cost:	\$7,579,302.00
Total FCI:	72.59 %
Total RSLI:	14.48 %
FCA Score:	27.41



Description:

The main building at Dresden Elementary School is a one-story building located at 2449 Dresden Drive in Chamblee, Georgia. Originally built in 1963, there have been three additions in 1965, 1967, and 1998, and minor renovations in 2005 and 2010. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2010, 2011, 2012	Fire Sprinkler System:	No
-----------------	------------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	48.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	48.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	32.40 %	35.74 %	\$412,440.00
B30 - Roofing	0.00 %	110.00 %	\$1,141,029.00
C10 - Interior Construction	45.91 %	15.68 %	\$92,982.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	18.91 %	41.59 %	\$640,486.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	0.00 %	110.00 %	\$1,414,919.00
D30 - HVAC	0.00 %	110.00 %	\$2,040,265.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	10.83 %	76.10 %	\$935,611.00
E10 - Equipment	0.00 %	110.00 %	\$536,011.00
E20 - Furnishings	0.00 %	110.00 %	\$287,263.00
F10 - Special Construction	0.00 %	100.00 %	\$78,296.00
Totals:	14.48 %	72.59 %	\$7,579,302.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). North Elevation - Jul 16, 2015



2). East Elevation - Jul 16, 2015



3). East Elevation - Jul 16, 2015



4). South Elevation - Jul 16, 2015



5). West Elevation - Jul 16, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1963, 1965, 1967 Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	48,631	100	1963	2063		48.00 %	0.00 %	48			\$315,615
A1020	Special Foundations	\$4.46	S.F.	0	100	1963	2063		48.00 %	0.00 %	48			\$0
A1030	Slab on Grade	\$7.09	S.F.	48,631	100	1963	2063		48.00 %	0.00 %	48			\$344,794
A2010	Basement Excavation	\$0.26	S.F.	0	100	1963	2063		48.00 %	0.00 %	48			\$0
A2020	Basement Walls	\$6.13	S.F.	0	100	1963	2063		48.00 %	0.00 %	48			\$0
B1010	Floor Construction	\$15.61	S.F.	0	100	1963	2063		48.00 %	0.00 %	48			\$0
B1020	Roof Construction	\$5.34	S.F.	48,631	100	1963	2063		48.00 %	0.00 %	48			\$259,690
B2010	Exterior Walls	\$16.02	S.F.	48,631	100	1963	2063		48.00 %	0.00 %	48			\$779,069
B2020	Exterior Windows	\$6.79	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$363,225.00	\$330,204
B2030	Exterior Doors	\$0.92	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$49,215.00	\$44,741
B3010	Roof Coverings - Asphal Shingles	\$4.32	S.F.	0	10	1963	1973		0.00 %	0.00 %	-42			\$0
B3010	Roof Coverings - BUR	\$20.70	S.F.	48,631	25	1963	1988		0.00 %	110.00 %	-27		\$1,107,328.00	\$1,006,662
B3010	Roof Coverings - EPDM	\$3.33	S.F.	0	15	1963	1978		0.00 %	0.00 %	-37			\$0
B3010	Roof Coverings - Preformed Metal	\$5.01	S.F.	0	30	1963	1993		0.00 %	0.00 %	-22			\$0
B3010	Roof Coverings - Standing Seam Metal	\$27.45	S.F.	0	75	1963	2038		30.67 %	0.00 %	23			\$0
B3020	Roof Openings	\$0.63	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$33,701.00	\$30,638
C1010	Partitions	\$7.01	S.F.	48,631	100	1963	2063		48.00 %	0.00 %	48			\$340,903
C1020	Interior Doors	\$2.39	S.F.	48,631	30	1963	1993		0.00 %	80.00 %	-22		\$92,982.00	\$116,228
C1030	Fittings	\$2.79	S.F.	48,631	20	2011	2031		80.00 %	0.00 %	16			\$135,680
C2010	Stair Construction	\$1.81	S.F.	0	0				0.00 %	0.00 %				\$0
C3010	Wall Finishes - Ceramic & Glazed	\$10.27	S.F.	19,452	30	1963	1993		0.00 %	110.00 %	-22		\$219,749.00	\$199,772
C3010	Wall Finishes - Paint	\$1.93	S.F.	29,179	10	2011	2021		60.00 %	0.00 %	6			\$56,315
C3010	Wall Finishes - Wall Coverings	\$2.13	S.F.	0	10	1963	1973		0.00 %	0.00 %	-42			\$0
C3020	Floor Finishes - Carpet	\$8.50	S.F.	3,473	8	2011	2019		50.00 %	0.00 %	4			\$29,521
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	4,298	50	1963	2013		0.00 %	110.00 %	-2		\$68,506.00	\$62,278
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	7,295	50	1963	2013		0.00 %	0.00 %	-2			\$386,708
C3020	Floor Finishes - VCT	\$9.54	S.F.	33,565	20	1963	1983		0.00 %	110.00 %	-32		\$352,231.00	\$320,210
C3020	Floor Finishes - Wood	\$14.70	S.F.	0	20	1963	1983		0.00 %	0.00 %	-32			\$0
C3030	Ceiling Finishes	\$9.98	S.F.	48,631	20	2005	2025		50.00 %	0.00 %	10			\$485,337
D1010	Elevators and Lifts	\$1.17	S.F.	0	30	1963	1993		0.00 %	0.00 %	-22			\$0
D2010	Plumbing Fixtures	\$17.66	S.F.	48,631	30	1998	2028	2015	0.00 %	110.00 %	0		\$944,706.00	\$858,823
D2020	Domestic Water Distribution	\$3.99	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$213,441.00	\$194,038
D2030	Sanitary Waste	\$3.41	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$182,415.00	\$165,832
D2040	Rain Water Drainage	\$0.98	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$52,424.00	\$47,658

School Assessment Report - 1963, 1965, 1967 Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	48,631	40	1963	2003		0.00 %	110.00 %	-12		\$21,933.00	\$19,939
D3020	Heat Generating Systems	\$4.55	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$243,398.00	\$221,271
D3030	Cooling Generating Systems	\$4.73	S.F.	48,631	30	1978	2008		0.00 %	110.00 %	-7		\$253,027.00	\$230,025
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	48,631	30	1978	2008		0.00 %	110.00 %	-7		\$294,752.00	\$267,957
D3050	Terminal & Package Units	\$18.52	S.F.	48,631	15	1978	1993		0.00 %	110.00 %	-22		\$990,711.00	\$900,646
D3060	Controls & Instrumentation	\$3.60	S.F.	48,631	20	1978	1998		0.00 %	110.00 %	-17		\$192,579.00	\$175,072
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$65,798.00	\$59,816
D4010	Sprinklers	\$4.75	S.F.	0	30	1963	1993		0.00 %	0.00 %	-22			\$0
D4020	Standpipes	\$0.51	S.F.	0	30	1963	1993		0.00 %	0.00 %	-22			\$0
D5010	Electrical Service/Distribution	\$1.81	S.F.	48,631	40	1963	2003		0.00 %	110.00 %	-12		\$96,824.00	\$88,022
D5020	Branch Wiring	\$6.78	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$362,690.00	\$329,718
D5020	Lighting	\$8.90	S.F.	48,631	30	1963	1993		0.00 %	110.00 %	-22		\$476,097.00	\$432,816
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	48,631	15	2005	2020		33.33 %	0.00 %	5			\$272,334
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	48,631	15	2005	2020		33.33 %	0.00 %	5			\$59,816
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	48,631	15	2005	2020		33.33 %	0.00 %	5			\$29,665
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	48,631	15	2011	2026		73.33 %	0.00 %	11			\$17,021
E1020	Institutional Equipment	\$0.40	S.F.	48,631	20	1963	1983		0.00 %	110.00 %	-32		\$21,398.00	\$19,452
E1090	Other Equipment (Kitchen Equipment)	\$9.62	S.F.	48,631	20	1963	1983		0.00 %	110.00 %	-32		\$514,613.00	\$467,830
E2010	Fixed Furnishings	\$5.37	S.F.	48,631	20	1963	1983		0.00 %	110.00 %	-32		\$287,263.00	\$261,148
F1010	Special Structures - Canopies	\$1.61	S.F.	48,631	25	1963	1988		0.00 %	100.00 %	-27		\$78,296.00	\$78,296
Total									14.48 %	72.59 %			\$7,579,302.00	\$10,441,560

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$7,579,302	\$0	\$0	\$0	\$36,549	\$461,386	\$73,968	\$0	\$0	\$0	\$717,478	\$8,868,683
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1020 - Special Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$363,225	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$363,225
B2030 - Exterior Doors	\$49,215	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$49,215
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Asphal Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$1,107,328	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,107,328
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Preformed Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$33,701	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$33,701
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1963, 1965, 1967 Building

C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$92,982	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$92,982
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic & Glazed	\$219,749	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$219,749
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$0	\$73,968	\$0	\$0	\$0	\$0	\$73,968
C3010 - Wall Finishes - Wall Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Carpet	\$0	\$0	\$0	\$0	\$36,549	\$0	\$0	\$0	\$0	\$0	\$0	\$36,549
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$68,506	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$68,506
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$352,231	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$352,231
C3020 - Floor Finishes - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$717,478	\$717,478
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$944,706	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$944,706
D2020 - Domestic Water Distribution	\$213,441	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$213,441
D2030 - Sanitary Waste	\$182,415	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$182,415
D2040 - Rain Water Drainage	\$52,424	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$52,424
D2090 - Other Plumbing Systems - Natural Gas	\$21,933	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,933
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$243,398	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$243,398
D3030 - Cooling Generating Systems	\$253,027	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$253,027
D3040 - Distribution & Exhaust Systems	\$294,752	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$294,752
D3050 - Terminal & Package Units	\$990,711	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$990,711
D3060 - Controls & Instrumentation	\$192,579	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$192,579
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$65,798	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,798
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1963, 1965, 1967 Building

D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$96,824	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$96,824
D5020 - Branch Wiring	\$362,690	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$362,690
D5020 - Lighting	\$476,097	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$476,097
D5030 - Communications and Security - Clock & PA Systems	\$0	\$0	\$0	\$0	\$0	\$347,280	\$0	\$0	\$0	\$0	\$0	\$347,280
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$76,278	\$0	\$0	\$0	\$0	\$0	\$76,278
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$37,828	\$0	\$0	\$0	\$0	\$0	\$37,828
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$21,398	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,398
E1090 - Other Equipment (Kitchen Equipment)	\$514,613	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$514,613
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$287,263	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$287,263
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$78,296	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$78,296

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$7,579,302.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$363,225.00	\$0.00	\$0.00	\$363,225.00
B2030	Exterior Doors	\$0.00	\$0.00	\$49,215.00	\$0.00	\$0.00	\$49,215.00
B3010	Roof Coverings - BUR	\$0.00	\$0.00	\$1,107,328.00	\$0.00	\$0.00	\$1,107,328.00
B3020	Roof Openings	\$0.00	\$0.00	\$33,701.00	\$0.00	\$0.00	\$33,701.00
C1020	Interior Doors	\$0.00	\$0.00	\$92,982.00	\$0.00	\$0.00	\$92,982.00
C3010	Wall Finishes - Ceramic & Glazed	\$0.00	\$0.00	\$219,749.00	\$0.00	\$0.00	\$219,749.00
C3020	Floor Finishes - Ceramic & Quarry Tile	\$0.00	\$0.00	\$68,506.00	\$0.00	\$0.00	\$68,506.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$352,231.00	\$0.00	\$0.00	\$352,231.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$944,706.00	\$0.00	\$0.00	\$944,706.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$213,441.00	\$0.00	\$0.00	\$213,441.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$182,415.00	\$0.00	\$0.00	\$182,415.00
D2040	Rain Water Drainage	\$0.00	\$0.00	\$52,424.00	\$0.00	\$0.00	\$52,424.00
D2090	Other Plumbing Systems - Natural Gas	\$0.00	\$0.00	\$21,933.00	\$0.00	\$0.00	\$21,933.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$243,398.00	\$0.00	\$0.00	\$243,398.00
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$253,027.00	\$0.00	\$0.00	\$253,027.00
D3040	Distribution & Exhaust Systems	\$0.00	\$0.00	\$294,752.00	\$0.00	\$0.00	\$294,752.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$990,711.00	\$0.00	\$0.00	\$990,711.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$192,579.00	\$0.00	\$0.00	\$192,579.00
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$0.00	\$0.00	\$65,798.00	\$0.00	\$0.00	\$65,798.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$96,824.00	\$0.00	\$0.00	\$96,824.00
D5020	Branch Wiring	\$0.00	\$0.00	\$362,690.00	\$0.00	\$0.00	\$362,690.00
D5020	Lighting	\$0.00	\$0.00	\$476,097.00	\$0.00	\$0.00	\$476,097.00
E1020	Institutional Equipment	\$0.00	\$0.00	\$21,398.00	\$0.00	\$0.00	\$21,398.00
E1090	Other Equipment (Kitchen Equipment)	\$0.00	\$0.00	\$514,613.00	\$0.00	\$0.00	\$514,613.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$287,263.00	\$0.00	\$0.00	\$287,263.00
F1010	Special Structures - Canopies	\$0.00	\$0.00	\$78,296.00	\$0.00	\$0.00	\$78,296.00
Total:		\$0.00	\$0.00	\$7,579,302.00	\$0.00	\$0.00	\$7,579,302.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$7,579,302.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B2020 - Exterior Windows



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.


Estimate: \$363,225.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The aluminum frame, operable, single pane windows are aged, not energy efficient, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$49,215.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: B3010 - Roof Coverings - BUR



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$1,107,328.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The built-up roof covering is aged, showing signs of failure, has reported leaks, and should be replaced. SPLOST project 106-422 to replace the roof on the 63, 65, and 67 buildings.

System: B3020 - Roof Openings



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$33,701.00

Assessor Name: Sam Mandola

Date Created: 07/16/2015

Notes: The roof openings are aging, showing signs of failure, and should be replaced in conjunction with the roof. SPLOST project 106-422 to replace the roof openings on the 63, 65, and 67 buildings.

System: C1020 - Interior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Building Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$92,982.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The interior doors are aged, failing, and should be renovated or to comply with building code and improve ADA accessibility.

System: C3010 - Wall Finishes - Ceramic & Glazed



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 19,452.00

Unit of Measure: S.F.

Estimate: \$219,749.00

Assessor Name: Ben Nixon

Date Created: 07/16/2015

Notes: The wall finishes are aged, scuffed and stained, and should be replaced.

System: C3020 - Floor Finishes - Ceramic & Quarry Tile



Location: Kitchen and Restrooms

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 4,298.00

Unit of Measure: S.F.

Estimate: \$68,506.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The tile floor covering is beyond its expected service life and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Classrooms and Cafeteria

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 33,565.00

Unit of Measure: S.F.

Estimate: \$352,231.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The VCT flooring has some deterioration due to age and wear, and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building

Distress: Damaged

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$944,706.00

Assessor Name: Sam Mandola

Date Created: 07/15/2015

Notes: Plumbing fixtures throughout the facility are failing early and need extensive maintenance, and should be scheduled for replacement. SPLOST project 106-422 to provide hall restroom renovations.

System: D2020 - Domestic Water Distribution



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.


Estimate: \$213,441.00

Assessor Name: Ben Nixon

Date Created: 07/14/2015

Notes: The domestic water distribution system is beyond its expected service life and should be scheduled for replacement.

System: D2030 - Sanitary Waste



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$182,415.00

Assessor Name: Ben Nixon

Date Created: 07/14/2015

Notes: The sanitary waste system is beyond its expected service life and should be scheduled for replacement.

System: D2040 - Rain Water Drainage



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$52,424.00

Assessor Name: Ben Nixon

Date Created: 07/15/2015

Notes: The rain water drainage system is in poor condition, beyond service life and should be scheduled for replacement.

System: D2090 - Other Plumbing Systems - Natural Gas



Location: Northeast Side of Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$21,933.00

Assessor Name: Ben Nixon

Date Created: 07/14/2015

Notes: The natural gas system is beyond its expected service life and should be scheduled for replacement.

System: D3020 - Heat Generating Systems



Location: Mechanical Room

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$243,398.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The boiler is beyond its expected service life and should be scheduled for replacement.

System: D3030 - Cooling Generating Systems



Location: Northeast Side of Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$253,027.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The cooling generating system is beyond its expected service life and should be scheduled for replacement.

System: D3040 - Distribution & Exhaust Systems



Location: Restrooms

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$294,752.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The distribution and exhaust systems are beyond their expected service life and should be scheduled for replacement.

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.


Estimate: \$990,711.00

Assessor Name: Ben Nixon

Date Created: 07/15/2015

Notes: The terminal and package units are beyond their expected service life, require extensive maintenance, and should be scheduled for replacement.

System: D3060 - Controls & Instrumentation



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$192,579.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The controls and instrumentation system is beyond its expected service life and should be scheduled for replacement.

System: D3090 - Other HVAC Systems/Equip - Kitchen Hood



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$65,798.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The kitchen hood is beyond service life and should be scheduled for replacement. Replacement of the kitchen hood is an add alternate under SPLOST IV.

System: D5010 - Electrical Service/Distribution



Location: Main Switch Room/Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$96,824.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The electrical service/distribution system is beyond its expected service life and no longer supports modern load requirements. The primary service and branch wiring should be scheduled for replacement.

System: D5020 - Branch Wiring



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Building Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$362,690.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The branch wiring system is beyond its expected service life, unable to meet current usage needs, and should be replaced. Electrical outlets in the kitchen are not GFI.

System: D5020 - Lighting



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.


Estimate: \$476,097.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The lighting system is beyond its expected service life and should be scheduled for replacement. SPLOST project 106-422 to replace the lighting system throughout the buildings.

System: E1020 - Institutional Equipment



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$21,398.00

Assessor Name: Ben Nixon

Date Created: 07/15/2015

Notes: Institutional equipment, such as theater and stage equipment, is beyond its expected service life and should be scheduled for replacement.

System: E1090 - Other Equipment (Kitchen Equipment)



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$514,613.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Kitchen equipment is beyond its expected service life and should be scheduled for replacement. SPLOST project 106-422 to replace the kitchen equipment.

System: E2010 - Fixed Furnishings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$287,263.00

Assessor Name: Ben Nixon

Date Created: 07/17/2015

Notes: Fixed furnishings, such as built-in cabinets, are beyond their expected service life, damaged and worn, and should be replaced.

System: F1010 - Special Structures - Canopies



Location: Exterior Walls

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 48,631.00

Unit of Measure: S.F.

Estimate: \$78,296.00

Assessor Name: Ben Nixon

Date Created: 10/07/2015

Notes: Canopies on the exterior walls of the building are beyond their expected service life, deteriorated, and should be repaired repaired/replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	120
Year Built:	1980
Last Renovation:	
Replacement Value:	\$9,669
Repair Cost:	\$2,902.00
Total FCI:	30.01 %
Total RSLI:	47.26 %
FCA Score:	69.99



Description:

The storage building at Dresden Elementary School is located at 2449 Dresden Drive in Chamblee, Georgia. Originally built in 1980, there have been no additions and no major renovations to this building. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	Fire Sprinkler System:	No
-----------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	65.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	65.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	57.29 %	13.04 %	\$686.00
B30 - Roofing	0.00 %	109.98 %	\$2,216.00
C10 - Interior Construction	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	0.00 %	0.00 %	\$0.00
D20 - Plumbing	0.00 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	0.00 %	\$0.00
Totals:	47.26 %	30.01 %	\$2,902.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). North Elevation - Jul 17, 2015



2). South Elevation - Jul 17, 2015



3). East Elevation - Jul 17, 2015



4). West Elevation - Jul 17, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.49	S.F.	0	100	1980	2080		65.00 %	0.00 %	65			\$0
A1030	Slab on Grade	\$3.60	S.F.	120	100	1980	2080		65.00 %	0.00 %	65			\$432
A2010	Basement Excavation	\$0.22	S.F.	0	100	1980	2080		65.00 %	0.00 %	65			\$0
A2020	Basement Walls	\$3.52	S.F.	0	100	1980	2080		65.00 %	0.00 %	65			\$0
B1020	Roof Construction	\$16.33	S.F.	120	100	1980	2080		65.00 %	0.00 %	65			\$1,960
B2010	Exterior Walls	\$38.65	S.F.	120	100	1980	2080		65.00 %	0.00 %	65			\$4,638
B2020	Exterior Windows	\$4.87	S.F.	0	30	1980	2010		0.00 %	0.00 %	-5			\$0
B2030	Exterior Doors	\$5.20	S.F.	120	30	1980	2010		0.00 %	109.94 %	-5		\$686.00	\$624
B3010	Roof Coverings	\$16.79	S.F.	120	20	1980	2000		0.00 %	109.98 %	-15		\$2,216.00	\$2,015
C1010	Partitions	\$13.04	S.F.	0	40	1980	2020		12.50 %	0.00 %	5			\$0
C1020	Interior Doors	\$2.61	S.F.	0	30	1980	2010		0.00 %	0.00 %	-5			\$0
C1030	Fittings	\$3.04	S.F.	0	20	1980	2000		0.00 %	0.00 %	-15			\$0
C3010	Wall Finishes	\$1.61	S.F.	0	20	1980	2000		0.00 %	0.00 %	-15			\$0
C3020	Floor Finishes	\$6.58	S.F.	0	20	1980	2000		0.00 %	0.00 %	-15			\$0
C3030	Ceiling Finishes	\$6.06	S.F.	0	20	1980	2000		0.00 %	0.00 %	-15			\$0
D2040	Rain Water Drainage	\$1.55	S.F.	0	30	1980	2010		0.00 %	0.00 %	-5			\$0
D5010	Electrical Service/Distribution	\$3.06	S.F.	0	30	1980	2010		0.00 %	0.00 %	-5			\$0
D5020	Lighting and Branch Wiring	\$12.57	S.F.	0	30	1980	2010		0.00 %	0.00 %	-5			\$0
Total									47.26 %	30.01 %			\$2,902.00	\$9,669

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%


School Assessment Report - 1980 Storage

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$2,902	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,902
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$686	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$686
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$2,216	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,216
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting and Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards. .
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$686.00	\$0.00	\$0.00	\$686.00
B3010	Roof Coverings	\$0.00	\$0.00	\$2,216.00	\$0.00	\$0.00	\$2,216.00
	Total:	\$0.00	\$0.00	\$2,902.00	\$0.00	\$0.00	\$2,902.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B2030 - Exterior Doors



Location: North Elevation

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 120.00

Unit of Measure: S.F.

Estimate: \$686.00

Assessor Name: Fernando Wolf

Date Created: 07/17/2015

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: B3010 - Roof Coverings



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 120.00

Unit of Measure: S.F.

Estimate: \$2,216.00

Assessor Name: Fernando Wolf

Date Created: 07/17/2015

Notes: The built-up roof covering is aged, showing signs of failure, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	15,651
Year Built:	1998
Last Renovation:	
Replacement Value:	\$3,183,539
Repair Cost:	\$478,780.00
Total FCI:	15.04 %
Total RSLI:	41.70 %
FCA Score:	84.96



Description:

The 1998 classroom addition at Dresden Elementary School is a one-story building located at 2449 Dresden Drive in Chamblee, Georgia. There have been no additions or renovations to this building. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2013	Fire Sprinkler System:	No
-----------------	------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	83.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	70.11 %	0.00 %	\$0.00
B30 - Roofing	32.33 %	0.00 %	\$0.00
C10 - Interior Construction	59.66 %	0.00 %	\$0.00
C20 - Stairs	83.00 %	0.00 %	\$0.00
C30 - Interior Finishes	33.13 %	0.00 %	\$0.00
D10 - Conveying	90.00 %	0.00 %	\$0.00
D20 - Plumbing	43.55 %	0.00 %	\$0.00
D30 - HVAC	7.93 %	82.86 %	\$478,780.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	41.82 %	0.00 %	\$0.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
F10 - Special Construction	32.00 %	0.00 %	\$0.00
Totals:	41.70 %	15.04 %	\$478,780.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). South Elevation - Jul 17, 2015



2). West Elevation - Jul 17, 2015



3). East Elevation - Jul 17, 2015



4). North Elevation - Jul 17, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1998 Addition

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	15,651	100	1998	2098		83.00 %	0.00 %	83			\$101,575
A1020	Special Foundations	\$4.46	S.F.	0	100	1998	2098		83.00 %	0.00 %	83			\$0
A1030	Slab on Grade	\$7.09	S.F.	15,651	100	1998	2098		83.00 %	0.00 %	83			\$110,966
A2010	Basement Excavation	\$0.26	S.F.	0	100	1998	2098		83.00 %	0.00 %	83			\$0
A2020	Basement Walls	\$6.13	S.F.	0	100	1998	2098		83.00 %	0.00 %	83			\$0
B1010	Floor Construction	\$15.61	S.F.	0	100	1998	2098		83.00 %	0.00 %	83			\$0
B1020	Roof Construction	\$5.34	S.F.	15,651	100	1998	2098		83.00 %	0.00 %	83			\$83,576
B2010	Exterior Walls	\$16.02	S.F.	15,651	100	1998	2098		83.00 %	0.00 %	83			\$250,729
B2020	Exterior Windows	\$6.79	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$106,270
B2030	Exterior Doors	\$0.92	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$14,399
B3010	Roof Coverings - Asphal Shingles	\$4.32	S.F.	0	10	1998	2008		0.00 %	0.00 %	-7			\$0
B3010	Roof Coverings - BUR	\$20.70	S.F.	15,651	25	1998	2023		32.00 %	0.00 %	8			\$323,976
B3010	Roof Coverings - EPDM	\$3.33	S.F.	0	15	1998	2013		0.00 %	0.00 %	-2			\$0
B3010	Roof Coverings - Preformed Metal	\$5.01	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
B3010	Roof Coverings - Standing Seam Metal	\$27.45	S.F.	0	75	1998	2073		77.33 %	0.00 %	58			\$0
B3020	Roof Openings	\$0.63	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$9,860
C1010	Partitions	\$7.01	S.F.	15,651	100	1998	2098		83.00 %	0.00 %	83			\$109,714
C1020	Interior Doors	\$2.39	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$37,406
C1030	Fittings	\$2.79	S.F.	15,651	20	1998	2018		15.00 %	0.00 %	3			\$43,666
C2010	Stair Construction	\$1.81	S.F.	15,651	100	1998	2098		83.00 %	0.00 %	83			\$28,328
C3010	Wall Finishes - Ceramic & Glazed	\$10.27	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
C3010	Wall Finishes - Paint	\$1.93	S.F.	15,651	10	2010	2020		50.00 %	0.00 %	5			\$30,206
C3010	Wall Finishes - Wall Coverings	\$2.13	S.F.	0	10	1998	2008		0.00 %	0.00 %	-7			\$0
C3020	Floor Finishes - Carpet	\$8.50	S.F.	0	8	1998	2006		0.00 %	0.00 %	-9			\$0
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	820	50	1998	2048		66.00 %	0.00 %	33			\$11,882
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	2,347	50	1998	2048		66.00 %	0.00 %	33			\$124,414
C3020	Floor Finishes - VCT	\$9.54	S.F.	12,484	20	1998	2018		15.00 %	0.00 %	3			\$119,097
C3020	Floor Finishes - Wood	\$14.70	S.F.	0	20	1998	2018		15.00 %	0.00 %	3			\$0
C3030	Ceiling Finishes	\$9.98	S.F.	15,651	20	1998	2018		15.00 %	0.00 %	3			\$156,197
D1010	Elevators and Lifts	\$1.17	S.F.	15,651	30	2012	2042		90.00 %	0.00 %	27			\$18,312
D2010	Plumbing Fixtures	\$17.66	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$276,397
D2020	Domestic Water Distribution	\$3.99	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$62,447
D2030	Sanitary Waste	\$3.41	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$53,370
D2040	Rain Water Drainage	\$0.98	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$15,338

School Assessment Report - 1998 Addition

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	15,651	40	1998	2038		57.50 %	0.00 %	23			\$6,417
D3020	Heat Generating Systems	\$4.55	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D3030	Cooling Generating Systems	\$4.73	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$86,237
D3050	Terminal & Package Units	\$27.81	S.F.	15,651	15	1998	2013		0.00 %	110.00 %	-2		\$478,780.00	\$435,254
D3060	Controls & Instrumentation	\$3.60	S.F.	15,651	20	1998	2018		15.00 %	0.00 %	3			\$56,344
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D4010	Sprinklers	\$4.75	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D4020	Standpipes	\$0.51	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D5010	Electrical Service/Distribution	\$1.81	S.F.	15,651	40	1998	2038		57.50 %	0.00 %	23			\$28,328
D5020	Branch Wiring	\$6.78	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$106,114
D5020	Lighting	\$8.90	S.F.	15,651	30	1998	2028		43.33 %	0.00 %	13			\$139,294
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	15,651	15	2005	2020		33.33 %	0.00 %	5			\$87,646
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	15,651	15	2005	2020		33.33 %	0.00 %	5			\$19,251
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	15,651	15	2005	2020		33.33 %	0.00 %	5			\$9,547
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	15,651	15	2011	2026		73.33 %	0.00 %	11			\$5,478
E1020	Institutional Equipment	\$0.40	S.F.	15,651	20	1998	2018		15.00 %	0.00 %	3			\$6,260
E1090	Other Equipment	\$8.75	S.F.	0	20	1998	2018		15.00 %	0.00 %	3			\$0
E2010	Fixed Furnishings	\$5.37	S.F.	15,651	20	1998	2018		15.00 %	0.00 %	3			\$84,046
F1010	Special Structures - Canopies	\$1.61	S.F.	15,651	25	1998	2023		32.00 %	0.00 %	8			\$25,198
Total									41.70 %	15.04 %			\$478,780.00	\$3,183,539

School Assessment Report - 1998 Addition

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$478,780	\$0	\$0	\$559,663	\$0	\$187,008	\$0	\$0	\$483,363	\$0	\$0	\$1,708,814
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1020 - Special Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Asphal Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$451,443	\$0	\$0	\$451,443
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Preformed Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1998 Addition

C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$52,487	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$52,487
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic & Glazed	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$38,519	\$0	\$0	\$0	\$0	\$0	\$38,519
C3010 - Wall Finishes - Wall Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$0	\$0	\$0	\$143,155	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$143,155
C3020 - Floor Finishes - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$187,749	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$187,749
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$478,780	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$478,780
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$67,725	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,725
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1998 Addition

D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Clock & PA Systems	\$0	\$0	\$0	\$0	\$0	\$111,766	\$0	\$0	\$0	\$0	\$0	\$111,766
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$24,549	\$0	\$0	\$0	\$0	\$0	\$24,549
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$12,175	\$0	\$0	\$0	\$0	\$0	\$12,175
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$7,525	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,525
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$101,023	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$101,023
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$31,920	\$0	\$0	\$31,920

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$478,780.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
D3050	Terminal & Package Units	\$0.00	\$0.00	\$478,780.00	\$0.00	\$0.00	\$478,780.00
	Total:	\$0.00	\$0.00	\$478,780.00	\$0.00	\$0.00	\$478,780.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$478,780.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: D3050 - Terminal & Package Units



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 15,651.00

Unit of Measure: S.F.

Estimate: \$478,780.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The terminal and package units are beyond their expected service life and should be scheduled for replacement.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	5,478
Year Built:	1998
Last Renovation:	
Replacement Value:	\$909,456
Repair Cost:	\$98,340.00
Total FCI:	10.81 %
Total RSLI:	58.16 %
FCA Score:	89.19



Description:

The 1998 gymnasium at Dresden Elementary School is a one-story building located at 2449 Dresden Drive in Chamblee, Georgia. There have been no additions and no major renovations to this building. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2020	Fire Sprinkler System:	No
-----------------	------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	79.34 %	0.00 %	\$0.00
B30 - Roofing	77.33 %	0.00 %	\$0.00
C10 - Interior Construction	66.23 %	0.00 %	\$0.00
C30 - Interior Finishes	48.89 %	9.45 %	\$10,001.00
D20 - Plumbing	43.60 %	0.00 %	\$0.00
D30 - HVAC	22.13 %	53.04 %	\$70,201.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	25.59 %	22.48 %	\$18,138.00
Totals:	58.16 %	10.81 %	\$98,340.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). North Elevation - Mar 24, 2011



2). East Elevation - Mar 24, 2011



3). South Elevation - Mar 24, 2011



4). West Elevation - Mar 24, 2011



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1998 Gym

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$9.34	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83			\$51,165
A1030	Slab on Grade	\$6.21	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83			\$34,018
B1020	Roof Construction	\$21.36	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83			\$117,010
B2010	Exterior Walls	\$19.80	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83			\$108,464
B2030	Exterior Doors	\$2.01	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$11,011
B3010	Roof Coverings - Standing Seam Metal	\$11.91	S.F.	5,478	75	1998	2073		77.33 %	0.00 %	58			\$65,243
C1010	Partitions	\$12.78	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83			\$70,009
C1020	Interior Doors	\$4.24	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23			\$23,227
C1030	Fittings	\$3.46	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3			\$18,954
C3010	Wall Finishes - Ceramic	\$6.65	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
C3010	Wall Finishes - Paint	\$1.41	S.F.	5,478	10	1998	2008		0.00 %	109.99 %	-7		\$8,496.00	\$7,724
C3020	Floor Finishes - Ceramic Tile	\$6.67	S.F.	274	8	1998	2006	2020	62.50 %	0.00 %	5			\$1,828
C3020	Floor Finishes - Neoprene	\$14.46	S.F.	4,931	50	1998	2048		66.00 %	0.00 %	33			\$71,302
C3020	Floor Finishes - VCT	\$5.01	S.F.	273	15	1998	2013		0.00 %	110.01 %	-2		\$1,505.00	\$1,368
C3030	Ceiling Finishes	\$4.31	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3			\$23,610
D2010	Plumbing Fixtures	\$9.66	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$52,917
D2020	Domestic Water Distribution	\$5.85	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$32,046
D2030	Sanitary Waste	\$0.87	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$4,766
D2040	Rain Water Drainage	\$0.22	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D2090	Other Plumbing Systems - Natural Gas	\$0.32	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23			\$1,753
D3040	Distribution Systems & Exhaust Systems	\$12.25	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$67,106
D3050	Terminal & Package Units	\$11.65	S.F.	5,478	15	1998	2013		0.00 %	110.00 %	-2		\$70,201.00	\$63,819
D3060	Controls & Instrumentation	\$0.26	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3			\$1,424
D4010	Sprinklers	\$3.84	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D5010	Electrical Service/Distribution	\$1.24	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23			\$6,793
D5020	Branch Wiring	\$5.24	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$28,705
D5020	Lighting	\$5.24	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3			\$28,705
D5030	Communications and Security - Fire Alarm	\$2.13	S.F.	5,478	15	1998	2013		0.00 %	110.00 %	-2		\$12,835.00	\$11,668
D5030	Communications and Security - Public Address & Clock System	\$0.88	S.F.	5,478	15	1998	2013		0.00 %	110.00 %	-2		\$5,303.00	\$4,821
D5030	Communications and Security - Security & CCTV	\$0.88	S.F.		15	1998	2013		0.00 %	0.00 %	-2			\$0
Total									58.16 %	10.81 %			\$98,340.00	\$909,456

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$98,340	\$0	\$0	\$87,377	\$0	\$2,330	\$0	\$0	\$0	\$0	\$11,418	\$199,465
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$22,782	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,782
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$8,496	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,418	\$19,914
C3020 - Floor Finishes - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$2,330	\$0	\$0	\$0	\$0	\$0	\$2,330
C3020 - Floor Finishes - Neoprene	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$1,505	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,505
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$28,379	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,379
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1998 Gym

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$70,201	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,201
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$1,712	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,712
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$34,503	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,503
D5030 - Communications and Security - Fire Alarm	\$12,835	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,835
D5030 - Communications and Security - Public Address & Clock System	\$5,303	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,303
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$98,340.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
C3010	Wall Finishes - Paint	\$0.00	\$0.00	\$8,496.00	\$0.00	\$0.00	\$8,496.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$1,505.00	\$0.00	\$0.00	\$1,505.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00	\$70,201.00
D5030	Communications and Security - Fire Alarm	\$0.00	\$0.00	\$12,835.00	\$0.00	\$0.00	\$12,835.00
D5030	Communications and Security - Public Address & Clock System	\$0.00	\$0.00	\$5,303.00	\$0.00	\$0.00	\$5,303.00
	Total:	\$0.00	\$0.00	\$98,340.00	\$0.00	\$0.00	\$98,340.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




Budget Estimate Total: \$98,340.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: C3010 - Wall Finishes - Paint



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$8,496.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The painted wall finishes are beyond their expected service life and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Entrance Area and Offices

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 273.00

Unit of Measure: S.F.

Estimate: \$1,505.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The VCT floor covering is beyond its expected service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Inadequate

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$70,201.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The primary heating and cooling system consists of gas fired unit heater and ventilation fans for the gym. A PTAC unit provides heating and cooling for the office. These units are beyond their expected service life and should be replace with a single package system. SPLOST project 106-422 to install a 20 ton HVAC package in the gym.

System: D5030 - Communications and Security - Fire Alarm



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$12,835.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The fire alarm system is beyond its expected service life and should be scheduled for replacement. An enunciator was not located in the facility.

System: D5030 - Communications and Security - Public Address & Clock System



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$5,303.00

Assessor Name: Ben Nixon

Date Created: 07/15/2015

Notes: The public address and clock system is beyond its expected service life and should be scheduled for replacement.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	69,880
Year Built:	1963
Last Renovation:	
Replacement Value:	\$1,603,333
Repair Cost:	\$1,492,070.00
Total FCI:	93.06 %
Total RSLI:	7.68 %
FCA Score:	6.94



Description:

The Dresden Elementary School site was originally constructed in 1963, has a total area of 9.1 acres, and is occupied by approximately 69,880 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, covered walkways, flag pole, landscaping, open fields, playgrounds and fencing. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site features.

Attributes:

General Attributes:

Site Code: 1185

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	4.20 %	95.55 %	\$850,223.00
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$501,947.00
G40 - Site Electrical Utilities	33.36 %	54.40 %	\$139,900.00
Totals:	7.68 %	93.06 %	\$1,492,070.00

Photo Album

The photo album consists of the various cardinal directions of the building.

- 1). Aerial Image of Dresden Elementary School - Oct 20, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$5.17	S.F.	38,381	25	1963	1988		0.00 %	110.00 %	-27		\$218,273.00	\$198,430
G2020	Parking Lots	\$4.56	S.F.	13,186	25	1963	1988		0.00 %	110.00 %	-27		\$66,141.00	\$60,128
G2030	Pedestrian Paving	\$1.50	S.F.	69,880	30	1963	1993		0.00 %	110.00 %	-22		\$115,302.00	\$104,820
G2040	Baseball Field	\$8.35	S.F.		20				0.00 %	0.00 %				\$0
G2040	Canopies	\$0.29	S.F.		0				0.00 %	0.00 %				\$0
G2040	Covered Walkways	\$48.72	S.F.	2,400	25	1998	2023		32.00 %	0.00 %	8			\$116,928
G2040	Fencing & Guardrails	\$0.91	S.F.	69,880	30	1963	1993		0.00 %	110.00 %	-22		\$69,950.00	\$63,591
G2040	Football Field	\$5.85	S.F.		20	1963	1983		0.00 %	0.00 %	-32			\$0
G2040	Hard Surface Play Area	\$6.26	S.F.	8,515	20	1963	1983		0.00 %	110.00 %	-32		\$58,634.00	\$53,304
G2040	Playing Field	\$3.92	S.F.	48,809	20	1963	1983		0.00 %	110.00 %	-32		\$210,464.00	\$191,331
G2040	Soccer/Lacross Field	\$5.00	S.F.		20	1963	1983		0.00 %	0.00 %	-32			\$0
G2040	Softball Field	\$8.86	S.F.		20	1963	1983		0.00 %	0.00 %	-32			\$0
G2040	Tennis Courts	\$18.47	S.F.		20	1963	1983		0.00 %	0.00 %	-32			\$0
G2040	Track	\$7.04	S.F.		10	1963	1973		0.00 %	0.00 %	-42			\$0
G2050	Landscaping	\$1.45	S.F.	69,880	15	1963	1978		0.00 %	110.00 %	-37		\$111,459.00	\$101,326
G3010	Water Supply	\$1.83	S.F.	69,880	50	1963	2013		0.00 %	110.00 %	-2		\$140,668.00	\$127,880
G3020	Sanitary Sewer	\$1.15	S.F.	69,880	50	1963	2013		0.00 %	110.00 %	-2		\$88,398.00	\$80,362
G3030	Storm Sewer	\$3.55	S.F.	69,880	50	1963	2013		0.00 %	110.00 %	-2		\$272,881.00	\$248,074
G3060	Fuel Distribution	\$0.78	S.F.		40	1963	2003		0.00 %	0.00 %	-12			\$0
G4010	Electrical Distribution	\$1.86	S.F.	69,880	50	1998	2048		66.00 %	0.00 %	33			\$129,977
G4020	Site Lighting	\$1.15	S.F.	69,880	30	1998	2028	2015	0.00 %	110.00 %	0		\$88,398.00	\$80,362
G4030	Site Communications & Security	\$0.67	S.F.	69,880	10	1998	2008		0.00 %	110.00 %	-7		\$51,502.00	\$46,820
Total									7.68 %	93.06 %			\$1,492,070.00	\$1,603,333

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

School Assessment Report - Site


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,492,070	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$162,933	\$0	\$69,214	\$1,724,218
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$218,273	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$218,273
G2020 - Parking Lots	\$66,141	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$66,141
G2030 - Pedestrian Paving	\$115,302	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$115,302
G2040 - Baseball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$162,933	\$0	\$0	\$162,933
G2040 - Fencing & Guardrails	\$69,950	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,950
G2040 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Hard Surface Play Area	\$58,634	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$58,634
G2040 - Playing Field	\$210,464	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$210,464
G2040 - Soccer/Lacross Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Softball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Tennis Courts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping	\$111,459	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$111,459
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$140,668	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$140,668
G3020 - Sanitary Sewer	\$88,398	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$88,398
G3030 - Storm Sewer	\$272,881	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$272,881
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$88,398	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$88,398
G4030 - Site Communications & Security	\$51,502	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,214	\$120,716

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
G2010	Roadways	\$0.00	\$0.00	\$218,273.00	\$0.00	\$0.00	\$218,273.00
G2020	Parking Lots	\$0.00	\$0.00	\$66,141.00	\$0.00	\$0.00	\$66,141.00
G2030	Pedestrian Paving	\$0.00	\$0.00	\$115,302.00	\$0.00	\$0.00	\$115,302.00
G2040	Fencing & Guardrails	\$0.00	\$0.00	\$69,950.00	\$0.00	\$0.00	\$69,950.00
G2040	Hard Surface Play Area	\$0.00	\$0.00	\$58,634.00	\$0.00	\$0.00	\$58,634.00
G2040	Playing Field	\$0.00	\$0.00	\$0.00	\$210,464.00	\$0.00	\$210,464.00
G2050	Landscaping	\$0.00	\$0.00	\$111,459.00	\$0.00	\$0.00	\$111,459.00
G3010	Water Supply	\$0.00	\$0.00	\$140,668.00	\$0.00	\$0.00	\$140,668.00
G3020	Sanitary Sewer	\$0.00	\$0.00	\$88,398.00	\$0.00	\$0.00	\$88,398.00
G3030	Storm Sewer	\$0.00	\$0.00	\$272,881.00	\$0.00	\$0.00	\$272,881.00
G4020	Site Lighting	\$0.00	\$88,398.00	\$0.00	\$0.00	\$0.00	\$88,398.00
G4030	Site Communications & Security	\$0.00	\$0.00	\$51,502.00	\$0.00	\$0.00	\$51,502.00
Total:		\$0.00	\$88,398.00	\$1,193,208.00	\$210,464.00	\$0.00	\$1,492,070.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,492,070.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 Priority:

System: G4020 - Site Lighting



Location: Site

Distress: Inadequate

Category: Deferred Maintenance / Safety

Priority: 2 Priority

Correction: Renew System

Qty: 69,880.00

Unit of Measure: S.F.

Estimate: \$88,398.00

Assessor Name: Sam Mandola

Date Created: 02/04/2016

Notes: Site lighting in the parking area is poor/inadequate and should be replaced and expanded for safety reasons.

Priority 3 Priority:

System: G2010 - Roadways



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 38,381.00

Unit of Measure: S.F.

Estimate: \$218,273.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Roadways are beyond their expected service life, damaged with many cracks, worn, and should be replaced.

System: G2020 - Parking Lots



Location: North Side of Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 13,186.00

Unit of Measure: S.F.

Estimate: \$66,141.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: The parking lot is beyond its expected service life, inadequate, not ADA compliant, has many repairs and potholes, and should be replaced. SPLOST project 106-422 to provide parking renovations.

System: G2030 - Pedestrian Paving



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,880.00

Unit of Measure: S.F.

Estimate: \$115,302.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Pedestrian paving is beyond its expected service life, damaged, and should be replaced.

System: G2040 - Fencing & Guardrails



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,880.00

Unit of Measure: S.F.

Estimate: \$69,950.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Fencing is beyond its expected service life, rusted, and should be scheduled for replacement.

System: G2040 - Hard Surface Play Area



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 8,515.00
Unit of Measure: S.F.
Estimate: \$58,634.00
Assessor Name: Sam Mandola
Date Created: 07/17/2015

Notes: The hard surface play area is beyond its expected service life, damaged with cracks, and should be replaced.

System: G2050 - Landscaping



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 69,880.00
Unit of Measure: S.F.
Estimate: \$111,459.00
Assessor Name: Sam Mandola
Date Created: 07/17/2015

Notes: Landscaping is beyond its expected service life, damaged, inadequate, and should be replaced. The site retention pond is severely overgrown and does not function as intended.

System: G3010 - Water Supply



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 69,880.00
Unit of Measure: S.F.
Estimate: \$140,668.00
Assessor Name: Sam Mandola
Date Created: 07/15/2015

Notes: The site water supply system is beyond its expected service life and should be scheduled for replacement.

System: G3020 - Sanitary Sewer



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 69,880.00
Unit of Measure: S.F.
Estimate: \$88,398.00
Assessor Name: Sam Mandola
Date Created: 07/15/2015

Notes: The site sanitary sewer system is beyond its expected service life and should be scheduled for replacement.

System: G3030 - Storm Sewer



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,880.00

Unit of Measure: S.F.

Estimate: \$272,881.00

Assessor Name: Sam Mandola

Date Created: 07/15/2015

Notes: The storm sewer system is beyond its expected service life and should be scheduled for replacement. The site retention pond is severely overgrown and does not function as intended.

System: G4030 - Site Communications & Security



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,880.00

Unit of Measure: S.F.

Estimate: \$51,502.00

Assessor Name: Sam Mandola

Date Created: 11/16/2015

Notes: Site communications and security are beyond their expected service life and should be scheduled for replacement.

Priority 4 Priority:

System: G2040 - Playing Field



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 4 Priority

Correction: Renew System

Qty: 48,809.00

Unit of Measure: S.F.

Estimate: \$210,464.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: The playing fields are beyond their expected service life, currently occupied with temporary trailers, and should be scheduled for renewal.

Glossary

Abandoned	A facility owned by a district that is not occupied and not maintained. See Vacant.
Additional Cost	Total project cost is composed of hard and soft costs. Additional costs or soft expenses are costs that are necessary to accomplish the corrective work but are not directly attributable to the deficient systems direct construction cost, which are often referred to as hard cost. The components included in the soft costs vary by owner but usually include architect and contractor fees, contingencies and other owner-incurred costs necessary to fully develop and build a facility. These soft cost factors can be adjusted anytime within the eCOMET® database at the owner's discretion.
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems, reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ASTM	ASTM International (ASTM): Originally known as the American Society for Testing and Materials, ASTM is an international standards organization that develops and publishes voluntary consensus technical standards for a wide range of materials, products, systems, and services.
BOMA	Building Owners Managers of America (BOMA): National organization of public and private facility owners focused on building management tools and maintenance techniques. eCOMET® reference: Building and component system effective economic life expectancies.
Building	A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior.
Building Addition	An area, space or component of a building added to a building after the original building's year built date. NOTE: As a convention in the database, "Main" was used to designate the original building. Additions built prior to 1983 (30 years) were included in the main building area calculations to reflect their predicted system depreciation characteristics and remaining service life.
Building Systems	eCOMET® uses UNIFORMAT II to organize building data. UNIFORMAT II was originally developed by the federal General Services Administration to delineate building costs by systems rather than by material. UNIFORMAT II was formalized by an NIST standard, NISTIR 6389 in 1999. It has been further quantified and updated by ASTM standard 2005, E1557-05. The Construction Specifications Institute, CSI, has taken over the standard as part of their MasterFormat / MasterSpec system.
Calculated Next Renewal	The year a system or building element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal refers to the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life. It is not normally included in an annual operating/maintenance budget. See calculated next renewal and next renewal.
City Cost Index (CCI)	RS Means provides building system, equipment, and construction costs at a national level. The City Cost Index (also provided by RS Means) localizes those costs to a geographic region of the United States. In eCOMET®, each building or site is assigned a City Cost Index, which adjusts all of the associated costs for systems, deficiencies and inventory to the local value.
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
Condition Budget	The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work.

School Assessment Report - Dresden Elementary

Condition Index (CI) %	The Condition Index (CI) also known as the Remaining Service Life Index (RSLI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude soft cost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).
Construction Specifications Institute	Construction Specifications Institute: Primary national organization specializing in construction materials data and data location in construction documents. eCOMET® reference: UNIFORMAT II materials classification.
Correction	Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a UNIFORMAT II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction.
Cost Model	A cost model is a list of facility systems which could represent the installed systems a given facility. Included in the cost model are standard unit cost estimates, gross areas, life cycles and installed dates. Also represented is the repair cost for deficient systems, replacement values. See eCOMET® cost models.
Criteria	Criteria refer to the set of requirements, guidelines or standards that are assessed and rated to develop a score.
Current Period	The Current Period is the current year plus a user defined number of forward years.
Current Replacement Value (CRV)	The Current Replacement Value (CRV) of a facility, building or system represents the hypothetical cost of rebuilding or replacing an existing facility under today's codes and construction standards, using its current configuration. It is calculated by multiplying the gross area of the facility by a square foot cost developed in that facility's cost model. Replacement cost includes construction costs and owner's additional or soft costs for fees, permits and other expenses to reflect a total project cost.
Deferred Maintenance	Deferred maintenance is condition work deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose.
Deficiency Category	Deficiency Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions include, but are not limited to: Accessibility Code Compliance, Appearance, Building Code Compliance, Deferred Maintenance, Energy, Environmental, Life Safety Code Compliance, and Safety.
Deficiency Distress	Deficiency Distress refers to a user-defined root cause of a deficiency. Distress descriptions are: Beyond Service Life, Damaged, Inadequate, Needs Remediation, and Missing.
Deficiency Priority	Deficiency Priority refers to a deficiency's urgency for repair as determined by the assessment team. Deficiencies were assigned a priority of 1 through 5, with Priority 1 deficiencies being the most urgent.
eCOMET®	Energy and Condition Management Estimation Technology (eCOMET®) is Parsons proprietary facility asset management software developed to provide facility managers with a state of the art, web-based tool to develop and maintain a comprehensive database of FCA data and information used for facility asset management, maintenance and repair, and capital renewal planning. eCOMET® is used by Parsons and its clients as the primary tool for collecting FCA data, preparing cost estimates, generating individual facility reports and cost estimates, and developing the overall capital renewal program.

School Assessment Report - Dresden Elementary

eCOMET® Cost Models	eCOMET® cost models are derived from RS Means Square Foot Cost Data cost models and these models are used to develop the current replacement value (CRV) and assign life cycle costs to the various systems within a building. Cost models are assigned current costs-per-square-foot to establish replacement values. The Cost models are designed to represent a client specific facility that meets local standards cost trends.
Element	Elements are the major components that comprise building systems as defined by UNIFORMAT II.
Expected Life	Also referred to as Useful Life. See Useful Life definition.
Facility	A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose.
Facility Attributes	Customizable eCOMET® fields to identify attributes specific to a facility. These fields are part of the eCOMET® database set-up with the owner.
Facility Condition Assessment (FCA)	A facility condition assessment (FCA) is a visual inspection of buildings and grounds at a facility to identify and estimate current and future needed repairs or replacements of major systems for planning and budgeting purposes. It is typically performed for organizations that are tasked with the day to day maintenance, operation, and capital renewal (replacement) of building systems and components of a large inventory of facilities. The primary goal of an FCA is to objectively and quantifiably identify, inspect, and prioritize the repair and replacement needs of the building and ground systems (e.g., roofs, windows, doors, floor finishes, plumbing fixtures, parking lot, and sidewalks) within facilities that have either failed or have surpassed their service life, and to identify and forecast future capital replacement needs for systems that have not yet failed, but planned replacement of those systems is needed to ensure that the facilities will continue to meet the mission of the organization.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition expressed as a percentage from 0.00% to 100.00% that is derived by dividing the cost to correct a facility's deficiencies by its Current Replacement Value (CRV). The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio, a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.
Forecast Period	The Forecast Period refers to a user defined number of years forward of the Current Period.
Gen (Generate)	The Cost Model has a Gen box for each system line item. By checking the box, eCOMET® will generate life cycle deficiencies based on the Year Installed and the Life for that system. Systems that typically do not re-generate (foundations, floor construction, roof construction, basement walls, etc.) would not have the Gen box checked as those systems would not re-generate at the end of a life cycle. In those instances, it would be more practical and cost effective to demolish the entire facility than renew those systems.
Gross Square Feet (GSF)	The area of the enclosed floor space of a building or building addition in square feet measured to the outside face of the enclosing wall.
Life cycle	Life cycle refers to the period of time that a building or site system or element can be expected to adequately serve its intended function. Parsons assigns expected life cycles to all building systems based on Building Operators and Managers of America (BOMA) recommended life cycles, manufacturers suggested life, and RS Means cost data, and client-provided historical data. BOMA standards are a nationally recognized source of life cycle data for various components and/or systems associated with facilities. RS Means is a national company specializing in construction estimating and costs.
Next Renewal	Next Renewal refers to a manually-adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately reflect current conditions.

School Assessment Report - Dresden Elementary

Order of Magnitude	Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.
Remaining Service Life (RSL)	RSL is the number of years of service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the Calculated Next Renewal date or the Next Renewal date whichever one is the later date.
Renewal Factors	Renewal factors represent the difference in cost of renovating or replacing an existing system, rather than new construction of a building system. For example, installing a new built-up roof on an existing building would include removing and disposing of the old roof, a cost not associated with new construction. Using a renewal premium to account for demolition and other difficulty costs, Parsons typically assigns a renewal factor of 110%.
Renewal Schedule	A timeline by year that indicates when the systems will need to be renewed and the estimated price of the renewal.
Repair Cost	Repair cost is the sum of all the deficiencies associated with a building or multiple buildings/facilities. It will include any applied soft costs or City Cost Indexes.
Replacement Value	See Current Replacement Value.
Site	A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.
Soft Costs	Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user-defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses.
Sustainability	Sustainability refers to the collection of policies and strategies that meet society's present needs without compromising the ability of future generations to meet their own needs.
System	System refers to building and related site work elements as described by ASTM UNIFORMAT II Classification for Building Elements (E1557-97), a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also UNIFORMAT II.
System Generated Deficiency	eCOMET® automatically generates system deficiencies based on system life cycles using the systems installation dates as the base year. By adjusting the Next Renewal date ahead or behind the predicted or stated life cycle date, a system cost will come due earlier or later than the originally installed life cycle date. This utility accounts for good maintenance conditions and a longer life, or early expiration of a system life due to any number of adverse factors such as poor installation, acts of god, material defects, poor design applications and other factors that may shorten the life of a material or system. It is important to mention that the condition of the systems is not necessarily a reflection of maintenance practices, but a combination of system usage and age.
UNIFORMAT	ASTM UNIFORMAT II, Classification for Building Elements (E1557-97), a publication of the Construction Specification Institute (CSI), is a format used to classify major facility components common to most buildings. The format is based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies.
Unit Price	The Unit Price (Raw) x (100% + the Additional Cost Template percentage).
Unit Price (Raw)	The actual \$/sq. ft cost being used for the building and systems. It will include adjustments for the City Cost Index applied to the facility.

School Assessment Report - Dresden Elementary

Useful Life	Also known as Expected Life, Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in the database are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from client- defined historical experience.
Vacant	Vacant refers to a facility that is not occupied but is a maintained facility by a district. See Abandoned.
Year Built	The year that a building or addition was originally built based on its date of substantial completion or occupancy.
Year Installed	The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.