

DeKalb County School District/Elementary Schools

Eldridge L. Miller Elementary

Final

School Assessment Report

May 19, 2016



Table of Contents

School Executive Summary	4
School Condition Summary	5
<u>1981 Building</u>	7
Executive Summary	7
Condition Summary	8
Photo Album	9
Condition Detail	10
System Listing	11
Renewal Schedule	13
Forecasted Sustainment Requirement	16
Deficiency Summary By System	17
Deficiency Summary By Priority	18
Deficiency By Priority Investment	19
Deficiency Summary By Category	20
Deficiency Details By Priority	21
<u>1986 Addition</u>	36
Executive Summary	36
Condition Summary	37
Photo Album	38
Condition Detail	39
System Listing	40
Renewal Schedule	42
Forecasted Sustainment Requirement	45
Deficiency Summary By System	46
Deficiency Summary By Priority	47
Deficiency By Priority Investment	48
Deficiency Summary By Category	49
Deficiency Details By Priority	50
<u>2003 Gym</u>	54

School Assessment Report

Executive Summary	54
Condition Summary	55
Photo Album	56
Condition Detail	57
System Listing	58
Renewal Schedule	59
Forecasted Sustainment Requirement	61
Deficiency Summary By System	62
Deficiency Summary By Priority	63
Deficiency By Priority Investment	64
Deficiency Summary By Category	65
Deficiency Details By Priority	66
<u>Site</u>	67
Executive Summary	67
Condition Summary	68
Photo Album	69
Condition Detail	70
System Listing	71
Renewal Schedule	72
Forecasted Sustainment Requirement	74
Deficiency Summary By System	75
Deficiency Summary By Priority	76
Deficiency By Priority Investment	77
Deficiency Summary By Category	78
Deficiency Details By Priority	79
Glossary	83

School Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	72,443
Year Built:	1981
Last Renovation:	
Replacement Value:	\$15,552,718
Repair Cost:	\$10,002,937.00
Total FCI:	64.32 %
Total RSLI:	21.15 %
FCA Score:	35.68



Description:

The Eldridge Miller Elementary School campus consists of two buildings located at 919 Martin Road in Stone Mountain, Georgia. The original campus was constructed in 1981, a classroom addition was constructed in 1986, and a gymnasium building was constructed in 2003. In addition to the buildings, the campus contains a covered walkway and playing field. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for each building and site improvement on the campus.

Attributes:

General Attributes:

Assigned Region:	Region 3	Board District:	District 6
DOE Facility:	181	Geographic Region:	Region 3
HS Attendance Area:	Redan HS	Jurisdictional City:	DeKalb County (Unincorporated)
Site Acreage:	10.9		

School Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	67.32 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	71.84 %	0.00 %	\$0.00
B20 - Exterior Enclosure	47.88 %	29.62 %	\$505,850.00
B30 - Roofing	70.59 %	0.00 %	\$0.00
C10 - Interior Construction	42.91 %	34.42 %	\$319,557.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	16.26 %	56.10 %	\$1,344,952.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	3.49 %	91.87 %	\$1,708,471.00
D30 - HVAC	1.57 %	105.83 %	\$2,825,460.00
D40 - Fire Protection	0.36 %	97.98 %	\$345,106.00
D50 - Electrical	5.92 %	82.13 %	\$1,441,261.00
E10 - Equipment	0.00 %	110.00 %	\$83,980.00
E20 - Furnishings	0.00 %	110.00 %	\$395,562.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
G20 - Site Improvements	4.86 %	99.72 %	\$941,098.00
G30 - Site Mechanical Utilities	30.19 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	32.56 %	34.37 %	\$91,640.00
Totals:	21.15 %	64.32 %	\$10,002,937.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 Priority	2 Priority	3 Priority	4 Priority	5 Priority
1981 Building	59,645	71.72	\$0.00	\$0.00	\$8,382,470.00	\$0.00	\$4,620.00
1986 Addition	7,320	39.41	\$0.00	\$0.00	\$512,908.00	\$0.00	\$0.00
2003 Gym	5,478	8.59	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00
Site	72,443	59.36	\$0.00	\$287,421.00	\$745,317.00	\$0.00	\$0.00
Total:		64.32	\$0.00	\$287,421.00	\$9,710,896.00	\$0.00	\$4,620.00

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	59,645
Year Built:	1981
Last Renovation:	
Replacement Value:	\$11,694,299
Repair Cost:	\$8,387,090.00
Total FCI:	71.72 %
Total RSLI:	18.71 %
FCA Score:	28.28



Description:

The main building at Eldridge Miller Elementary School is a one-story building located at 919 Martin Road in Stone Mountain, Georgia. Originally built in 1981, there has been one addition in 1986, a roofing renovation in 2010, and communications and security upgrade in 2005. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2010	Fire Sprinkler System:	Yes
-----------------	------	------------------------	-----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	66.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	66.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	44.56 %	35.74 %	\$505,850.00
B30 - Roofing	66.67 %	0.00 %	\$0.00
C10 - Interior Construction	37.95 %	40.86 %	\$297,092.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	16.01 %	54.98 %	\$1,195,752.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	0.23 %	108.29 %	\$1,708,471.00
D30 - HVAC	0.00 %	110.00 %	\$2,502,346.00
D40 - Fire Protection	0.00 %	110.00 %	\$345,106.00
D50 - Electrical	3.55 %	93.89 %	\$1,396,170.00
E10 - Equipment	0.00 %	110.00 %	\$83,980.00
E20 - Furnishings	0.00 %	110.00 %	\$352,323.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
Totals:	18.71 %	71.72 %	\$8,387,090.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). East Elevation - Jul 02, 2015



2). South Elevation - Jul 02, 2015



3). North Elevation - Jul 02, 2015



4). West Elevation - Jul 02, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1981 Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	59,645	100	1981	2081		66.00 %	0.00 %	66			\$387,096
A1020	Special Foundations	\$4.46	S.F.	0	100	1981	2081		66.00 %	0.00 %	66			\$0
A1030	Slab on Grade	\$7.09	S.F.	59,645	100	1981	2081		66.00 %	0.00 %	66			\$422,883
A2010	Basement Excavation	\$0.26	S.F.	0	100	1981	2081		66.00 %	0.00 %	66			\$0
A2020	Basement Walls	\$6.13	S.F.	0	100	1981	2081		66.00 %	0.00 %	66			\$0
B1010	Floor Construction	\$15.61	S.F.	0	100	1981	2081		66.00 %	0.00 %	66			\$0
B1020	Roof Construction	\$5.34	S.F.	59,645	100	1981	2081		66.00 %	0.00 %	66			\$318,504
B2010	Exterior Walls	\$16.02	S.F.	59,645	100	1981	2081		66.00 %	0.00 %	66			\$955,513
B2020	Exterior Windows	\$6.79	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$445,489.00	\$404,990
B2030	Exterior Doors	\$0.92	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$60,361.00	\$54,873
B3010	Roof Coverings - Asphalt Shingles	\$4.32	S.F.	0	10	1981	1991		0.00 %	0.00 %	-24			\$0
B3010	Roof Coverings - BUR	\$6.49	S.F.	0	25	1981	2006		0.00 %	0.00 %	-9			\$0
B3010	Roof Coverings - EPDM	\$3.33	S.F.	59,645	15	2010	2025		66.67 %	0.00 %	10			\$198,618
B3010	Roof Coverings - Preformed Metal	\$5.01	S.F.	0	30	1981	2011		0.00 %	0.00 %	-4			\$0
B3010	Roof Coverings - Standing Seam Metal	\$27.45	S.F.	0	75	1981	2056		54.67 %	0.00 %	41			\$0
B3020	Roof Openings	\$0.63	S.F.	0	30	1981	2011		0.00 %	0.00 %	-4			\$0
C1010	Partitions	\$7.01	S.F.	59,645	100	1981	2081		66.00 %	0.00 %	66			\$418,111
C1020	Interior Doors	\$2.39	S.F.	59,645	30	1981	2011		0.00 %	80.00 %	-4		\$114,041.00	\$142,552
C1030	Fittings	\$2.79	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$183,051.00	\$166,410
C2010	Stair Construction	\$1.81	S.F.	0	100	1981	2081		66.00 %	0.00 %	66			\$0
C3010	Wall Finishes - Ceramic & Glazed	\$10.27	S.F.	5,965	30	1981	2011		0.00 %	110.00 %	-4		\$67,387.00	\$61,261
C3010	Wall Finishes - Paint	\$1.93	S.F.	53,080	10	1981	1991		0.00 %	110.00 %	-24		\$112,689.00	\$102,444
C3010	Wall Finishes - Wood Panelling	\$7.00	S.F.	600	15	1981	1996		0.00 %	110.00 %	-19		\$4,620.00	\$4,200
C3020	Floor Finishes - Carpet	\$8.50	S.F.	10,043	8	1981	1989		0.00 %	110.00 %	-26		\$93,902.00	\$85,366
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	5,611	50	1981	2031		32.00 %	0.00 %	16			\$81,303
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	18,989	50	1981	2031		32.00 %	0.00 %	16			\$1,006,607
C3020	Floor Finishes - VCT	\$9.54	S.F.	25,002	20	1981	2001		0.00 %	110.00 %	-14		\$262,371.00	\$238,519
C3020	Floor Finishes - Wood	\$14.70	S.F.	0	20	1981	2001		0.00 %	0.00 %	-14			\$0
C3030	Ceiling Finishes	\$9.98	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$654,783.00	\$595,257
D1010	Elevators and Lifts	\$1.17	S.F.	0	30	1981	2011		0.00 %	0.00 %	-4			\$0
D2010	Plumbing Fixtures	\$17.66	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$1,158,664.00	\$1,053,331
D2020	Domestic Water Distribution	\$3.99	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$261,782.00	\$237,984
D2030	Sanitary Waste	\$3.41	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$223,728.00	\$203,389
D2040	Rain Water Drainage	\$0.98	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$64,297.00	\$58,452

School Assessment Report - 1981 Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	59,645	40	1981	2021		15.00 %	0.00 %	6			\$24,454
D3020	Heat Generating Systems	\$4.55	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$298,523.00	\$271,385
D3030	Cooling Generating Systems	\$4.73	S.F.	59,645	25	1981	2006		0.00 %	110.00 %	-9		\$310,333.00	\$282,121
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$361,508.00	\$328,644
D3050	Terminal & Package Units	\$18.52	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$1,215,088.00	\$1,104,625
D3060	Controls & Instrumentation	\$3.60	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$236,194.00	\$214,722
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$80,700.00	\$73,363
D4010	Sprinklers	\$4.75	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$311,645.00	\$283,314
D4020	Standpipes	\$0.51	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$33,461.00	\$30,419
D5010	Electrical Service/Distribution	\$1.81	S.F.	59,645	40	1981	2021		15.00 %	0.00 %	6			\$107,957
D5020	Branch Wiring	\$6.78	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$444,832.00	\$404,393
D5020	Lighting	\$8.90	S.F.	59,645	30	1981	2011		0.00 %	110.00 %	-4		\$583,925.00	\$530,841
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	59,645	15	1981	1996		0.00 %	110.00 %	-19		\$367,413.00	\$334,012
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	59,645	15	2005	2020		33.33 %	0.00 %	5			\$73,363
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	59,645	15	2005	2020		33.33 %	0.00 %	5			\$36,383
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	0	20	1981	2001		0.00 %	0.00 %	-14			\$0
E1010	Commercial Equipment	\$7.92	S.F.	0	20	1981	2001		0.00 %	0.00 %	-14			\$0
E1020	Institutional Equipment	\$0.40	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$26,244.00	\$23,858
E1090	Other Equipment	\$0.88	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$57,736.00	\$52,488
E2010	Fixed Furnishings	\$5.37	S.F.	59,645	20	1981	2001		0.00 %	110.00 %	-14		\$352,323.00	\$320,294
F1010	Special Structures - Canopies	\$1.61	S.F.	0	25	1981	2006		0.00 %	0.00 %	-9			\$0
Total									18.71 %	71.72 %			\$8,387,090.00	\$11,694,299

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$8,387,090	\$0	\$0	\$0	\$0	\$139,950	\$173,917	\$0	\$118,952	\$0	\$445,063	\$9,264,973
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1020 - Special Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$445,489	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$445,489
B2030 - Exterior Doors	\$60,361	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$60,361
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$293,619	\$293,619
B3010 - Roof Coverings - Preformed Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1981 Building

C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$114,041	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$114,041
C1030 - Fittings	\$183,051	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$183,051
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic & Glazed	\$67,387	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,387
C3010 - Wall Finishes - Paint	\$112,689	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$151,445	\$264,134
C3010 - Wall Finishes - Wood Panelling	\$4,620	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,620
C3020 - Floor Finishes - Carpet	\$93,902	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$118,952	\$0	\$0	\$212,854
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$262,371	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$262,371
C3020 - Floor Finishes - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$654,783	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$654,783
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$1,158,664	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,158,664
D2020 - Domestic Water Distribution	\$261,782	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$261,782
D2030 - Sanitary Waste	\$223,728	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$223,728
D2040 - Rain Water Drainage	\$64,297	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$64,297
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$32,120	\$0	\$0	\$0	\$0	\$32,120
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$298,523	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$298,523
D3030 - Cooling Generating Systems	\$310,333	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$310,333
D3040 - Distribution & Exhaust Systems	\$361,508	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$361,508
D3050 - Terminal & Package Units	\$1,215,088	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,215,088
D3060 - Controls & Instrumentation	\$236,194	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$236,194
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$80,700	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$80,700
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1981 Building

D4010 - Sprinklers	\$311,645	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$311,645
D4020 - Standpipes	\$33,461	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$33,461
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$141,797	\$0	\$0	\$0	\$0	\$141,797
D5020 - Branch Wiring	\$444,832	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$444,832
D5020 - Lighting	\$583,925	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$583,925
D5030 - Communications and Security - Clock & PA Systems	\$367,413	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$367,413
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$93,553	\$0	\$0	\$0	\$0	\$0	\$93,553
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$46,396	\$0	\$0	\$0	\$0	\$0	\$46,396
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$26,244	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,244
E1090 - Other Equipment	\$57,736	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$57,736
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$352,323	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$352,323
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$8,387,090.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$445,489.00	\$0.00	\$0.00	\$445,489.00
B2030	Exterior Doors	\$0.00	\$0.00	\$60,361.00	\$0.00	\$0.00	\$60,361.00
C1020	Interior Doors	\$0.00	\$0.00	\$114,041.00	\$0.00	\$0.00	\$114,041.00
C1030	Fittings	\$0.00	\$0.00	\$183,051.00	\$0.00	\$0.00	\$183,051.00
C3010	Wall Finishes - Ceramic & Glazed	\$0.00	\$0.00	\$67,387.00	\$0.00	\$0.00	\$67,387.00
C3010	Wall Finishes - Paint	\$0.00	\$0.00	\$112,689.00	\$0.00	\$0.00	\$112,689.00
C3010	Wall Finishes - Wood Panelling	\$0.00	\$0.00	\$0.00	\$0.00	\$4,620.00	\$4,620.00
C3020	Floor Finishes - Carpet	\$0.00	\$0.00	\$93,902.00	\$0.00	\$0.00	\$93,902.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$262,371.00	\$0.00	\$0.00	\$262,371.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$654,783.00	\$0.00	\$0.00	\$654,783.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$1,158,664.00	\$0.00	\$0.00	\$1,158,664.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$261,782.00	\$0.00	\$0.00	\$261,782.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$223,728.00	\$0.00	\$0.00	\$223,728.00
D2040	Rain Water Drainage	\$0.00	\$0.00	\$64,297.00	\$0.00	\$0.00	\$64,297.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$298,523.00	\$0.00	\$0.00	\$298,523.00
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$310,333.00	\$0.00	\$0.00	\$310,333.00
D3040	Distribution & Exhaust Systems	\$0.00	\$0.00	\$361,508.00	\$0.00	\$0.00	\$361,508.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$1,215,088.00	\$0.00	\$0.00	\$1,215,088.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$236,194.00	\$0.00	\$0.00	\$236,194.00
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$0.00	\$0.00	\$80,700.00	\$0.00	\$0.00	\$80,700.00
D4010	Sprinklers	\$0.00	\$0.00	\$311,645.00	\$0.00	\$0.00	\$311,645.00
D4020	Standpipes	\$0.00	\$0.00	\$33,461.00	\$0.00	\$0.00	\$33,461.00
D5020	Branch Wiring	\$0.00	\$0.00	\$444,832.00	\$0.00	\$0.00	\$444,832.00
D5020	Lighting	\$0.00	\$0.00	\$583,925.00	\$0.00	\$0.00	\$583,925.00
D5030	Communications and Security - Clock & PA Systems	\$0.00	\$0.00	\$367,413.00	\$0.00	\$0.00	\$367,413.00
E1020	Institutional Equipment	\$0.00	\$0.00	\$26,244.00	\$0.00	\$0.00	\$26,244.00
E1090	Other Equipment	\$0.00	\$0.00	\$57,736.00	\$0.00	\$0.00	\$57,736.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$352,323.00	\$0.00	\$0.00	\$352,323.00
Total:		\$0.00	\$0.00	\$8,382,470.00	\$0.00	\$4,620.00	\$8,387,090.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$8,387,090.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B2020 - Exterior Windows



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$445,489.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The aluminum frame, operable, double pane windows are aged, have failing seals, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$60,361.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The original exterior doors are beyond their expected service life, have some deterioration due, and should be replaced.

System: C1020 - Interior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$114,041.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The interior doors are aged, failing, not ADA compliant, and should be replaced.

System: C1030 - Fittings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$183,051.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Fittings, such as toilet partitions, handrails and signage, are beyond their expected service life and should be replaced. SPLOST project 108-422 to update ADA compliance in the hall restroom.

System: C3010 - Wall Finishes - Ceramic & Glazed



Location: Restrooms
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 5,965.00
Unit of Measure: S.F.
Estimate: \$67,387.00
Assessor Name: Sam Mandola
Date Created: 04/11/2015

Notes: The wall tiles are aged, scuffed and faded, and should be replaced.

System: C3010 - Wall Finishes - Paint



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 53,080.00
Unit of Measure: S.F.
Estimate: \$112,689.00
Assessor Name: Sam Mandola
Date Created: 04/11/2015

Notes: The painted wall finish is deteriorating due to age and numerous layers of paint, which is now easy to peel off.

System: C3020 - Floor Finishes - Carpet



Location: Office and Teachers Lounge

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 10,043.00

Unit of Measure: S.F.

Estimate: \$93,902.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The carpet is stained, showing signs of failure, and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Cafeteria and Classrooms

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 25,002.00

Unit of Measure: S.F.

Estimate: \$262,371.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The VCT flooring is aged, cracked and worn, and should be replaced.

School Assessment Report - 1981 Building

System: C3030 - Ceiling Finishes



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Appearance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$654,783.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The acoustical ceiling system is deteriorating due to age and the environment, and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$1,158,664.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Plumbing fixtures are beyond service life, damaged, not ADA compliant, and should be scheduled for replacement. SPLOST project 108-422 to update ADA compliance in the hall restroom.

System: D2020 - Domestic Water Distribution



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$261,782.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The domestic water distribution system is beyond its expected service life and should be scheduled for replacement.

System: D2030 - Sanitary Waste



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$223,728.00

Assessor Name: Sam Mandola

Date Created: 07/04/2015

Notes: The sanitary waste system is beyond its expected service life and should be scheduled for replacement. SPLOST project 108-422 to replace grease trap.

System: D2040 - Rain Water Drainage



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$64,297.00

Assessor Name: Sam Mandola

Date Created: 07/04/2015

Notes: The rainwater drainage system is beyond its expected service life and should be scheduled for replacement.

System: D3020 - Heat Generating Systems



Location: Mechanical Room

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$298,523.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The boiler is beyond its expected service life and should be scheduled for replacement.

System: D3030 - Cooling Generating Systems



Location: Northwest Side of Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 Priority
Correction: Renew System
Qty: 59,645.00
Unit of Measure: S.F.
Estimate: \$310,333.00
Assessor Name: Sam Mandola
Date Created: 07/04/2015

Notes: The cooling generating system is beyond its expected service life, noisy, and should be scheduled for replacement.


System: D3040 - Distribution & Exhaust Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 Priority
Correction: Renew System
Qty: 59,645.00
Unit of Measure: S.F.
Estimate: \$361,508.00
Assessor Name: Sam Mandola
Date Created: 04/11/2015

Notes: The distribution and exhaust systems are beyond their expected service life and should be scheduled for replacement.

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$1,215,088.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The primary water source heat pumps and factory integrated controls are beyond their expected service life and should be scheduled for replacement.

System: D3060 - Controls & Instrumentation



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$236,194.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The controls and instrumentation system is beyond its expected service life and should be scheduled for replacement.

System: D3090 - Other HVAC Systems/Equip - Kitchen Hood



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$80,700.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The kitchen hood system is beyond its expected service life and should be scheduled for replacement.

System: D4010 - Sprinklers



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$311,645.00

Assessor Name: Sam Mandola

Date Created: 07/04/2015

Notes: The sprinkler system is beyond its expected service life and should be scheduled for replacement.

System: D4020 - Standpipes



Location: Northwest Side of Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 59,645.00
Unit of Measure: S.F.
Estimate: \$33,461.00
Assessor Name: Sam Mandola
Date Created: 07/04/2015

Notes: Standpipes are beyond their expected service life and should be scheduled for replacement.

System: D5020 - Branch Wiring



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 59,645.00
Unit of Measure: S.F.
Estimate: \$444,832.00
Assessor Name: Sam Mandola
Date Created: 04/11/2015

Notes: The branch wiring system is beyond its expected service life and should be scheduled for replacement.

System: D5020 - Lighting



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$583,925.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The lighting system is beyond its expected service life and should be scheduled for replacement.

System: D5030 - Communications and Security - Clock & PA Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$367,413.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Clock and PA systems are beyond their expected service life and should be scheduled for replacement.

System: E1020 - Institutional Equipment



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$26,244.00

Assessor Name: Sam Mandola

Date Created: 07/04/2015

Notes: Institutional equipment, such as theater and stage equipment, is beyond its expected service life and should be scheduled for replacement.

System: E1090 - Other Equipment



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$57,736.00

Assessor Name: Sam Mandola

Date Created: 07/04/2015

Notes: Under the Capital Improvements program the grease trap is scheduled for replacement.

System: E2010 - Fixed Furnishings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 59,645.00

Unit of Measure: S.F.

Estimate: \$352,323.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Fixed furnishings, such as built-in cabinets, are beyond their expected service life and worn, and should be replaced.

Priority 5 Priority:

System: C3010 - Wall Finishes - Wood Panelling



Location: Principal's Office

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 5 Priority

Correction: Renew System

Qty: 600.00

Unit of Measure: S.F.

Estimate: \$4,620.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Panels are beyond their expected service and should be replaced or refinished.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	7,320
Year Built:	1986
Last Renovation:	
Replacement Value:	\$1,301,580
Repair Cost:	\$512,908.00
Total FCI:	39.41 %
Total RSLI:	21.16 %
FCA Score:	60.59



Description:

The 1986 classroom addition at Eldridge Miller Elementary School is a one-story building located at 919 Martin Road in Stone Mountain, Georgia. There has been a roofing renovation in 2010 and communications and security upgrade in 2005. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2011	Fire Sprinkler System:	Yes
-----------------	------	------------------------	-----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	71.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	71.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	49.18 %	0.00 %	\$0.00
B30 - Roofing	66.67 %	0.00 %	\$0.00
C10 - Interior Construction	41.48 %	25.18 %	\$22,465.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	11.08 %	91.63 %	\$149,200.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	3.33 %	0.00 %	\$0.00
D30 - HVAC	0.42 %	96.30 %	\$252,913.00
D40 - Fire Protection	3.33 %	0.00 %	\$0.00
D50 - Electrical	6.55 %	24.71 %	\$45,091.00
E10 - Equipment	0.00 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$43,239.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
Totals:	21.16 %	39.41 %	\$512,908.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). North Elevation - Jul 03, 2015



2). West Elevation - Jul 03, 2015



3). Southwest Elevation - Jul 03, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1986 Addition

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	7,320	100	1986	2086		71.00 %	0.00 %	71			\$47,507
A1020	Special Foundations	\$4.46	S.F.	0	100	1986	2086		71.00 %	0.00 %	71			\$0
A1030	Slab on Grade	\$7.09	S.F.	7,320	100	1986	2086		71.00 %	0.00 %	71			\$51,899
A2010	Basement Excavation	\$0.26	S.F.	0	100	1986	2086		71.00 %	0.00 %	71			\$0
A2020	Basement Walls	\$6.13	S.F.	0	100	1986	2086		71.00 %	0.00 %	71			\$0
B1010	Floor Construction	\$15.61	S.F.	0	100	1986	2086		71.00 %	0.00 %	71			\$0
B1020	Roof Construction	\$5.34	S.F.	7,320	100	1986	2086		71.00 %	0.00 %	71			\$39,089
B2010	Exterior Walls	\$16.02	S.F.	7,320	100	1986	2086		71.00 %	0.00 %	71			\$117,266
B2020	Exterior Windows	\$6.79	S.F.	7,230	30	1986	2016		3.33 %	0.00 %	1			\$49,092
B2030	Exterior Doors	\$0.92	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$6,734
B3010	Roof Coverings - Asphalt Shingles	\$4.32	S.F.	0	10	1986	1996		0.00 %	0.00 %	-19			\$0
B3010	Roof Coverings - BUR	\$6.49	S.F.	0	25	1986	2011		0.00 %	0.00 %	-4			\$0
B3010	Roof Coverings - EPDM	\$3.33	S.F.	7,320	15	2010	2025		66.67 %	0.00 %	10			\$24,376
B3010	Roof Coverings - Preformed Metal	\$5.01	S.F.	0	30	1986	2016		3.33 %	0.00 %	1			\$0
B3010	Roof Coverings - Standing Seam Metal	\$27.45	S.F.	0	75	1986	2061		61.33 %	0.00 %	46			\$0
B3020	Roof Openings	\$0.63	S.F.	0	30	1986	2016		3.33 %	0.00 %	1			\$0
C1010	Partitions	\$7.01	S.F.	7,320	100	1986	2086		71.00 %	0.00 %	71			\$51,313
C1020	Interior Doors	\$2.39	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$17,495
C1030	Fittings	\$2.79	S.F.	7,320	20	1986	2006		0.00 %	110.00 %	-9		\$22,465.00	\$20,423
C2010	Stair Construction	\$1.81	S.F.	0	100	1986	2086		71.00 %	0.00 %	71			\$0
C3010	Wall Finishes - Ceramic & Glazed	\$10.27	S.F.	365	30	1986	2016		3.33 %	0.00 %	1			\$3,749
C3010	Wall Finishes - Paint	\$1.93	S.F.	6,955	10	2015	2025		100.00 %	0.00 %	10			\$13,423
C3010	Wall Finishes - Wall Coverings	\$2.13	S.F.	0	10	1986	1996		0.00 %	0.00 %	-19			\$0
C3020	Floor Finishes - Carpet	\$8.50	S.F.	165	8	1986	1994	2020	62.50 %	0.00 %	5			\$1,403
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	595	50	1986	2036		42.00 %	0.00 %	21			\$8,622
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	0	50	1986	2036		42.00 %	0.00 %	21			\$0
C3020	Floor Finishes - VCT	\$9.54	S.F.	6,560	20	1986	2006		0.00 %	110.00 %	-9		\$68,841.00	\$62,582
C3020	Floor Finishes - Wood	\$14.70	S.F.	0	20	1986	2006		0.00 %	0.00 %	-9			\$0
C3030	Ceiling Finishes	\$9.98	S.F.	7,320	20	1986	2006		0.00 %	110.00 %	-9		\$80,359.00	\$73,054
D1010	Elevators and Lifts	\$1.17	S.F.	0	30	1986	2016		3.33 %	0.00 %	1			\$0
D2010	Plumbing Fixtures	\$17.66	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$129,271
D2020	Domestic Water Distribution	\$3.99	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$29,207
D2030	Sanitary Waste	\$3.41	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$24,961
D2040	Rain Water Drainage	\$0.98	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$7,174

School Assessment Report - 1986 Addition

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.		40	1986	2026		27.50 %	0.00 %	11			\$0
D3020	Heat Generating Systems	\$4.55	S.F.	0	30	1986	2016		3.33 %	0.00 %	1			\$0
D3030	Cooling Generating Systems	\$4.73	S.F.	0	30	1986	2016		3.33 %	0.00 %	1			\$0
D3040	Distribution & Exhaust Systems	\$4.47	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$32,720
D3050	Terminal & Package Units	\$27.81	S.F.	7,320	20	1986	2006		0.00 %	110.00 %	-9		\$223,926.00	\$203,569
D3060	Controls & Instrumentation	\$3.60	S.F.	7,320	20	1986	2006		0.00 %	110.00 %	-9		\$28,987.00	\$26,352
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	0	30	1986	2016		3.33 %	0.00 %	1			\$0
D4010	Sprinklers	\$4.75	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$34,770
D4020	Standpipes	\$0.51	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$3,733
D5010	Electrical Service/Distribution	\$1.81	S.F.	7,320	40	1986	2026		27.50 %	0.00 %	11			\$13,249
D5020	Branch Wiring	\$6.78	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$49,630
D5020	Lighting	\$8.90	S.F.	7,320	30	1986	2016		3.33 %	0.00 %	1			\$65,148
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	7,320	15	1986	2001		0.00 %	110.00 %	-14		\$45,091.00	\$40,992
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	7,320	15	2005	2020		33.33 %	0.00 %	5			\$9,004
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	7,320	15	2005	2020		33.33 %	0.00 %	5			\$4,465
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	0	15	1986	2001		0.00 %	0.00 %	-14			\$0
E1010	Commercial Equipment	\$7.92	S.F.	0	20	1986	2006		0.00 %	0.00 %	-9			\$0
E1020	Institutional Equipment	\$0.40	S.F.		0				0.00 %	0.00 %				\$0
E1090	Other Equipment	\$0.88	S.F.	0	20	1986	2006		0.00 %	0.00 %	-9			\$0
E2010	Fixed Furnishings	\$5.37	S.F.	7,320	20	1986	2006		0.00 %	110.00 %	-9		\$43,239.00	\$39,308
F1010	Special Structures - Canopies	\$1.61	S.F.	0	25	1986	2011		0.00 %	0.00 %	-4			\$0
Total									21.16 %	39.41 %			\$512,908.00	\$1,301,580

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$512,908	\$508,617	\$0	\$0	\$0	\$18,965	\$0	\$0	\$0	\$0	\$55,877	\$1,096,367
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1020 - Special Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$55,621	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,621
B2030 - Exterior Doors	\$0	\$7,630	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,630
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$36,034	\$36,034
B3010 - Roof Coverings - Preformed Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1986 Addition

C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$14,416	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,416
C1030 - Fittings	\$22,465	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,465
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic & Glazed	\$0	\$4,247	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,247
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$19,843	\$19,843
C3010 - Wall Finishes - Wall Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Carpet	\$0	\$0	\$0	\$0	\$0	\$1,789	\$0	\$0	\$0	\$0	\$0	\$1,789
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$68,841	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$68,841
C3020 - Floor Finishes - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$80,359	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$80,359
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$146,464	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$146,464
D2020 - Domestic Water Distribution	\$0	\$33,091	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$33,091
D2030 - Sanitary Waste	\$0	\$28,281	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,281
D2040 - Rain Water Drainage	\$0	\$8,128	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,128
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution & Exhaust Systems	\$0	\$37,072	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,072
D3050 - Terminal & Package Units	\$223,926	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$223,926
D3060 - Controls & Instrumentation	\$28,987	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,987
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1986 Addition

D4010 - Sprinklers	\$0	\$39,394	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,394
D4020 - Standpipes	\$0	\$4,230	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,230
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$56,231	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$56,231
D5020 - Lighting	\$0	\$73,813	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$73,813
D5030 - Communications and Security - Clock & PA Systems	\$45,091	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$45,091
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$11,481	\$0	\$0	\$0	\$0	\$0	\$11,481
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$5,694	\$0	\$0	\$0	\$0	\$0	\$5,694
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$43,239	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$43,239
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$512,908.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
C1030	Fittings	\$0.00	\$0.00	\$22,465.00	\$0.00	\$0.00	\$22,465.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$68,841.00	\$0.00	\$0.00	\$68,841.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$80,359.00	\$0.00	\$0.00	\$80,359.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$223,926.00	\$0.00	\$0.00	\$223,926.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$28,987.00	\$0.00	\$0.00	\$28,987.00
D5030	Communications and Security - Clock & PA Systems	\$0.00	\$0.00	\$45,091.00	\$0.00	\$0.00	\$45,091.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$43,239.00	\$0.00	\$0.00	\$43,239.00
	Total:	\$0.00	\$0.00	\$512,908.00	\$0.00	\$0.00	\$512,908.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$512,908.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: C1030 - Fittings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 7,320.00

Unit of Measure: S.F.

Estimate: \$22,465.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: Fittings, such as toilet partitions, handrails and signage, are beyond their expected service life and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Corridors and Classrooms

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 6,560.00

Unit of Measure: S.F.

Estimate: \$68,841.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The VCT flooring is aged and worn, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Appearance

Priority: 3 Priority

Correction: Renew System

Qty: 7,320.00

Unit of Measure: S.F.

Estimate: \$80,359.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The acoustical ceiling system is damaged due to roof leaks and should be replaced.

System: D3050 - Terminal & Package Units



Location: Mechanical Room

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 7,320.00

Unit of Measure: S.F.


Estimate: \$223,926.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The primary water source heat pumps and air handlers are beyond service life, not code compliant, and should be scheduled for replacement. SPLOST project 108-422 to replace the water source heat pumps.

System: D3060 - Controls & Instrumentation



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 7,320.00

Unit of Measure: S.F.

Estimate: \$28,987.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: The controls and instrumentation system is beyond its expected service life and should be scheduled for replacement.

System: D5030 - Communications and Security - Clock & PA Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 7,320.00

Unit of Measure: S.F.

Estimate: \$45,091.00

Assessor Name: Eduardo Lopez

Date Created: 04/11/2015

Notes: Clock and PA systems are beyond their expected service life and should be scheduled for replacement.

System: E2010 - Fixed Furnishings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 7,320.00

Unit of Measure: S.F.

Estimate: \$43,239.00

Assessor Name: Eduardo Lopez

Date Created: 01/17/2016

Notes: Fixed furnishings are beyond their expected service life and should be scheduled for replacement.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	5,478
Year Built:	2003
Last Renovation:	
Replacement Value:	\$816,963
Repair Cost:	\$70,201.00
Total FCI:	8.59 %
Total RSLI:	65.33 %
FCA Score:	91.41



Description:

The 2003 gymnasium at Eldridge Miller Elementary School is a one-story building located at 919 Martin Road in Stone Mountain, Georgia. There have been no additions or major renovations to this building. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2020	Fire Sprinkler System:	No
-----------------	------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	88.00 %	0.00 %	\$0.00
B10 - Superstructure	88.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	85.42 %	0.00 %	\$0.00
B30 - Roofing	84.00 %	0.00 %	\$0.00
C10 - Interior Construction	76.16 %	0.00 %	\$0.00
C30 - Interior Finishes	39.48 %	0.00 %	\$0.00
D20 - Plumbing	60.00 %	0.00 %	\$0.00
D30 - HVAC	30.85 %	53.04 %	\$70,201.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	45.89 %	0.00 %	\$0.00
Totals:	65.33 %	8.59 %	\$70,201.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). Southeast Elevation - Jul 03, 2015



2). South Elevation - Jul 03, 2015



3). East Elevation - Jul 03, 2015



4). West Elevation - Jul 03, 2015



5). North Elevation - Jul 03, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$9.34	S.F.	0	100	2003	2103		88.00 %	0.00 %	88			\$0
A1030	Slab on Grade	\$6.21	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$34,018
B1020	Roof Construction	\$21.36	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$117,010
B2010	Exterior Walls	\$19.80	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$108,464
B2030	Exterior Doors	\$2.01	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$11,011
B3010	Roof Coverings - Standing Seam Metal	\$11.91	S.F.	5,478	75	2003	2078		84.00 %	0.00 %	63			\$65,243
C1010	Partitions	\$12.78	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$70,009
C1020	Interior Doors	\$4.24	S.F.	5,478	40	2003	2043		70.00 %	0.00 %	28			\$23,227
C1030	Fittings	\$3.46	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$18,954
C3010	Wall Finishes - Ceramic	\$6.65	S.F.	0	30	2003	2033		60.00 %	0.00 %	18			\$0
C3010	Wall Finishes - Paint	\$1.41	S.F.	5,478	10	2015	2025		100.00 %	0.00 %	10			\$7,724
C3020	Floor Finishes - Ceramic Tile	\$6.67	S.F.	545	20	2003	2023		40.00 %	0.00 %	8			\$3,635
C3020	Floor Finishes - Neoprene	\$14.46	S.F.	0	50	2003	2053		76.00 %	0.00 %	38			\$0
C3020	Floor Finishes - VCT	\$5.01	S.F.	4,933	15	2003	2018		20.00 %	0.00 %	3			\$24,714
C3030	Ceiling Finishes	\$4.31	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$23,610
D2010	Plumbing Fixtures	\$9.66	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$52,917
D2020	Domestic Water Distribution	\$5.85	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$32,046
D2030	Sanitary Waste	\$0.87	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$4,766
D2040	Rain Water Drainage	\$0.22	S.F.	0	30	2003	2033		60.00 %	0.00 %	18			\$0
D2090	Other Plumbing Systems - Natural Gas	\$0.32	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$1,753
D3040	Distribution Systems & Exhaust Systems	\$12.25	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$67,106
D3050	Terminal & Package Units	\$11.65	S.F.	5,478	15	2003	2018	2015	0.00 %	110.00 %	0		\$70,201.00	\$63,819
D3060	Controls & Instrumentation	\$0.26	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$1,424
D4010	Sprinklers	\$3.84	S.F.	0	30	2003	2033		60.00 %	0.00 %	18			\$0
D5010	Electrical Service/Distribution	\$1.24	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$6,793
D5020	Branch Wiring	\$5.24	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$28,705
D5020	Lighting	\$5.24	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$28,705
D5030	Communications and Security - Fire Alarm	\$2.13	S.F.	5,478	15	2005	2020		33.33 %	0.00 %	5			\$11,668
D5030	Communications and Security - Public Address & Clock System	\$0.88	S.F.	5,478	15	2003	2018		20.00 %	0.00 %	3			\$4,821
D5030	Communications and Security - Security & CCTV	\$0.88	S.F.	5,478	15	2005	2020		33.33 %	0.00 %	5			\$4,821
Total									65.33 %	8.59 %			\$70,201.00	\$816,963

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$70,201	\$0	\$0	\$35,502	\$0	\$21,027	\$0	\$0	\$106,359	\$0	\$11,418	\$244,507
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,411	\$0	\$0	\$26,411
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,418	\$11,418
C3020 - Floor Finishes - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,066	\$0	\$0	\$5,066
C3020 - Floor Finishes - Neoprene	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$0	\$0	\$0	\$29,707	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,707
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$32,899	\$0	\$0	\$32,899
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 2003 Gym

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$70,201	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,201
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,985	\$0	\$0	\$1,985
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,998	\$0	\$0	\$39,998
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$14,879	\$0	\$0	\$0	\$0	\$0	\$14,879
D5030 - Communications and Security - Public Address & Clock System	\$0	\$0	\$0	\$5,795	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,795
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$6,148	\$0	\$0	\$0	\$0	\$0	\$6,148

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
D3050	Terminal & Package Units	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00	\$70,201.00
	Total:	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00	\$70,201.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Inadequate

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$70,201.00

Assessor Name: Sam Mandola

Date Created: 07/04/2015

Notes: The primary heating and cooling system consists of gas fire units heater, ventilation fans, and single PTAC unit in the office, which are inadequate and nearing the end of their expected life. These units should be replaced with a packaged system. SPLOST project 108-422 to install a 20 ton HVAC package in the gym.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	72,443
Year Built:	1981
Last Renovation:	
Replacement Value:	\$1,739,876
Repair Cost:	\$1,032,738.00
Total FCI:	59.36 %
Total RSLI:	16.81 %
FCA Score:	40.64



Description:

The Eldridge Miller Elementary School site was originally constructed in 1981, has a total area of 10.9 acres, and is occupied by approximately 72,443 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site features.

Attributes:

General Attributes:

Site Code: 1075

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	4.86 %	99.72 %	\$941,098.00
G30 - Site Mechanical Utilities	30.19 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	32.56 %	34.37 %	\$91,640.00
Totals:	16.81 %	59.36 %	\$1,032,738.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). Aerial Image of Eldridge L. Miller
Elementary School - Oct 20, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$5.17	S.F.	45,705	25	1981	2006		0.00 %	110.00 %	-9		\$259,924.00	\$236,295
G2020	Parking Lots	\$4.56	S.F.	17,177	25	1981	2006		0.00 %	110.00 %	-9		\$86,160.00	\$78,327
G2030	Pedestrian Paving	\$1.50	S.F.	72,443	30	1981	2011		0.00 %	110.00 %	-4		\$119,531.00	\$108,665
G2040	Baseball Field	\$8.35	S.F.		20				0.00 %	0.00 %				\$0
G2040	Canopies	\$0.29	S.F.		25				0.00 %	0.00 %				\$0
G2040	Covered Walkways	\$48.72	S.F.	1,810	25	2003	2028		52.00 %	0.00 %	13			\$88,183
G2040	Fencing & Guardrails	\$0.91	S.F.	72,443	30	1981	2011		0.00 %	110.00 %	-4		\$72,515.00	\$65,923
G2040	Football Field	\$5.85	S.F.		20				0.00 %	0.00 %				\$0
G2040	Hard Surface Play Area	\$6.26	S.F.		20				0.00 %	0.00 %				\$0
G2040	Playing Field	\$3.92	S.F.	66,656	20	1981	2001		0.00 %	110.00 %	-14		\$287,421.00	\$261,292
G2040	Soccer/Lacross Field	\$5.00	S.F.		20				0.00 %	0.00 %				\$0
G2040	Softball Field	\$8.86	S.F.		20				0.00 %	0.00 %				\$0
G2040	Tennis Courts	\$18.47	S.F.		20				0.00 %	0.00 %				\$0
G2040	Track	\$7.04	S.F.		10				0.00 %	0.00 %				\$0
G2050	Landscaping	\$1.45	S.F.	72,443	15	1981	1996		0.00 %	110.00 %	-19		\$115,547.00	\$105,042
G3010	Water Supply	\$1.83	S.F.	72,443	50	1981	2031		32.00 %	0.00 %	16			\$132,571
G3020	Sanitary Sewer	\$1.15	S.F.	72,443	50	1981	2031		32.00 %	0.00 %	16			\$83,309
G3030	Storm Sewer	\$3.55	S.F.	72,443	50	1981	2031		32.00 %	0.00 %	16			\$257,173
G3060	Fuel Distribution	\$0.78	S.F.	72,443	40	1981	2021		15.00 %	0.00 %	6			\$56,506
G4010	Electrical Distribution	\$1.86	S.F.	72,443	50	1981	2031		32.00 %	0.00 %	16			\$134,744
G4020	Site Lighting	\$1.15	S.F.	72,443	30	1981	2011		0.00 %	110.00 %	-4		\$91,640.00	\$83,309
G4030	Site Communications & Security	\$0.67	S.F.	72,443	10	2014	2024		90.00 %	0.00 %	9			\$48,537
Total									16.81 %	59.36 %			\$1,032,738.00	\$1,739,876

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

School Assessment Report - Site


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,032,738	\$0	\$0	\$0	\$0	\$0	\$74,218	\$0	\$0	\$69,662	\$0	\$1,176,617
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$259,924	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$259,924
G2020 - Parking Lots	\$86,160	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$86,160
G2030 - Pedestrian Paving	\$119,531	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$119,531
G2040 - Baseball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Fencing & Guardrails	\$72,515	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$72,515
G2040 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Hard Surface Play Area	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Playing Field	\$287,421	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$287,421
G2040 - Soccer/Lacross Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Softball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Tennis Courts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping	\$115,547	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$115,547
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$74,218	\$0	\$0	\$0	\$0	\$74,218
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$91,640	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$91,640
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,662	\$0	\$69,662

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
G2010	Roadways	\$0.00	\$0.00	\$259,924.00	\$0.00	\$0.00	\$259,924.00
G2020	Parking Lots	\$0.00	\$0.00	\$86,160.00	\$0.00	\$0.00	\$86,160.00
G2030	Pedestrian Paving	\$0.00	\$0.00	\$119,531.00	\$0.00	\$0.00	\$119,531.00
G2040	Fencing & Guardrails	\$0.00	\$0.00	\$72,515.00	\$0.00	\$0.00	\$72,515.00
G2040	Playing Field	\$0.00	\$287,421.00	\$0.00	\$0.00	\$0.00	\$287,421.00
G2050	Landscaping	\$0.00	\$0.00	\$115,547.00	\$0.00	\$0.00	\$115,547.00
G4020	Site Lighting	\$0.00	\$0.00	\$91,640.00	\$0.00	\$0.00	\$91,640.00
	Total:	\$0.00	\$287,421.00	\$745,317.00	\$0.00	\$0.00	\$1,032,738.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 Priority:

System: G2040 - Playing Field



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 2 Priority

Correction: Renew System

Qty: 66,656.00

Unit of Measure: S.F.

Estimate: \$287,421.00

Assessor Name: Eduardo Lopez

Date Created: 07/03/2015

Notes: The playing fields are beyond their expected service life, have bare spots, and should be re-sodded to prevent erosion.

Priority 3 Priority:

System: G2010 - Roadways



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 45,705.00

Unit of Measure: S.F.

Estimate: \$259,924.00

Assessor Name: Eduardo Lopez

Date Created: 07/03/2015

Notes: Roadways are beyond their expected service life, damaged with many cracks and potholes, worn, and should be replaced.

System: G2020 - Parking Lots



Location: North and East Parking Lots

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 17,177.00

Unit of Measure: S.F.

Estimate: \$86,160.00

Assessor Name: Eduardo Lopez

Date Created: 07/03/2015

Notes: The parking lot is beyond its expected service life, has many repairs and potholes, and should be replaced and re-striped.

System: G2030 - Pedestrian Paving



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 72,443.00

Unit of Measure: S.F.

Estimate: \$119,531.00

Assessor Name: Eduardo Lopez

Date Created: 07/03/2015

Notes: Pedestrian paving is beyond its expected service life, damaged, and should be replaced.

System: G2040 - Fencing & Guardrails



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 72,443.00

Unit of Measure: S.F.

Estimate: \$72,515.00

Assessor Name: Eduardo Lopez

Date Created: 07/03/2015

Notes: Fencing is beyond its expected service life, damaged, and should be scheduled for replacement.

System: G2050 - Landscaping



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 72,443.00

Unit of Measure: S.F.

Estimate: \$115,547.00

Assessor Name: Eduardo Lopez

Date Created: 07/03/2015

Notes: Landscaping is beyond its expected service life, missing and damaged in multiple areas, and should be replaced to prevent erosion.

System: G4020 - Site Lighting



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 72,443.00

Unit of Measure: S.F.

Estimate: \$91,640.00

Assessor Name: Eduardo Lopez

Date Created: 07/04/2015

Notes: Site lighting is beyond its expected service life, inadequate, and should be scheduled for replacement.

Glossary

Abandoned	A facility owned by a district that is not occupied and not maintained. See Vacant.
Additional Cost	Total project cost is composed of hard and soft costs. Additional costs or soft expenses are costs that are necessary to accomplish the corrective work but are not directly attributable to the deficient systems direct construction cost, which are often referred to as hard cost. The components included in the soft costs vary by owner but usually include architect and contractor fees, contingencies and other owner-incurred costs necessary to fully develop and build a facility. These soft cost factors can be adjusted anytime within the eCOMET® database at the owner's discretion.
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems, reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ASTM	ASTM International (ASTM): Originally known as the American Society for Testing and Materials, ASTM is an international standards organization that develops and publishes voluntary consensus technical standards for a wide range of materials, products, systems, and services.
BOMA	Building Owners Managers of America (BOMA): National organization of public and private facility owners focused on building management tools and maintenance techniques. eCOMET® reference: Building and component system effective economic life expectancies.
Building	A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior.
Building Addition	An area, space or component of a building added to a building after the original building's year built date. NOTE: As a convention in the database, "Main" was used to designate the original building. Additions built prior to 1983 (30 years) were included in the main building area calculations to reflect their predicted system depreciation characteristics and remaining service life.
Building Systems	eCOMET® uses UNIFORMAT II to organize building data. UNIFORMAT II was originally developed by the federal General Services Administration to delineate building costs by systems rather than by material. UNIFORMAT II was formalized by an NIST standard, NISTIR 6389 in 1999. It has been further quantified and updated by ASTM standard 2005, E1557-05. The Construction Specifications Institute, CSI, has taken over the standard as part of their MasterFormat / MasterSpec system.
Calculated Next Renewal	The year a system or building element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal refers to the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life. It is not normally included in an annual operating/maintenance budget. See calculated next renewal and next renewal.
City Cost Index (CCI)	RS Means provides building system, equipment, and construction costs at a national level. The City Cost Index (also provided by RS Means) localizes those costs to a geographic region of the United States. In eCOMET®, each building or site is assigned a City Cost Index, which adjusts all of the associated costs for systems, deficiencies and inventory to the local value.
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
Condition Budget	The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work.

School Assessment Report - Eldridge L. Miller Elementary

Condition Index (CI) %	The Condition Index (CI) also known as the Remaining Service Life Index (RSLI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude soft cost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).
Construction Specifications Institute	Construction Specifications Institute: Primary national organization specializing in construction materials data and data location in construction documents. eCOMET® reference: UNIFORMAT II materials classification.
Correction	Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a UNIFORMAT II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction.
Cost Model	A cost model is a list of facility systems which could represent the installed systems a given facility. Included in the cost model are standard unit cost estimates, gross areas, life cycles and installed dates. Also represented is the repair cost for deficient systems, replacement values. See eCOMET® cost models.
Criteria	Criteria refer to the set of requirements, guidelines or standards that are assessed and rated to develop a score.
Current Period	The Current Period is the current year plus a user defined number of forward years.
Current Replacement Value (CRV)	The Current Replacement Value (CRV) of a facility, building or system represents the hypothetical cost of rebuilding or replacing an existing facility under today's codes and construction standards, using its current configuration. It is calculated by multiplying the gross area of the facility by a square foot cost developed in that facility's cost model. Replacement cost includes construction costs and owner's additional or soft costs for fees, permits and other expenses to reflect a total project cost.
Deferred Maintenance	Deferred maintenance is condition work deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose.
Deficiency Category	Deficiency Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions include, but are not limited to: Accessibility Code Compliance, Appearance, Building Code Compliance, Deferred Maintenance, Energy, Environmental, Life Safety Code Compliance, and Safety.
Deficiency Distress	Deficiency Distress refers to a user-defined root cause of a deficiency. Distress descriptions are: Beyond Service Life, Damaged, Inadequate, Needs Remediation, and Missing.
Deficiency Priority	Deficiency Priority refers to a deficiency's urgency for repair as determined by the assessment team. Deficiencies were assigned a priority of 1 through 5, with Priority 1 deficiencies being the most urgent.
eCOMET®	Energy and Condition Management Estimation Technology (eCOMET®) is Parsons proprietary facility asset management software developed to provide facility managers with a state of the art, web-based tool to develop and maintain a comprehensive database of FCA data and information used for facility asset management, maintenance and repair, and capital renewal planning. eCOMET® is used by Parsons and its clients as the primary tool for collecting FCA data, preparing cost estimates, generating individual facility reports and cost estimates, and developing the overall capital renewal program.

School Assessment Report - Eldridge L. Miller Elementary

eCOMET® Cost Models	eCOMET® cost models are derived from RS Means Square Foot Cost Data cost models and these models are used to develop the current replacement value (CRV) and assign life cycle costs to the various systems within a building. Cost models are assigned current costs-per-square-foot to establish replacement values. The Cost models are designed to represent a client specific facility that meets local standards cost trends.
Element	Elements are the major components that comprise building systems as defined by UNIFORMAT II.
Expected Life	Also referred to as Useful Life. See Useful Life definition.
Facility	A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose.
Facility Attributes	Customizable eCOMET® fields to identify attributes specific to a facility. These fields are part of the eCOMET® database set-up with the owner.
Facility Condition Assessment (FCA)	A facility condition assessment (FCA) is a visual inspection of buildings and grounds at a facility to identify and estimate current and future needed repairs or replacements of major systems for planning and budgeting purposes. It is typically performed for organizations that are tasked with the day to day maintenance, operation, and capital renewal (replacement) of building systems and components of a large inventory of facilities. The primary goal of an FCA is to objectively and quantifiably identify, inspect, and prioritize the repair and replacement needs of the building and ground systems (e.g., roofs, windows, doors, floor finishes, plumbing fixtures, parking lot, and sidewalks) within facilities that have either failed or have surpassed their service life, and to identify and forecast future capital replacement needs for systems that have not yet failed, but planned replacement of those systems is needed to ensure that the facilities will continue to meet the mission of the organization.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition expressed as a percentage from 0.00% to 100.00% that is derived by dividing the cost to correct a facility's deficiencies by its Current Replacement Value (CRV). The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio, a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.
Forecast Period	The Forecast Period refers to a user defined number of years forward of the Current Period.
Gen (Generate)	The Cost Model has a Gen box for each system line item. By checking the box, eCOMET® will generate life cycle deficiencies based on the Year Installed and the Life for that system. Systems that typically do not re-generate (foundations, floor construction, roof construction, basement walls, etc.) would not have the Gen box checked as those systems would not re-generate at the end of a life cycle. In those instances, it would be more practical and cost effective to demolish the entire facility than renew those systems.
Gross Square Feet (GSF)	The area of the enclosed floor space of a building or building addition in square feet measured to the outside face of the enclosing wall.
Life cycle	Life cycle refers to the period of time that a building or site system or element can be expected to adequately serve its intended function. Parsons assigns expected life cycles to all building systems based on Building Operators and Managers of America (BOMA) recommended life cycles, manufacturers suggested life, and RS Means cost data, and client-provided historical data. BOMA standards are a nationally recognized source of life cycle data for various components and/or systems associated with facilities. RS Means is a national company specializing in construction estimating and costs.
Next Renewal	Next Renewal refers to a manually-adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately reflect current conditions.

School Assessment Report - Eldridge L. Miller Elementary

Order of Magnitude	Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.
Remaining Service Life (RSL)	RSL is the number of years of service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the Calculated Next Renewal date or the Next Renewal date whichever one is the later date.
Renewal Factors	Renewal factors represent the difference in cost of renovating or replacing an existing system, rather than new construction of a building system. For example, installing a new built-up roof on an existing building would include removing and disposing of the old roof, a cost not associated with new construction. Using a renewal premium to account for demolition and other difficulty costs, Parsons typically assigns a renewal factor of 110%.
Renewal Schedule	A timeline by year that indicates when the systems will need to be renewed and the estimated price of the renewal.
Repair Cost	Repair cost is the sum of all the deficiencies associated with a building or multiple buildings/facilities. It will include any applied soft costs or City Cost Indexes.
Replacement Value	See Current Replacement Value.
Site	A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.
Soft Costs	Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user-defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses.
Sustainability	Sustainability refers to the collection of policies and strategies that meet society's present needs without compromising the ability of future generations to meet their own needs.
System	System refers to building and related site work elements as described by ASTM UNIFORMAT II Classification for Building Elements (E1557-97), a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also UNIFORMAT II.
System Generated Deficiency	eCOMET® automatically generates system deficiencies based on system life cycles using the systems installation dates as the base year. By adjusting the Next Renewal date ahead or behind the predicted or stated life cycle date, a system cost will come due earlier or later than the originally installed life cycle date. This utility accounts for good maintenance conditions and a longer life, or early expiration of a system life due to any number of adverse factors such as poor installation, acts of god, material defects, poor design applications and other factors that may shorten the life of a material or system. It is important to mention that the condition of the systems is not necessarily a reflection of maintenance practices, but a combination of system usage and age.
UNIFORMAT	ASTM UNIFORMAT II, Classification for Building Elements (E1557-97), a publication of the Construction Specification Institute (CSI), is a format used to classify major facility components common to most buildings. The format is based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies.
Unit Price	The Unit Price (Raw) x (100% + the Additional Cost Template percentage).
Unit Price (Raw)	The actual \$/sq. ft cost being used for the building and systems. It will include adjustments for the City Cost Index applied to the facility.

School Assessment Report - Eldridge L. Miller Elementary

Useful Life	Also known as Expected Life, Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in the database are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from client- defined historical experience.
Vacant	Vacant refers to a facility that is not occupied but is a maintained facility by a district. See Abandoned.
Year Built	The year that a building or addition was originally built based on its date of substantial completion or occupancy.
Year Installed	The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.