

DeKalb County School District/Leased/Charter

Museum School of Avondale Estates at Forrest Hills

Final School Assessment Report

May 20, 2016



Table of Contents

School Executive Summary	5
School Condition Summary	7
<u>1954 Storage Building</u>	9
Executive Summary	9
Condition Summary	10
Photo Album	11
Condition Detail	12
System Listing	13
Renewal Schedule	14
Forecasted Sustainment Requirement	15
Deficiency Summary By System	16
Deficiency Summary By Priority	17
Deficiency By Priority Investment	18
Deficiency Summary By Category	19
Deficiency Details By Priority	20
<u>1954, 1957, 1970 Building</u>	21
Executive Summary	21
Condition Summary	22
Photo Album	23
Condition Detail	24
System Listing	25
Renewal Schedule	27
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>1998 Addition</u>	41

School Assessment Report

Executive Summary	41
Condition Summary	42
Photo Album	43
Condition Detail	44
System Listing	45
Renewal Schedule	47
Forecasted Sustainment Requirement	50
Deficiency Summary By System	51
Deficiency Summary By Priority	52
Deficiency By Priority Investment	53
Deficiency Summary By Category	54
Deficiency Details By Priority	55
<u>1998 Gym</u>	56
Executive Summary	56
Condition Summary	57
Photo Album	58
Condition Detail	59
System Listing	60
Renewal Schedule	61
Forecasted Sustainment Requirement	63
Deficiency Summary By System	64
Deficiency Summary By Priority	65
Deficiency By Priority Investment	66
Deficiency Summary By Category	67
Deficiency Details By Priority	68
<u>Site</u>	69
Executive Summary	69
Condition Summary	70
Photo Album	71
Condition Detail	72
System Listing	73

School Assessment Report

Renewal Schedule	74
Forecasted Sustainment Requirement	75
Deficiency Summary By System	76
Deficiency Summary By Priority	77
Deficiency By Priority Investment	78
Deficiency Summary By Category	79
Deficiency Details By Priority	80
Glossary	85

School Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	68,530
Year Built:	1954
Last Renovation:	2015
Replacement Value:	\$15,972,860
Repair Cost:	\$3,089,919.79
Total FCI:	19.34 %
Total RSLI:	49.48 %
FCA Score:	80.66



Description:

The Museum School of Avondale Estates at Forrest Hills campus consists of two buildings located at 923 Forrest Blvd in Decatur, Georgia. The original campus was constructed in 1954, additions to the main school building were constructed in 1957, 1970, 1998, and 2013, and a gymnasium building was constructed in 1998. In addition to these buildings, the campus contains a storage building, covered walkway, hard surface play area, and playing field. Major renovations to the main school building have been underway since 2012 and are expected to be complete in 2016. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for each building and site improvement on the campus.

School Assessment Report - Museum School of Avondale Estates at Forrest Hills

Attributes:

General Attributes:

Assigned Region:	Region 2	Board District:	District 3
DOE Facility:	4056	Geographic Region:	Region 2
HS Attendance Area:	Druid Hills HS	Jurisdictional City:	DeKalb County (Unincorporated)
Site Acreage:	10.5		

School Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	56.56 %	0.00 %	\$0.00
A20 - Basement Construction	39.00 %	0.00 %	\$0.00
B10 - Superstructure	56.29 %	0.00 %	\$0.00
B20 - Exterior Enclosure	24.68 %	22.25 %	\$359,989.32
B30 - Roofing	18.23 %	57.07 %	\$659,095.05
C10 - Interior Construction	52.22 %	0.06 %	\$502.09
C20 - Stairs	55.24 %	0.00 %	\$0.00
C30 - Interior Finishes	75.23 %	0.00 %	\$0.00
D10 - Conveying	43.33 %	0.00 %	\$0.00
D20 - Plumbing	46.63 %	21.65 %	\$371,465.87
D30 - HVAC	69.45 %	8.32 %	\$208,108.00
D40 - Fire Protection	43.33 %	0.00 %	\$0.00
D50 - Electrical	47.99 %	24.31 %	\$392,890.00
E10 - Equipment	56.14 %	0.00 %	\$0.00
E20 - Furnishings	71.14 %	0.00 %	\$0.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
G20 - Site Improvements	18.02 %	75.80 %	\$455,254.19
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$500,152.29
G40 - Site Electrical Utilities	40.87 %	55.60 %	\$142,462.98
Totals:	49.48 %	19.34 %	\$3,089,919.79

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 Priority	2 Priority	3 Priority	4 Priority	5 Priority
1954 Storage Building	100	29.99	\$0.00	\$0.00	\$2,415.00	\$0.00	\$0.00
1954, 1957, 1970 Building	41,580	21.70	\$0.00	\$371,358.41	\$1,616,349.87	\$0.00	\$0.00
1998 Addition	21,372	0.04	\$0.00	\$0.00	\$1,927.05	\$0.00	\$0.00
1998 Gym	5,478	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	68,530	83.71	\$0.00	\$0.00	\$1,097,869.46	\$0.00	\$0.00
Total:		19.34	\$0.00	\$371,358.41	\$2,718,561.38	\$0.00	\$0.00

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Charter
Gross Area (SF):	100
Year Built:	1954
Last Renovation:	
Replacement Value:	\$8,053
Repair Cost:	\$2,415.00
Total FCI:	29.99 %
Total RSLI:	9.65 %
FCA Score:	70.01



Description:

The 1954 storage building at Museum School of Avondale Estates at Forrest Hills is located at 923 Forrest Blvd in Decatur, Georgia. There have been no additions and no major renovations. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	Fire Sprinkler System:	No
-----------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	39.00 %	0.00 %	\$0.00
B10 - Superstructure	39.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	0.00 %	12.97 %	\$568.00
B30 - Roofing	0.00 %	110.01 %	\$1,847.00
D20 - Plumbing	0.00 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	0.00 %	\$0.00
Totals:	9.65 %	29.99 %	\$2,415.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). Northeast Elevation - Feb 24, 2011



2). Southeast Elevation - Feb 24, 2011



3). Southwest Elevation - Feb 24, 2011



4). Northwest Elevation - Feb 24, 2011



5). Northwest Elevation - Feb 24, 2011



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1030	Slab on Grade	\$3.60	S.F.	100	100	1954	2054		39.00 %	0.00 %	39	NA		\$360
B1020	Roof Construction	\$16.33	S.F.	100	100	1954	2054		39.00 %	0.00 %	39	NA		\$1,633
B2010	Exterior Walls	\$38.65	S.F.	100	60	1954	2014		0.00 %	0.00 %	-1	NA		\$3,865
B2030	Exterior Doors	\$5.16	S.F.	100	30	1954	1984		0.00 %	110.08 %	-31	NA	\$568.00	\$516
B3010	Roof Coverings	\$16.79	S.F.	100	25	1954	1979		0.00 %	110.01 %	-36	NA	\$1,847.00	\$1,679
D2040	Rain Water Drainage	\$1.55	S.F.	0	30	1954	1984		0.00 %	0.00 %	-31			\$0
D5010	Electrical Service/Distribution	\$3.06	S.F.	0	40	1954	1994		0.00 %	0.00 %	-21			\$0
D5020	Lighting and Branch Wiring	\$12.57	S.F.	0	30	1954	1984		0.00 %	0.00 %	-31			\$0
Total									9.65 %	29.99 %			\$2,415.00	\$8,053

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$2,415	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,415
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$568	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$568
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$1,847	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,847
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting and Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards. .
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$568.00	\$0.00	\$0.00	\$568.00
B3010	Roof Coverings	\$0.00	\$0.00	\$1,847.00	\$0.00	\$0.00	\$1,847.00
	Total:	\$0.00	\$0.00	\$2,415.00	\$0.00	\$0.00	\$2,415.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B2030 - Exterior Doors



Location: Northwest Elevation

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 100.00

Unit of Measure: S.F.

Estimate: \$568.00

Assessor Name: Fernando Wolf

Date Created: 04/11/2015

Notes: The exterior door is beyond its expected service life, rusted, and should be replaced.

System: B3010 - Roof Coverings



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 100.00

Unit of Measure: S.F.

Estimate: \$1,847.00

Assessor Name: Fernando Wolf

Date Created: 07/28/2015

Notes: The built-up roof covering is aged, showing signs of failure, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Charter
Gross Area (SF):	41,580
Year Built:	1954
Last Renovation:	2015
Replacement Value:	\$9,159,794
Repair Cost:	\$1,987,708.28
Total FCI:	21.70 %
Total RSLI:	44.33 %
FCA Score:	78.30



Description:

The main building at Museum School of Avondale Estates at Forrest Hills is a one-story building located at 923 Forrest Blvd in Decatur, Georgia. Originally built in 1954, there have been four additions in 1957, 1970, 1998 and 2013, and major renovations in progress or recently completed (2012-2016). This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2010, 2011, 2012	Fire Sprinkler System:	No
-----------------	------------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	39.00 %	0.00 %	\$0.00
A20 - Basement Construction	39.00 %	0.00 %	\$0.00
B10 - Superstructure	39.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	0.00 %	36.43 %	\$359,421.32
B30 - Roofing	5.75 %	103.67 %	\$655,321.00
C10 - Interior Construction	42.49 %	0.10 %	\$502.09
C20 - Stairs	39.00 %	0.00 %	\$0.00
C30 - Interior Finishes	72.93 %	0.00 %	\$0.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	48.54 %	35.08 %	\$371,465.87
D30 - HVAC	65.48 %	13.17 %	\$208,108.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	29.82 %	37.90 %	\$392,890.00
E10 - Equipment	85.00 %	0.00 %	\$0.00
E20 - Furnishings	100.00 %	0.00 %	\$0.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
Totals:	44.33 %	21.70 %	\$1,987,708.28

Photo Album

The photo album consists of the various cardinal directions of the building.

1). Southeast Elevation - Feb 24, 2011



2). Southwest Elevation - Feb 24, 2011



3). Northwest Elevation - Feb 24, 2011



4). Northeast Elevation - Feb 24, 2011



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1954, 1957, 1970 Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	41,580	100	1954	2054		39.00 %	0.00 %	39	NA		\$269,854
A1030	Slab on Grade	\$7.09	S.F.	41,580	100	1954	2054		39.00 %	0.00 %	39	NA		\$294,802
A2010	Basement Excavation	\$0.22	S.F.	26,100	100	1954	2054		39.00 %	0.00 %	39			\$5,742
A2020	Basement Walls	\$5.55	S.F.	26,100	100	1954	2054		39.00 %	0.00 %	39			\$144,855
B1010	Floor Construction	\$15.61	S.F.	41,580	100	1954	2054		39.00 %	0.00 %	39	NA		\$649,064
B1020	Roof Construction	\$5.34	S.F.	41,580	100	1954	2054		39.00 %	0.00 %	39	NA		\$222,037
B2010	Exterior Walls	\$16.02	S.F.	41,580	60	1954	2014		0.00 %	1.02 %	-1	NA	\$6,781.32	\$666,112
B2020	Exterior Windows	\$6.79	S.F.	41,580	30	1954	1984		0.00 %	110.00 %	-31	NA	\$310,561.00	\$282,328
B2030	Exterior Doors	\$0.92	S.F.	41,580	30	1954	1984		0.00 %	110.00 %	-31	NA	\$42,079.00	\$38,254
B3010	Roof Coverings - BUR	\$20.70	S.F.	28,780	25	1954	1979		0.00 %	110.00 %	-36		\$655,321.00	\$595,746
B3010	Roof Coverings - EPDM	\$2.84	S.F.	12,800	15	2015	2030		100.00 %	0.00 %	15			\$36,352
C1010	Partitions	\$7.01	S.F.	41,580	40	1954	1994		0.00 %	0.00 %	-21	NA		\$291,476
C1020	Interior Doors	\$2.39	S.F.	41,580	30	2015	2045		100.00 %	0.51 %	30	NA	\$502.09	\$99,376
C1030	Fittings	\$2.79	S.F.	41,580	20	2015	2035		100.00 %	0.00 %	20	NA		\$116,008
C2010	Stair Construction	\$1.59	S.F.	41,580	100	1954	2054		39.00 %	0.00 %	39			\$66,112
C3010	Wall Finishes - Ceramic Tile	\$10.27	S.F.	20,790	30	2015	2045		100.00 %	0.00 %	30	NA		\$213,513
C3010	Wall Finishes - Paint	\$1.93	S.F.	20,790	10	2015	2025		100.00 %	0.00 %	10	NA		\$40,125
C3010	Wall Finishes - Wall Coverings	\$2.13	S.F.	0	10	2015	2025		100.00 %	0.00 %	10	NA		\$0
C3020	Floor Finishes - Carpet	\$8.50	S.F.	3,326	8	2015	2023		100.00 %	0.00 %	8	NA		\$28,271
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	6,237	50	2015	2065		100.00 %	0.00 %	50	NA		\$90,374
C3020	Floor Finishes - Rubber	\$23.34	S.F.	832	10	2015	2025		100.00 %	0.00 %	10	NA		\$19,419
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	8,316	50	1954	2004	2020	10.00 %	0.00 %	5	NA		\$440,831
C3020	Floor Finishes - VCT	\$9.54	S.F.	22,869	20	2015	2035		100.00 %	0.00 %	20	NA		\$218,170
C3030	Ceiling Finishes	\$9.98	S.F.	41,580	20	2015	2035		100.00 %	0.00 %	20	NA		\$414,968
D1010	Elevators and Lifts	\$1.17	S.F.	0	30	1954	1984		0.00 %	0.00 %	-31			\$0
D2010	Plumbing Fixtures	\$17.66	S.F.	41,580	30	2006	2036		70.00 %	1.94 %	21		\$14,250.87	\$734,303
D2020	Domestic Water Distribution	\$3.99	S.F.	41,580	30	1954	1984		0.00 %	110.00 %	-31		\$182,495.00	\$165,904
D2030	Sanitary Waste	\$3.41	S.F.	41,580	30	1954	1984		0.00 %	110.00 %	-31		\$155,967.00	\$141,788
D2040	Rain Water Drainage	\$0.98	S.F.	0	30	1954	1984		0.00 %	0.00 %	-31			\$0
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	41,580	40	1954	1994		0.00 %	110.00 %	-21		\$18,753.00	\$17,048
D3020	Heat Generating Systems	\$4.55	S.F.	41,580	30	1975	2005		0.00 %	110.00 %	-10		\$208,108.00	\$189,189
D3030	Cooling Generating Systems	\$4.73	S.F.	41,580	25	1998	2023		32.00 %	0.00 %	8			\$196,673
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	41,580	30	2012	2042		90.00 %	0.00 %	27			\$229,106
D3050	Terminal & Package Units	\$18.52	S.F.	41,580	15	2012	2027		80.00 %	0.00 %	12			\$770,062

School Assessment Report - 1954, 1957, 1970 Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D3060	Controls & Instrumentation	\$3.60	S.F.	41,580	20	2015	2035		100.00 %	0.00 %	20			\$149,688
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.10	S.F.	41,580	30	1954	1984		0.00 %	0.00 %	-31			\$45,738
D4010	Sprinklers	\$4.75	S.F.	0	30	1954	1984		0.00 %	0.00 %	-31			\$0
D4020	Standpipes	\$0.51	S.F.	0	30	1954	1984		0.00 %	0.00 %	-31			\$0
D5010	Electrical Service/Distribution	\$1.81	S.F.	41,580	40	1954	1994		0.00 %	110.00 %	-21		\$82,786.00	\$75,260
D5020	Branch Wiring	\$6.78	S.F.	41,580	30	1954	1984		0.00 %	110.00 %	-31		\$310,104.00	\$281,912
D5020	Lighting	\$8.90	S.F.	41,580	30	1990	2020		16.67 %	0.00 %	5			\$370,062
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	41,580	15	2012	2027		80.00 %	0.00 %	12			\$232,848
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	41,580	15	2012	2027		80.00 %	0.00 %	12			\$51,143
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	41,580	15	2012	2027		80.00 %	0.00 %	12			\$25,364
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	0	15	1954	1969		0.00 %	0.00 %	-46			\$0
E1010	Commercial Equipment	\$7.92	S.F.	0	20	1954	1974		0.00 %	0.00 %	-41			\$0
E1020	Institutional Equipment	\$0.40	S.F.	41,580	20	2012	2032		85.00 %	0.00 %	17			\$16,632
E1090	Other Equipment	\$10.98	S.F.	0	20	1954	1974		0.00 %	0.00 %	-41			\$0
E2010	Fixed Furnishings	\$5.37	S.F.	41,580	20	2015	2035		100.00 %	0.00 %	20	NA		\$223,285
F1010	Special Structures - Canopies	\$1.61	S.F.	0	25	1954	1979		0.00 %	0.00 %	-36			\$0
Total									44.33 %	21.70 %			\$1,987,708.28	\$9,159,794

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,987,708	\$0	\$0	\$0	\$0	\$1,034,052	\$0	\$0	\$313,448	\$0	\$88,024	\$3,423,232
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$6,781	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,781
B2020 - Exterior Windows	\$310,561	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$310,561
B2030 - Exterior Doors	\$42,079	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$42,079
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$655,321	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$655,321
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$502	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$502
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1954, 1957, 1970 Building

C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$59,316	\$59,316
C3010 - Wall Finishes - Wall Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,394	\$0	\$0	\$39,394
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Rubber	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,707	\$28,707
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$562,148	\$0	\$0	\$0	\$0	\$0	\$562,148
C3020 - Floor Finishes - VCT	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$14,251	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,251
D2020 - Domestic Water Distribution	\$182,495	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$182,495
D2030 - Sanitary Waste	\$155,967	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$155,967
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$18,753	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,753
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$208,108	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$208,108
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$274,054	\$0	\$0	\$274,054
D3040 - Distribution & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$82,786	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$82,786
D5020 - Branch Wiring	\$310,104	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$310,104


School Assessment Report - 1954, 1957, 1970 Building

D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$471,903	\$0	\$0	\$0	\$0	\$0	\$471,903
D5030 - Communications and Security - Clock & PA Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$1,987,708.28

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards. .
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2010	Exterior Walls	\$0.00	\$6,781.32	\$0.00	\$0.00	\$0.00	\$6,781.32
B2020	Exterior Windows	\$0.00	\$0.00	\$310,561.00	\$0.00	\$0.00	\$310,561.00
B2030	Exterior Doors	\$0.00	\$0.00	\$42,079.00	\$0.00	\$0.00	\$42,079.00
B3010	Roof Coverings - BUR	\$0.00	\$0.00	\$655,321.00	\$0.00	\$0.00	\$655,321.00
C1020	Interior Doors	\$0.00	\$502.09	\$0.00	\$0.00	\$0.00	\$502.09
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$14,250.87	\$0.00	\$0.00	\$14,250.87
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$182,495.00	\$0.00	\$0.00	\$182,495.00
D2030	Sanitary Waste	\$0.00	\$155,967.00	\$0.00	\$0.00	\$0.00	\$155,967.00
D2090	Other Plumbing Systems - Natural Gas	\$0.00	\$0.00	\$18,753.00	\$0.00	\$0.00	\$18,753.00
D3020	Heat Generating Systems	\$0.00	\$208,108.00	\$0.00	\$0.00	\$0.00	\$208,108.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$82,786.00	\$0.00	\$0.00	\$82,786.00
D5020	Branch Wiring	\$0.00	\$0.00	\$310,104.00	\$0.00	\$0.00	\$310,104.00
Total:		\$0.00	\$371,358.41	\$1,616,349.87	\$0.00	\$0.00	\$1,987,708.28

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,987,708.28

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 Priority:

System: B2010 - Exterior Walls



Location: Southwest Elevation

Distress: Damaged

Category: Deferred Maintenance

Priority: 2 Priority

Correction: Repair 8" concrete block wall, 1st floor

Qty: 150.00

Unit of Measure: S.F.

Estimate: \$6,781.32

Assessor Name: Sam Mandola

Date Created: 08/26/2015

Notes: The concrete wall near the southwest elevation is damaged and should be repaired.

System: C1020 - Interior Doors



Location: Electrical Room

Distress: Needs Remediation

Category: Building Code Compliance

Priority: 2 Priority

Correction: Repair door swing as per building code

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$502.09

Assessor Name: Sam Mandola

Date Created: 08/26/2015

Notes: The door of the electrical room does not swing in the direction of the exit with fire exit hardware and should be corrected.

System: D2030 - Sanitary Waste



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 2 Priority

Correction: Renew System

Qty: 41,580.00

Unit of Measure: S.F.

Estimate: \$155,967.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The sanitary waste piping is aged, showing signs of failure, and should be replaced. Piping has reportedly been repaired since the assessment, but the system is in need of replacement.

System: D3020 - Heat Generating Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 2 Priority

Correction: Renew System

Qty: 41,580.00

Unit of Measure: S.F.

Estimate: \$208,108.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The heating system, including distribution pump, piping and water source heat pumps, are aged and should be replaced. The water source heat pumps that were not operational during the 2015 assessment have since been replaced. The overall system, however, is still beyond its expected service life.

Priority 3 Priority:

System: B2020 - Exterior Windows



Location: All Exterior Walls

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 41,580.00

Unit of Measure: S.F.

Estimate: \$310,561.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The aluminum frame, operable, single pane windows are aged, rusted, not energy efficient, and should be replaced. Renovation scheduled to be completed by 2016.

System: B2030 - Exterior Doors



Location: North, East and South Elevations

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 41,580.00

Unit of Measure: S.F.

Estimate: \$42,079.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The original exterior doors are aged, rusted, and scheduled for renovation 2015 - 2016.

School Assessment Report - 1954, 1957, 1970 Building

System: B3010 - Roof Coverings - BUR



Location: Roof

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 28,780.00

Unit of Measure: S.F.

Estimate: \$655,321.00

Assessor Name: Sam Mandola

Date Created: 08/25/2015

Notes: Built-up roof covering is in deteriorating condition with cracks, patches, and reported water leaks, and should be scheduled for replacement.

System: D2010 - Plumbing Fixtures



Location: Throughout Building

Distress: Needs Remediation

Category: Accessibility Code Compliance

Priority: 3 Priority

Correction: Remove/replace drinking fountain w/recessed ADA compliant drinking fountain

Qty: 5.00

Unit of Measure: Ea.

Estimate: \$14,250.87

Assessor Name: Sam Mandola

Date Created: 08/25/2015

Notes: Water fountains protrude into the hallway more than four inches. Protrusions are not ADA compliant if more than four inches.

System: D2020 - Domestic Water Distribution



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 41,580.00

Unit of Measure: S.F.

Estimate: \$182,495.00

Assessor Name: Sam Mandola

Date Created: 05/04/2015

Notes: The domestic water distribution system is beyond its expected service life and should be scheduled for replacement.

System: D2090 - Other Plumbing Systems - Natural Gas



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 41,580.00

Unit of Measure: S.F.

Estimate: \$18,753.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The natural gas system and associated piping are aged and should be replaced.

System: D5010 - Electrical Service/Distribution



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 41,580.00
Unit of Measure: S.F.
Estimate: \$82,786.00
Assessor Name: Sam Mandola
Date Created: 04/11/2015

Notes: The original electrical distribution system is aged, in marginal condition, and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 41,580.00
Unit of Measure: S.F.
Estimate: \$310,104.00
Assessor Name: Sam Mandola
Date Created: 04/11/2015

Notes: The branch wiring is aged and should be replaced. Ensure GFI outlets are installed in wet areas.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Charter
Gross Area (SF):	21,372
Year Built:	1998
Last Renovation:	2013
Replacement Value:	\$4,579,243
Repair Cost:	\$1,927.05
Total FCI:	0.04 %
Total RSLI:	67.14 %
FCA Score:	99.96



Description:

The 1998 classroom addition at the Museum School of Avondale Estates at Forrest Hills is a two-story building located at 923 Forrest Blvd in Decatur, Georgia. There has been one bridge addition in 2013 and major renovations in progress or recently completed (2012-2016). This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2013	Fire Sprinkler System:	Yes
-----------------	------	------------------------	-----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	62.46 %	0.00 %	\$0.00
B30 - Roofing	32.00 %	0.42 %	\$1,927.05
C10 - Interior Construction	71.96 %	0.00 %	\$0.00
C20 - Stairs	83.00 %	0.00 %	\$0.00
C30 - Interior Finishes	86.29 %	0.00 %	\$0.00
D10 - Conveying	43.33 %	0.00 %	\$0.00
D20 - Plumbing	43.55 %	0.00 %	\$0.00
D30 - HVAC	78.91 %	0.00 %	\$0.00
D40 - Fire Protection	43.33 %	0.00 %	\$0.00
D50 - Electrical	86.78 %	0.00 %	\$0.00
E10 - Equipment	0.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
Totals:	67.14 %	0.04 %	\$1,927.05

Photo Album

The photo album consists of the various cardinal directions of the building.

1). Northeast Elevation - May 11, 2015



2). Southeast Elevation - May 11, 2015



3). Northwest Elevation - May 11, 2015



4). Southeast Elevation - Aug 22, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1998 Addition

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	21,372	100	1998	2098		83.00 %	0.00 %	83	NA		\$138,704
A1030	Slab on Grade	\$7.09	S.F.	21,372	100	1998	2098		83.00 %	0.00 %	83	NA		\$151,527
B1010	Floor Construction	\$15.61	S.F.	21,372	100	1998	2098		83.00 %	0.00 %	83	NA		\$333,617
B1020	Roof Construction	\$5.34	S.F.	21,372	100	1998	2098		83.00 %	0.00 %	83	NA		\$114,126
B2010	Exterior Walls	\$16.02	S.F.	21,372	60	1998	2058		71.67 %	0.00 %	43	NA		\$342,379
B2020	Exterior Windows	\$6.79	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13	NA		\$145,116
B2030	Exterior Doors	\$0.92	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13	NA		\$19,662
B3010	Roof Coverings - BUR	\$20.70	S.F.	21,372	25	1998	2023		32.00 %	0.00 %	8			\$442,400
B3020	Roof Openings	\$0.63	S.F.	21,372	25	1998	2023		32.00 %	14.31 %	8	NA	\$1,927.05	\$13,464
C1010	Partitions	\$7.01	S.F.	21,372	40	1998	2038		57.50 %	0.00 %	23	NA		\$149,818
C1020	Interior Doors	\$2.39	S.F.	21,372	30	2013	2043		93.33 %	0.00 %	28	NA		\$51,079
C1030	Fittings	\$2.79	S.F.	21,372	20	2013	2033		90.00 %	0.00 %	18	NA		\$59,628
C2010	Stair Construction	\$1.81	S.F.	21,372	100	1998	2098		83.00 %	0.00 %	83	NA		\$38,683
C3010	Wall Finishes - Paint & Covering	\$1.77	S.F.	21,372	10	2013	2023		80.00 %	0.00 %	8			\$37,828
C3020	Floor Finishes - Carpet	\$8.50	S.F.	2,137	8	2013	2021		75.00 %	0.00 %	6	NA		\$18,165
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	855	50	1998	2048		66.00 %	0.00 %	33	NA		\$12,389
C3020	Floor Finishes - Rubber	\$23.34	S.F.	1,068	10	2013	2023		80.00 %	0.00 %	8	NA		\$24,927
C3020	Floor Finishes - VCT	\$9.54	S.F.	17,312	15	2013	2028		86.67 %	0.00 %	13	NA		\$165,156
C3030	Ceiling Finishes	\$9.98	S.F.	21,372	20	2013	2033		90.00 %	0.00 %	18	NA		\$213,293
D1010	Elevators and Lifts	\$1.17	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$25,005
D2010	Plumbing Fixtures	\$17.66	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$377,430
D2020	Domestic Water Distribution	\$3.99	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$85,274
D2030	Sanitary Waste	\$3.41	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$72,879
D2040	Rain Water Drainage	\$0.98	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$20,945
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	21,372	40	1998	2038		57.50 %	0.00 %	23			\$8,763
D3020	Heat Generating Systems	\$4.55	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D3030	Cooling Generating Systems	\$4.73	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	21,372	30	2012	2042		90.00 %	0.00 %	27			\$117,760
D3050	Terminal & Package Units	\$27.72	S.F.	21,372	20	2012	2032		85.00 %	0.00 %	17			\$592,432
D3060	Controls & Instrumentation	\$3.60	S.F.	21,372	20	1998	2018		15.00 %	0.00 %	3			\$76,939
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D4010	Sprinklers	\$4.75	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$101,517
D4020	Standpipes	\$0.51	S.F.	21,372	30	1998	2028		43.33 %	0.00 %	13			\$10,900
D5010	Electrical Service/Distribution	\$1.81	S.F.	0	40	1998	2038		57.50 %	0.00 %	23			\$0

School Assessment Report - 1998 Addition

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D5020	Branch Wiring	\$6.78	S.F.	21,372	30	2012	2042		90.00 %	0.00 %	27			\$144,902
D5020	Lighting	\$8.90	S.F.	21,372	30	2012	2042		90.00 %	0.00 %	27			\$190,211
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	21,372	15	2012	2027		80.00 %	0.00 %	12			\$119,683
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	21,372	15	2012	2027		80.00 %	0.00 %	12			\$26,288
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	21,372	15	2012	2027		80.00 %	0.00 %	12			\$13,037
D5090	Other Electrical Systems - Emergency Generator	\$0.35	S.F.	0	15	1998	2013		0.00 %	0.00 %	-2			\$0
E1010	Commercial Equipment	\$7.92	S.F.	0	20	1998	2018		15.00 %	0.00 %	3			\$0
E1020	Institutional Equipment	\$0.40	S.F.	21,372	20				0.00 %	0.00 %				\$8,549
E1090	Other Equipment	\$0.88	S.F.	0	20	1998	2018		15.00 %	0.00 %	3			\$0
E2010	Fixed Furnishings	\$5.37	S.F.	21,372	20	1998	2018		15.00 %	0.00 %	3			\$114,768
F1010	Special Structures - Canopies	\$1.61	S.F.	0	25	1998	2023		32.00 %	0.00 %	8			\$0
Total									67.14 %	0.04 %			\$1,927.05	\$4,579,243

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,927	\$0	\$0	\$230,431	\$0	\$0	\$23,858	\$0	\$722,670	\$0	\$0	\$978,886
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$616,461	\$0	\$0	\$616,461
B3020 - Roof Openings	\$1,927	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,762	\$0	\$0	\$20,689
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint & Covering	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$52,712	\$0	\$0	\$52,712
C3020 - Floor Finishes - Carpet	\$0	\$0	\$0	\$0	\$0	\$0	\$23,858	\$0	\$0	\$0	\$0	\$23,858

School Assessment Report - 1998 Addition

C3020 - Floor Finishes - Ceramic & Quarry Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Rubber	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,735	\$0	\$0	\$34,735
C3020 - Floor Finishes - VCT	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$92,481	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$92,481
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Clock & PA Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1998 Addition

E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$137,950	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$137,950
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.




Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B3020	Roof Openings	\$0.00	\$0.00	\$1,927.05	\$0.00	\$0.00	\$1,927.05
	Total:	\$0.00	\$0.00	\$1,927.05	\$0.00	\$0.00	\$1,927.05

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: B3020 - Roof Openings



Location: Roof

Distress: Inadequate

Category: Building Code Compliance

Priority: 3 Priority

Correction: Replace roof hatch and structure single unit

Qty: 1.00

Unit of Measure: Ea.

Estimate: \$1,927.05

Assessor Name: Ben Nixon

Date Created: 07/28/2015

Notes: Roof hatch is unsafe and does not comply with building codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Charter
Gross Area (SF):	5,478
Year Built:	1998
Last Renovation:	2012
Replacement Value:	\$914,268
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	60.61 %
FCA Score:	100.00



Description:

The 1998 gymnasium building at the Museum School of Avondale Estates at Forrest Hills is a one-story building located at 923 Forrest Blvd in Decatur, Georgia. There have been no additions or major renovations. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2020	Fire Sprinkler System:	No
-----------------	------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	69.06 %	0.00 %	\$0.00
B30 - Roofing	43.33 %	0.00 %	\$0.00
C10 - Interior Construction	50.32 %	0.00 %	\$0.00
C30 - Interior Finishes	57.79 %	0.00 %	\$0.00
D20 - Plumbing	43.60 %	0.00 %	\$0.00
D30 - HVAC	60.71 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	44.09 %	0.00 %	\$0.00
Totals:	60.61 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). Southeast Elevation - Jun 03, 2015



2). Northeast Elevation - Jun 03, 2015



3). Northwest Elevation - Jun 03, 2015



4). Southwest Elevation - Jun 03, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$9.34	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83	NA		\$51,165
A1030	Slab on Grade	\$6.21	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83	NA		\$34,018
B1020	Roof Construction	\$21.36	S.F.	5,478	100	1998	2098		83.00 %	0.00 %	83	NA		\$117,010
B2010	Exterior Walls	\$19.80	S.F.	5,478	60	1998	2058		71.67 %	0.00 %	43	NA		\$108,464
B2030	Exterior Doors	\$2.01	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13	NA		\$11,011
B3010	Roof Coverings - Standing Seam Metal	\$11.91	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13	NA		\$65,243
C1010	Partitions	\$12.78	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23	NA		\$70,009
C1020	Interior Doors	\$4.24	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23	NA		\$23,227
C1030	Fittings	\$3.46	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3	NA		\$18,954
C3010	Wall Finishes - Paint	\$1.41	S.F.	5,478	10	2012	2022		70.00 %	0.00 %	7	NA		\$7,724
C3020	Floor Finishes - Ceramic Tile	\$6.67	S.F.	274	50	1998	2048		66.00 %	0.00 %	33	NA		\$1,828
C3020	Floor Finishes - Neoprene	\$14.46	S.F.	4,930	10	2012	2022		70.00 %	0.00 %	7	NA		\$71,288
C3020	Floor Finishes - VCT	\$5.01	S.F.	274	15	2012	2027		80.00 %	0.00 %	12	NA		\$1,373
C3030	Ceiling Finishes	\$4.31	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3	NA		\$23,610
D2010	Plumbing Fixtures	\$9.66	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$52,917
D2020	Domestic Water Distribution	\$5.85	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$32,046
D2030	Sanitary Waste	\$0.87	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$4,766
D2040	Rain Water Drainage	\$0.22	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D2090	Other Plumbing Systems - Natural Gas	\$0.32	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23			\$1,753
D3040	Distribution Systems & Exhaust Systems	\$12.25	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$67,106
D3050	Terminal & Package Units	\$11.65	S.F.	5,478	15	2012	2027		80.00 %	0.00 %	12			\$63,819
D3060	Controls & Instrumentation	\$0.26	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3			\$1,424
D4010	Sprinklers	\$3.84	S.F.	0	30	1998	2028		43.33 %	0.00 %	13			\$0
D5010	Electrical Service/Distribution	\$1.24	S.F.	5,478	40	1998	2038		57.50 %	0.00 %	23			\$6,793
D5020	Branch Wiring	\$5.24	S.F.	5,478	30	1998	2028		43.33 %	0.00 %	13			\$28,705
D5020	Lighting	\$5.24	S.F.	5,478	20	1998	2018		15.00 %	0.00 %	3			\$28,705
D5030	Communications and Security - Fire Alarm	\$2.13	S.F.	5,478	15	2012	2027		80.00 %	0.00 %	12			\$11,668
D5030	Communications and Security - Public Address & Clock System	\$0.88	S.F.	5,478	15	2012	2027		80.00 %	0.00 %	12			\$4,821
D5030	Communications and Security - Security & CCTV	\$0.88	S.F.	5,478	15	2012	2027		80.00 %	0.00 %	12			\$4,821
Total									60.61 %					\$914,268

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$0	\$0	\$0	\$87,377	\$0	\$0	\$0	\$106,892	\$0	\$0	\$0	\$194,269
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$22,782	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,782
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$10,449	\$0	\$0	\$0	\$10,449
C3020 - Floor Finishes - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Neoprene	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$96,443	\$0	\$0	\$0	\$96,443
C3020 - Floor Finishes - VCT	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$28,379	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,379
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1998 Gym

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$1,712	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,712
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$34,503	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,503
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Public Address & Clock System	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Charter
Gross Area (SF):	68,530
Year Built:	1954
Last Renovation:	
Replacement Value:	\$1,311,502
Repair Cost:	\$1,097,869.46
Total FCI:	83.71 %
Total RSLI:	16.24 %
FCA Score:	16.29



Description:

The Museum School of Avondale Estates at Forrest Hills site was originally constructed in 1954, has a total area of 10.5 acres, and is occupied by approximately 69,630 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, covered walkways, flag pole, landscaping, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site features.

Attributes:

General Attributes:

Site Code:	1928
------------	------

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	18.02 %	75.80 %	\$455,254.19
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$500,152.29
G40 - Site Electrical Utilities	40.87 %	55.60 %	\$142,462.98
Totals:	16.24 %	83.71 %	\$1,097,869.46

Photo Album

The photo album consists of the various cardinal directions of the building.

- 1). Aerial Image of Museum School of Avondale Estates at Forrest Hills - Jul 09, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$5.17	S.F.	14,898	25	1954	1979		0.00 %	110.00 %	-36	NA	\$84,724.93	\$77,023
G2020	Parking Lots	\$4.56	S.F.	8,070	30	1954	1984		0.00 %	110.00 %	-31		\$40,479.12	\$36,799
G2030	Pedestrian Paving	\$1.50	S.F.	69,630	30	1954	1984		0.00 %	110.00 %	-31	NA	\$114,889.50	\$104,445
G2040	Covered Walkways	\$48.72	S.F.	1,760	25	1998	2023		32.00 %	0.00 %	8	NA		\$85,747
G2040	Fencing & Guardrails	\$0.91	S.F.	69,630	30	1954	1984		0.00 %	110.00 %	-31	NA	\$69,699.63	\$63,363
G2040	Hard Surface Play Area	\$6.26	S.F.		0				0.00 %	0.00 %		NA		\$0
G2040	Playing Field	\$3.92	S.F.	33,734	20	1954	1974		0.00 %	110.00 %	-41	NA	\$145,461.01	\$132,237
G2050	Landscaping	\$1.45	S.F.	69,630	15	2012	2027		80.00 %	0.00 %	12	NA		\$100,964
G3010	Water Supply	\$1.83	S.F.	69,630	50	1954	2004		0.00 %	110.00 %	-11		\$140,165.19	\$127,423
G3020	Sanitary Sewer	\$1.15	S.F.	69,630	50	1954	2004		0.00 %	110.00 %	-11		\$88,081.95	\$80,075
G3030	Storm Sewer	\$3.55	S.F.	69,630	50	1954	2004		0.00 %	110.00 %	-11		\$271,905.15	\$247,187
G3060	Fuel Distribution	\$0.78	S.F.	0	40	1954	1994		0.00 %	0.00 %	-21			\$0
G4010	Electrical Distribution	\$1.86	S.F.	69,630	50	1954	2004		0.00 %	110.00 %	-11		\$142,462.98	\$129,512
G4020	Site Lighting	\$1.15	S.F.	69,630	30	2012	2042		90.00 %	0.00 %	27			\$80,075
G4030	Site Communications & Security	\$0.67	S.F.	69,630	10	2012	2022		70.00 %	0.00 %	7			\$46,652
Total									16.24 %	83.71 %			\$1,097,869.46	\$1,311,502

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,097,869	\$0	\$0	\$0	\$0	\$0	\$0	\$63,113	\$119,484	\$0	\$0	\$1,280,467
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$84,725	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$84,725
G2020 - Parking Lots	\$40,479	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$40,479
G2030 - Pedestrian Paving	\$114,890	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$114,890
G2040 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$119,484	\$0	\$0	\$119,484
G2040 - Fencing & Guardrails	\$69,700	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,700
G2040 - Hard Surface Play Area	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Playing Field	\$145,461	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$145,461
G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$140,165	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$140,165
G3020 - Sanitary Sewer	\$88,082	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$88,082
G3030 - Storm Sewer	\$271,905	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$271,905
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$142,463	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$142,463
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$63,113	\$0	\$0	\$0	\$63,113

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$1,097,869.46

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
G2010	Roadways	\$0.00	\$0.00	\$84,724.93	\$0.00	\$0.00	\$84,724.93
G2020	Parking Lots	\$0.00	\$0.00	\$40,479.12	\$0.00	\$0.00	\$40,479.12
G2030	Pedestrian Paving	\$0.00	\$0.00	\$114,889.50	\$0.00	\$0.00	\$114,889.50
G2040	Fencing & Guardrails	\$0.00	\$0.00	\$69,699.63	\$0.00	\$0.00	\$69,699.63
G2040	Playing Field	\$0.00	\$0.00	\$145,461.01	\$0.00	\$0.00	\$145,461.01
G3010	Water Supply	\$0.00	\$0.00	\$140,165.19	\$0.00	\$0.00	\$140,165.19
G3020	Sanitary Sewer	\$0.00	\$0.00	\$88,081.95	\$0.00	\$0.00	\$88,081.95
G3030	Storm Sewer	\$0.00	\$0.00	\$271,905.15	\$0.00	\$0.00	\$271,905.15
G4010	Electrical Distribution	\$0.00	\$0.00	\$142,462.98	\$0.00	\$0.00	\$142,462.98
	Total:	\$0.00	\$0.00	\$1,097,869.46	\$0.00	\$0.00	\$1,097,869.46

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,097,869.46

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: G2010 - Roadways



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 14,898.00

Unit of Measure: S.F.

Estimate: \$84,724.93

Assessor Name: Eduardo Lopez

Date Created: 05/13/2015

Notes: The asphalt roadways are beyond their expected service life, deteriorating, and should be scheduled for replacement.

System: G2020 - Parking Lots



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 8,070.00

Unit of Measure: S.F.

Estimate: \$40,479.12

Assessor Name: Eduardo Lopez

Date Created: 05/27/2015

Notes: The parking lot is beyond its expected service life, deteriorating, not ADA compliant, and should be scheduled for replacement.

System: G2030 - Pedestrian Paving



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 69,630.00

Unit of Measure: S.F.

Estimate: \$114,889.50

Assessor Name: Eduardo Lopez

Date Created: 05/27/2015

Notes: Pedestrian paving is badly damaged with cracks, not ADA compliant, and should be scheduled for replacement. Renovation is scheduled for 2016.

System: G2040 - Fencing & Guardrails



Location: Site

Distress: Damaged

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,630.00

Unit of Measure: S.F.

Estimate: \$69,699.63

Assessor Name: Eduardo Lopez

Date Created: 05/11/2015

Notes: Fencing and guardrails are beyond their expected service life, deteriorating, and should be scheduled for replacement. Renovation is scheduled for 2016.

School Assessment Report - Site

System: G2040 - Playing Field



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 33,734.00

Unit of Measure: S.F.

Estimate: \$145,461.01

Assessor Name: Eduardo Lopez

Date Created: 07/28/2015

Notes: The playing field is damaged in areas and should be re-sodded.

System: G3010 - Water Supply



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,630.00

Unit of Measure: S.F.

Estimate: \$140,165.19

Assessor Name: Eduardo Lopez

Date Created: 06/03/2015

Notes: The water supply system is beyond its expected service life and should be scheduled for replacement.

System: G3020 - Sanitary Sewer



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,630.00

Unit of Measure: S.F.

Estimate: \$88,081.95

Assessor Name: Eduardo Lopez

Date Created: 06/03/2015

Notes: The sanitary sewer system is beyond its expected service life and should be scheduled for replacement.

System: G3030 - Storm Sewer



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,630.00

Unit of Measure: S.F.

Estimate: \$271,905.15

Assessor Name: Eduardo Lopez

Date Created: 06/03/2015

Notes: The storm sewer system is beyond its expected service life and should be scheduled for replacement.

System: G4010 - Electrical Distribution



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 69,630.00

Unit of Measure: S.F.

Estimate: \$142,462.98

Assessor Name: Eduardo Lopez

Date Created: 06/03/2015

Notes: The electrical service and distribution is beyond its expected service life and should be scheduled for replacement.

Glossary

Abandoned	A facility owned by a district that is not occupied and not maintained. See Vacant.
Additional Cost	Total project cost is composed of hard and soft costs. Additional costs or soft expenses are costs that are necessary to accomplish the corrective work but are not directly attributable to the deficient systems direct construction cost, which are often referred to as hard cost. The components included in the soft costs vary by owner but usually include architect and contractor fees, contingencies and other owner-incurred costs necessary to fully develop and build a facility. These soft cost factors can be adjusted anytime within the eCOMET® database at the owner's discretion.
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems, reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ASTM	ASTM International (ASTM): Originally known as the American Society for Testing and Materials, ASTM is an international standards organization that develops and publishes voluntary consensus technical standards for a wide range of materials, products, systems, and services.
BOMA	Building Owners Managers of America (BOMA): National organization of public and private facility owners focused on building management tools and maintenance techniques. eCOMET® reference: Building and component system effective economic life expectancies.
Building	A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior.
Building Addition	An area, space or component of a building added to a building after the original building's year built date. NOTE: As a convention in the database, "Main" was used to designate the original building. Additions built prior to 1983 (30 years) were included in the main building area calculations to reflect their predicted system depreciation characteristics and remaining service life.
Building Systems	eCOMET® uses UNIFORMAT II to organize building data. UNIFORMAT II was originally developed by the federal General Services Administration to delineate building costs by systems rather than by material. UNIFORMAT II was formalized by an NIST standard, NISTIR 6389 in 1999. It has been further quantified and updated by ASTM standard 2005, E1557-05. The Construction Specifications Institute, CSI, has taken over the standard as part of their MasterFormat / MasterSpec system.
Calculated Next Renewal	The year a system or building element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal refers to the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life. It is not normally included in an annual operating/maintenance budget. See calculated next renewal and next renewal.
City Cost Index (CCI)	RS Means provides building system, equipment, and construction costs at a national level. The City Cost Index (also provided by RS Means) localizes those costs to a geographic region of the United States. In eCOMET®, each building or site is assigned a City Cost Index, which adjusts all of the associated costs for systems, deficiencies and inventory to the local value.
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
Condition Budget	The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work.

School Assessment Report - Museum School of Avondale Estates at Forrest Hills

Condition Index (CI) %	The Condition Index (CI) also known as the Remaining Service Life Index (RSLI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude soft cost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).
Construction Specifications Institute	Construction Specifications Institute: Primary national organization specializing in construction materials data and data location in construction documents. eCOMET® reference: UNIFORMAT II materials classification.
Correction	Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a UNIFORMAT II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction.
Cost Model	A cost model is a list of facility systems which could represent the installed systems a given facility. Included in the cost model are standard unit cost estimates, gross areas, life cycles and installed dates. Also represented is the repair cost for deficient systems, replacement values. See eCOMET® cost models.
Criteria	Criteria refer to the set of requirements, guidelines or standards that are assessed and rated to develop a score.
Current Period	The Current Period is the current year plus a user defined number of forward years.
Current Replacement Value (CRV)	The Current Replacement Value (CRV) of a facility, building or system represents the hypothetical cost of rebuilding or replacing an existing facility under today's codes and construction standards, using its current configuration. It is calculated by multiplying the gross area of the facility by a square foot cost developed in that facility's cost model. Replacement cost includes construction costs and owner's additional or soft costs for fees, permits and other expenses to reflect a total project cost.
Deferred Maintenance	Deferred maintenance is condition work deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose.
Deficiency Category	Deficiency Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions include, but are not limited to: Accessibility Code Compliance, Appearance, Building Code Compliance, Deferred Maintenance, Energy, Environmental, Life Safety Code Compliance, and Safety.
Deficiency Distress	Deficiency Distress refers to a user-defined root cause of a deficiency. Distress descriptions are: Beyond Service Life, Damaged, Inadequate, Needs Remediation, and Missing.
Deficiency Priority	Deficiency Priority refers to a deficiency's urgency for repair as determined by the assessment team. Deficiencies were assigned a priority of 1 through 5, with Priority 1 deficiencies being the most urgent.
eCOMET®	Energy and Condition Management Estimation Technology (eCOMET®) is Parsons proprietary facility asset management software developed to provide facility managers with a state of the art, web-based tool to develop and maintain a comprehensive database of FCA data and information used for facility asset management, maintenance and repair, and capital renewal planning. eCOMET® is used by Parsons and its clients as the primary tool for collecting FCA data, preparing cost estimates, generating individual facility reports and cost estimates, and developing the overall capital renewal program.

School Assessment Report - Museum School of Avondale Estates at Forrest Hills

eCOMET® Cost Models	eCOMET® cost models are derived from RS Means Square Foot Cost Data cost models and these models are used to develop the current replacement value (CRV) and assign life cycle costs to the various systems within a building. Cost models are assigned current costs-per-square-foot to establish replacement values. The Cost models are designed to represent a client specific facility that meets local standards cost trends.
Element	Elements are the major components that comprise building systems as defined by UNIFORMAT II.
Expected Life	Also referred to as Useful Life. See Useful Life definition.
Facility	A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose.
Facility Attributes	Customizable eCOMET® fields to identify attributes specific to a facility. These fields are part of the eCOMET® database set-up with the owner.
Facility Condition Assessment (FCA)	A facility condition assessment (FCA) is a visual inspection of buildings and grounds at a facility to identify and estimate current and future needed repairs or replacements of major systems for planning and budgeting purposes. It is typically performed for organizations that are tasked with the day to day maintenance, operation, and capital renewal (replacement) of building systems and components of a large inventory of facilities. The primary goal of an FCA is to objectively and quantifiably identify, inspect, and prioritize the repair and replacement needs of the building and ground systems (e.g., roofs, windows, doors, floor finishes, plumbing fixtures, parking lot, and sidewalks) within facilities that have either failed or have surpassed their service life, and to identify and forecast future capital replacement needs for systems that have not yet failed, but planned replacement of those systems is needed to ensure that the facilities will continue to meet the mission of the organization.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition expressed as a percentage from 0.00% to 100.00% that is derived by dividing the cost to correct a facility's deficiencies by its Current Replacement Value (CRV). The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio, a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.
Forecast Period	The Forecast Period refers to a user defined number of years forward of the Current Period.
Gen (Generate)	The Cost Model has a Gen box for each system line item. By checking the box, eCOMET® will generate life cycle deficiencies based on the Year Installed and the Life for that system. Systems that typically do not re-generate (foundations, floor construction, roof construction, basement walls, etc.) would not have the Gen box checked as those systems would not re-generate at the end of a life cycle. In those instances, it would be more practical and cost effective to demolish the entire facility than renew those systems.
Gross Square Feet (GSF)	The area of the enclosed floor space of a building or building addition in square feet measured to the outside face of the enclosing wall.
Life cycle	Life cycle refers to the period of time that a building or site system or element can be expected to adequately serve its intended function. Parsons assigns expected life cycles to all building systems based on Building Operators and Managers of America (BOMA) recommended life cycles, manufacturers suggested life, and RS Means cost data, and client-provided historical data. BOMA standards are a nationally recognized source of life cycle data for various components and/or systems associated with facilities. RS Means is a national company specializing in construction estimating and costs.
Next Renewal	Next Renewal refers to a manually-adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately reflect current conditions.

School Assessment Report - Museum School of Avondale Estates at Forrest Hills

Order of Magnitude	Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.
Remaining Service Life (RSL)	RSL is the number of years of service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the Calculated Next Renewal date or the Next Renewal date whichever one is the later date.
Renewal Factors	Renewal factors represent the difference in cost of renovating or replacing an existing system, rather than new construction of a building system. For example, installing a new built-up roof on an existing building would include removing and disposing of the old roof, a cost not associated with new construction. Using a renewal premium to account for demolition and other difficulty costs, Parsons typically assigns a renewal factor of 110%.
Renewal Schedule	A timeline by year that indicates when the systems will need to be renewed and the estimated price of the renewal.
Repair Cost	Repair cost is the sum of all the deficiencies associated with a building or multiple buildings/facilities. It will include any applied soft costs or City Cost Indexes.
Replacement Value	See Current Replacement Value.
Site	A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.
Soft Costs	Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user-defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses.
Sustainability	Sustainability refers to the collection of policies and strategies that meet society's present needs without compromising the ability of future generations to meet their own needs.
System	System refers to building and related site work elements as described by ASTM UNIFORMAT II Classification for Building Elements (E1557-97), a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also UNIFORMAT II.
System Generated Deficiency	eCOMET® automatically generates system deficiencies based on system life cycles using the systems installation dates as the base year. By adjusting the Next Renewal date ahead or behind the predicted or stated life cycle date, a system cost will come due earlier or later than the originally installed life cycle date. This utility accounts for good maintenance conditions and a longer life, or early expiration of a system life due to any number of adverse factors such as poor installation, acts of god, material defects, poor design applications and other factors that may shorten the life of a material or system. It is important to mention that the condition of the systems is not necessarily a reflection of maintenance practices, but a combination of system usage and age.
UNIFORMAT	ASTM UNIFORMAT II, Classification for Building Elements (E1557-97), a publication of the Construction Specification Institute (CSI), is a format used to classify major facility components common to most buildings. The format is based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies.
Unit Price	The Unit Price (Raw) x (100% + the Additional Cost Template percentage).
Unit Price (Raw)	The actual \$/sq. ft cost being used for the building and systems. It will include adjustments for the City Cost Index applied to the facility.

Useful Life	Also known as Expected Life, Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in the database are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from client- defined historical experience.
Vacant	Vacant refers to a facility that is not occupied but is a maintained facility by a district. See Abandoned.
Year Built	The year that a building or addition was originally built based on its date of substantial completion or occupancy.
Year Installed	The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.