

DeKalb County School District/Elementary Schools

Sagamore Hills Elementary

Final

School Assessment Report

May 20, 2016



Table of Contents

School Executive Summary	4
School Condition Summary	6
<u>1961, 1963 Building</u>	8
Executive Summary	8
Condition Summary	9
Photo Album	10
Condition Detail	11
System Listing	12
Renewal Schedule	14
Forecasted Sustainment Requirement	17
Deficiency Summary By System	18
Deficiency Summary By Priority	19
Deficiency By Priority Investment	20
Deficiency Summary By Category	21
Deficiency Details By Priority	22
<u>2003 Gym</u>	33
Executive Summary	33
Condition Summary	34
Photo Album	35
Condition Detail	36
System Listing	37
Renewal Schedule	38
Forecasted Sustainment Requirement	40
Deficiency Summary By System	41
Deficiency Summary By Priority	42
Deficiency By Priority Investment	43
Deficiency Summary By Category	44
Deficiency Details By Priority	45
<u>2005 Storage Building</u>	46

School Assessment Report

Executive Summary	46
Condition Summary	47
Photo Album	48
Condition Detail	49
System Listing	50
Renewal Schedule	51
Forecasted Sustainment Requirement	54
Deficiency Summary By System	55
Deficiency Summary By Priority	56
Deficiency By Priority Investment	57
Deficiency Summary By Category	58
Deficiency Details By Priority	59
<u>Site</u>	60
Executive Summary	60
Condition Summary	61
Photo Album	62
Condition Detail	63
System Listing	64
Renewal Schedule	65
Forecasted Sustainment Requirement	67
Deficiency Summary By System	68
Deficiency Summary By Priority	69
Deficiency By Priority Investment	70
Deficiency Summary By Category	71
Deficiency Details By Priority	72
Glossary	78

School Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	55,011
Year Built:	1961
Last Renovation:	2008
Replacement Value:	\$12,825,642
Repair Cost:	\$6,329,331.64
Total FCI:	49.35 %
Total RSLI:	28.63 %
FCA Score:	50.65



Description:

The Sagamore Hills Elementary School campus consists of two buildings located at 1865 Alderbrook Road NE in Atlanta, Georgia. The original campus was constructed in 1961, an addition to the main school building was constructed in 1963, and a gymnasium building was constructed in 2003. In addition to these buildings, the campus contains a storage shed, covered walkway, hard surface play area, playground, and playing field. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for each building and site improvement on the campus.

School Assessment Report - Sagamore Hills Elementary

Attributes:

General Attributes:

Assigned Region:	Region 2	Board District:	District 4
DOE Facility:	5065	Geographic Region:	Region 2
HS Attendance Area:	Lakeside HS	Jurisdictional City:	DeKalb County (Unincorporated)
Site Acreage:	9.7		

School Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	50.73 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	59.06 %	0.00 %	\$0.00
B20 - Exterior Enclosure	36.28 %	32.32 %	\$419,072.00
B30 - Roofing	76.53 %	0.00 %	\$0.00
C10 - Interior Construction	34.35 %	34.37 %	\$246,127.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	2.87 %	56.10 %	\$954,397.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	60.79 %	30.33 %	\$424,507.00
D30 - HVAC	4.34 %	93.52 %	\$1,886,178.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	27.32 %	40.87 %	\$538,414.64
E10 - Equipment	0.00 %	110.00 %	\$473,426.00
E20 - Furnishings	0.00 %	110.00 %	\$291,883.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
G20 - Site Improvements	17.18 %	52.67 %	\$430,299.00
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$442,343.00
G40 - Site Electrical Utilities	0.00 %	110.00 %	\$222,685.00
Totals:	28.63 %	49.35 %	\$6,329,331.64

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 Priority	2 Priority	3 Priority	4 Priority	5 Priority
1961, 1963 Building	49,413	49.26	\$0.00	\$190,003.64	\$4,973,800.00	\$0.00	\$0.00
2003 Gym	5,478	7.71	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00
2005 Storage Building	120	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	55,011	77.05	\$0.00	\$220,209.00	\$875,118.00	\$0.00	\$0.00
Total:		49.35	\$0.00	\$410,212.64	\$5,919,119.00	\$0.00	\$0.00

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	49,413
Year Built:	1961
Last Renovation:	1995
Replacement Value:	\$10,483,641
Repair Cost:	\$5,163,803.64
Total FCI:	49.26 %
Total RSLI:	28.03 %
FCA Score:	50.74



Description:

The main building at Sagamore Hills Elementary School is a one-story building located at 1865 Alderbrook Road N.E. in Atlanta, Georgia. Originally built in 1961, there has been one addition in 1963 and numerous renovations. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2010, 2011	Fire Sprinkler System:	No
-----------------	------------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	46.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	46.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	31.05 %	35.74 %	\$419,072.00
B30 - Roofing	76.12 %	0.00 %	\$0.00
C10 - Interior Construction	26.45 %	40.86 %	\$246,127.00
C20 - Stairs	0.00 %	0.00 %	\$0.00
C30 - Interior Finishes	1.20 %	59.62 %	\$954,397.00
D10 - Conveying	0.00 %	0.00 %	\$0.00
D20 - Plumbing	60.83 %	32.48 %	\$424,507.00
D30 - HVAC	2.48 %	96.36 %	\$1,815,977.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	26.15 %	43.71 %	\$538,414.64
E10 - Equipment	0.00 %	110.00 %	\$473,426.00
E20 - Furnishings	0.00 %	110.00 %	\$291,883.00
F10 - Special Construction	0.00 %	0.00 %	\$0.00
Totals:	28.03 %	49.26 %	\$5,163,803.64

Photo Album

The photo album consists of the various cardinal directions of the building.

1). South Elevation - Jul 17, 2015



2). South Elevation - Jul 17, 2015



3). West Elevation - Jul 17, 2015



4). East Elevation - Jul 17, 2015



5). North Elevation - Jul 17, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

School Assessment Report - 1961, 1963 Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.49	S.F.	49,413	100	1961	2061		46.00 %	0.00 %	46			\$320,690
A1020	Special Foundations	\$0.00	S.F.		100				0.00 %	0.00 %				\$0
A1030	Slab on Grade	\$7.09	S.F.	49,413	100	1961	2061		46.00 %	0.00 %	46			\$350,338
A2010	Basement Excavation	\$0.00	S.F.		100				0.00 %	0.00 %				\$0
A2020	Basement Walls	\$0.00	S.F.		100				0.00 %	0.00 %				\$0
B1010	Floor Construction	\$0.00	S.F.		100				0.00 %	0.00 %				\$0
B1020	Roof Construction	\$5.34	S.F.	49,413	100	1961	2061		46.00 %	0.00 %	46			\$263,865
B2010	Exterior Walls	\$16.02	S.F.	49,413	100	1961	2061		46.00 %	0.00 %	46			\$791,596
B2020	Exterior Windows	\$6.79	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$369,066.00	\$335,514
B2030	Exterior Doors	\$0.92	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$50,006.00	\$45,460
B3010	Roof Coverings - Asphal Shingles	\$0.00	S.F.		10	1961	1971		0.00 %	0.00 %	-44			\$0
B3010	Roof Coverings - BUR	\$20.70	S.F.	49,413	25	2009	2034		76.00 %	0.00 %	19			\$1,022,849
B3010	Roof Coverings - EPDM	\$0.00	S.F.		15	1961	1976		0.00 %	0.00 %	-39			\$0
B3010	Roof Coverings - Preformed Metal	\$0.00	S.F.		30	1961	1991		0.00 %	0.00 %	-24			\$0
B3010	Roof Coverings - Standing Seam Metal	\$0.00	S.F.		75	1961	2036		28.00 %	0.00 %	21			\$0
B3020	Roof Openings	\$0.63	S.F.	49,413	30	2009	2039		80.00 %	0.00 %	24			\$31,130
C1010	Partitions	\$7.01	S.F.	49,413	100	1961	2061		46.00 %	0.00 %	46			\$346,385
C1020	Interior Doors	\$2.39	S.F.	49,413	30	1961	1991		0.00 %	80.00 %	-24		\$94,478.00	\$118,097
C1030	Fittings	\$2.79	S.F.	49,413	20	1961	1981		0.00 %	110.00 %	-34		\$151,649.00	\$137,862
C2010	Stair Construction	\$0.00	S.F.		100	1961	2061		46.00 %	0.00 %	46			\$0
C3010	Wall Finishes - Ceramic & Glazed	\$10.27	S.F.	24,706	30	1961	1991		0.00 %	0.00 %	-24			\$253,731
C3010	Wall Finishes - Paint	\$1.93	S.F.	24,707	10	2008	2018		30.00 %	0.00 %	3			\$47,685
C3010	Wall Finishes - Wall Coverings	\$0.00	S.F.		10	1961	1971		0.00 %	0.00 %	-44			\$0
C3020	Floor Finishes - Carpet	\$8.50	S.F.	4,560	8	2008	2016		12.50 %	0.00 %	1			\$38,760
C3020	Floor Finishes - Ceramic & Quarry Tile	\$14.49	S.F.	3,494	50	1961	2011		0.00 %	110.00 %	-4		\$55,691.00	\$50,628
C3020	Floor Finishes - Terrazzo	\$53.01	S.F.	7,411	50	1961	2011		0.00 %	0.00 %	-4			\$392,857
C3020	Floor Finishes - VCT	\$9.54	S.F.	33,948	20	1961	1981		0.00 %	110.00 %	-34		\$356,250.00	\$323,864
C3020	Floor Finishes - Wood	\$0.00	S.F.		20	1961	1981		0.00 %	0.00 %	-34			\$0
C3030	Ceiling Finishes	\$9.98	S.F.	49,413	20	1961	1981		0.00 %	110.00 %	-34		\$542,456.00	\$493,142
D1010	Elevators and Lifts	\$0.00	S.F.		30	1961	1991		0.00 %	0.00 %	-24			\$0
D2010	Plumbing Fixtures	\$17.66	S.F.	49,413	30	2011	2041		86.67 %	0.00 %	26			\$872,634
D2020	Domestic Water Distribution	\$3.99	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$216,874.00	\$197,158
D2030	Sanitary Waste	\$3.41	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$185,348.00	\$168,498
D2040	Rain Water Drainage	\$0.98	S.F.	49,413	30	2009	2039		80.00 %	0.00 %	24			\$48,425

School Assessment Report - 1961, 1963 Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D2090	Other Plumbing Systems - Natural Gas	\$0.41	S.F.	49,413	40	1961	2001		0.00 %	110.00 %	-14		\$22,285.00	\$20,259
D3020	Heat Generating Systems	\$4.55	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$247,312.00	\$224,829
D3030	Cooling Generating Systems	\$4.73	S.F.	49,413	25	1995	2020		20.00 %	0.00 %	5			\$233,723
D3040	Distribution & Exhaust Systems	\$5.51	S.F.	49,413	30	1985	2015		0.00 %	110.00 %	0		\$299,492.00	\$272,266
D3050	Terminal & Package Units	\$18.52	S.F.	49,413	15	1961	1976		0.00 %	110.00 %	-39		\$1,006,642.00	\$915,129
D3060	Controls & Instrumentation	\$3.60	S.F.	49,413	20	1985	2005		0.00 %	110.00 %	-10		\$195,675.00	\$177,887
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$1.23	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$66,856.00	\$60,778
D4010	Sprinklers	\$0.00	S.F.		30				0.00 %	0.00 %				\$0
D4020	Standpipes	\$0.00	S.F.		30				0.00 %	0.00 %				\$0
D5010	Electrical Service/Distribution	\$1.81	S.F.	49,413	40	1961	2001		0.00 %	110.00 %	-14		\$98,381.00	\$89,438
D5020	Branch Wiring	\$6.78	S.F.	49,413	30	1961	1991		0.00 %	110.00 %	-24		\$368,522.00	\$335,020
D5020	Lighting	\$8.90	S.F.	49,413	30	2000	2030		50.00 %	1.06 %	15		\$4,655.64	\$439,776
D5030	Communications and Security - Clock & PA Systems	\$5.60	S.F.	49,413	15	2005	2020		33.33 %	0.00 %	5			\$276,713
D5030	Communications and Security - Fire Alarm	\$1.23	S.F.	49,413	15	2005	2020	2015	0.00 %	110.00 %	0		\$66,856.00	\$60,778
D5030	Communications and Security - Security & CCTV	\$0.61	S.F.	49,413	15	2005	2020		33.33 %	0.00 %	5			\$30,142
D5090	Other Electrical Systems - Emergency Generator	\$0.00	S.F.		15	1961	1976		0.00 %	0.00 %	-39			\$0
E1010	Commercial Equipment	\$0.00	S.F.		20	1961	1981		0.00 %	0.00 %	-34			\$0
E1020	Institutional Equipment	\$0.40	S.F.	49,413	20	1961	1981		0.00 %	110.00 %	-34		\$21,742.00	\$19,765
E1090	Other Equipment - Kitchen Equipment	\$8.31	S.F.	49,413	20	1961	1981		0.00 %	110.00 %	-34		\$451,684.00	\$410,622
E2010	Fixed Furnishings	\$5.37	S.F.	49,413	20	1961	1981		0.00 %	110.00 %	-34		\$291,883.00	\$265,348
F1010	Special Structures - Canopies	\$0.00	S.F.		25	1961	1986	2020	20.00 %	0.00 %	5			\$0
Total									28.03 %	49.26 %			\$5,163,803.64	\$10,483,641

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$5,163,804	\$43,915	\$0	\$57,317	\$0	\$689,346	\$0	\$0	\$0	\$55,630	\$0	\$6,010,012
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1020 - Special Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$369,066	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$369,066
B2030 - Exterior Doors	\$50,006	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$50,006
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Asphal Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - BUR	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - EPDM	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Preformed Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

School Assessment Report - 1961, 1963 Building

C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$94,478	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$94,478
C1030 - Fittings	\$151,649	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$151,649
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic & Glazed	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$57,317	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$57,317
C3010 - Wall Finishes - Wall Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Carpet	\$0	\$43,915	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,630	\$0	\$99,545
C3020 - Floor Finishes - Ceramic & Quarry Tile	\$55,691	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,691
C3020 - Floor Finishes - Terrazzo	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - VCT	\$356,250	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$356,250
C3020 - Floor Finishes - Wood	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$542,456	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$542,456
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$216,874	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$216,874
D2030 - Sanitary Waste	\$185,348	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$185,348
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$22,285	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,285
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$247,312	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$247,312
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$298,045	\$0	\$0	\$0	\$0	\$0	\$298,045
D3040 - Distribution & Exhaust Systems	\$299,492	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$299,492
D3050 - Terminal & Package Units	\$1,006,642	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,006,642
D3060 - Controls & Instrumentation	\$195,675	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$195,675
D3090 - Other HVAC Systems/Equip - Kitchen Hood	\$66,856	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$66,856
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 1961, 1963 Building

D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$98,381	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$98,381
D5020 - Branch Wiring	\$368,522	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$368,522
D5020 - Lighting	\$4,656	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,656
D5030 - Communications and Security - Clock & PA Systems	\$0	\$0	\$0	\$0	\$0	\$352,864	\$0	\$0	\$0	\$0	\$0	\$352,864
D5030 - Communications and Security - Fire Alarm	\$66,856	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$66,856
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$0	\$0	\$38,437	\$0	\$0	\$0	\$0	\$0	\$38,437
D5090 - Other Electrical Systems - Emergency Generator	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$21,742	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,742
E1090 - Other Equipment - Kitchen Equipment	\$451,684	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$451,684
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$291,883	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$291,883
F - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F10 - Special Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
F1010 - Special Structures - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$5,163,803.64

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$369,066.00	\$0.00	\$0.00	\$369,066.00
B2030	Exterior Doors	\$0.00	\$0.00	\$50,006.00	\$0.00	\$0.00	\$50,006.00
C1020	Interior Doors	\$0.00	\$0.00	\$94,478.00	\$0.00	\$0.00	\$94,478.00
C1030	Fittings	\$0.00	\$0.00	\$151,649.00	\$0.00	\$0.00	\$151,649.00
C3020	Floor Finishes - Ceramic & Quarry Tile	\$0.00	\$0.00	\$55,691.00	\$0.00	\$0.00	\$55,691.00
C3020	Floor Finishes - VCT	\$0.00	\$0.00	\$356,250.00	\$0.00	\$0.00	\$356,250.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$542,456.00	\$0.00	\$0.00	\$542,456.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$216,874.00	\$0.00	\$0.00	\$216,874.00
D2030	Sanitary Waste	\$0.00	\$185,348.00	\$0.00	\$0.00	\$0.00	\$185,348.00
D2090	Other Plumbing Systems - Natural Gas	\$0.00	\$0.00	\$22,285.00	\$0.00	\$0.00	\$22,285.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$247,312.00	\$0.00	\$0.00	\$247,312.00
D3040	Distribution & Exhaust Systems	\$0.00	\$0.00	\$299,492.00	\$0.00	\$0.00	\$299,492.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$1,006,642.00	\$0.00	\$0.00	\$1,006,642.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$195,675.00	\$0.00	\$0.00	\$195,675.00
D3090	Other HVAC Systems/Equip - Kitchen Hood	\$0.00	\$0.00	\$66,856.00	\$0.00	\$0.00	\$66,856.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$98,381.00	\$0.00	\$0.00	\$98,381.00
D5020	Branch Wiring	\$0.00	\$0.00	\$368,522.00	\$0.00	\$0.00	\$368,522.00
D5020	Lighting	\$0.00	\$4,655.64	\$0.00	\$0.00	\$0.00	\$4,655.64
D5030	Communications and Security - Fire Alarm	\$0.00	\$0.00	\$66,856.00	\$0.00	\$0.00	\$66,856.00
E1020	Institutional Equipment	\$0.00	\$0.00	\$21,742.00	\$0.00	\$0.00	\$21,742.00
E1090	Other Equipment - Kitchen Equipment	\$0.00	\$0.00	\$451,684.00	\$0.00	\$0.00	\$451,684.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$291,883.00	\$0.00	\$0.00	\$291,883.00
Total:		\$0.00	\$190,003.64	\$4,973,800.00	\$0.00	\$0.00	\$5,163,803.64

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$5,163,803.64

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 Priority:

System: D2030 - Sanitary Waste



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 2 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$185,348.00

Assessor Name: Sam Mandola

Date Created: 07/13/2015

Notes: The sanitary waste system is beyond its expected service life and should be scheduled for replacement.

System: D5020 - Lighting



Location: Hallways

Distress: Missing

Category: Building Code Compliance

Priority: 2 Priority

Correction: Replace fluorescent fixture, lay-in, recess mtd, 2' x 4', four 32 W

Qty: 15.00

Unit of Measure: Ea.

Estimate: \$4,655.64

Assessor Name: Ben Nixon

Date Created: 07/13/2015

Notes: The facility does not meet current code for emergency lighting systems in hallways or other common use areas.

Priority 3 Priority:

System: B2020 - Exterior Windows



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$369,066.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The aluminum frame, operable, single pane windows are aged, not energy efficient, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$50,006.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C1020 - Interior Doors



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$94,478.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The interior doors have some deterioration due to age, are not ADA compliant, and should be replaced.

System: C1030 - Fittings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Accessibility Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$151,649.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: Fittings, such as toilet partitions, handrails and signage, are beyond their expected service life, not ADA compliant, and should be replaced. SPLOST project 128-422 to provide hall restroom renovations.

System: C3020 - Floor Finishes - Ceramic & Quarry Tile



Location: Kitchen and Restrooms

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 3,494.00

Unit of Measure: S.F.

Estimate: \$55,691.00

Assessor Name: Ben Nixon

Date Created: 07/17/2015

Notes: The tile floor covering is beyond its expected service life, worn, and should be replaced.

System: C3020 - Floor Finishes - VCT



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 33,948.00

Unit of Measure: S.F.

Estimate: \$356,250.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The VCT flooring is aged and worn, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$542,456.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The acoustical ceiling tiles and grid system is damaged and should be renewed.

System: D2020 - Domestic Water Distribution



Location: Boiler Room

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$216,874.00

Assessor Name: Ben Nixon

Date Created: 07/13/2015

Notes: The domestic water distribution system is beyond its expected service life, has water quality issues, and should be scheduled for replacement. SPLOST project 128-422 to replace the water source heat pumps and fan coil units in the 1961 and 1963 buildings.

System: D2090 - Other Plumbing Systems - Natural Gas



Location: Northwest Side of Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Building Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$22,285.00

Assessor Name: Ben Nixon

Date Created: 07/13/2015

Notes: The natural gas system is beyond its expected service life, not building code compliant, and should be scheduled for replacement. Natural gas piping is not sleeved or vented in boiler/mechanical room.

System: D3020 - Heat Generating Systems



Location: Mechanical Room

Distress: Beyond Service Life

Category: Deferred Maintenance / Environmental

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$247,312.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The original boiler is beyond its expected service life and inadequate, contains hazardous materials, and should be scheduled for replacement.

System: D3040 - Distribution & Exhaust Systems



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$299,492.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The distribution and exhaust systems are beyond their service life, inadequate, and should be scheduled for replacement. Restrooms lack working exhaust systems.

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$1,006,642.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The water source heat pumps, fan coil units and integrated controls are beyond their expected service life and should be scheduled for replacement. SPLOST project 128-422 to replace the water source heat pumps and fan coil units in the 1961 and 1963 buildings.

System: D3060 - Controls & Instrumentation



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$195,675.00

Assessor Name: Ben Nixon

Date Created: 07/13/2015

Notes: The pneumatic controls and instrumentation system is beyond its expected service life, antiquated, and should be scheduled for replacement with a modern DDC electrical control system.

System: D3090 - Other HVAC Systems/Equip - Kitchen Hood



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$66,856.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The kitchen hood system is beyond its expected service life and should be scheduled for replacement.

System: D5010 - Electrical Service/Distribution



Location: Main Switch Room/Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance / Building Code Compliance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$98,381.00

Assessor Name: Sam Mandola

Date Created: 04/11/2015

Notes: The primary service entrance and associated distribution panels are beyond their expected service life, not code compliant, and should be scheduled for replacement. There is insufficient clearance in front of electrical panels throughout the facility. Electrical outlets are not GFI in wet areas. SPLOST project 128-422 to upgrade the electrical service and distribution to meet current building loads in the 61 and 63 buildings.

System: D5020 - Branch Wiring



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$368,522.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: The branch wiring system is beyond its expected service life and should be scheduled for replacement.

System: D5030 - Communications and Security - Fire Alarm



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$66,856.00

Assessor Name: Ben Nixon

Date Created: 07/13/2015

Notes: The fire alarm system is beyond its expected service life, reported to have frequent false alarms, and should be scheduled for replacement.

System: F1020 - Institutional Equipment



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$21,742.00

Assessor Name: Ben Nixon

Date Created: 02/05/2016

Notes: Institutional equipment, such as theater and stage equipment, library equipment and audio-visual equipment, is beyond its expected service life and should be scheduled for replacement.

System: E1090 - Other Equipment - Kitchen Equipment



Location: Kitchen

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$451,684.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Kitchen equipment is beyond service life and should be scheduled for replacement. The grease trap is scheduled for replacement under SPLOST project 128-422.

System: E2010 - Fixed Furnishings



Location: Throughout Building

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 49,413.00

Unit of Measure: S.F.

Estimate: \$291,883.00

Assessor Name: Ben Nixon

Date Created: 04/11/2015

Notes: Fixed furnishings, such as built-in cabinets, are beyond their expected service life and worn, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	5,478
Year Built:	2003
Last Renovation:	
Replacement Value:	\$910,151
Repair Cost:	\$70,201.00
Total FCI:	7.71 %
Total RSLI:	64.19 %
FCA Score:	92.29



Description:

The 2003 gymnasium at Sagamore Hills Elementary School is a one-story building located at 1865 Alderbrook Road N.E. in Atlanta, Georgia. There has been no additions or major renovations to this building. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes:	2020	Fire Sprinkler System:	No
-----------------	------	------------------------	----

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	88.00 %	0.00 %	\$0.00
B10 - Superstructure	88.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	85.42 %	0.00 %	\$0.00
B30 - Roofing	84.00 %	0.00 %	\$0.00
C10 - Interior Construction	76.16 %	0.00 %	\$0.00
C30 - Interior Finishes	29.48 %	0.00 %	\$0.00
D20 - Plumbing	60.19 %	0.00 %	\$0.00
D30 - HVAC	30.85 %	53.04 %	\$70,201.00
D40 - Fire Protection	0.00 %	0.00 %	\$0.00
D50 - Electrical	44.11 %	0.00 %	\$0.00
Totals:	64.19 %	7.71 %	\$70,201.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). East Elevation - Jul 17, 2015



2). West Elevation - Jul 17, 2015



3). North Elevation - Jul 17, 2015



4). South Elevation - Jul 17, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$9.34	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$51,165
A1030	Slab on Grade	\$6.21	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$34,018
B1020	Roof Construction	\$21.36	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$117,010
B2010	Exterior Walls	\$19.80	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$108,464
B2030	Exterior Doors	\$2.01	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$11,011
B3010	Roof Coverings - Standing Seam Metal	\$11.91	S.F.	5,478	75	2003	2078		84.00 %	0.00 %	63			\$65,243
C1010	Partitions	\$12.78	S.F.	5,478	100	2003	2103		88.00 %	0.00 %	88			\$70,009
C1020	Interior Doors	\$4.24	S.F.	5,478	40	2003	2043		70.00 %	0.00 %	28			\$23,227
C1030	Fittings	\$3.46	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$18,954
C3010	Wall Finishes - Ceramic	\$6.65	S.F.		30	2003	2033		60.00 %	0.00 %	18			\$0
C3010	Wall Finishes - Paint	\$1.41	S.F.	5,478	10	2012	2022		70.00 %	0.00 %	7			\$7,724
C3020	Floor Finishes - Ceramic Tile	\$6.67	S.F.	253	50	2003	2053		76.00 %	0.00 %	38			\$1,688
C3020	Floor Finishes - Neoprene	\$14.46	S.F.	4,554	15	2003	2018		20.00 %	0.00 %	3			\$65,851
C3020	Floor Finishes - VCT	\$5.01	S.F.	325	15	2003	2018		20.00 %	0.00 %	3			\$1,628
C3030	Ceiling Finishes	\$4.31	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$23,610
D2010	Plumbing Fixtures	\$9.66	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$52,917
D2020	Domestic Water Distribution	\$5.85	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$32,046
D2030	Sanitary Waste	\$0.87	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$4,766
D2040	Rain Water Drainage	\$0.22	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$1,205
D2090	Other Plumbing Systems - Natural Gas	\$0.32	S.F.	5,478	40	2003	2043		70.00 %	0.00 %	28			\$1,753
D3040	Distribution Systems & Exhaust Systems	\$12.25	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$67,106
D3050	Terminal & Package Units	\$11.65	S.F.	5,478	15	2003	2018	2015	0.00 %	110.00 %	0		\$70,201.00	\$63,819
D3060	Controls & Instrumentation	\$0.26	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$1,424
D4010	Sprinklers	\$3.84	S.F.	0	30	2003	2033		60.00 %	0.00 %	18			\$0
D5010	Electrical Service/Distribution	\$1.24	S.F.	5,478	40	2003	2043		70.00 %	0.00 %	28			\$6,793
D5020	Branch Wiring	\$5.24	S.F.	5,478	30	2003	2033		60.00 %	0.00 %	18			\$28,705
D5020	Lighting	\$5.24	S.F.	5,478	20	2003	2023		40.00 %	0.00 %	8			\$28,705
D5030	Communications and Security - Fire Alarm	\$2.13	S.F.	5,478	15	2003	2018		20.00 %	0.00 %	3			\$11,668
D5030	Communications and Security - Public Address & Clock System	\$0.88	S.F.	5,478	15	2003	2018		20.00 %	0.00 %	3			\$4,821
D5030	Communications and Security - Security & CCTV	\$0.88	S.F.	5,478	15	2003	2018		20.00 %	0.00 %	3			\$4,821
Total									64.19 %	7.71 %			\$70,201.00	\$910,151

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$70,201	\$0	\$0	\$106,724	\$0	\$0	\$0	\$10,449	\$101,293	\$0	\$0	\$288,668
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings - Standing Seam Metal	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,411	\$0	\$0	\$26,411
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Ceramic	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes - Paint	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$10,449	\$0	\$0	\$0	\$10,449
C3020 - Floor Finishes - Ceramic Tile	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes - Neoprene	\$0	\$0	\$0	\$79,153	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,153
C3020 - Floor Finishes - VCT	\$0	\$0	\$0	\$1,957	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,957
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$32,899	\$0	\$0	\$32,899
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


School Assessment Report - 2003 Gym

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems - Natural Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems & Exhaust Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$70,201	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,201
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,985	\$0	\$0	\$1,985
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,998	\$0	\$0	\$39,998
D5030 - Communications and Security - Fire Alarm	\$0	\$0	\$0	\$14,025	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,025
D5030 - Communications and Security - Public Address & Clock System	\$0	\$0	\$0	\$5,795	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,795
D5030 - Communications and Security - Security & CCTV	\$0	\$0	\$0	\$5,795	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,795

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$70,201.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
D3050	Terminal & Package Units	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00	\$70,201.00
	Total:	\$0.00	\$0.00	\$70,201.00	\$0.00	\$0.00	\$70,201.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 Priority:

System: D3050 - Terminal & Package Units



Location: Throughout Building

Distress: Inadequate

Category: Deferred Maintenance / Energy

Priority: 3 Priority

Correction: Renew System

Qty: 5,478.00

Unit of Measure: S.F.

Estimate: \$70,201.00

Assessor Name: Sam Mandola

Date Created: 07/13/2015

Notes: The primary heating for the gym consists of gas fired unit heaters. The cooling system consist of a single PTAC unit in the office and ventilation fans for the gym area. The gym is scheduled to receive a 20 ton package unit under SPLOST project 128-422.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	120
Year Built:	2005
Last Renovation:	
Replacement Value:	\$10,274
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	79.65 %
FCA Score:	100.00



Description:

The storage building at Sagamore Hills Elementary School is a one-story building located at 1865 Alderbrook Road N.E. in Atlanta, Georgia. Originally built in 2005, there have been no additions and no renovations to this building. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report.

Attributes:

General Attributes:

Building Codes: Fire Sprinkler System: No

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	0.00 %	0.00 %	\$0.00
A20 - Basement Construction	0.00 %	0.00 %	\$0.00
B10 - Superstructure	90.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	89.53 %	0.00 %	\$0.00
B30 - Roofing	50.00 %	0.00 %	\$0.00
C10 - Interior Construction	75.00 %	0.00 %	\$0.00
C30 - Interior Finishes	0.00 %	0.00 %	\$0.00
D20 - Plumbing	0.00 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	0.00 %	\$0.00
Totals:	79.65 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building.

1). West Elevation - Jul 17, 2015



2). Southwest Elevation - Mar 03, 2016



3). South Elevation - Mar 03, 2016



4). East Elevation - Mar 03, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$0.00	S.F.	120	100	2005	2105		90.00 %	0.00 %	90			\$0
A1030	Slab on Grade	\$0.00	S.F.	120	100	2005	2105		90.00 %	0.00 %	90			\$0
A2010	Basement Excavation	\$0.00	S.F.	120	100	2005	2105		90.00 %	0.00 %	90			\$0
A2020	Basement Walls	\$0.00	S.F.	120	100	2005	2105		90.00 %	0.00 %	90			\$0
B1020	Roof Construction	\$16.33	S.F.	120	100	2005	2105		90.00 %	0.00 %	90			\$1,960
B2010	Exterior Walls	\$38.65	S.F.	120	100	2005	2105		90.00 %	0.00 %	90			\$4,638
B2020	Exterior Windows	\$0.00	S.F.	120	30	2005	2035		66.67 %	0.00 %	20			\$0
B2030	Exterior Doors	\$0.80	S.F.	120	30	2005	2035		66.67 %	0.00 %	20			\$96
B3010	Roof Coverings	\$16.79	S.F.	120	20	2005	2025		50.00 %	0.00 %	10			\$2,015
C1010	Partitions	\$13.04	S.F.	120	40	2005	2045		75.00 %	0.00 %	30			\$1,565
C1020	Interior Doors	\$0.00	S.F.	120	30	2005	2035		66.67 %	0.00 %	20			\$0
C1030	Fittings	\$0.00	S.F.	120	20	2005	2025		50.00 %	0.00 %	10			\$0
C3010	Wall Finishes	\$0.00	S.F.	120	20	2005	2025		50.00 %	0.00 %	10			\$0
C3020	Floor Finishes	\$0.00	S.F.	120	20	2005	2025		50.00 %	0.00 %	10			\$0
C3030	Ceiling Finishes	\$0.00	S.F.	120	20	2005	2025		50.00 %	0.00 %	10			\$0
D2040	Rain Water Drainage	\$0.00	S.F.	120	30	2005	2035		66.67 %	0.00 %	20			\$0
D5010	Electrical Service/Distribution	\$0.00	S.F.	120	30	2005	2035		66.67 %	0.00 %	20			\$0
D5020	Lighting and Branch Wiring	\$0.00	S.F.	120	30	2005	2035		66.67 %	0.00 %	20			\$0
Total									79.65 %					\$10,274

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%


School Assessment Report - 2005 Storage Building

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,978	\$2,978
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,978	\$2,978
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting and Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System

Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	Elementary School
Gross Area (SF):	55,011
Year Built:	1961
Last Renovation:	
Replacement Value:	\$1,421,576
Repair Cost:	\$1,095,327.00
Total FCI:	77.05 %
Total RSLI:	9.87 %
FCA Score:	22.95



Description:

The Sagamore Elementary School site was originally constructed in 1961, has a total area of 9.6 acres, and is occupied by approximately 55,011 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2015 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for the site features.

Attributes:

General Attributes:

Site Code: 1575

Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	17.18 %	52.67 %	\$430,299.00
G30 - Site Mechanical Utilities	0.00 %	110.00 %	\$442,343.00
G40 - Site Electrical Utilities	0.00 %	110.00 %	\$222,685.00
Totals:	9.87 %	77.05 %	\$1,095,327.00

Photo Album

The photo album consists of the various cardinal directions of the building.

- 1). Aerial Image of Sagamore Elementary School - Oct 22, 2015



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system.
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$5.17	S.F.	26,485	25	1961	1986		0.00 %	110.00 %	-29		\$150,620.00	\$136,927
G2020	Parking Lots	\$4.56	S.F.	9,191	25	1961	1986		0.00 %	110.00 %	-29		\$46,102.00	\$41,911
G2030	Pedestrian Paving	\$1.50	S.F.	55,011	30	1961	1991		0.00 %	110.00 %	-24		\$90,768.00	\$82,517
G2040	Baseball Field	\$8.35	S.F.		0				0.00 %	0.00 %				\$0
G2040	Canopies	\$0.29	S.F.		0				0.00 %	0.00 %				\$0
G2040	Covered Walkways	\$48.72	S.F.	1,120	25	2003	2028		52.00 %	0.00 %	13			\$54,566
G2040	Fencing & Guardrails	\$0.91	S.F.	55,011	30	1961	1991		0.00 %	110.00 %	-24		\$55,066.00	\$50,060
G2040	Football Field	\$5.85	S.F.		20				0.00 %	0.00 %				\$0
G2040	Hard Surface Play Area	\$6.26	S.F.	20,427	20	2003	2023		40.00 %	0.00 %	8			\$127,873
G2040	Playing Field	\$3.92	S.F.	62,088	20	1961	1981	2020	25.00 %	0.00 %	5			\$243,385
G2040	Soccer/Lacross Field	\$5.00	S.F.		20				0.00 %	0.00 %				\$0
G2040	Softball Field	\$8.86	S.F.		20				0.00 %	0.00 %				\$0
G2040	Tennis Courts	\$18.47	S.F.		20				0.00 %	0.00 %				\$0
G2040	Track	\$7.04	S.F.		10				0.00 %	0.00 %				\$0
G2050	Landscaping	\$1.45	S.F.	55,011	15	1961	1976		0.00 %	110.00 %	-39		\$87,743.00	\$79,766
G3010	Water Supply	\$1.83	S.F.	55,011	50	1961	2011		0.00 %	110.00 %	-4		\$110,737.00	\$100,670
G3020	Sanitary Sewer	\$1.15	S.F.	55,011	50	1961	2011		0.00 %	110.00 %	-4		\$69,589.00	\$63,263
G3030	Storm Sewer	\$3.55	S.F.	55,011	50	1961	2011		0.00 %	110.00 %	-4		\$214,818.00	\$195,289
G3060	Fuel Distribution	\$0.78	S.F.	55,011	40	1961	2001		0.00 %	110.00 %	-14		\$47,199.00	\$42,909
G4010	Electrical Distribution	\$1.86	S.F.	55,011	50	1961	2011		0.00 %	110.00 %	-4		\$112,553.00	\$102,320
G4020	Site Lighting	\$1.15	S.F.	55,011	30	1961	1991		0.00 %	110.00 %	-24		\$69,589.00	\$63,263
G4030	Site Communications & Security	\$0.67	S.F.	55,011	10	1961	1971		0.00 %	110.00 %	-44		\$40,543.00	\$36,857
Total									9.87 %	77.05 %			\$1,095,327.00	\$1,421,576

Renewal Schedule

eComet forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

School Assessment Report - Site


Inflation Rate: 3%

System	Current Deficiencies	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	Total
Total:	\$1,095,327	\$0	\$0	\$0	\$0	\$310,364	\$0	\$0	\$178,184	\$0	\$54,486	\$1,638,362
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$150,620	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$150,620
G2020 - Parking Lots	\$46,102	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$46,102
G2030 - Pedestrian Paving	\$90,768	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$90,768
G2040 - Baseball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Fencing & Guardrails	\$55,066	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,066
G2040 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Hard Surface Play Area	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$178,184	\$0	\$0	\$178,184
G2040 - Playing Field	\$0	\$0	\$0	\$0	\$0	\$310,364	\$0	\$0	\$0	\$0	\$0	\$310,364
G2040 - Soccer/Lacross Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Softball Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Tennis Courts	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2050 - Landscaping	\$87,743	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$87,743
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$110,737	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$110,737
G3020 - Sanitary Sewer	\$69,589	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,589
G3030 - Storm Sewer	\$214,818	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$214,818
G3060 - Fuel Distribution	\$47,199	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,199
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$112,553	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$112,553
G4020 - Site Lighting	\$69,589	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,589
G4030 - Site Communications & Security	\$40,543	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$54,486	\$95,029

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and the forecasted capital renewal (system replacement) requirements over the next ten years.



Deficiency Summary by System


Current deficiencies include assemblies that have reached or exceed their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Service Life'. The following chart lists all current deficiencies associated with this facility broken down by UNIFORMAT system.



Budget Estimate Total: \$1,095,327.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Deficiency By Priority Investment Table


The table below shows the current investment cost grouped by deficiency priority and building system. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

- **Priority 1** deficiencies require immediate review to correct a potential life/safety hazard, stop accelerated deterioration, or return a facility to operation.
- **Priority 2** deficiencies could become a Priority 1 deficiency, if not corrected within the next 2-3 years. These include intermittent operations, rapid deterioration, or potential life/safety hazards.
- **Priority 3** deficiencies require appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further and not completed within the next 3-5 years.
- **Priority 4** deficiencies represent a sensible improvement to existing conditions. The recommended improvements are not required for the basic functionality of the facility; however addressing these deficiencies will improve overall usability and/or reduce long term maintenance costs. Repairs for these deficiencies may be budgeted and scheduled for completion within the next 5-7 years.
- **Priority 5** deficiencies will include conditions that have no impact on the function or usability of the facility, such as appearance. No action is required for these deficiencies, but they are tracked since they may require future inspection or be completed as part of related repairs in contiguous areas of the facility.

System Code	System Description	Priority 1	Priority 2	Priority 3	Priority 4	Priority 5	Total
G2010	Roadways	\$0.00	\$150,620.00	\$0.00	\$0.00	\$0.00	\$150,620.00
G2020	Parking Lots	\$0.00	\$0.00	\$46,102.00	\$0.00	\$0.00	\$46,102.00
G2030	Pedestrian Paving	\$0.00	\$0.00	\$90,768.00	\$0.00	\$0.00	\$90,768.00
G2040	Fencing & Guardrails	\$0.00	\$0.00	\$55,066.00	\$0.00	\$0.00	\$55,066.00
G2050	Landscaping	\$0.00	\$0.00	\$87,743.00	\$0.00	\$0.00	\$87,743.00
G3010	Water Supply	\$0.00	\$0.00	\$110,737.00	\$0.00	\$0.00	\$110,737.00
G3020	Sanitary Sewer	\$0.00	\$0.00	\$69,589.00	\$0.00	\$0.00	\$69,589.00
G3030	Storm Sewer	\$0.00	\$0.00	\$214,818.00	\$0.00	\$0.00	\$214,818.00
G3060	Fuel Distribution	\$0.00	\$0.00	\$47,199.00	\$0.00	\$0.00	\$47,199.00
G4010	Electrical Distribution	\$0.00	\$0.00	\$112,553.00	\$0.00	\$0.00	\$112,553.00
G4020	Site Lighting	\$0.00	\$69,589.00	\$0.00	\$0.00	\$0.00	\$69,589.00
G4030	Site Communications & Security	\$0.00	\$0.00	\$40,543.00	\$0.00	\$0.00	\$40,543.00
Total:		\$0.00	\$220,209.00	\$875,118.00	\$0.00	\$0.00	\$1,095,327.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,095,327.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 Priority:

System: G2010 - Roadways



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Safety

Priority: 2 Priority

Correction: Renew System

Qty: 26,485.00

Unit of Measure: S.F.

Estimate: \$150,620.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Roadways are beyond their expected service life, have some deterioration, and should be replaced and expanded to better accommodate carpool, buses, etc.

System: G4020 - Site Lighting



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance / Safety

Priority: 2 Priority

Correction: Renew System

Qty: 55,011.00

Unit of Measure: S.F.

Estimate: \$69,589.00

Assessor Name: Sam Mandola

Date Created: 07/13/2015

Notes: Site lighting is beyond its expected service life, poor/inadequate, and should be scheduled for replacement.

Priority 3 Priority:

System: G2020 - Parking Lots



Location: North and South Side of Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 9,191.00

Unit of Measure: S.F.

Estimate: \$46,102.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: The parking lot is beyond its expected service life, deteriorated, inadequate, and should be replaced and expanded. School staff reports that there are not enough parking spaces for staff members and much less for parents and visitors. SPLOST project 128-422 to provide parking renovations.

System: G2030 - Pedestrian Paving



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 55,011.00

Unit of Measure: S.F.

Estimate: \$90,768.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Pedestrian paving is beyond its expected service life, damaged, and should be replaced.

System: G2040 - Fencing & Guardrails



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 55,011.00

Unit of Measure: S.F.

Estimate: \$55,066.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Fencing is beyond its expected service life, rusted, and should be scheduled for replacement.

System: G2050 - Landscaping



Location: Site

Distress: Beyond Service Life

Category: Deferred Maintenance

Priority: 3 Priority

Correction: Renew System

Qty: 55,011.00

Unit of Measure: S.F.

Estimate: \$87,743.00

Assessor Name: Sam Mandola

Date Created: 07/17/2015

Notes: Landscaping is beyond its expected service life, damaged, and should be replaced to prevent erosion.

System: G3010 - Water Supply



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 55,011.00
Unit of Measure: S.F.
Estimate: \$110,737.00
Assessor Name: Sam Mandola
Date Created: 07/13/2015

Notes: The site water supply system, including fire protection system, hydrants and piping, is beyond its expected service life and should be scheduled for replacement.

System: G3020 - Sanitary Sewer



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 55,011.00
Unit of Measure: S.F.
Estimate: \$69,589.00
Assessor Name: Sam Mandola
Date Created: 07/13/2015

Notes: The site sanitary sewer system is beyond its expected service life and should be scheduled for replacement.

System: G3030 - Storm Sewer



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 55,011.00
Unit of Measure: S.F.
Estimate: \$214,818.00
Assessor Name: Sam Mandola
Date Created: 07/13/2015

Notes: The storm sewer system is beyond its expected service life and should be scheduled for replacement. School staff reports flooding in the field when it rains.

System: G3060 - Fuel Distribution



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 55,011.00
Unit of Measure: S.F.
Estimate: \$47,199.00
Assessor Name: Sam Mandola
Date Created: 07/13/2015

Notes: The fuel distribution system is beyond service life and should be scheduled for replacement.

System: G4010 - Electrical Distribution



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 55,011.00
Unit of Measure: S.F.
Estimate: \$112,553.00
Assessor Name: Sam Mandola
Date Created: 07/13/2015

Notes: The pole mounted electrical service distribution system is beyond its expected service life and should be scheduled for replacement.

System: G4030 - Site Communications & Security



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 Priority
Correction: Renew System
Qty: 55,011.00
Unit of Measure: S.F.
Estimate: \$40,543.00
Assessor Name: Sam Mandola
Date Created: 02/05/2016

Notes: Site communications and security systems are beyond their expected service life and should be scheduled for replacement.

Glossary

Abandoned	A facility owned by a district that is not occupied and not maintained. See Vacant.
Additional Cost	Total project cost is composed of hard and soft costs. Additional costs or soft expenses are costs that are necessary to accomplish the corrective work but are not directly attributable to the deficient systems direct construction cost, which are often referred to as hard cost. The components included in the soft costs vary by owner but usually include architect and contractor fees, contingencies and other owner-incurred costs necessary to fully develop and build a facility. These soft cost factors can be adjusted anytime within the eCOMET® database at the owner's discretion.
Assessment	Visual survey of a facility to determine its condition. It involves looking at the age of systems, reviewing information from local sources and visual evidence of potential problems to assign a condition rating. It does not include destructive testing of materials or testing of systems or equipment for functionality.
ASTM	ASTM International (ASTM): Originally known as the American Society for Testing and Materials, ASTM is an international standards organization that develops and publishes voluntary consensus technical standards for a wide range of materials, products, systems, and services.
BOMA	Building Owners Managers of America (BOMA): National organization of public and private facility owners focused on building management tools and maintenance techniques. eCOMET® reference: Building and component system effective economic life expectancies.
Building	A fully enclosed and roofed structure that can be traversed internally without exiting to the exterior.
Building Addition	An area, space or component of a building added to a building after the original building's year built date. NOTE: As a convention in the database, "Main" was used to designate the original building. Additions built prior to 1983 (30 years) were included in the main building area calculations to reflect their predicted system depreciation characteristics and remaining service life.
Building Systems	eCOMET® uses UNIFORMAT II to organize building data. UNIFORMAT II was originally developed by the federal General Services Administration to delineate building costs by systems rather than by material. UNIFORMAT II was formalized by an NIST standard, NISTIR 6389 in 1999. It has been further quantified and updated by ASTM standard 2005, E1557-05. The Construction Specifications Institute, CSI, has taken over the standard as part of their MasterFormat / MasterSpec system.
Calculated Next Renewal	The year a system or building element would be expected to expire based solely on the date it was installed and the expected useful lifetime for that kind of system.
Capital Renewal	Capital renewal refers to the cyclical replacement of building systems or elements as they become obsolete or beyond their useful life. It is not normally included in an annual operating/maintenance budget. See calculated next renewal and next renewal.
City Cost Index (CCI)	RS Means provides building system, equipment, and construction costs at a national level. The City Cost Index (also provided by RS Means) localizes those costs to a geographic region of the United States. In eCOMET®, each building or site is assigned a City Cost Index, which adjusts all of the associated costs for systems, deficiencies and inventory to the local value.
Condition	Condition refers to the state of physical fitness or readiness of a facility system or system element for its intended use.
Condition Budget	The Condition Budget, also known as Condition Needs, represents the budgeted contractor installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging the work.

School Assessment Report - Sagamore Hills Elementary

Condition Index (CI) %	The Condition Index (CI) also known as the Remaining Service Life Index (RSLI) is calculated as the sum of a renewable system's Remaining Service Life (RSL) Value divided by the sum of a system's Replacement Value (both values exclude soft cost to simplify calculation updates) expressed as a percentage ranging from 100.00% (new) to 0.00% (expired - no remaining life).
Construction Specifications Institute	Construction Specifications Institute: Primary national organization specializing in construction materials data and data location in construction documents. eCOMET® reference: UNIFORMAT II materials classification.
Correction	Correction refers to an assessor's recommended deficiency repair or replacement action. For any system or element deficiency, there can be multiple and alternative solutions for its repair or replacement. A Correction is user defined and tied to a UNIFORMAT II element, or system it is intended to address. It excludes other peripheral costs that may also be included in the packaging of repair, replacement or renewal improvements that may also be triggered by the deficiency correction.
Cost Model	A cost model is a list of facility systems which could represent the installed systems a given facility. Included in the cost model are standard unit cost estimates, gross areas, life cycles and installed dates. Also represented is the repair cost for deficient systems, replacement values. See eCOMET® cost models.
Criteria	Criteria refer to the set of requirements, guidelines or standards that are assessed and rated to develop a score.
Current Period	The Current Period is the current year plus a user defined number of forward years.
Current Replacement Value (CRV)	The Current Replacement Value (CRV) of a facility, building or system represents the hypothetical cost of rebuilding or replacing an existing facility under today's codes and construction standards, using its current configuration. It is calculated by multiplying the gross area of the facility by a square foot cost developed in that facility's cost model. Replacement cost includes construction costs and owner's additional or soft costs for fees, permits and other expenses to reflect a total project cost.
Deferred Maintenance	Deferred maintenance is condition work deferred on a planned or unplanned basis to a future budget cycle or postponed until funds are available.
Deficiency	A deficiency is a repair item that is damaged, missing, inadequate or insufficient for an intended purpose.
Deficiency Category	Deficiency Category refers to the type or class of a user defined deficiency grouping with shared or similar characteristics. Category descriptions include, but are not limited to: Accessibility Code Compliance, Appearance, Building Code Compliance, Deferred Maintenance, Energy, Environmental, Life Safety Code Compliance, and Safety.
Deficiency Distress	Deficiency Distress refers to a user-defined root cause of a deficiency. Distress descriptions are: Beyond Service Life, Damaged, Inadequate, Needs Remediation, and Missing.
Deficiency Priority	Deficiency Priority refers to a deficiency's urgency for repair as determined by the assessment team. Deficiencies were assigned a priority of 1 through 5, with Priority 1 deficiencies being the most urgent.
eCOMET®	Energy and Condition Management Estimation Technology (eCOMET®) is Parsons proprietary facility asset management software developed to provide facility managers with a state of the art, web-based tool to develop and maintain a comprehensive database of FCA data and information used for facility asset management, maintenance and repair, and capital renewal planning. eCOMET® is used by Parsons and its clients as the primary tool for collecting FCA data, preparing cost estimates, generating individual facility reports and cost estimates, and developing the overall capital renewal program.

School Assessment Report - Sagamore Hills Elementary

eCOMET® Cost Models	eCOMET® cost models are derived from RS Means Square Foot Cost Data cost models and these models are used to develop the current replacement value (CRV) and assign life cycle costs to the various systems within a building. Cost models are assigned current costs-per-square-foot to establish replacement values. The Cost models are designed to represent a client specific facility that meets local standards cost trends.
Element	Elements are the major components that comprise building systems as defined by UNIFORMAT II.
Expected Life	Also referred to as Useful Life. See Useful Life definition.
Facility	A facility refers to site(s), building(s), or building addition(s), or combinations thereof that provide a particular service or support of an educational purpose.
Facility Attributes	Customizable eCOMET® fields to identify attributes specific to a facility. These fields are part of the eCOMET® database set-up with the owner.
Facility Condition Assessment (FCA)	A facility condition assessment (FCA) is a visual inspection of buildings and grounds at a facility to identify and estimate current and future needed repairs or replacements of major systems for planning and budgeting purposes. It is typically performed for organizations that are tasked with the day to day maintenance, operation, and capital renewal (replacement) of building systems and components of a large inventory of facilities. The primary goal of an FCA is to objectively and quantifiably identify, inspect, and prioritize the repair and replacement needs of the building and ground systems (e.g., roofs, windows, doors, floor finishes, plumbing fixtures, parking lot, and sidewalks) within facilities that have either failed or have surpassed their service life, and to identify and forecast future capital replacement needs for systems that have not yet failed, but planned replacement of those systems is needed to ensure that the facilities will continue to meet the mission of the organization.
Facility Condition Index (FCI)	FCI is an industry-standard measurement of a facility's condition expressed as a percentage from 0.00% to 100.00% that is derived by dividing the cost to correct a facility's deficiencies by its Current Replacement Value (CRV). The higher the FCI the poorer the condition of a facility. After an FCI is established for all buildings within a portfolio, a building's condition can be ranked relative to other buildings. The FCI may also represent the condition of a portfolio based on the cumulative FCIs of the portfolio's facilities.
Forecast Period	The Forecast Period refers to a user defined number of years forward of the Current Period.
Gen (Generate)	The Cost Model has a Gen box for each system line item. By checking the box, eCOMET® will generate life cycle deficiencies based on the Year Installed and the Life for that system. Systems that typically do not re-generate (foundations, floor construction, roof construction, basement walls, etc.) would not have the Gen box checked as those systems would not re-generate at the end of a life cycle. In those instances, it would be more practical and cost effective to demolish the entire facility than renew those systems.
Gross Square Feet (GSF)	The area of the enclosed floor space of a building or building addition in square feet measured to the outside face of the enclosing wall.
Life cycle	Life cycle refers to the period of time that a building or site system or element can be expected to adequately serve its intended function. Parsons assigns expected life cycles to all building systems based on Building Operators and Managers of America (BOMA) recommended life cycles, manufacturers suggested life, and RS Means cost data, and client-provided historical data. BOMA standards are a nationally recognized source of life cycle data for various components and/or systems associated with facilities. RS Means is a national company specializing in construction estimating and costs.
Next Renewal	Next Renewal refers to a manually-adjusted expected useful life of a system or element based on on-site inspection either by reducing or extending the Calculated Next Renewal to more accurately reflect current conditions.

School Assessment Report - Sagamore Hills Elementary

Order of Magnitude	Order of Magnitude refers to a rough approximation made with a degree of knowledge and confidence that the budgeted, projected or estimated cost falls within a reasonable range of cost values.
Remaining Service Life (RSL)	RSL is the number of years of service remaining for a system or equipment item. It is automatically calculated based on the difference between the current year and the Calculated Next Renewal date or the Next Renewal date whichever one is the later date.
Renewal Factors	Renewal factors represent the difference in cost of renovating or replacing an existing system, rather than new construction of a building system. For example, installing a new built-up roof on an existing building would include removing and disposing of the old roof, a cost not associated with new construction. Using a renewal premium to account for demolition and other difficulty costs, Parsons typically assigns a renewal factor of 110%.
Renewal Schedule	A timeline by year that indicates when the systems will need to be renewed and the estimated price of the renewal.
Repair Cost	Repair cost is the sum of all the deficiencies associated with a building or multiple buildings/facilities. It will include any applied soft costs or City Cost Indexes.
Replacement Value	See Current Replacement Value.
Site	A facility's grounds and its utilities, roadways, landscaping, fencing and other typical land improvements needed to support a facility.
Soft Costs	Soft Costs are a construction industry term that refers to expense items that are not considered direct construction costs. Soft costs are user-defined and include architectural, engineering, management, testing, and mitigation fees, and other owner pre- and post-construction expenses.
Sustainability	Sustainability refers to the collection of policies and strategies that meet society's present needs without compromising the ability of future generations to meet their own needs.
System	System refers to building and related site work elements as described by ASTM UNIFORMAT II Classification for Building Elements (E1557-97), a format for classifying major facility elements common to most buildings. Elements usually perform a given function regardless of the design specification construction method or materials used. See also UNIFORMAT II.
System Generated Deficiency	eCOMET® automatically generates system deficiencies based on system life cycles using the systems installation dates as the base year. By adjusting the Next Renewal date ahead or behind the predicted or stated life cycle date, a system cost will come due earlier or later than the originally installed life cycle date. This utility accounts for good maintenance conditions and a longer life, or early expiration of a system life due to any number of adverse factors such as poor installation, acts of god, material defects, poor design applications and other factors that may shorten the life of a material or system. It is important to mention that the condition of the systems is not necessarily a reflection of maintenance practices, but a combination of system usage and age.
UNIFORMAT	ASTM UNIFORMAT II, Classification for Building Elements (E1557-97), a publication of the Construction Specification Institute (CSI), is a format used to classify major facility components common to most buildings. The format is based on functional elements or parts of a facility characterized by their functions without regard to the materials and methods used to accomplish them. These elements are often referred to as systems or assemblies.
Unit Price	The Unit Price (Raw) x (100% + the Additional Cost Template percentage).
Unit Price (Raw)	The actual \$/sq. ft cost being used for the building and systems. It will include adjustments for the City Cost Index applied to the facility.

School Assessment Report - Sagamore Hills Elementary

Useful Life	Also known as Expected Life, Useful Life refers to the intrinsic period of time a system or element is expected to perform as intended. Useful life is generally provided by manufacturers of materials, systems and elements through their literature, testing and experience. Useful Lives in the database are derived from the Building Owners and Managers (BOMA) organization's guidelines, RSMeans cost data, and from client- defined historical experience.
Vacant	Vacant refers to a facility that is not occupied but is a maintained facility by a district. See Abandoned.
Year Built	The year that a building or addition was originally built based on its date of substantial completion or occupancy.
Year Installed	The year a system or element was built or the most recent major renovation date where a minimum of 70% of the system's Current Replacement Value (CRV) was replaced.