

School Name: International Stu	dent Center at Fo	ormer Midw	ay ES	Grade Configuration:
Score: 54.99				
Category	Points Earned	Possible Points	Rating	Comment
Art				
Environment	0.418	0.523	Good	The art room does not have adequate air-conditioning.
Size	0.653	1.306	Poor	The art room is approximately 50% the square footage compared to the standard.
Location	0.255	0.392	Fair	The art room is located adjacent to the music room. The art room is a significant distance from many of the classrooms. The art room does not have an outside patio.
Storage/Fixed Equip	0.196	0.392	Poor	The room is equipped with only one sink. It does have a kin, but it is not working. There is not a display space for student art.
Career, Technical and Agricultura	l Education			
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
Computer Labs				
Environment	0.193	0.296	Fair	The computer lab is a general classroom that is used to teach computers. It does not have adequate HVAC.
Size	0.481	0.741	Fair	The computer lab is approximately 75% of the standard in size.
Location	0.222	0.222	Excel	
Storage/Fixed Equip	0.111	0.222	Poor	The computer lab is equipped with chalkboards. It does not have a teacher storage cabinet. It utilizes numerous power strips. It does not contain a motion sensor for lighting or security cameras.
Early Childhood Education				
Environment			N/A	
Size			N/A	The school was originally designed with early childhood education/prekindergarten facilities. These are currently being used as general education classrooms. The school does not have any early education programming.
Location			N/A	can, caacanon programming.

Page 1 of 6



School Name: International Student Center at Former Midway ES					Grade Configuration: 3-12
Score:	54.99				
Category		Points Earned	Possible Points	Rating	Comment
Early Childhood	Education				
Storage/Fixed	Equip			N/A	
General Classroo	oms				
Environment		2.247	3.457	Fair	The lighting in the classrooms in the older wing of the building is poor and needs to be replaced. The older classrooms need to be refurbished.
Size		6.913	8.641	Good	The general classrooms are approximately 85% of the standard size.
Location		1.296	2.592	Poor	The intensive English classes have students from third through ninth grade in close proximity to each other.
Storage/Fixed	Equip	1.685	2.592	Fair	Twelve classrooms have sinks. Some of the classrooms have chalkboards, other classrooms have whiteboards, and some of the classrooms don't have either one.
Instructional Res	source Rooms				
Environment		0.000	0.700	Unsat	The school does not have instructional resource rooms.
Size		0.000	1.749	Unsat	The school does not have instructional resource rooms.
Location		0.000	0.525	Unsat	The school does not have instructional resource rooms.
Storage/Fixed	Equip	0.000	0.525	Unsat	The school does not have instructional resource rooms.
Kindergarten &	Pre-Kindergarten				
Environment				N/A	
Size				N/A	
Location				N/A	
Storage/Fixed	Equip			N/A	
Learning Enviror	nment				
Learning Style	Variety	0.000	4.938	Unsat	The school was not designed for large group, small group, or individualized instructional spaces.
Interior Enviro	onment	1.284	1.975	Fair	The older portion of the building is showing significant wear and tear and needs to be refurbished. The consistency of the HVAC system between spaces is a concern. The older portion of the building has old obsolete fluorescent lighting.

Page 2 of 6



School Name: International Student Center at Former Midway ES Grade Configuration: 3-12

Score: 54.99	Points	Possible Points	Rating	Comment
Category	Earned			
Learning Environment				
Exterior Environment	0.963	1.481	Fair	The exterior of the building is showing it's age and needs to be refurbished. The building is located on multiple levels of the hill which require students to climb numerous stairs.
Environment	0.570	0.713	Good	
Media Center				
Size	0.000	1.783	Unsat	The media center is approximately 33% of the size standard.
Location	0.348	0.535	Fair	The media center is at the opposite end of the building from the intensive English programming
Storage/Fixed Equip	0.348	0.535	Fair	The office/work area is extremely small.
Music				
Environment	0.437	0.672	Fair	The music room has low ceilings, tile floors, and lacks acoustic treatments normally found in a music room.
Size	0.840	1.681	Poor	The music room is approximately 50% the size of the music room standard.
Location	0.403	0.504	Good	The music room is located the end the hall and is adjacent to general classrooms. Noise infiltration from the music room can be an issue.
Storage/Fixed Equip	0.403	0.504	Good	The music room does not have a practice room, and drinking fountain.
Performing Arts				
Environment	0.715	0.893	Good	The cafeteria serves as the school auditorium. It does not have any specialized acoustic treatments. The stage area is not ADA accessible.
Size	1.451	2.233	Fair	The stage and cafeteria are small and cannot accommodate the total student body.
Location	0.435	0.670	Fair	The cafeteria/stage is not in close proximity to the music room. The stage is located at the far end of the cafeteria.
Storage/Fixed Equip	0.000	0.670	Unsat	It does not have dressing rooms, the area does not have a lobby for the selling of tickets.
Physical Education				
Environment	1.541	2.370	Fair	The gymnasium does not have air-conditioning. The building is a separate building from the rest of the school facility and is accessed by stairs. The building does not have natural lighting.
Size	0.000	5.926	Unsat	The gymnasium is approximately 25% of the size standard.

Page 3 of 6



	ident Center at Fo			
Score: 54.99	5	5 11		
Category	Points Earned	Possible Points	Rating	Comment
Physical Education				
Location	1.155	1.778	Fair	The gymnasium is a separate building which is accessed primarily by stairs.
Storage/Fixed Equip	0.889	1.778	Poor	The gymnasium does not have a wood floor, there is no padding on the wall behind the basketball goals. It does not have any seating. The gymnasium is not equipped with any locker rooms.
Science				
Environment	0.286	0.572	Poor	The school provides science instruction in general classrooms that are not equipped with any science equipment. These rooms do not have consistent HVAC.
Size	0.929	1.429	Fair	The general classrooms that are used to teach science meet approximately 65% standard.
Location	0.343	0.429	Good	
Storage/Fixed Equip	0.000	0.429	Unsat	The science classrooms do not all have a sink, do not have lab tables, or student workstations, and do not have demonstration areas. The rooms lack adequate safety equipment. There is no storage or prep room. They do not have a dishwasher and refrigerator.
Self-Contained Special Education				
Environment	0.000	0.466	Unsat	The school does not have a self-contained special education classroom.
Size	0.000	1.166	Unsat	The school does not have a self-contained special education classroom.
Location	0.000	0.350	Unsat	The school does not have a self-contained special education classroom.
Storage/Fixed Equip	0.000	0.350	Unsat	The school does not have a self-contained special education classroom.
Non-Instructional Spaces				
Administration	0.856	1.712	Poor	The administrative areas are extremely small. They do not have built-in cabinetry for storage of supplies and materials. The school only has a reception area in the foyer. The area in front of th counter in the main office is extremely small.
Cafeteria	3.950	4.938	Good	The cafeteria does not have adequate storage for tables and chairs. It does not have a restroom in close proximity with hot water. The cafeteria has one serving line.
Food Service and Prep	4.257	6.550	Fair	The kitchen is not air-conditioned. The kitchen only has one serving line with the other serving line being in the cafeteria utilizing portable equipment. The food preparation area is small.

Page 4 of 6



School Name: International Student Center at Former Midway ES Grade Configuration: 3-12

Score: 54.99	Points Earned	Possible Points	Rating	Comment
Category				
Non-Instructional Spaces				
Clinic	0.000	0.252	Unsat	The school does not have a clinic. When children become sick the principal and administrative assistant tend to their needs.
Counseling	0.154	0.308	Poor	The counseling area does not have a reception area or conference room. The student records are stored in a small closet adjacent to the restroom in the Principal's office. They are not stored in fire/waterproof files.
Custodial and Maintenance	0.395	0.494	Good	All of the custodial sinks are wall-mounted.
Student Restrooms	0.438	0.875	Poor	The restrooms in the original building are not well lighted, properly ventilated, and are in need of significant refurbishing.
Faculty Work Space and Toilets	0.437	0.672	Fair	The school has a small room that has a copier and contains the mailboxes.
Outside Spaces				
Vehicular Traffic	1.481	2.963	Poor	The school utilizes two separate bus lanes one in front of the building in the parking lot and one side the building in a parking lot. There is a covered loading area in front of the building there is not one on the side of the building.
Pedestrian Traffic	0.216	0.332	Fair	Because of the multiple layers of the school grounds, students with disabilities cannot easily access all of the school facilities.
Parking	1.638	2.521	Fair	The school does not have adequate off-street parking for staff and visitors.
Athletic Fields and Facilities	1.707	2.626	Fair	The school does not have any athletic programming. The school does have a large open field on a lower level.
Safety and Security				
Fencing	0.916	1.409	Fair	The school does not have adequate fencing around the perimeter of the school.
Signage & Way Finding	0.088	0.176	Poor	There is not adequate internal directional signage. The signage identifying the front of the building is not adequate. The drop off lanes are not well signed. The classrooms have identifying signage beyond the room number.
Ease of Supervision	1.284	1.975	Fair	Due to the configuration of the building line of sight supervision is difficult. The school is equipped with limited security cameras.
Controlled Entrances	0.321	0.494	Fair	The school does not have a security vestibule. There is not direct line of sight supervision of the front door from the main office. The school is equipped with a card/camera entry system.

Page 5 of 6



School Name: International Studen	t Center at Fo	ormer Midw	ay ES	Grade Configuration: 3-12
Score: 54.99				
Category	Points Earned	Possible Points	Rating	Comment
Technology Readiness				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	The classrooms in the old original building do not have adequate electrical outlets and utilize extension cords.
Equity of Access, Wireless & Drops	0.670	1.000	Fair	There are areas within the building where the wireless network is not sufficient.
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Video streaming is not always consistent.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	54.99 /	100.00 =	54.99	

2/23/2016 Page 6 of 6