

School Name: Midvale ES Grade Configuration: PK-5

Score:

80.90

Category	Points Earned	Possible Points	Rating	Comment		
Art						
Environment	0.274	0.421	Fair	The art classroom is housed in a general education classroom. Its spatial configuration does not align with the instructional program needs. The natural light level is low.		
Size	0.684	1.053	Fair	The art classroom meets 77% of the space standard.		
Location	0.253	0.316	Good			
Storage/Fixed Equip	0.000	0.316	Unsat	The space is lacking adequate permanent casework, appropriate materials and project storage, sinks with clay traps, kiln with appropriate ventilation, and display case.		
Computer Labs						
Environment	0.246	0.307	Good			
Size	0.614	0.768	Good	The computer lab meets 87% of the adequate space standard.		
Location	0.184	0.230	Good	The computer lab is not centrally located, but on an upper level.		
Storage/Fixed Equip	0.184	0.230	Good			
Early Childhood Education						
Environment	0.360	0.450	Good			
Size	0.900	1.125	Good			
Location	0.270	0.337	Good			
Storage/Fixed Equip	0.270	0.337	Good			
General Classrooms						
Environment	3.528	4.410	Good	The HVAC is inconsistent.		
Size	11.025	11.025	Excel	The classrooms occupy 97% of the adequate space standard.		
Location	3.307	3.307	Excel			
Storage/Fixed Equip	2.150	3.307	Fair	There are no sinks or bubblers in the rooms.		
Instructional Resource Rooms						
Environment	0.518	0.648	Good	The HVAC is inconsistent. This classroom has had an ongoing problem with moisture.		
Size	1.620	1.620	Excel	The classroom meets 97% of the adequate space standard.		
2/22/2016				Page 1 c		

Page 1 of 5



School Name: Midvale ES Grade Configuration: PK-5

Score:

80.90

Category	Points Earned	Possible Points	Rating	Comment
Instructional Resource Rooms				
Location	0.389	0.486	Good	
Storage/Fixed Equip	0.389	0.486	Good	
Kindergarten & Pre-Kindergarten				
Environment	0.300	0.375	Good	
Size	0.751	0.938	Good	
Location	0.183	0.282	Fair	The classrooms are located some distance from loading and drop-off zones.
Storage/Fixed Equip	0.183	0.282	Fair	There are no sinks or bubblers in the room. Storage is inadequate.
Learning Environment				
Learning Style Variety	4.500	4.500	Excel	
Interior Environment	1.440	1.800	Good	The HVAC is inconsistent. Moisture is an ongoing problem.
Exterior Environment	1.080	1.350	Good	
Environment	0.702	0.877	Good	
Media Center				
Size	0.000	2.193	Unsat	The media center meets 48% of the adequate space standard.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	
Music				
Environment	0.533	0.667	Good	
Size	1.083	1.667	Fair	The music classroom is housed in a general education classroom. It meets 77% of the adequate space standard.
Location	0.325	0.500	Fair	The music classroom is located between a special needs class and a kindergarten class.
Storage/Fixed Equip	0.325	0.500	Fair	Music instruments are currently stored on the performing arts stage in the cafeteria. The classroom has inadequate storage space instruments.



School Name: Midvale ES Grade Configuration: PK-5

Score:

80.90

Category	Points Earned	Possible Points	Rating	Comment
Performing Arts				
Environment	0.354	0.544	Fair	There is no ADA access to the stage.
Size	1.088	1.360	Good	
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
Physical Education				
Environment	1.382	1.728	Good	
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	
Science				
Environment	0.000	0.450	Unsat	
Size	0.000	1.125	Unsat	There are STEM classrooms, but no regular science rooms.
Location	0.000	0.337	Unsat	
Storage/Fixed Equip	0.000	0.337	Unsat	
Self-Contained Special Education				
Environment	0.346	0.432	Good	
Size	0.864	1.080	Good	The special needs classes are housed in kindergarten classrooms meeting 93% of the adequate space standard.
Location	0.259	0.324	Good	
Storage/Fixed Equip	0.162	0.324	Poor	The present space does not have adequate storage for special needs equipment. The restrooms are not ADA sized or specially equipped. There is no hot water in these spaces.
Non-Instructional Spaces				
Administration	1.842	2.302	Good	
Cafeteria	3.600	4.500	Good	There are restrooms nearby but they do not have hot water.
2/23/2016				Page 3 of 5



School Name: Midvale ES Grade Configuration: PK-5

Score:

80.90

Category	Points Earned	Possible Points	Rating	Comment
Non-Instructional Spaces				
Food Service and Prep	4.467	5.584	Good	
Clinic	0.421	0.526	Good	
Counseling	0.211	0.263	Good	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.639	0.798	Good	There are no urinal partitions in the restrooms.
Faculty Work Space and Toilets	0.912	1.140	Good	
Outside Spaces				
Vehicular Traffic	1.440	1.800	Good	
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.585	0.731	Good	
Play Areas	1.685	2.107	Good	The hard surface play area is small.
Safety and Security				
Fencing	0.542	0.677	Good	
Signage & Way Finding	0.720	0.900	Good	The Under Surveillance and Subject to Search signs are missing.
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	This site does not have a vestibule.
Technology Readiness				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
				Daniel Auf E

Page 4 of 5



School Name: Midvale ES Grade Configuration: PK-5

Score:	80.90				
Category		Points Earned	Possible Points	Rating	Comment
Technology Re	eadiness				
Faculty & St	taff Technology	1.000	1.000	Good	
Laptop Cart	:S	1.000	1.000	Good	
Telephone/	'PA	1.000	1.000	Good	
Total		80.90 /	100.00 <b>=</b>	80.90	

2/23/2016 Page 5 of 5