

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Sagamore Hills ES

Grade Configuration: PK-5

Score: 77.44

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.337	0.421	Good	
Size	0.684	1.053	Fair	The art room meets 76% of the adequate space standard.
Location	0.205	0.316	Fair	The art classroom is located next to and across from general education classrooms allowing noise transfer.
Storage/Fixed Equip	0.205	0.316	Fair	The art room is lacking adequate storage for student work, both flat and 3-dimensional. There is no clay trap in the sink.
<i>Computer Labs</i>				
Environment	0.246	0.307	Good	
Size	0.614	0.768	Good	The computer lab meets 86% of the space standard.
Location	0.150	0.230	Fair	While the computer lab is located on an interior wall, it lies across from the schools entrance and next to the art room, allowing noise transfer.
Storage/Fixed Equip	0.184	0.230	Good	
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>General Classrooms</i>				
Environment	3.528	4.410	Good	The HVAC is inconsistent in effective climate control.
Size	11.025	11.025	Excel	General education classrooms meet 95% of the adequate space standard.
Location	2.646	3.307	Good	
Storage/Fixed Equip	2.646	3.307	Good	There are no sinks or bubblers in the classrooms.
<i>Instructional Resource Rooms</i>				
Environment	0.000	0.648	Unsat	The resource program is delivered in two portables.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Sagamore Hills ES

Grade Configuration: PK-5

Score: 77.44

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Size	0.000	1.620	Unsat	The resource program is delivered in two portables.
Location	0.000	0.486	Unsat	The resource program is delivered in two portables.
Storage/Fixed Equip	0.000	0.486	Unsat	The resource program is delivered in two portables.
<i>Kindergarten &amp; Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	The HVAC is inconsistent.
Size	0.751	0.938	Good	The kindergarten classrooms meet 86% of the adequate space standard.
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.183	0.282	Fair	The storage for the classrooms is not adequate. The sinks and restrooms need to be refurbished
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	The school has many excellent qualities for the learning environment. The HVAC is inconsistent.
Exterior Environment	1.080	1.350	Good	
Environment	0.702	0.877	Good	
<i>Media Center</i>				
Size	0.000	2.193	Unsat	The media center meets 35% of the space standard.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	
<i>Music</i>				
Environment	0.533	0.667	Good	
Size	1.083	1.667	Fair	The music space meets 76% of the adequate space standard. It is held in a general education classroom.
Location	0.400	0.500	Good	
Storage/Fixed Equip	0.325	0.500	Fair	The space is lacking sufficient storage for instruments. There is no sink or bubbler in the room.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Sagamore Hills ES

Grade Configuration:

PK-5

Score: 77.44

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.354	0.544	Fair	There is no ADA access to the stage.
Size	1.088	1.360	Good	
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.382	1.728	Good	There are floor tiles just inside the gym entrance that need replacing.
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	
<i>Science</i>				
Environment	0.000	0.450	Unsat	There is no designed space for science.
Size	0.000	1.125	Unsat	
Location	0.000	0.337	Unsat	
Storage/Fixed Equip	0.000	0.337	Unsat	
<i>Self-Contained Special Education</i>				
Environment	0.346	0.432	Good	The HVAC is inconsistent.
Size	0.864	1.080	Good	
Location	0.259	0.324	Good	
Storage/Fixed Equip	0.211	0.324	Fair	There is no hot water or changing space.
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	
Cafeteria	3.600	4.500	Good	There is no nearby restroom with hot water.
Food Service and Prep	4.467	5.584	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Sagamore Hills ES

Grade Configuration: PK-5

Score: 77.44

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Clinic	0.421	0.526	Good	
Counseling	0.211	0.263	Good	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.639	0.798	Good	There are no urinal partitions in the boys restroom.
Faculty Work Space and Toilets	1.140	1.140	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	1.170	1.800	Fair	The buses and cars share the same drop off and loading space
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.475	0.731	Fair	There is a shortage parking spaces. The school has a strong contingent of volunteers supporting the school.
Play Areas	2.107	2.107	Excel	
<i>Safety and Security</i>				
Fencing	0.440	0.677	Fair	There is no fencing around the school. The north boundary of the school borders a creek. This allows for possible access.
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	There is no vestibule.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Sagamore Hills ES

Grade Configuration: PK-5

Score: 77.44

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

---

## *Technology Readiness*

Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
<b>Total</b>	<b>77.44</b>	<b>100.00</b>	<b>=</b>	<b>77.44</b>