

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Cedar Grove MS

Grade Configuration:

6-8

Score: 87.43

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.464	0.580	Good	
Size	1.451	1.451	Excel	The large art space and its three adjacent smaller rooms meet the size standard.
Location	0.435	0.435	Excel	There is access to an outdoor patio.
Storage/Fixed Equip	0.283	0.435	Fair	There is limited storage space in one of the side room. The sinks in the art classroom do not have clay traps. There is one kiln, but two vent systems in the kiln room.
<i>Career, Technical and Agricultural Education</i>				
Environment	0.971	1.214	Good	The three career technical education classroom/labs do not have natural light.
Size	1.973	3.035	Fair	The digital design technology lab meets the designated size standard. The business lab and the family lab are undersized.
Location	0.728	0.911	Good	
Storage/Fixed Equip	0.592	0.911	Fair	The digital design has a lab with immovable wooden multi- station carousels, and a lecture room with tiered concrete flooring.
<i>Computer Labs</i>				
Environment	0.270	0.270	Excel	
Size	0.675	0.675	Excel	
Location	0.132	0.202	Fair	Several computer labs have exterior windows with no secure coverings.
Storage/Fixed Equip	0.162	0.202	Good	There are no motion sensors in the computer labs. Surveillance cameras in the adjacent hallways can view the entrances.
<i>General Classrooms</i>				
Environment	3.510	3.510	Excel	Nearly all general classrooms have windows, natural light, good lighting, and good HVAC.
Size	8.775	8.775	Excel	The vast majority of general classrooms meet 90% or more of the size standard.
Location	2.632	2.632	Excel	
Storage/Fixed Equip	2.632	2.632	Excel	Nearly all general classrooms are identical in fixed equipment, with a lockable wardrobe, cabinet and case work with counters, and Promethean boards.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Cedar Grove MS

Grade Configuration:

6-8

Score: 87.43

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.590	0.737	Good	
Size	1.474	1.842	Good	
Location	0.442	0.553	Good	
Storage/Fixed Equip	0.442	0.553	Good	
<i>Learning Environment</i>				
Learning Style Variety	4.500	4.500	Excel	The school is bright with modern features, fixtures, and surfaces inside and out, lots of natural light, wide and straight hallways. Spaces are available for learning activities outside the traditional classroom setting.
Interior Environment	1.800	1.800	Excel	The school is bright with modern features, fixtures, and surfaces inside and out, lots of natural light, wide and straight hallways.
Exterior Environment	1.350	1.350	Excel	The school facility and grounds are clean, well-kept and visually appealing.
Environment	0.668	0.835	Good	There are inset ceiling skylights to provide natural light.
<i>Media Center</i>				
Size	1.670	2.088	Good	The media center has all of the required spaces, including office, workrooms, conference room, storage rooms, and a restroom. In total, the media center is roughly 85% of the size standard.
Location	0.626	0.626	Excel	
Storage/Fixed Equip	0.501	0.626	Good	Central area bookcases are roughly 5 feet high, limiting visibility. There are a set of drop poles in the middle of the room providing power connections to the computer banks.
<i>Music</i>				
Environment	0.530	0.662	Good	There are three rooms designed for music instruction. One is not currently used for music. One of the active music rooms has no natural light.
Size	1.076	1.655	Fair	The band room meets or exceeds the size standard, while the second practice room is roughly half the required size. A third room meets the size standard.
Location	0.497	0.497	Excel	
Storage/Fixed Equip	0.397	0.497	Good	A sink and drinking water are not available in the music rooms, and bathrooms are in a nearby hallway. There are storage, office space, and practice rooms available in all three.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Cedar Grove MS

Grade Configuration:

6-8

Score: 87.43

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.301	0.377	Good	This is a shared space in the cafeteria with a stage. The room has no acoustical treatments to reduce noise. The stage is ADA accessible from the rear only.
Size	0.612	0.942	Fair	There is no lobby and no storage or dressing room spaces.
Location	0.226	0.283	Good	
Storage/Fixed Equip	0.184	0.283	Fair	It has curtains, lighting and a portable sound system, but no other technology equipment. Storage rooms behind the stage are not directly accessible from inside the cafetorium.
<i>Physical Education</i>				
Environment	2.160	2.160	Excel	
Size	5.400	5.400	Excel	
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.296	1.620	Good	
<i>Science</i>				
Environment	0.859	0.859	Excel	Science rooms are set up with appropriate work tables, chairs, and some natural light.
Size	2.147	2.147	Excel	All science labs share storage and preparation rooms. There are two sets of science quads that share one preparation/storage room per quad. There are two pairs of rooms that share a preparation room per pair. Each science lab is about 95% of the size standard.
Location	0.644	0.644	Excel	Quad rooms have access to adjacent courtyards.
Storage/Fixed Equip	0.419	0.644	Fair	Not all required safety equipment is readily available in all lab space or adjacent preparation rooms. Missing items differ by room. All suites have fire extinguishers.
<i>Self-Contained Special Education</i>				
Environment	0.393	0.491	Good	
Size	0.983	1.228	Good	The rooms are somewhat undersized.
Location	0.239	0.368	Fair	The rooms are located towards the end of their respective instructional hallways away from other areas of the school such as media center and cafeteria. Changing tables, and personal care supplies are located in ADA restrooms down the hall.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Cedar Grove MS

Grade Configuration:

6-8

Score: 87.43

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Storage/Fixed Equip	0.239	0.368	Fair	The is inadequate storage space in the rooms for required equipment. There is no designated family living center space outside their rooms.
<i>Non-Instructional Spaces</i>				
Administration	1.886	1.886	Excel	The school has ample office, meeting, and work space within their respective halls.
Cafeteria	2.880	3.600	Good	This is a cafetorium with a stage. There is no storage space for tables and chairs directly accessible from the cafeteria. Nearby restrooms do not have hot water.
Food Service and Prep	3.344	5.144	Fair	There is no HVAC in the kitchen area.
Clinic	0.000	0.306	Unsat	There is no clinic at the school.
Counseling	0.382	0.382	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.668	0.835	Good	Some restrooms do not have partitions between urinals.
Faculty Work Space and Toilets	0.652	0.815	Good	There is a teacher workroom with appropriate fixtures, casework, equipment, and a sink. Restrooms are nearby.
<i>Outside Spaces</i>				
Vehicular Traffic	2.880	3.600	Good	Student drop-off is routed through the front parking lot. Bus drop-off and pick up is separate and routed around the school to the main gym entry.
Pedestrian Traffic	0.311	0.389	Good	
Parking	0.774	0.774	Excel	
Athletic Fields and Facilities	0.471	0.942	Poor	There are two tennis courts, a practice football/soccer field with surrounding asphalt track, and a single ball field. There are no fixtures, storage or seating at any field. The track and ball field are in need of repair. The track surface is cracking.
<i>Safety and Security</i>				
Fencing	0.559	0.698	Good	
Signage & Way Finding	0.585	0.900	Fair	A number of rooms do not have permanent room numbers posted.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Cedar Grove MS

Grade Configuration: 6-8

Score: 87.43

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Ease of Supervision	2.160	2.700	Good	The school has long straight hallways providing good sight lines. There are some exterior areas not completely visible by security cameras.
Controlled Entrances	0.292	0.450	Fair	The main entry has card/camera security access with a security office as well as the main office visibility on either side of the entry lobby.
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	Several server rooms are not properly cooled.
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	All have access to desktops and interactive boards.
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	87.43 / 100.00 =		87.43	