

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Henderson MS

Grade Configuration: 6-8

Score: 70.89

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.311	0.622	Poor	The lighting fixtures are older in design and have less capability in providing consistent and non-glaring light. The HVAC system is inconsistent. The cinderblock walls diminish acoustical quality, and the older deteriorating facility does not support positive aesthetics.
Size	1.556	1.556	Excel	
Location	0.467	0.467	Excel	
Storage/Fixed Equip	0.374	0.467	Good	
<i>Career, Technical and Agricultural Education</i>				
Environment			N/A	Henderson Middle School does not include a Career Tech Ed program.
Size			N/A	Henderson Middle School does not include a Career Tech Ed program.
Location			N/A	Henderson Middle School does not include a Career Tech Ed program.
Storage/Fixed Equip			N/A	Henderson Middle School does not include a Career Tech Ed program.
<i>Computer Labs</i>				
Environment	0.145	0.290	Poor	The lighting fixtures are older in design and have less capability in providing consistent and non-glaring light. The HVAC system is inconsistent. The cinderblock walls diminish acoustical quality, and the older deteriorating facility does not support positive aesthetics.
Size	0.579	0.724	Good	
Location	0.174	0.217	Good	
Storage/Fixed Equip	0.109	0.217	Poor	The computer labs lack adequate storage, motion sensor lighting, and security cameras in the rooms.
<i>General Classrooms</i>				
Environment	2.447	3.764	Fair	The HVAC system is inconsistent throughout the main building. Noise bleeds into the rooms from the halls, and the rooms need updating and refurbishing.
Size	6.116	9.410	Fair	Classrooms are approximately 78% of the standard in size.
Location	2.258	2.823	Good	
Storage/Fixed Equip	2.258	2.823	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Henderson MS

Grade Configuration: 6-8

Score: 70.89

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.000	0.790	Unsat	The Instructional Resource program is located in the portable buildings.
Size	0.000	1.975	Unsat	The Instructional Resource program is located in the portable buildings.
Location	0.000	0.593	Unsat	The Instructional Resource program is located in the portable buildings.
Storage/Fixed Equip	0.000	0.593	Unsat	The Instructional Resource program is located in the portable buildings.
<i>Learning Environment</i>				
Learning Style Variety	3.137	4.825	Fair	Henderson Middle School lacks flexible learning spaces for more than 30% of the programs.
Interior Environment	0.965	1.930	Poor	The lighting fixtures are older in design and have less capability in providing consistent and non-glaring light. The HVAC system is inconsistent throughout the main building. The cinderblock walls diminish acoustical quality, and the older deteriorating facility does not support positive aesthetics.
Exterior Environment	0.724	1.448	Poor	The exterior areas do include some outdoor labs and art patios, it does not include covered instructional areas and social areas.
Environment	0.448	0.896	Poor	The media center's lighting fixtures are older in design and have less capability in providing consistent and non-glaring light. The HVAC system is inconsistent. The older deteriorating facility does not support positive aesthetics, and it lacks flexible learning spaces.
<i>Media Center</i>				
Size	1.455	2.239	Fair	The media center is 79% of the District standard for size.
Location	0.537	0.672	Good	
Storage/Fixed Equip	0.537	0.672	Good	
<i>Music</i>				
Environment	0.461	0.710	Fair	The HVAC system is inconsistent. The area needs updating and/or refurbishing.
Size	1.775	1.775	Excel	
Location	0.532	0.532	Excel	
Storage/Fixed Equip	0.426	0.532	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Henderson MS

Grade Configuration: 6-8

Score: 70.89

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.202	0.404	Poor	The performing arts lighting fixtures are older in design and have little capability in providing consistent and non-glaring light. The HVAC system is inconsistent. The cinderblock walls diminish acoustical quality, and it lacks updating and/or refurbishing.
Size	0.808	1.010	Good	
Location	0.303	0.303	Excel	
Storage/Fixed Equip	0.152	0.303	Poor	The performing arts area lacks ADA stage access, adequate storage and a sound system.
<i>Physical Education</i>				
Environment	1.158	2.316	Poor	The PE area HVAC system is inconsistent. It needs updating and/or refurbishing, it lacks natural lighting, and the acoustics can be very loud.
Size	5.791	5.791	Excel	
Location	1.390	1.737	Good	The PE area is not capable of being secured from other parts of the building.
Storage/Fixed Equip	1.737	1.737	Excel	
<i>Science</i>				
Environment	0.599	0.921	Fair	The HVAC system is inconsistent. Noise bleeds into the rooms from the halls, and the rooms need updating and/or refurbishing.
Size	2.302	2.302	Excel	
Location	0.553	0.691	Good	
Storage/Fixed Equip	0.553	0.691	Good	
<i>Self-Contained Special Education</i>				
Environment	0.263	0.527	Poor	The HVAC system is inconsistent. The noise bleeds into the room from the halls and the room needs renovating and updating.
Size	0.658	1.317	Poor	The special education resource program areas lack a family living center, an ADA restroom with hot water, and adequate storage.
Location	0.316	0.395	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Henderson MS

Grade Configuration: 6-8

Score: 70.89

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Storage/Fixed Equip	0.257	0.395	Fair	The special education resource program areas lack adequate permanent casework and adequate storage for special needs equipment.
<i>Non-Instructional Spaces</i>				
Administration	1.011	2.023	Poor	The administration area lacks meeting space in the principal's office, adequate storage, and a conference room. It also lacks updating and/or refurbishing.
Cafeteria	3.088	3.860	Good	
Food Service and Prep	3.586	5.516	Fair	Food service serves only two lunch lines, due to the configuration of the cafeteria and food services area. The student population suggests three lunch lines.
Clinic	0.000	0.328	Unsat	Henderson Middle School does not house a formal clinic.
Counseling	0.205	0.410	Poor	The HVAC system is inconsistent in the counseling area. The aesthetics are loud, the area lacks updating and/or refurbishing, and it lacks a conference room.
Custodial and Maintenance	0.314	0.483	Fair	Custodial services lacks a receiving area and floor mop sinks.
Student Restrooms	0.716	0.896	Good	
Faculty Work Space and Toilets	0.699	0.874	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	2.509	3.860	Fair	Due to one entrance and egress point, vehicular traffic lacks good separation. There is significant traffic congestion during drop-off and dismissal times.
Pedestrian Traffic	0.334	0.417	Good	
Parking	0.664	0.830	Good	Parking areas lack adequate lighting.
Athletic Fields and Facilities	0.657	1.010	Fair	The athletic fields are not easily accessible or adjacent to the school, and they lack ADA restrooms accessibility within 150 feet.
<i>Safety and Security</i>				
Fencing	0.599	0.749	Good	
Signage & Way Finding	0.627	0.965	Fair	The school lacks adequate public interior and exterior signage including "Under Surveillance" and "Subject to Search."
Ease of Supervision	1.882	2.895	Fair	Henderson Middle School lacks adequate lighting and security cameras.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Henderson MS

Grade Configuration: 6-8

Score: 70.89

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Controlled Entrances	0.000	0.483	Unsat	Henderson Middle School lacks ADA access in the front, a vestibule, and a controlled entrance system.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	Some science areas lack adequate electrical power.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Internet connectivity has been inconsistent the majority of the time.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	70.89	100.00	=	70.89