

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Panola Way ES

Grade Configuration: PK-5

Score: 64.48

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.281	0.432	Fair	The HVAC is inconsistent throughout the building and broken in other parts of the building. Some rooms are hot and others very cold. The art room has ceiling tile. Walls and cabinetry look worn and tired. Lighting is inadequate in the art room, making it dark.
Size	0.864	1.080	Good	
Location	0.211	0.324	Fair	The art room does not have direct access to the outside. There are no outside patio areas.
Storage/Fixed Equip	0.211	0.324	Fair	There is one sink, which does not have a clay trap. There is bulletin board space to display 2-D projects but no designated display space for 3-D projects. There is no kiln. There is no non-flammable shelving.
<i>Computer Labs</i>				
Environment	0.205	0.315	Fair	The HVAC is inconsistent. Computer labs are very hot. The music room has ceiling tile. Ceiling is regular height. Walls and cabinetry look worn and tired. Lighting is inadequate.
Size	0.512	0.787	Fair	The two computer labs are approximately 77% and 85% of the standard.
Location	0.236	0.236	Excel	
Storage/Fixed Equip	0.118	0.236	Poor	There was no teacher cabinet, storage cabinet or bookcase in the computer labs. Power strips were used liberally. The classroom had no security camera or motion sensor lighting. The lab had fixed rows.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment	2.262	4.523	Poor	The HVAC is inconsistent. Most of the rooms have ceiling tile. Walls, cabinetry, and carpet look worn and tired. Lighting is inadequate in some rooms.
Size	9.046	11.308	Good	The general classrooms range from 85% to 96% of the standard.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Panola Way ES

Grade Configuration: PK-5

Score: 64.48

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Location	2.205	3.392	Fair	The fourth grade classrooms are directly across from the cafeteria which houses the band and orchestra. Noise infiltration is an issue. First grade classes are not close to the office.
Storage/Fixed Equip	1.696	3.392	Poor	Most classrooms do not have a wall of cabinetry. Many do not have lockable teacher cabinets. There are no cubbies. Most of the classrooms do not have a sink or bubbler. Some of the classrooms are in rooms with cabinetry too low for the age of the students.
<i>Instructional Resource Rooms</i>				
Environment	0.332	0.665	Poor	The HVAC is inconsistent. Most of the rooms have ceiling tile. Walls and cabinetry look worn and tired. Lighting is inadequate in some rooms. The speech teacher is in a former storage room with no ventilation. Noise intrusion is an issue.
Size	1.080	1.662	Fair	The special education resource rooms are approximately 75% to 88% of the standard. The math resource teacher has no designated space. The speech teacher is in a former closet. The OT/PT's use a conference room in the media center. In each instructional resource room, two teachers and two Para educators share a regular classroom space. With four desks, there is limited instructional space.
Location	0.249	0.498	Poor	Spaces are not located conveniently.
Storage/Fixed Equip	0.249	0.498	Poor	There is no storage for the math resource teacher and limited storage for the speech teacher. There is limited storage for each teacher.
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.192	0.385	Poor	The HVAC is inconsistent. Most of the rooms have ceiling tile. Walls, cabinetry, and carpet look worn and tired. Lighting is inadequate in some rooms.
Size	0.481	0.962	Poor	There are no restrooms in any of the prekindergarten or kindergarten classrooms.
Location	0.144	0.289	Poor	The kindergarten and prekindergarten classrooms are on the opposite end of the building from the bus drop-off/pick-up area.
Storage/Fixed Equip	0.188	0.289	Fair	One of the prekindergarten classrooms does not have a sink or bubbler.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Panola Way ES

Grade Configuration: PK-5

Score: 64.48

Category	Points Earned	Possible Points	Rating	Comment
<i>Learning Environment</i>				
Learning Style Variety	0.000	4.615	Unsat	There are no designed spaces that support small group learning or shared learning spaces for two classroom. Spaces are not flexible. There is not space for differentiated instruction to accommodate multiple teaching and learning styles. The facility lacks space for storage of student projects.
Interior Environment	0.923	1.846	Poor	The HVAC is inconsistent. Most of the rooms have ceiling tile. Walls, cabinetry, and carpeted areas look worn and tired. Lighting is inadequate in some rooms.
Exterior Environment	0.692	1.385	Poor	There are no outside areas designated for outdoor learning labs, art patios, or covered/open instructional areas. There is one small social gathering space.
Environment	0.450	0.900	Poor	The media center is dark and uninviting. The HVAC is inconsistent so the media center can be warm at times. The carpet is extremely worn creating a safety hazard. The casework and furniture are showing their age, being very worn. There is no natural lighting. The book cases are sparsely filled. There are no inviting spaces for children to curl up and read.
<i>Media Center</i>				
Size	1.462	2.249	Fair	The media center is approximately 65% of the standard.
Location	0.540	0.675	Good	
Storage/Fixed Equip	0.439	0.675	Fair	The computers are fixed in rows based on the electrical outlets and wiring. The casework is not on casters. There is no lockable display space near the entrance to the media center. The carpet and paint are showing their age. There are no upholstery student chairs. There are not 32 computer stations.
<i>Music</i>				
Environment	0.444	0.684	Fair	The HVAC is inconsistent. The music room has ceiling tile. Ceiling is regular height. Walls and cabinetry look worn and tired. Lighting is inadequate.
Size	1.368	1.709	Good	
Location	0.410	0.513	Good	
Storage/Fixed Equip	0.410	0.513	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Panola Way ES

Grade Configuration: PK-5

Score: 64.48

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.363	0.558	Fair	The cafeteria is showing its age and is worn. The curtains on the stage are faded and worn. The stage floor is showing signs of wear.
Size	1.395	1.395	Excel	
Location	0.418	0.418	Excel	
Storage/Fixed Equip	0.272	0.418	Fair	There is little storage for props or equipment.
<i>Physical Education</i>				
Environment	1.152	1.772	Fair	The gym has no functioning HVAC. It was uncomfortably hot. The lighting was inadequate.
Size	4.431	4.431	Excel	
Location	1.329	1.329	Excel	
Storage/Fixed Equip	1.329	1.329	Excel	
<i>Science</i>				
Environment	0.300	0.462	Fair	The HVAC is inconsistent. The science room has ceiling tile. Walls and cabinetry look worn and tired. Lighting is inadequate.
Size	0.923	1.154	Good	
Location	0.277	0.346	Good	
Storage/Fixed Equip	0.277	0.346	Good	
<i>Self-Contained Special Education</i>				
Environment	0.222	0.443	Poor	The HVAC is inconsistent. Most of the rooms have ceiling tile. Walls and cabinetry look worn and tired. Lighting is inadequate in some rooms. The special education classrooms are not warm and inviting spaces.
Size	0.000	1.108	Unsat	There is no family living center. There is no ADA restroom with a changing table and storage for toiletry supplies. There is no hot water in the restroom.
Location	0.332	0.332	Excel	
Storage/Fixed Equip	0.166	0.332	Poor	Neither of the two special education classrooms have a wall of cabinetry. These two classrooms do not have a sink or bubbler. There is not special needs storage. There is no family living center.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Panola Way ES

Grade Configuration: PK-5

Score: 64.48

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Administration	1.535	2.361	Fair	The office is not an adequate size for the population of the school. The student files are housed in a storage room with no fireproof door or fire/water proof file cabinets. The administration area is worn and looks tired. The reception/secretary area is dark.
Cafeteria	2.308	4.615	Poor	The cafeteria is used for the band and orchestra teachers. Table and chair storage is inadequate. There is no hot water in the student restrooms adjacent to the cafeteria.
Food Service and Prep	3.722	5.727	Fair	The food service area is very warm. There was lukewarm water in the food service restroom. There is no natural light.
Clinic	0.351	0.540	Fair	There is only one cot. There is a restroom but it is not an ADA restroom.
Counseling	0.135	0.270	Poor	There is no reception area for either of the counselors. There is no conference room for the counselors. The student records are stored in the administration area in file cabinets that are not fire or water proof.
Custodial and Maintenance	0.231	0.462	Poor	There was bug spray and other chemicals in an unlocked closet in the custodial room. The custodial rooms were old, dirty and disorganized.
Student Restrooms	0.409	0.819	Poor	The student restrooms are not well ventilated. The boys restrooms have a definite smell. There is no privacy panel between the urinals. There is no hot water. There are no restrooms in prekindergarten and kindergarten. There is no ADA unisex restroom in the school.
Faculty Work Space and Toilets	0.760	1.170	Fair	There is one workroom with two copiers for almost 50 staff. This is not an adequate space for the number of staff. The room is very dark and uninviting.
<i>Outside Spaces</i>				
Vehicular Traffic	0.000	1.846	Unsat	There is no covered area for the bus loading area. There is not adequate lighting in the bus loading area. The designated bus area cannot hold all the busses. There is a designated car pick up/drop off area but it is not separated from the busses.
Pedestrian Traffic	0.449	0.898	Poor	There are no marked crosswalks for pedestrians from parked cars to the school entrance.
Parking	0.487	0.750	Fair	There are signs designating three visitor parking stalls. Visitor and bus parking is inadequate. The parking lot is not well lit.
Play Areas	1.080	2.161	Poor	There is no hard surfaced area. The play area has some ADA equipment, but there is no hard surface that would allow ADA access to the equipment

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Panola Way ES

Grade Configuration: PK-5

Score: 64.48

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Fencing	0.694	0.694	Excel	
Signage & Way Finding	0.462	0.923	Poor	There is no signage on the exterior of the building to direct visitors to the front entrance. There is no signage inside the building directing people to the administration area, auditorium, gym, etc. There is only signage identifying the bus lane and stating when it is only a bus lane. There are no signs for "Under Surveillance" and "Subject to Search".
Ease of Supervision	1.385	2.769	Poor	The lights do not work in the parking lot. There are security cameras but not enough to have full view of all parts of the building exterior. The parking lots do not have security cameras.
Controlled Entrances	0.462	0.462	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	The space for the IDF & MDF equipment is not designed to hold this equipment. The space is not climate controlled and is very hot.
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	0.670	1.000	Fair	The facility has T1 based connectivity.
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	64.48	100.00	=	64.48