

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stephenson HS

Grade Configuration: 9-12

Score: 77.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.389	0.599	Fair	There is no natural light.
Size	1.496	1.496	Excel	
Location	0.292	0.449	Fair	Only a small corner of the room is situated on an exterior wall of the school. It has a door to the outside.
Storage/Fixed Equip	0.292	0.449	Fair	There is inadequate storage and display space.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.000	1.538	Fair	The school store is very warm and humid (HVAC issues), and a portion of the broadcast production area is used as classroom space.
Size	2.499	3.845	Fair	The combined ROTC spaces (two classrooms, office and storage rooms) totals approximately 65% of the size standard. There is no drill pad. The broadcast/video space is also about 60% of the size required.
Location	0.923	1.154	Good	
Storage/Fixed Equip	0.750	1.154	Fair	The ROTC program lacks adequate storage space. The engineering technology space has old quad computer carrels, carpeted flooring in the main instructional area, and old work tables are not appropriate for the current instructional program.
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	Those rooms on ground floor exterior walls do not have security covers on windows.
Size	0.675	0.675	Excel	
Location	0.132	0.202	Fair	Most general computer labs are located adjacent to the media center, but some distance from the freshmen academy.
Storage/Fixed Equip	0.132	0.202	Fair	Most computer labs lack storage, had no motion sensors, and security cameras are located in adjacent hallways at varying distances from the entry door.
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	Nearly all classrooms have windows, but there are inconsistencies in HVAC on an individual room basis.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stephenson HS

Grade Configuration: 9-12

Score: 77.78

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Size	7.020	8.775	Good	Nearly all classrooms in the main building are within 90% or better of the size standard, while the vast majority of classrooms in the Freshmen Academy are approximately 75% of the size standard.
Location	2.632	2.632	Excel	
Storage/Fixed Equip	1.711	2.632	Fair	Some classrooms do not have an adequate number of computers.
<i>Instructional Resource Rooms</i>				
Environment	0.359	0.719	Poor	There are very few instructional resource rooms available throughout the school.
Size	1.438	1.797	Good	
Location	0.431	0.539	Good	
Storage/Fixed Equip	0.431	0.539	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	There are individual room HVAC issues throughout the school, Hall intersections are extremely congested during class changes.
Exterior Environment	1.080	1.350	Good	There is a tiered outdoor classroom and a greenhouse behind the main school building. There is an outside patio area near the freshmen academy cafeteria.
Environment	0.607	0.759	Good	The media center does not have natural light.
<i>Media Center</i>				
Size	1.897	1.897	Excel	The media center with all of its offices, storage and workrooms meets the size standard.
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.455	0.569	Good	
<i>Music</i>				
Environment	0.347	0.534	Fair	The freshmen music room is a general classroom with no acoustical treatments and features applicable for music instruction.
Size	1.336	1.336	Excel	All three music rooms meet size standards.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stephenson HS

Grade Configuration: 9-12

Score: 77.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Location	0.321	0.401	Good	The band and orchestra rooms are located adjacent to the stage and performing arts auditorium. The choral room is at the far end of the freshmen academy building.
Storage/Fixed Equip	0.261	0.401	Fair	There is no fixed conductor podiums, the choral room has fixed metal risers, and access to water is in the adjacent hallways.
<i>Performing Arts</i>				
Environment	0.188	0.289	Fair	The front of the stage is not ADA accessible. The seating area has lighting and inconsistent HVAC issues.
Size	0.469	0.721	Fair	There is no black box drama space. The current dance instruction is held in a converted regular classroom located in the freshmen academy building with no adjacent changing area.
Location	0.141	0.216	Fair	The auditorium is adjacent to the cafeteria and access to other parts of the school cannot be completely restricted. The backstage loading access to outside is down a regular hallway.
Storage/Fixed Equip	0.108	0.216	Poor	The dance room has no storage, no changing area, and no sprung/wooden floor. Theater lighting and audio equipment are not operational.
<i>Physical Education</i>				
Environment	1.728	2.160	Good	
Size	3.510	5.400	Fair	In total the gym, locker rooms, weight and wrestling rooms meet the physical education space size standard. The gym itself accounts for approximately 70% of the required space. However, there is no auxiliary gym.
Location	1.296	1.620	Good	
Storage/Fixed Equip	1.296	1.620	Good	
<i>Science</i>				
Environment	0.597	0.747	Good	
Size	1.494	1.867	Good	Roughly two-thirds of the science lab/classrooms meet the size standard, while one-third are just under 90% of the standard.
Location	0.560	0.560	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stephenson HS

Grade Configuration: 9-12

Score: 77.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Science</i>				
Storage/Fixed Equip	0.364	0.560	Fair	Although the labs have work stations around the perimeter of each room, there are moveable work tables and chairs in the center of each. Prep rooms have designated hazardous materials storage space, but some are fixed wooden cabinetry with fireproof lining.
<i>Self-Contained Special Education</i>				
Environment	0.383	0.479	Good	
Size	0.779	1.198	Fair	The moderate needs students are located in two undersized general classrooms. The severe needs students are in a multi-room space that includes a family living center, and in total exceeds the space standard.
Location	0.288	0.359	Good	
Storage/Fixed Equip	0.288	0.359	Good	
<i>Non-Instructional Spaces</i>				
Administration	1.879	2.349	Good	
Cafeteria	2.340	3.600	Fair	The cafeteria is located near the front main entry and is the center intersection of the building's two main hallways. There is not storage space in the cafeteria for tables and chairs.
Food Service and Prep	3.676	4.595	Good	
Clinic	0.000	0.214	Unsat	There is no clinic.
Counseling	0.681	0.681	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.534	0.821	Fair	Some restrooms have ventilation issues and no partitions between urinals.
Faculty Work Space and Toilets	0.513	0.641	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	0.585	0.900	Fair	Although the bus drop-off lanes are separate, and parents are diverted through the adjacent front parking lot, parents use the bus lanes as well.
Pedestrian Traffic	0.573	0.882	Fair	Students dropped off by parents must cross the bus lanes, and there are no designated crosswalks.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stephenson HS

Grade Configuration: 9-12

Score: 77.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Outside Spaces</i>				
Parking	1.233	1.897	Fair	There is ample parking around the school, but light and camera coverage is inadequate.
Athletic Fields and Facilities	1.618	2.488	Fair	The school has one grass practice field shared by football and soccer. Only the baseball field is lighted, there are minimal bleachers, no drinking fountain, no restrooms and the fields are not easily ADA accessible.
<i>Safety and Security</i>				
Fencing	0.495	0.762	Fair	Fencing does not cover the full perimeter of the rear of the school property that is wooded and adjacent to neighborhoods.
Signage & Way Finding	0.720	0.900	Good	Only the Drug-Free Zone and Weapons-Free school signs are visible.
Ease of Supervision	1.755	2.700	Fair	Interior sight lines are good, but security cameras at end of hallways do not provide detailed views of a reasonable distance down the halls.
Controlled Entrances	0.292	0.450	Fair	There is no security vestibule at the main entry points of the school or the Freshmen Academy.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	There are not enough power outlets in the designated cart storage room to charge all at once, so some carts are charged in a second room without the required security features.
Telephone/PA	1.000	1.000	Good	
Total	77.78	100.00	=	77.78