Building S.P.A.C.E.S Facility Educational Adequacy Report

School Name: Livsey ES	**Grade Configuration:**	PK-5
Score: 70.61		

Category	Points Earned	Possible Points	Rating	Comment
Art				
Environment	0.000	0.432	Unsat	Art instruction is held in a portable classroom.
Size	0.000	1.080	Unsat	Art instruction is held in a portable classroom.
Location	0.000	0.324	Unsat	Art instruction is held in a portable classroom.
Storage/Fixed Equip	0.000	0.324	Unsat	Art instruction is held in a portable classroom.
Computer Labs				
Environment	0.205	0.315	Fair	Has a post-construction added wall, there is noise transfer between adjacent rooms, and a noisy wall AC unit.
Size	0.512	0.787	Fair	The computer room is about 65% of the size standard.
Location	0.189	0.236	Good	
Storage/Fixed Equip	0.154	0.236	Fair	There is limited storage, no motion sensor and a security camera is in the hallway that captures the entry door area.
Early Childhood Education				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	
General Classrooms				
Environment	3.618	4.523	Good	
Size	9.046	11.308	Good	
Location	2.714	3.392	Good	
Storage/Fixed Equip	2.714	3.392	Good	
Instructional Resource Rooms				
Environment	0.532	0.665	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report

School Name:	Livsey ES	
Score:	70.61	

| | **Grade Configuration:** | **PK-5** |

Category	Points Earned	Possible Points	Rating	Comment
Instructional Resource Rooms				
Size	1.329	1.662	Good	
Location	0.399	0.498	Good	
Storage/Fixed Equip	0.399	0.498	Good	
Kindergarten & Pre-Kindergarten				
Environment	0.308	0.385	Good	
Size	0.770	0.962	Good	The kindergarten and prekindergarten rooms on average meet about 85% of the size standard.
Location	0.231	0.289	Good	
Storage/Fixed Equip	0.231	0.289	Good	
Learning Environment				
Learning Style Variety	3.692	4.615	Good	
Interior Environment	1.477	1.846	Good	
Exterior Environment	0.900	1.385	Fair	The exterior of the building is aged and showing wear and tear.
Environment	0.720	0.900	Good	
Media Center				
Size	0.000	2.249	Unsat	media center is less than half the size standard.
Location	0.540	0.675	Good	
Storage/Fixed Equip	0.540	0.675	Good	
Music				
Environment	0.000	0.684	Unsat	Music instruction is held in a portable classroom.
Size	0.000	1.709	Unsat	Music instruction is held in a portable classroom.
Location	0.000	0.513	Unsat	Music instruction is held in a portable classroom.
Storage/Fixed Equip	0.000	0.513	Unsat	Music instruction is held in a portable classroom.

Building S.P.A.C.E.S Facility Educational Adequacy Report

School Name:	Livsey ES			Grade Configuration:	PK-5

Score: 70.61

Category	Points Earned	Possible Points	Rating	Comment
Performing Arts				
Environment	0.446	0.558	Good	
Size	1.395	1.395	Excel	
Location	0.418	0.418	Excel	
Storage/Fixed Equip	0.272	0.418	Fair	There is no storage related to the stage.
Physical Education				
Environment	1.152	1.772	Fair	The two exhaust fans create considerable noise.
Size	3.545	4.431	Good	
Location	1.329	1.329	Excel	
Storage/Fixed Equip	1.063	1.329	Good	There is no storage related to the stage.
Science				
Environment	0.369	0.462	Good	
Size	0.923	1.154	Good	
Location	0.277	0.346	Good	
Storage/Fixed Equip	0.277	0.346	Good	
Self-Contained Special Education				
Environment	0.354	0.443	Good	
Size	0.720	1.108	Fair	The two self-contained rooms are less than the size standard. There is no family living center.
Location	0.266	0.332	Good	
Storage/Fixed Equip	0.216	0.332	Fair	ADA bathrooms with space for changing table and supplies are located nearby down the hall.
Non-Instructional Spaces				
Administration	1.181	2.361	Poor	The main entry is not visible form the reception desk, there is no conference room, and limited storage and work area in the administrative office suite. Teacher mailboxes are in the small waiting area.

Building S.P.A.C.E.S Facility Educational Adequacy Report

School Name: Livsey ES

Score: 70.61

Grade Configuration: PK-5

Category	Points Earned	Possible Points	Rating	Comment
Non-Instructional Spaces				
Cafeteria	3.000	4.615	Fair	There is one serving line, no storage for tables and chairs, and the cafeteria has little noise reduction features.
Food Service and Prep	3.722	5.727	Fair	There is no HVAC in the food preparation areas. There is no security camera near the delivery dock entry, the driveway access to the loading dock is hard to navigate.
Clinic	0.351	0.540	Fair	There is room for a nurse desk and some required storage cabinets, and not much else. There is only one portable cot which is unfolded when needed. There is access to an adjacent ADA bathroom.
Counseling	0.175	0.270	Fair	The single counseling office is in the administrative suite, has no waiting area, and no meeting space for more two persons besides counselor.
Custodial and Maintenance	0.369	0.462	Good	
Student Restrooms	0.655	0.819	Good	
Faculty Work Space and Toilets	0.936	1.170	Good	
Outside Spaces				
Vehicular Traffic	1.200	1.846	Fair	Drop-off and pick-up locations differ from morning and afternoon, and at times bus and parent traffic may coincide for short periods of time.
Pedestrian Traffic	0.719	0.898	Good	
Parking	0.487	0.750	Fair	Lighting is lacking in part of back parking lot farther from the building.
Play Areas	1.404	2.161	Fair	Part of the play area is up over a hill and not visible from the level of the school.
Safety and Security				
Fencing	0.555	0.694	Good	
Signage & Way Finding	0.600	0.923	Fair	Two of the required warning signs are not visible inside or outside the school, "Under Surveillance" and "Subject to Search".
Ease of Supervision	2.215	2.769	Good	
Controlled Entrances	0.300	0.462	Fair	Although the main entry is card controlled and camera monitored, once entering the building a person is not readily visible from the main office suite.

Building S.P.A.C.E.S Facility Educational Adequacy Report

School Name:	Livsey ES	Grade Configuration: PK-5
Score:	70.61	

Category	Points Earned	Possible Points	Rating	Comment
Technology Readiness				
IDF & MDF Environment	0.000	1.500	Unsat	The MDF equipment is located in the custodial office and storage area surrounded by supplies and unrelated equipment. The is an independent cooling system, but it was not working.
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	***70.61*** /	***100.00*** =	**70.61**	