Facility Condition Assessment Report

1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summ	Report Date: 28 Jun 2011
Facility: \Elementary Schools Address: 2968 Cravenridge D		
Attributes:		
Enaility Code		
Facility Code Super Cluster	3050 1	
	3050 1 Elementary School Year Built:	

Facility Description:

The Ashford Park Elementary School campus consists of two buildings located at 2968 Cravenridge Drive NE in Atlanta, Georgia. The original campus was constructed in 1955, an addition to the main school building was constructed in 1960, and a gymnasium building was constructed in 2000. In addition to these buildings, the campus contains a storage building, covered walkway, hard surface play area, and playfield. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for each building and other facilities on the campus.

Current Repair Cost: \$2,702,772.61

Replacement Cost: \$10,716,577.88

FCI: 25.22%



25-Mar-2011 Ashford Park Elementary School

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 FCI Report Ashford Park Elementary Weighted FCI Report

Facility Name	Last Renovation	Cost Per Sq. Ft.	Gross Area (Sq. Ft.)	Repair Cost	Replacement Cost	Weighted FCI	Critical wt 1.25	Potentially Critical wt 1.1	Necessary wt 1	Recommended wt 0.75	Discretionary wt 0.5
Ashford Park Elementary\Hard Surface Play Area		\$11.31	8,000	\$98,572	\$90,518	108.90%	\$0	\$0	\$98,572	\$0	\$0
Ashford Park Elementary\Playfield		\$6.22	78,520	\$141,477	\$488,740	28.95%	\$0	\$0	\$141,477	\$0	\$0
Ashford Park Elementary∖ 1955, 1960 Building	Jan 1986	\$182.33	44,248	\$2,189,313	\$8,067,890	27.14%	\$0	\$0	\$2,189,313	\$0	\$0
Ashford Park Elementary\ 2000 Gym		\$168.12	5,478	\$168,651	\$920,939	18.31%	\$0	\$0	\$168,651	\$0	\$0
Ashford Park Elementary\Site		\$21.56	49,726	\$104,759	\$1,072,023	9.77%	\$0	\$0	\$104,759	\$0	\$0
Ashford Park Elementary\2000 Covered Walkway		\$27.64	2,500	\$0	\$69,104	0.00%	\$0	\$0	\$0	\$0	\$0
Ashford Park Elementary\ 1960 Storage		\$66.94	110	\$0	\$7,364	0.00%	\$0	\$0	\$0	\$0	\$0

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Survey Report Ashford Park Elementary Detailed Facility Needs Assessment Report

acility Name	Assembly	System	Material	Distress	Correction	Qty	Unit	Raw Cost	Additional Cost	Total Cost	Priority	Def. Cat.	Location / Note
Element Ashforo 1955 Build	ounty School Sy tary Schools d Park Element , 1960 Building ding Systems 32020	ary	System	Beyond Service Life	Renew System	1	Ea.	\$1,982,278 \$1,982,278 \$1,982,278 \$1,586,410 \$1,586,410 \$222,921	\$720,494 \$720,494 \$720,494 \$602,903 \$602,903 \$84,720	\$2,702,773 \$2,702,773 \$2,702,773 \$2,189,313 \$2,189,313 \$307,641	Necess ary	Deferred Maintena nce	The original metal frame, single pane, operable windows are aged, worn, and inefficient, and should be replaced.
C	C1020	Interior Doors	System	Beyond Service Life	Renew System	1	Ea.	\$53,452	\$20,314	\$73,765	Necess ary	Deferred Maintena nce	The doors are original and worn and should be replaced.
C	C1030	Fittings	System	Beyond Service Life	Renew System	1	Ea.	\$90,045	\$34,221	\$124,265	Necess ary	Deferred Maintena nce	Fittings, such as chalk and tack boards, toilet and bath accessories, toilet partitions, and shelving, are aged, worn, and damaged, and should be replaced.
(C3020	Floor Finishes - Carpet	System	Beyond Service Life	Renew System	1	Ea.	\$13,876	\$5,273	\$19,149	Necess ary	Deferred Maintena nce	The carpet is aged, worn, and stained, and should be replaced.
(C3020	Floor Finishes - VCT	System	Beyond Service Life	Renew System	1	Ea.	\$226,333	\$86,016	\$312,349	Necess ary	Deferred Maintena nce	The VCT and VAT are aged, worn, scuffed, and separating, and should be replaced.
C	C3030	Ceiling Finishes	System	Beyond Service Life	Renew System	1	Ea.	\$316,860	\$120,420	\$437,280	Necess ary	Deferred Maintena nce	The acoustical ceiling tile and grid system is aged and stained and should be replaced.
[03020	Heat Generating Systems	System	Beyond Service Life	Renew System	1	Ea.	\$146,505	\$55,678	\$202,183	Necess ary	Deferred Maintena nce	The original boiler is aged and inefficient and should be replaced with an energy efficient model.
[D3090	Other HVAC Systems/Equip - Kitchen Hood	System	Beyond Service Life	Renew System	1	Ea.	\$41,372	\$15,723	\$57,095	Necess ary	Deferred Maintena nce	The original kitchen hood is aged, worn, and inefficient, and should be replaced.
E	E1090	Other Equipment (Kitchen Equipment)	System	Beyond Service Life	Renew System	1	Ea.	\$326,108	\$123,935	\$450,043	Necess ary	Deferred Maintena nce	The kitchen equipment is aged and inefficient and should be replaced.
E	2010	Fixed Furnishings	System	Beyond Service Life	Renew System	1	Ea.	\$148,939	\$56,603	\$205,542	Necess ary	Deferred Maintena nce	Fixed furnishings, such as the base/wall cabinets, counter tops, window shades, and fixed seating, are worn, beyond their service life, and should be replaced.

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Survey Report Ashford Park Elementary Detailed Facility Needs Assessment Report

Facility Name	Assembly	System	Material	Distress	Correction	Qty	Unit	Raw Cost	Additional Cost	Total Cost	Priority	Def. Cat.	Location / Note
·		1	1	1				1	1			1	
	00 Gym							\$122,211	\$46,440	\$168,651			
ы	uilding Systems C3010	Wall Finishes -	System	Beyond	Renew System	1	Ea.	\$122,211 \$6,628	\$46,440 \$2,519	\$168,651 \$9 147	Necess	Deferred	The wall paint is aged and scuffed
	00010	Paint	eyetetti	Service Life		•	20.	<i>Q</i> 0 ,020	\$2,010	<i>Q</i> O <i></i>	ary	Maintena	and should be repainted.
							_	*- / * - *	* ***	* · · · · · · · ·		nce	
	C3020	Floor Finishes - Neoprene	System	Beyond Service Life	Renew System	1	Ea.	\$74,892	\$28,459	\$103,350	Necess ary	Deferred Maintena	The neoprene flooring is worn, has bubbles, and should be
		Neoprene		OCIVICO EIIC							ary	nce	replaced.
	D3050	Terminal &	Packaged	Missing	Install Package A/C - 20	1	Ea.	\$40,691	\$15,463	\$56,154		Capital	An air conditioning system is
		Package Units	A/C, Elec. Ht., Const.		ton						ary	Improvem ent	missing in the gymnasium and should be installed.
			Volume									ent	should be installed.
Har	rd Surface Play A	Area						\$78,232	\$20,340	\$98,572			
Bu	uilding Systems		_				_	\$78,232	\$20,340	\$98,572			
	F1040	Special Facilities -	System	Beyond Service Life	Renew System	1	Ea.	\$78,232	\$20,340	\$98,572	Necess ary	Deferred Maintena	The hard surface play area is aged and cracked and should be
		Basketball		Service Life							ary	nce	resurfaced and repainted.
		Court Hard											·
		Surface											
Die	vfield							\$112,284	\$29,194	\$141,477			
	uilding Systems							\$112,284 \$112,284	\$29,194 \$29,194	\$141,477			
	F1040	Special	System	Beyond	Renew System	1	Ea.	\$17,274	\$4,491	\$21,766	Necess	Deferred	The play field turf is worn and
		Facilities -		Service Life							ary	Maintena	damaged and should be reseeded.
		Sports Field - Natural Turf										nce	
	G2040	Site	System	Beyond	Renew System	1	Ea.	\$95,009	\$24,702	\$119,712	Necess	Deferred	The fence is rusted and damaged
		Development -		Service Life							ary	Maintena	and should be replaced.
		Fencing										nce	
Site								\$83,142	\$21.617	\$104,759			
	uilding Systems							\$83,142	\$21,617 \$21,617	\$104,759			
	G2030	Pedestrian	System	Beyond	Renew System	1	Ea.	\$71,655	\$18,630	\$90,286		Deferred	The pedestrian paving and
		Paving		Service Life							ary	Maintena nce	walkways are aged and damaged and should be replaced.
	G2040	Site	System	Beyond	Renew System	1	Ea.	\$11,487	\$2,987	\$14,473	Necess	Deferred	Site development features, such
		Development		Service Life	-,			. ,	• ,	. ,	ary	Maintena	as the flagpole, site furnishings,
												nce	and signage, are beyond their service life and should be
													replaced.

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: Elementary Schools Ashford Park Elementary 1955, 1960 Building Address: 2968 Cravenridge Drive N.E., Atlanta, GA 30319

Attributes: Building Codes	2010, 2011		
Fire Sprinkler System	No		
General Information:			
Function:	Elementary School	Year Built:	1955
Gross Area:	44,248 S.F.	Last Renovation:	1986

Facility Description:

The Ashford Park Elementary School main building is a one-story building located at 2968 Cravenridge Drive NE in Atlanta, Georgia. Originally built in 1955, there has been one addition in 1960 and a number of partial renovations since 1986. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Energy conservation opportunities for this building include: 1) Replacing the original exterior windows and doors; and 2) Replacing the current energy management system with a building automation management system that completely controls HVAC, lighting, and site lighting.

Current Repair Cost: \$2,189,313.00



25-Mar-2011 North Elevation

Replacement Cost: \$8,067,890.09



25-Mar-2011 East Elevation

FCI: 27.14%



25-Mar-2011 South Elevation



25-Mar-2011 West Elevation

DeKalb County School Sys	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Building Condition:

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$182.33	S.F.	44,248	108	\$8,699,727	39	1976	1963	2015		\$2,189,312	\$8,067,890	27
Substructure	\$13.21	S.F.	44,248	100	\$584,383	100	1955					\$584,383	
Foundations	\$13.21	S.F.	44,248	100	\$584,383	100	1955					\$584,383	
Standard Foundations	\$6.49	S.F.	44,248	100	\$287,001	100	1955					\$287,001	
Special Foundations	\$4.14	S.F.	0	100		100	0						
Slab on Grade	\$6.72	S.F.	44,248	100	\$297,382	100	1955					\$297,382	
Basement Construction			0			0	0						
Basement Excavation	\$0.22	S.F.	0	100		100	0						
Basement Walls	\$5.93	S.F.	0	100		100	0						
Shell	\$32.20	S.F.	44,248	100	\$1,483,492	69	1980	1985	2017		\$307,641	\$1,424,626	22
								1900	2017		\$307,041		22
Superstructure	\$4.43	S.F.	44,248	100	\$196,016	100	0					\$196,016	
Floor Construction	\$14.15	S.F.	0	100		100	0						
Roof Construction	\$4.43	S.F.	44,248	100	\$196,016	100	0					\$196,016	
Exterior Enclosure	\$21.65	S.F.	44,248	103	\$989,910	75	1955	1985	2017		\$307,641	\$958,096	32
Exterior Walls	\$14.46	S.F.	44,248	100	\$639,952	100	0					\$639,952	
Exterior Windows	\$6.32	S.F.	44,248	110	\$307,641	30	1955	1985			\$307,641	\$279,674	110
Exterior Doors	\$0.87	S.F.	44,248	110	\$42,317	30	1955	1985	2017	7		\$38,470	
Roofing	\$6.11	S.F.	44,248	110	\$297,566	25	2005	2030				\$270,514	
Roof Coverings - Asphal	\$3.70	S.F.	0	110	• • • • • •	10	0						
	<i>40.10</i>	0.1.	v										
Shingles	¢E EF		44.040	440	¢070.000	05	2005	2022				604E 470	
Roof Coverings - BUR	\$5.55	S.F.	44,248	110	\$270,026	25	2005	2030				\$245,478	
Roof Coverings - EPDM	\$2.84	S.F.	0	110		15	0						
Roof Coverings - Preformed	\$4.28	S.F.	0	110		30	0						
Metal													
Roof Coverings - Standing	\$23.47	S.F.	0	110		75	0						
Seam Metal													
Roof Openings	\$0.57	S.F.	44,248	110	\$27,540	30	2005	2035				\$25,036	
Interiors	\$40.04	S.F.	44,248	108	\$1,921,061	40	1960	1963	2018		\$966,808	\$1,771,569	55
Interior Construction	\$11.04	S.F.	44,248	104	\$509,701	70	1955	1975			\$198,030	\$488,514	41
Partitions	\$6.40	S.F.	44,248	110	\$311,671	100	1955	10/0			\$100,000	\$283,338	
								1005			AT0 705		
Interior Doors	\$2.08	S.F.	44,248	80	\$73,765	30	1955	1985			\$73,765	\$92,207	80
Fittings	\$2.55	S.F.	44,248	110	\$124,265	20	1955	1975			\$124,265	\$112,969	110
Stairs			0			0	0						
Stair Construction		S.F.	0	100		100	0						
Interior Finishes	\$29.00	S.F.	44,248	110	\$1,411,360	29	1965	1963	2018		\$768,778	\$1,283,055	60
Wall Finishes - Ceramic &	\$9.58	S.F.	17,699	110	\$186,463	30	1955	1985	2020	10		\$169,512	
Glazed													
Wall Finishes - Paint	\$1.81	S.F.	26,549	110	\$52,796	10	2004	2014				\$47,997	
Wall Finishes - Wall Coverings	\$1.99	S.F.	0	110		10	0	-					
Floor Finishes - Carpet	\$7.87	S.F.	2,213	110	\$19,149	8	1955	1963			\$19,149	\$17,408	110
		S.F.							2010	0	¢13,143		110
Floor Finishes - Ceramic &	\$13.40	5.F.	3,097	110	\$45,651	50	1955	2005	2018	8		\$41,500	
Quarry Tile												-	
Floor Finishes - Terrazzo	\$48.99	S.F.	6,637	110	\$357,672	50	1955	2005	2018	8		\$325,157	
Floor Finishes - VCT	\$8.79	S.F.	32,301	110	\$312,349	20	1955	1975			\$312,349	\$283,954	110
Floor Finishes - Wood	\$13.58	S.F.	0	110		20	0						
Ceiling Finishes	\$8.98	S.F.	44,248	110	\$437,280	20	1955	1975			\$437,280	\$397,527	110
Services	\$82.24	S.F.	44,248	110	\$4,002,691	23	1986	1985	2015		\$259,278	\$3,638,811	7
Conveying			0			0	0						
Elevators and Lifts		S.F.	0	110		30	0						
Plumbing	\$24.01	S.F.	44,248	110	\$1,168,767	23	1972	1985	2015			\$1,062,516	
-		5.F. S.F.			\$783,880	23	2010	2030	2013			\$1,062,516	
Plumbing Fixtures	\$16.11		44,248	110					00.17				
Domestic Water Distribution	\$3.59	S.F.	44,248	110	\$174,643	30	1955	1985	2015	5		\$158,767	
Sanitary Waste	\$3.05	S.F.	44,248	110	\$148,447	30	1955	1985	2015	5		\$134,952	
Rain Water Drainage	\$0.88	S.F.	44,248	110	\$42,989	30	1955	1985	2015	5		\$39,081	
Other Plumbing Systems -	\$0.39	S.F.	44,248	110	\$18,808	30	1986	2016				\$17,098	
Natural Gas													
HVAC	\$33.87	S.F.	44,248	110	\$1,648,365	21	1989	1985			\$259,278	\$1,498,513	17
Heat Generating Systems	\$4.15	S.F.	44,248	110	\$202,183	30	1955	1985			\$202,183	\$183,803	110
Cooling Generating Systems	\$4.22	S.F.	44,248	110	\$205,542	30	2010	2040			÷=02,100	\$186,856	
Distribution & Exhaust Systems	\$3.80	3.F. S.F.	44,248	110	\$205,542	30	2010	2040				\$167,926	
-				110									
Terminal & Package Units	\$17.29	S.F.	44,248		\$841,647	15	2004	2019				\$765,133	
Controls & Instrumentation	\$3.23	S.F.	44,248	110	\$157,179	20	2004	2024				\$142,890	
Other HVAC Systems/Equip -	\$1.17	S.F.	44,248	110	\$57,095	30	1955	1985		T	\$57,095	\$51,905	110
Kitchen Hood													
			0			0	0						
Fire Protection													
	\$4.25	S.F.	0	110		30	0						
Fire Protection	\$4.25 \$0.44	S.F. S.F.		110 110		30 30	0						

1701 N	lountain	Indus	strial	Blvd
Stone I	Mountair	n, GA	300	83

COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Electrical Service/Distribution	\$1.95	S.F.	44,248	110	\$94,710	30	1986	2016				\$86,100	
Branch Wiring	\$6.53	S.F.	44,248	110	\$317,717	30	1986	2016				\$288,833	
Lighting	\$8.58	S.F.	44,248	110	\$417,801	30	1986	2016				\$379,819	
Communications and Security -	\$5.51	S.F.	44,248	110	\$268,010	10	2004	2014				\$243,646	
Clock & PA Systems													
Communications and Security -	\$1.20	S.F.	44,248	110	\$58,438	10	2004	2014				\$53,126	
Fire Alarm													
Communications and Security -	\$0.59	S.F.	44,248	110	\$28,883	10	2004	2014				\$26,258	
Security & CCTV													
Equipment & Furnishings	\$13.47	S.F.	44,248	110	\$655,585	20	1955	1975			\$655,585	\$595,986	110
Equipment	\$9.25	S.F.	44,248	110	\$450,043	20	1955	1975			\$450,043	\$409,130	110
Commercial Equipment	\$0.77	S.F.	0	110		20	0						
Institutional Equipment	\$0.40	S.F.	0	110		20	0						
Other Equipment (Kitchen	\$9.25	S.F.	44,248	110	\$450,043	20	1955	1975			\$450,043	\$409,130	110
Equipment)													
Furnishings	\$4.22	S.F.	44,248	110	\$205,542	20	1955	1975			\$205,542	\$186,856	110
Fixed Furnishings	\$4.22	S.F.	44,248	110	\$205,542	20	1955	1975			\$205,542	\$186,856	110
Special Construction	\$1.19	S.F.	44,248	100	\$52,515	25	1955	1980	2020			\$52,515	
Special Construction	\$1.19	S.F.	44,248	100	\$52,515	25	1955	1980	2020			\$52,515	
Special Structures - Canopies	\$1.19	S.F.	44,248	100	\$52,515	25	1955	1980	2020	10		\$52,515	

DeKalb County School System										
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011								

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$2,189,312		\$459,352	\$424,387	\$1,013,792	\$52,045	\$535,175	\$1,098,158	\$321,167		
Substructure											
Foundations											
Standard Foundations											
Special Foundations											
Slab on Grade											
Basement Construction											
Basement Excavation											
Basement Walls											
Shell	\$307,641					\$52,045					
Superstructure											
Floor Construction											
Roof Construction											
Exterior Enclosure	\$307,641					\$52,045					
Exterior Walls											
Exterior Windows	\$307,641										
Exterior Doors						\$52,045					
Roofing						40-,0 · · ·					
Roof Coverings - Asphal Shingles											
Roof Coverings - Asphal Shingles											
Roof Coverings - EPDM											
Roof Coverings - Preformed Metal											
Roof Coverings - Standing Seam											
Metal											
Roof Openings											
Interiors	\$966,808		\$59,423				\$535,175		\$250,591		
Interior Construction	\$198,030										
Partitions											
Interior Doors	\$73,765										
Fittings	\$124,265										
Stairs											
Stair Construction											
Interior Finishes	\$768,778		\$59,423				\$535,175		\$250 501		
	\$700,770		\$59,423				\$535,175		\$250,591		
Wall Finishes - Ceramic & Glazed									\$250,591		
Wall Finishes - Paint			\$59,423								
Wall Finishes - Wall Coverings											
Floor Finishes - Carpet	\$19,149						\$24,257				
Floor Finishes - Ceramic & Quarry							\$57,829				
Tile											
Floor Finishes - Terrazzo							\$453,089				
Floor Finishes - VCT	\$312,349										
Floor Finishes - Wood											
Ceiling Finishes	\$437,280										
Services	\$259,278		\$399,929	\$424,387	\$1,013,792			\$1,098,158			
Conveying	<i>\$200,210</i>		4000,020	¥727,307	÷.,010,732			÷.,000,100			
Elevators and Lifts											
				£404.007	£00.457						
Plumbing				\$424,387	\$22,457						
Plumbing Fixtures											
Domestic Water Distribution				\$202,460							
Sanitary Waste				\$172,091							
Rain Water Drainage				\$49,836							
Other Plumbing Systems - Natural					\$22,457						
Gas											
HVAC	\$259,278							\$1,098,158			
Heat Generating Systems	\$202,183										
Cooling Generating Systems	,										
Distribution & Exhaust Systems											
Terminal & Package Units								\$1 000 450			
								\$1,098,158			
Controls & Instrumentation											
Other HVAC Systems/Equip -	\$57,095										
Kitchen Hood											
Fire Protection											
Sprinklers											
Standpipes											
	1 I.		\$399,929		\$991,335						

DeKalb County School System 1701 Mountain Industrial Blvd Stone Mountain, GA 30083 COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report Report Date: 28 Jun 2011 Systems 2010-12 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Electrical Service/Distribution					\$113,089						
Branch Wiring					\$379,370						
Lighting					\$498,876						
Communications and Security -			\$301,648								
Clock & PA Systems											
Communications and Security - Fire			\$65,773								
Alarm											
Communications and Security -			\$32,508								
Security & CCTV											
Equipment & Furnishings	\$655,585										
Equipment	\$450,043										
Commercial Equipment											
Institutional Equipment											
Other Equipment (Kitchen	\$450,043										
Equipment)											
Furnishings	\$205,542										
Fixed Furnishings	\$205,542										
Special Construction									\$70,576		
Special Construction									\$70,576		
Special Structures - Canopies								1	\$70,576		

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	B2020	Priority:	3	
System:	Exterior Windows	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The original metal frame, single pan	e, operable windows are aged.	worn, and inefficient	and should be replaced.



Estimates:

Correction: Note: Raw Cost \$222,921.42 Plus or (Minus) Additional Cost 584,719.63 Total Estimated Amount \$307,641.05

Deficiency: Assembly: System: Material:	C1020 Interior Doors System	Surveyor/Update: Priority: Quantity:	Chuck Gulley 3 1	Wed, 13-Apr-2011
Distress: Category:	Beyond Service Life Deferred Maintenance			

Deferred Ma Renew Syste	intenance	
		d worn and should be repla
144.200		
- AND		
	1	



Estimates:

 Raw Cost
 \$53,451.58

 Plus or (Minus) Additional Cost Total Estimated Amount
 \$20,313.88

 \$73,765.46
 \$73,765.46

COMET4 Facility Report 1701 Mountain Industrial Blvd Ashford Park Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Deficiency:

Deficiency:		Surveyor/Update:	Chuck Gulley	Tue, 29-Mar-2011
Assembly:	C1030	Priority:	3	
System:	Fittings	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	Fittings, such as chalk and tack boards and damaged, and should be replaced	·	s, toilet partitions, and	d shelving, are aged, worn,



Estimates:

Raw Cost	\$90,044.68
Plus or (Minus) Additional Cost	\$34,220.81
Total Estimated Amount	\$124,265.49

Deficiency:

00
Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

Priority: C3020 Quantity: **Floor Finishes - Carpet** System Beyond Service Life **Deferred Maintenance Renew System** The carpet is aged, worn, and stained, and should be replaced.



Estimates:

Surveyor/Update: Chuck Gulley 3 1

Wed, 13-Apr-2011

Raw Cost \$13,875.51 Plus or (Minus) Additional Cost \$5,273.28 Total Estimated Amount \$19,148.79

 1701 Mountain Industrial Blvd
 COMET4 Facility Report
 Report Date: 28 Jun 2011

 Stone Mountain, GA 30083
 Ashford Park Elementary Facility Executive Summary Report
 Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	C3020	Priority:	3	
System:	Floor Finishes - VCT	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The VCT and VAT are aged, worn, scu	uffed, and separating, and sho	ould be replaced.	



Estimates:

Raw Cost	\$226,333.11
Plus or (Minus) Additional Cost	\$86,016.21
Total Estimated Amount	\$312,349.32

Wed, 13-Apr-2011

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

 C3030
 Priority:
 3

 Ceiling Finishes
 Quantity:
 1

 System
 Beyond Service Life
 1

 Deferred Maintenance
 Renew System
 1

 The acoustical ceiling tile and grid system is aged and stained and should be replaced.
 1

Surveyor/Update:

Chuck Gulley



Estimates:

Raw Cost	\$316,859.93
Plus or (Minus) Additional Cost	\$120,420.26
Total Estimated Amount	\$437,280.19

COMET4 Facility Report 1701 Mountain Industrial Blvd Ashford Park Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	D3020	Priority:	3	
System:	Heat Generating Systems	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The original boiler is aged and ineffici	ent and should be replaced w	vith an energy efficie	nt model.



Estimates:

Raw Cost	\$146,505.13
Plus or (Minus) Additional Cost	\$55,678.18
Total Estimated Amount	\$202,183.31

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

D3090 Other HVAC Systems/Equip - Kitchen Hood Quantity: 1 System **Beyond Service Life Deferred Maintenance Renew System** The original kitchen hood is aged, worn, and inefficient, and should be replaced.



Estimates:

Raw Cost \$41,371.88 Plus or (Minus) Additional Cost \$15,723.08 Total Estimated Amount \$57,094.96

\$55,678.18	us or (Minus) Additional Cost
	Total Estimated Amount

Surveyor/Update: Chuck Gulley Priority: 3

Thu, 14-Apr-2011

COMET4 Facility Report 1701 Mountain Industrial Blvd Ashford Park Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 1955, 1960 Building (continued)

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	E1090	Priority:	3	
System:	Other Equipment (Kitchen Equipment)	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The kitchen equipment is aged and inefficient	nt and should be replace	ced.	



Estimates:

Raw Cost	\$326,107.76
Plus or (Minus) Additional Cost	\$123,934.83
Total Estimated Amount	\$450,042.59

Deficiency:

Assembly: System: Material: Distress: Category: Correction: Note:

E2010 **Fixed Furnishings** System **Beyond Service Life Deferred Maintenance Renew System**

Surveyor/Update: Chuck Gulley Priority:

3 Quantity: 1

Wed, 13-Apr-2011

Fixed furnishings, such as the base/wall cabinets, counter tops, window shades, and fixed seating, are worn, beyond their service life, and should be replaced.



Estimates:

Raw Cost \$148,938.77 Plus or (Minus) Additional Cost \$56,603.07 Total Estimated Amount \$205,541.84

DeKalb County School Sy	vstem			
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COM Ashford Park Elementar	Report	Report Date: 28 Jun 2011	
	s∖Ashford Park Elementary∖ 19€ Drive N.E., Atlanta, GA 30319	60 Storage		
Attributes: Fire Sprinkler System	No			
General Information: Function: Gross Area:	Storage Building 110 S.F.	Year Built: Last Renovation:	1960	

Facility Description:

The Storage Building at Ashford Park Elementary School is located at 2968 Cravenridge Drive NE in Atlanta, Georgia. There have been no additions and no major renovations. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Current Repair Cost: \$0.00

Replacement Cost: \$7,363.82

FCI: 0.00%



25-Mar-2011 South Elevation



25-Mar-2011 East Elevation



25-Mar-2011 Southeast Elevation



25-Mar-2011 West Elevation

DeKalb County School Sy	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 1960 Storage (continued)

Building Condition:

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$66.94	S.F.	110	102	\$7,529	81	1980	1990			0	\$7,363	
Substructure	\$3.41	S.F.	110	100	\$375	100	1960					\$375	
Foundations	\$3.41	S.F.	110	100	\$375	100	1960					\$375	
Standard Foundations	\$4.49	S.F.	0	100		100	1960						
Slab on Grade	\$3.41	S.F.	110	100	\$375	100	1960					\$375	
Basement Construction			0			0	0						
Basement Excavation	\$0.21	S.F.	0	100		100	1960						
Basement Walls	\$3.41	S.F.	0	100		100	1960						
Shell	\$63.53	S.F.	110	102	\$7,154	80	1985	1990				\$6,988	
Superstructure	\$13.56	S.F.	110	100	\$1,492	100	1960					\$1,492	
Roof Construction	\$13.57	S.F.	110	100	\$1,492	100	1960					\$1,492	
Exterior Enclosure	\$35.60	S.F.	110	100	\$3,924	98	1985	1990				\$3,916	
Exterior Walls	\$34.87	S.F.	110	100	\$3,836	100	1960					\$3,836	
Exterior Windows	\$4.54	S.F.	0	110		30	1960	1990					
Exterior Doors	\$0.73	S.F.	110	110	\$88	30	2010	2040				\$80	
Roofing	\$14.36	S.F.	110	110	\$1,738	20	2010	2030				\$1,580	
Roof Coverings	\$14.37	S.F.	110	110	\$1,738	20	2010	2030				\$1,580	
Interiors			0			0	0						
Interior Construction			0			0	0						
Partitions	\$11.92	S.F.	0	110		40	0						
Interior Doors	\$2.26	S.F.	0	80		30	0						
Fittings	\$2.79	S.F.	0	110		20	0						
Interior Finishes			0			0	0						
Wall Finishes	\$1.50	S.F.	0	110		20	0						
Floor Finishes	\$6.07	S.F.	0	110		20	0						
Ceiling Finishes	\$5.44	S.F.	0	110		20	0						
Services			0			0	0						
Plumbing			0			0	0						
Rain Water Drainage	\$1.38	S.F.	0	110		30	0						
Electrical			0			0	0						
Electrical Service/Distribution	\$3.30	S.F.	0	110		30	0						
Lighting and Branch Wiring	\$12.12	S.F.	0	110		30	0			1			

DeKalb County School Sys	tem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 1960 Storage (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total											
Substructure											
Foundations											
Standard Foundations											
Slab on Grade											
Basement Construction											
Basement Excavation											
Basement Walls											
Shell											
Superstructure											
Roof Construction						1					
Exterior Enclosure						1					
Exterior Walls											
Exterior Windows											
Exterior Doors											
Roofing											
Roof Coverings											
Interiors											
Interior Construction											
Partitions											
Interior Doors											
Fittings											
Interior Finishes											
Wall Finishes											
Floor Finishes											
Ceiling Finishes											
Services											
Plumbing											
Rain Water Drainage	-										
Electrical	-										
Electrical Service/Distribution	-										
Lighting and Branch Wiring											

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\ 1960 Storage (continued)

Deficiency Sheet:

*** No Deficiencies Found ***

DeKalb County School System COMET4 Facility Report Report Date: 28 Jun 2011 1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report Report Date: 28 Jun 2011 Facility: Lelementary Schools\Ashford Park Elementary\ 2000 Gym Address: 2968 Cravenridge Drive N.E., Atlanta, GA 30319 Attributes: Building Codes 2020 Fire Sprinkler System No

General Information: Function: Gross Area:	Elementary School 5,478 S.F.	Year Built: Last Renovation:	2000

Facility Description:

The 2000 Gymnasium at Ashford Park Elementary School is a one-story building located at 2968 Cravenridge Drive NE in Atlanta, Georgia. There have been no additions and no major renovations to this building. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

An energy conservation opportunity for this building is to select and install an energy efficient cooling system.

Current Repair Cost: \$168,651.19

Replacement Cost: \$920,939.25

FCI: 18.31%



25-Mar-2011 North Elevation



25-Mar-2011 East Elevation



25-Mar-2011 South Elevation



25-Mar-2011 West Elevation

DeKalb County School Sy	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\ 2000 Gym (continued)

Building Condition:

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$168.12	S.F.	5,478	106	\$979,775	53	2000	2008	2015		\$168,651	\$920,942	18
Substructure	\$17.07	S.F.	5,478	100	\$93,513	100	2000					\$93,513	
Foundations	\$17.07	S.F.	5,478	100	\$93,513	100	2000					\$93,513	
Standard Foundations	\$10.57	S.F.	5,478	100	\$57,907	100	2000					\$57,907	
Slab on Grade	\$6.50	S.F.	5,478	100	\$35,606	100	2000					\$35,606	
Shell	\$45.06	S.F.	5,478	103	\$254,585	89	2000	2030				\$246,822	
Superstructure	\$14.21	S.F.	5,478	100	\$77,864	100	2000					\$77,864	
Roof Construction	\$14.21	S.F.	5,478	100	\$77,864	100	2000					\$77,864	
Exterior Enclosure	\$18.96	S.F.	5,478	101	\$105,124	91	2000	2030				\$103,869	
Exterior Walls	\$16.67	S.F.	5,478	100	\$91,320	100	2000					\$91,320	
Exterior Doors	\$2.29	S.F.	5,478	110	\$13,804	30	2000	2030				\$12,549	
Roofing	\$11.88	S.F.	5,478	110	\$71,597	75	2000	2075				\$65,089	
Roof Coverings - Standing	\$11.88	S.F.	5,478	110	\$71,597	75	2000	2075				\$65,089	
Seam Metal													
Interiors	\$45.28	S.F.	5,478	107	\$265,876	41	2000	2008			\$112,497	\$248,056	45
Interior Construction	\$21.51	S.F.	5,478	104	\$122,655	76	2000	2020				\$117,855	+
Partitions	\$13.57	S.F.	5,478	110	\$81,742	100	2000					\$74,311	
Interior Doors	\$4.25	S.F.	5,478	80	\$18,627	40	2000	2040				\$23,284	
Fittings	\$3.70	S.F.	5,478	110	\$22,286	20	2000	2020				\$20,260	
Interior Finishes	\$23.77	S.F.	5,478	110	\$143,221	11	2000	2008			\$112,497	\$130,201	86
Wall Finishes - Ceramic	\$7.19	S.F.	0	110	\$110, <u>22</u> 1	30	2000	2000			¢112,101	\$100,201	
Wall Finishes - Paint	\$1.52	S.F.	5,478	110	\$9,147	10	2000	2010			\$9,147	\$8,316	110
Floor Finishes - Ceramic Tile	\$7.16	S.F.	274	110	\$2,159	50	2000	2050			\$0,111	\$1,962	
Floor Finishes - Neoprene	\$19.06	S.F.	4,930	110	\$103,350	8	2000	2000			\$103,350	\$93,955	110
Floor Finishes - VCT	\$5.38	S.F.	4,930	110	\$1,622	15	2000	2000			\$105,550	\$1,475	110
Ceiling Finishes	\$4.47	S.F.	5,478	110	\$26,943	20	2000	2013				\$24,493	
Services	\$60.71	S.F.	5,478	110	\$365,801	20	2000	2020	2015		\$56,154	\$332,551	17
Plumbing	\$14.37	S.F.	5,478	110	\$86,565	30	2000	2010	2015		\$30,134	\$78,696	17
Plumbing Fixtures	\$7.20	S.F.	5,478	110	\$43,407	30	2000	2030				\$39,461	
Domestic Water Distribution	\$7.20	3.F. S.F.	5,478	110	\$35,923	30	2000	2030				\$39,401	
	\$0.87	S.F.		110	\$5,239	30	2000	2030				\$4,763	
Sanitary Waste	\$0.87	5.F. S.F.	5,478	110	\$5,239	30	2000	2030				\$4,763	
Rain Water Drainage	\$0.22	S.F. S.F.	0	110	\$1,996	30	2000	2030				¢4.04.4	
Other Plumbing Systems -	ф 0.33	э.г.	5,478	110	\$1,990	30	2000	2030				\$1,814	
Natural Gas	\$00.04	0.5	E 470	110	\$170.000	01	0000	0045			\$50 454	\$450 7 40	
HVAC	\$28.61	S.F.	5,478	110	\$172,382	21	2000	2015			\$56,154	\$156,712	36
Distribution Systems & Exhaust	\$10.39	S.F.	5,478	110	\$62,616	30	2000	2030				\$56,924	
Systems	A (a a a		E 170		\$ 100.000			0045			A E0.454	A2 (32 (
Terminal & Package Units	\$16.63	S.F.	5,478	110	\$100,203	15	2000	2015			\$56,154	\$91,094	62
Controls & Instrumentation	\$1.59	S.F.	5,478	110	\$9,563	20	2000	2020				\$8,694	
Fire Protection			0			0	0						
Sprinklers	\$3.91	S.F.	0	110		30	2000						
Electrical	\$17.73	S.F.	5,478	110	\$106,854	22	2000	2010	2015			\$97,143	
Electrical Service/Distribution	\$1.34	S.F.	5,478	110	\$8,066	30	2000	2030				\$7,333	
Branch Wiring	\$5.96	S.F.	5,478	110	\$35,923	30	2000	2030				\$32,658	
Lighting	\$5.96	S.F.	5,478	110	\$35,923	20	2000	2020				\$32,658	
Communications and Security -	\$2.46	S.F.	5,478	110	\$14,802	10	2000	2010	2015	5		\$13,456	
Fire Alarm													
Communications and Security -	\$1.01	S.F.	5,478	110	\$6,070	20	2000	2020				\$5,519	1
Public Address & Clock System													
Communications and Security -	\$1.01	S.F.	5,478	110	\$6,070	10	2000	2010	2015	5		\$5,519	
Security & CCTV						1							1

DeKalb County School System							
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011					

Facility: \Elementary Schools\Ashford Park Elementary\ 2000 Gym (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$168,651			\$142,239			\$130,921		\$147,740		
Substructure											
Foundations											
Standard Foundations											
Slab on Grade											
Shell											
Superstructure											
Roof Construction											
Exterior Enclosure											
Exterior Walls											
Exterior Doors											
Roofing											
Roof Coverings - Standing Seam											
Metal											
	\$112,497			\$1,880			\$130,921		\$78,452		
Interiors Interior Construction	φ112,497			φ1,00U			\$130,921		\$78,452 \$29,950		-
									¢∠9,950		
Partitions											
Interior Doors									000.050		
Fittings	<u> </u>			A 1 00-			A 100 05 :		\$29,950		
Interior Finishes	\$112,497			\$1,880			\$130,921		\$48,502		
Wall Finishes - Ceramic											
Wall Finishes - Paint	\$9,147								\$12,293		
Floor Finishes - Ceramic Tile											
Floor Finishes - Neoprene	\$103,350						\$130,921				
Floor Finishes - VCT				\$1,880							
Ceiling Finishes									\$36,209		
Services	\$56,154			\$140,359					\$69,288		
Plumbing											
Plumbing Fixtures											
Domestic Water Distribution											
Sanitary Waste											
Rain Water Drainage											
Other Plumbing Systems - Natural											
Gas											
HVAC	\$56,154			\$116,163					\$12,852		
Distribution Systems & Exhaust							+		+ +		
Systems											
Terminal & Package Units	\$56,154		+	\$116,163		+			+		+
Controls & Instrumentation							+ +		\$12,852		
Fire Protection							+ +				
Sprinklers			+			+			+ +		+
Electrical				\$24,196			+		\$56,436		
Electrical Service/Distribution				<i>42.,.30</i>			+		\$55,150		
Branch Wiring							+		++		
Lighting									\$48,278		
Communications and Security - Fire				\$17,159					ψ 1 0,270		-
				\$17,10 9							
Alarm									\$0.450		
Communications and Security -									\$8,158		
Public Address & Clock System				a							
Communications and Security -				\$7,037							
Security & CCTV											1

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\ 2000 Gym (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	C3010	Priority:	3	
System:	Wall Finishes - Paint	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The wall paint is aged and scuffed a	and should be repainted.		



Estimates:

Raw Cost	\$6,628.38
Plus or (Minus) Additional Cost	\$2,518.78
Total Estimated Amount	\$9,147.16

Wed, 13-Apr-2011

Deficiency:		Surveyor/Update:	Chuck Gulley
Assembly:	C3020	Priority:	3
System:	Floor Finishes - Neoprene	Quantity:	1
Material:	System		
Distress:	Beyond Service Life		
Category:	Deferred Maintenance		
Correction:	Renew System		
Note:	The neoprene flooring is worn, has bubb	les, and should be replace	d.



Estimates:

Raw Cost	\$74.891.63

\$74,091.0 3
\$28,458.82
\$103,350.45

1701 Mountain Industrial Blvd	COMET4 Facility Report	Report
Stone Mountain, GA 30083	Ashford Park Elementary Facility Executive Summary Report	opon

Facility: \Elementary Schools\Ashford Park Elementary\ 2000 Gym (continued)

Deficiency:

Deficiency:		Surveyor/Update:	Chuck Gulley
Assembly:	D3050	Priority:	3
System:	Terminal & Package Units	Quantity:	1
Material:	Packaged A/C, Elec. Ht., Const. Volume		
Distress:	Missing		
Category:	Capital Improvement		
Correction:	Install Package A/C - 20 ton		
Note:	An air conditioning system is missing in the	gymnasium and shoul	d be installed.



Estimates:

Raw Cost \$40,691.00 Plus or (Minus) Additional Cost \$15,462.58 Total Estimated Amount \$56,153.58

Sun, 26-Jun-2011

COMET4 Facility Report 1701 Mountain Industrial Blvd Ashford Park Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Ashford Park Elementary\2000 Covered Walkway Address: 2968 Cravenridge Drive N.E., Atlanta, GA 30319

Attributes: ***None***

General Information: Function:

Gross Area:

Elementary School 2,500 S.F.

Year Built: Last Renovation:

FCI: 0.00%

2000

Facility Description:

An engineered metal covered walkway connects the main school building with the gymnasium and provides some weather protection for the students.

Replacement Cost: \$69,103.50

Current Repair Cost: \$0.00



25-Mar-2011 East Elevation



25-Mar-2011 West Elevation



25-Mar-2011 South Elevation



25-Mar-2011 North Elevation

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\2000 Covered Walkway (continued)

Building Condition:

		Unit of				1		Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$27.64	S.F.	2,500	100	\$69,104	25	2000	2025			0	\$69,104	
Special Construction	\$27.64	S.F.	2,500	100	\$69,104	25	2000	2025				\$69,104	
Special Construction	\$27.64	S.F.	2,500	100	\$69,104	25	2000	2025				\$69,104	
Special Structures - Covered Walkways Metal	\$27.64	S.F.	2,500	100	\$69,104	25	2000	2025				\$69,104	

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\2000 Covered Walkway (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total											
Special Construction											
Special Construction											
Special Structures - Covered											
Walkways Metal											

 1701 Mountain Industrial Blvd
 COMET4 Facility Report

 Stone Mountain, GA 30083
 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\2000 Covered Walkway (continued)

Deficiency Sheet:

*** No Deficiencies Found ***

DeKalb County School Sy 1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COME Ashford Park Elementary	Report	Report Date: 28 Jun 2011	
	s\Ashford Park Elementary\ Hard Drive N.E., Atlanta, GA 30319	Surface Play Area		
Attributes: ***None***				
General Information: Function: Gross Area:	Elementary School 8,000 S.F.	Year Built: Last Renovation:	1986	
Facility Description:				

The Hard Surface Play Area at Ashford Park Elementary School is located on the campus grounds. There have been no additions and no major renovations. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Current Repair Cost: \$98,572.32

Replacement Cost: \$90,518.40

FCI: 108.90%



25-Mar-2011 Hard Surface Play Area

DeKalb County School Sys	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\Hard Surface Play Area (continued)

Building Condition:

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$11.31	S.F.	8,000	110	\$99,479	21	1986	1986			\$98,572	\$90,518	109
Equipment & Furnishings			0			0	0						
Equipment			0			0	0						
Other Equipment	\$1.94	S.F.	0	0		0	1986	1986					
Special Construction	\$11.20	S.F.	8,000	110	\$98,572	20	1986	2006			\$98,572	\$89,611	110
Special Construction	\$11.20	S.F.	8,000	110	\$98,572	20	1986	2006			\$98,572	\$89,611	110
Special Facilities - Basketball	\$11.20	S.F.	8,000	110	\$98,572	20	1986	2006			\$98,572	\$89,611	110
Court Hard Surface													
Building Sitework	\$0.11	S.F.	8,000	100	\$907	100	1986					\$907	
Site Preparation	\$0.11	S.F.	8,000	100	\$907	100	1986					\$907	
Site Earthwork	\$0.11	S.F.	8,000	100	\$907	100	1986					\$907	
Site Improvements			0			0	0						
Site Development - Fencing	\$0.84	S.F.	0	100		30	1986						
Site Electrical Utilities			0			0	0						
Site Lighting	\$0.69	S.F.	0	100		30	1986						

DeKalb County School Sys	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\Hard Surface Play Area (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$98,572										
Equipment & Furnishings											
Equipment											
Other Equipment											
Special Construction	\$98,572										
Special Construction	\$98,572										
Special Facilities - Basketball Court	\$98,572										
Hard Surface											
Building Sitework											
Site Preparation											
Site Earthwork											
Site Improvements											
Site Development - Fencing			1								
Site Electrical Utilities											
Site Lighting											

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\Hard Surface Play Area (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Chuck Gulley	Sat, 25-Jun-2011
Assembly:	F1040	Priority:	3	
System:	Special Facilities - Basketball Court Hard	Quantity:	1	
-	Surface			
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The hard surface play area is aged and crack	ed and should be res	urfaced and repainted	d.



Estimates:

Raw Cost\$78,232.00Plus or (Minus) Additional Cost\$20,340.32Total Estimated Amount\$98,572.32

DeKalb County School S 1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COME	T4 Facility Report Facility Executive Summary	Report	Report Date: 28 Jun 2011
	ls∖Ashford Park Elementary∖ Playf Drive N.E., Atlanta, GA 30319	ield		
Attributes: ***None***				
General Information: Function: Gross Area:	Elementary School 78,520 S.F.	Year Built: Last Renovation:	1955	
Facility Description:				

The Playfield at Ashford Park Elementary School is located on the campus grounds. There have been no additions and no major renovations. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Current Repair Cost: \$141,477.34

Replacement Cost: \$488,739.89 **FCI:** 28.95%

25-Mar-2011 Playfield at Ashford Park Elementary School 1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\Playfield (continued)

Building Condition:

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$6.22	S.F.	78,520	103	\$501,602	77	1955	1965			\$141,478	\$488,740	29
Special Construction	\$0.25	S.F.	78,520	110	\$21,766	10	1955	1965			\$21,766	\$19,787	110
Special Construction	\$0.25	S.F.	78,520	110	\$21,766	10	1955	1965			\$21,766	\$19,787	110
Special Facilities - Sports Field -	\$0.25	S.F.	78,520	110	\$21,766	10	1955	1965			\$21,766	\$19,787	110
Natural Turf													
Building Sitework	\$5.97	S.F.	78,520	102	\$479,836	80	1955	1975			\$119,712	\$468,953	26
Site Preparation	\$4.59	S.F.	78,520	100	\$360,124	100	1955					\$360,124	
Site Earthwork	\$4.59	S.F.	78,520	100	\$360,124	100	1955					\$360,124	
Site Improvements	\$1.39	S.F.	78,520	110	\$119,712	20	1955	1975			\$119,712	\$108,829	110
Site Development - Fencing	\$1.39	S.F.	78,520	110	\$119,712	20	1955	1975			\$119,712	\$108,829	110
Landscaping - Irrigation	\$0.09	S.F.	0	110		20	1955						
Site Mechanical Utilities			0			0	0						
Water Supply - Water Service	\$0.34	S.F.	0	110		30	1955						
Site Electrical Utilities			0			0	0						
Site Lighting	\$1.69	S.F.	0	110		30	1955						

DeKalb County School Sys	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

1

Facility: \Elementary Schools\Ashford Park Elementary\Playfield (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$141,478								\$29,251		
Special Construction	\$21,766								\$29,251		
Special Construction	\$21,766								\$29,251		
Special Facilities - Sports Field -	\$21,766								\$29,251		
Natural Turf											
Building Sitework	\$119,712										
Site Preparation											
Site Earthwork											
Site Improvements	\$119,712										
Site Development - Fencing	\$119,712										
Landscaping - Irrigation											
Site Mechanical Utilities											
Water Supply - Water Service											
Site Electrical Utilities			1	1	1		1				
Site Lighting											

COMET4 Facility Report 1701 Mountain Industrial Blvd Ashford Park Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Ashford Park Elementary\Playfield (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	F1040	Priority:	3	
System:	Special Facilities - Sports Field - Natural Turf	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The play field turf is worn and damaged and sh	ould be reseeded.		



Estimates:

Raw Cost \$17,274.40 Plus or (Minus) Additional Cost \$4,491.34 Total Estimated Amount \$21,765.74

Deficiency:

Deficiency:		Surveyor/Update:
Assembly:	G2040	Priority:
System:	Site Development - Fencing	Quantity:
Material:	System	
Distress:	Beyond Service Life	
Category:	Deferred Maintenance	
Correction:	Renew System	
Note:	The fence is rusted and damaged and s	should be replaced.



Estimates:

Chuck Gulley

3

1

Wed, 13-Apr-2011

\$95,009.20	Raw Cost
\$24,702.39	Plus or (Minus) Additional Cost
\$119,711.59	Total Estimated Amount

DeKalb County School Sys	stem					
1701 Mountain Industrial Blvd Stone Mountain, GA 30083		COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report				
Facility: \Elementary Schools' Address: 2968 Cravenridge D	\Ashford Park Elementary\ Site rive N.E., Atlanta, GA 30319					
Attributes: Site Code	1025					
General Information: Function: Gross Area:	Elementary School 49,726 S.F.	Year Built: Last Renovation:	1955			
Facility Description:						

The Ashford Elementary School site was originally constructed in 1955, has a total area of 7.2 acres, and is occupied by approximately 49,726 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for the site features.

Current Repair Cost: \$104,758.76

Replacement Cost: \$1,072,022.94 **FCI:** 9.77%



04-Nov-2010 Aerial Image of Ashford Park Elementary School

DeKalb County School Sy	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Ashford Park Elementary\Site (continued)

Building Condition:

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$21.56	S.F.	49,726	110	\$1,179,224	35	1963	1965	2016		\$104,759	\$1,072,020	10
Building Sitework	\$21.56	S.F.	49,726	110	\$1,179,224	35	1963	1965	2016		\$104,759	\$1,072,020	10
Site Improvements	\$9.89	S.F.	49,726	110	\$541,024	21	1955	1965	2016		\$104,759	\$491,839	21
Roadways	\$3.25	S.F.	49,726	110	\$177,814	25	1955	1980	2016	6		\$161,649	
Parking Lots	\$1.47	S.F.	49,726	110	\$80,637	25	1955	1980	2016	6		\$73,306	
Pedestrian Paving	\$1.65	S.F.	49,726	110	\$90,286	30	1955	1985			\$90,286	\$82,078	110
Site Development	\$0.26	S.F.	49,726	110	\$14,473	10	1955	1965			\$14,473	\$13,157	110
Site Development 2			0			0	0						
Fence & Guardrails	\$1.98	S.F.	0	100		30	1955	1985					
Landscaping	\$3.25	S.F.	49,726	110	\$177,814	10	1955					\$161,649	
Site Mechanical Utilities	\$10.46	S.F.	49,726	110	\$572,037	50	1963	2005	2020			\$520,033	
Water Supply	\$2.38	S.F.	49,726	110	\$130,259	50	1955	2005	2020	10		\$118,417	
Sanitary Sewer	\$2.36	S.F.	49,726	110	\$128,881	50	1955	2005	2020	10		\$117,164	
Storm Sewer	\$5.51	S.F.	49,726	110	\$301,181	50	1955	2005	2020	10		\$273,801	
Fuel Distribution - Gas	\$0.21	S.F.	49,726	110	\$11,716	30	1986	2016				\$10,651	
Site Electrical Utilities	\$1.21	S.F.	49,726	110	\$66,163	30	1986	2016				\$60,148	
Electrical Distribution	\$0.52	S.F.	49,726	110	\$28,257	30	1986	2016				\$25,688	
Site Lighting	\$0.69	S.F.	49,726	110	\$37,906	30	1986	2016				\$34,460	

DeKalb County School Sys	stem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Ashford Park Elementary Facility Executive Summary Report	Report D

Facility: \Elementary Schools\Ashford Park Elementary\Site (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$104,759				\$401,596				\$772,477		
Building Sitework	\$104,759				\$401,596				\$772,477		
Site Improvements	\$104,759				\$308,603				\$19,451		
Roadways					\$212,319						
Parking Lots					\$96,284						
Pedestrian Paving	\$90,286										
Site Development	\$14,473								\$19,451		
Site Development 2											
Fence & Guardrails											
Landscaping											
Site Mechanical Utilities					\$13,990				\$753,026		
Water Supply									\$175,058		
Sanitary Sewer									\$173,205		
Storm Sewer									\$404,763		
Fuel Distribution - Gas					\$13,990						
Site Electrical Utilities					\$79,003		1	1			
Electrical Distribution					\$33,741						
Site Lighting					\$45,262						

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Ashford Park Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Ashford Park Elementary\Site (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Chuck Gulley	Wed, 13-Apr-2011
Assembly:	G2030	Priority:	3	
System:	Pedestrian Paving	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The pedestrian paving and walkways are aged a	and damaged and sl	hould be replaced.	



Estimates:

Raw Cost	\$71,655.17
Plus or (Minus) Additional Cost	\$18,630.34
Total Estimated Amount	\$90,285.51

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:



Estimates:

Raw Cost	\$11,486.71
Plus or (Minus) Additional Cost	\$2,986.54
Total Estimated Amount	\$14,473.25

Educational Adequacy Report

BASYS Building Assessment System

Suitability Report - Full

Project #: 4469	County:	DeKalb		Site #: 3050			
Project: Assessments 2010	nents 2010 ^{Region:} 1		^{Site:} Ashford Park ES				
Grade Config: PK-5	Site Type:	Elementary		Site Size: 0.00			
Suitability			Rating	Score	Possible Score	Pero Sco	
Suitability - Elementary							
Site							
Traffic			Fair	1.34	2.00	6	
Pedestrian Traffic			Good	0.97	0.97	10	
Parking			Fair	0.54	0.81	6	
Playground			Poor	0.77	2.34	3	
Safety and Security							
Fencing			Fair	0.50	0.75	e	
Signage & Way Finding			Fair	0.67	1.00	6	
Ease of Supervision			G/F	3.50	3.50	10	
Limited Entrances			G/F	0.50	0.50	10	
Interior Circulation			G/F	0.50	0.50	10	
Sprinkler System			Unsat	0.00	0.50		
School Climate							
Learning Style Variety			P/U	0.00	5.00		
School Environment			G/F	5.00	5.00	10	
Landscaping			P/U	0.00	1.00		
General Classrooms							
Size			Good	16.45	16.45	10	
Adjacencies			Fair	2.36	3.53	6	
Storage\Fixed Equip.			Fair	2.36	3.53	6	
Remedial - Special Needs							
Size			Good	3.50	3.50	10	
Adjacencies			G/F	0.75	0.75	10	
Storage\Fixed Equip.			G/F	0.75	0.75	10	
Library							
Size			P/U	0.00	3.41		
Adjacencies			G/F	0.73	0.73	10	
Storage\Fixed Equip.			G/F	0.73	0.73	10	
P.E.							
Size			Fair	3.36	6.72	5	
Adjacencies			G/F	1.44	1.44	10	
Storage\Fixed Equip.			G/F	1.44	1.44	10	
Music							
Size			P/U	0.00	2.59		
Adjacencies			P/U	0.00	0.56		
Storage\Fixed Equip.			P/U	0.00	0.56		

^{Project #:} 4469 ^{Project:} Assessments 2010	^{County:} DeKalb ^{Region:} 1	^{Site #:} 3050 ^{Site:} Ashford Park ES				
Grade Config: PK-5	Site Type: Elementary		Site Size: 0.00			
Suitability		Rating	Score	Possible Score	Percent Score	
Art						
Size		Good	1.64	1.64	100.00	
Adjacencies		G/F	0.35	0.35	100.00	
Storage\Fixed Equip.		P/U	0.00	0.35	0.00	
Performing Arts\Auditorium						
Size		Good	2.12	2.12	100.00	
Adjacencies		Fair	0.30	0.45	67.00	
Storage\Fixed Equip.		Fair	0.23	0.45	50.00	
Computer Labs						
Size		P/U	0.00	1.19	0.00	
Adjacencies		G/F	0.26	0.26	100.00	
Storage\Fixed Equip.		G/F	0.26	0.26	100.00	
Kindergarten						
Size		P/U	0.00	2.86	0.00	
Adjacencies		G/F	0.61	0.61	100.00	
Storage\Fixed Equip.		P/U	0.00	0.61	0.00	
Administration						
Size		Fair	1.25	2.49	50.00	
Adjacencies		G/F	0.53	0.53	100.00	
Storage\Fixed Equip.		G/F	0.53	0.53	100.00	
Restrooms (Student)		Fair	0.44	0.89	50.00	
Teacher Lounge and Work Room(s)		Fair	0.63	1.27	50.00	
Cafeteria		Unsat	0.00	5.00	0.00	
Food Prep		Fair	4.16	6.20	67.00	
Counseling		Good	0.29	0.29	100.00	
Clinic		P/U	0.00	0.58	0.00	
Custodial & Maintenance		G/F	0.50	0.50	100.00	
Total For Site:			62.28	100.00	62.28	

Comments

Suitability - Elementary

Ashford Park is a traditional pre-k through grade 5 elementary school located in the heart of a residential neighborhood.

Suitability - Elementary->Site-->Traffic

The parent drop lane is on street, but one-way and seems to work well and have good separation.

Suitability - Elementary->Site-->Pedestrian Traffic

The site needs additional sidewalks around the building on both sides.

Suitability - Elementary->Site-->Parking

The off street parking is inadequate for the school on a daily basis and very inadequate for school events. Some of the off street parking is on dirt.

Suitability - Elementary->Site-->Playground

The school has a large field that is poorly graded. It floods during rains, has poor ADA accessibility, has no sprinkler system and the grass is in poor condition. Portable trailers on the fields are an obstruction for supervision. The blacktop play area is cracked with grass growing through and has no lines or basketball hoops, etc. Playground equipment has ramps, but no fencing and is on wood chips.

Project #:	4469	County:	DeKalb		Site #: 3050		
Project:	Assessments 2010	Region:	1	Site: Ashford Park ES			
Grade Config:	РК-5	Site Type:	Elementary	Site Size: 0.00			
						Possible	Percent
Suitability				Rating	Score	Score	Score

Suitability - Elementary->Safety and Security-->Fencing One area of the fence near the playground is damaged and down, and fencing is needed near the parent drop off to prevent unfettered access to the playground areas. Suitability - Elementary->Safety and Security-->Signage & Way Finding All rooms are well marked; however, the site lacks way finding to the major spaces. Suitability - Elementary->Safety and Security-->Ease of Supervision The lighting outside is inadequate. Suitability - Elementary->Safety and Security-->Sprinkler System The school does not have fire sprinklers. Suitability - Elementary->School Climate-->Learning Style Variety The school lacks small group breakout or testing areas. Suitability - Elementary->School Climate-->School Environment The hall lighting was reported as inconsistent, but appeared adequate. Suitability - Elementary->School Climate-->Landscaping The school has landscaping, but the grass is spotty in the fields and some other areas - reflected in the site rating. The fields have serious drainage issues and the blacktop was cracked and barely usable. Suitability - Elementary->General Classrooms-->Adjacencies Some of the classes are not near the computer lab which is isolated on one side of the school. Suitability - Elementary->General Classrooms-->Storage\Fixed Equip. Storage was adequate, and most classes had smartboards instead of whiteboards. Suitability - Elementary->Library-->Size The library is only 2,160 square feet, well below the 4,500 DCSS standard. Suitability - Elementary->P.E.-->Size The gym square footage of 4,410 is below the DCSS standard of 5,400. Suitability - Elementary->Music-->Size The music room is 912 square feet and below the 1,100 DCSS standard. Suitability - Elementary->Music-->Adjacencies The music room is located in the middle of classrooms. Suitability - Elementary->Music-->Storage\Fixed Equip. The room lacked adequate storage and does not have a whiteboard. Suitability - Elementary->Art-->Size The art room is also the music room. Suitability - Elementary->Art-->Storage\Fixed Equip. The room lacked adequate storage and does not have a whiteboard. Suitability - Elementary->Performing Arts\Auditorium-->Adjacencies Noise from the stage extends to the main office. There is not sufficient acoustical separation. Suitability - Elementary->Performing Arts\Auditorium-->Storage\Fixed Equip. The stage lacks adequate storage. Suitability - Elementary->Computer Labs-->Size The computer lab is 744 square feet and less than the 1,100 DCSS standard. Suitability - Elementary->Kindergarten-->Size All of the kindergarten and pre-k spaces are less than 800 square feet and do not meet the 900 square foot DCSS standard.

Project #: Project:	Assessments 2010	County: Region:	DeKalb 1		^{Site #:} 3050 ^{Site:} Ashford Park ES					
Grade Config:	PK-5	Site Type:	Elementary		Site Size: 0.00					
Suitability				Rating	Score	Possible Score	Percent Score			
Suitability - Elementary->Kindergarten>Storage\Fixed Equip. The storage for all the kindergarten and pre-k spaces is limited.										
•	Elementary->Administration>S office is inadequate in size for th									
•	Elementary->Restrooms (Studer restrooms generally lacked priva	,	d some stalls had	broken locks.						
The workro	Elementary->Teacher Lounge an oom is too small and has an inac e of the facility making accessib	dequate number	,	n the workroom a	ind lounge are	isolated				
The cafete	Elementary->Cafeteria ria is about 3,600 square feet, b everal electrical outlets that do n		DCSS standards.	The space is cra	amped, lacks s	storage,				
The food p	Elementary->Food Prep rep area is small for a school of adequate in size.	this size and ha	s limited storage a	and very old equi	ipment. The of	fice in the				
•	Elementary->Clinic s too small and lacks an attache	ed bathroom.								
•	Elementary->Custodial & Mainte ustodial closets lacked adequate									

Technology Readiness Report

Technology Readiness Report - Full

Project #: 4469	County:	DeKalb		Site #:	3050		
Project: Assessments 2010	Region:	1		Site:	Ashford Park ES		
Technology Readiness			Rating		Score	Possible Score	Percent Score
Technology Readiness							
MDF\IT Equipment Environment			Fair		7.50	15.00	50.00
Electrical Power			Good		10.00	10.00	100.00
Cooling			Good		10.00	10.00	100.00
Drops			Poor		3.30	10.00	33.00
Wireless			Unsat		0.00	5.00	0.00
WAN Backbone			Good		10.00	10.00	100.00
LAN-WAN Performance			Fair		6.70	10.00	67.00
Video Distribution			Unsat		0.00	5.00	0.00
Voice Distribution			Good		5.00	5.00	100.00
Faculty & Staff Technology			Good		10.00	10.00	100.00
Emergency Alert			Good		5.00	5.00	100.00
Projectors			Unsat		0.00	5.00	0.00
Total For Site:					67.50	100.00	67.50

Comments

Technology Readiness->MDF\IT Equipment Environment

The equipment area is properly conditioned and accessible, but is in a regular office type room with glass windows to the outside and on the door, making security tenuous. The space is large but lacks storage areas.

Technology Readiness->Drops

All rooms have two drops, but few have four computers per room. Most rooms have only one drop for the teacher and a smartboard.

Technology Readiness->Wireless Only the media center and portables have wireless.

Technology Readiness->LAN-WAN Performance Staff estimate the Internet reliability at 80-90 percent.

Technology Readiness->Video Distribution Only the media center has access to cable.

Technology Readiness->Projectors

All classes except 3-4 have smartboards (approximately 93 percent); however, some are on carts or wall mounted.