Facility Condition Assessment Report

1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Avondale Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011
Facility: \Elementary Schools\ Address: 10 Lakeshore Drive,		
Attributes: Facility Code	5050	
Attributes: Facility Code Super Cluster	5050 5	

Facility Description:

Gross Area:

The Avondale Elementary School campus consists of two buildings located at 10 Lakeshore Drive in Avondale Estates, Georgia. The original campus was constructed in 1953, additions to the main school building were constructed in 1967, 1975, 1988, and 1994, and a gymnasium building was constructed in 2003. In addition to these buildings, the campus contains a storage building. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for each building or other facility on the campus.

71,576 S.F.

Current Repair Cost: \$10,226,565.99

Replacement Cost: \$19,641,998.99

Last Renovation:

FCI: 52.06%



03-Dec-2010 Avondale Elementary School

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 FCI Report Avondale Elementary Weighted FCI Report

Report Date: 28 Jun 2011

Facility Name	Last Renovation	Cost Per Sq. Ft.	Gross Area (Sq. Ft.)	Repair Cost	Replacement Cost	Weighted FCI	Critical wt 1.25	Potentially Critical wt 1.1	Necessary wt 1	Recommended wt 0.75	Discretionary wt 0.5
Avondale Elementary\Site		\$95.98	71,567	\$6,454,826	\$6,869,262	93.97%	\$0	\$0	\$6,454,826	\$0	\$0
Avondale Elementary\1953, 1967, 1975	Jan 1975	\$187.05	44,882	\$3,470,891	\$8,395,071	38.35%	\$0	\$0	\$2,473,431	\$989,133	\$8,327
Building											
Avondale Elementary\2003 Gym		\$152.52	5,478	\$165,574	\$835,515	19.82%	\$0	\$0	\$165,574	\$0	\$0
Avondale Elementary\1988 Addition		\$162.32	9,450	\$135,274	\$1,533,949	6.61%	\$0	\$0	\$0	\$135,274	\$0
Avondale Elementary\Storage Building		\$71.43	100	\$0	\$7,143	0.00%	\$0	\$0	\$0	\$0	\$0
Avondale Elementary\1994 Addition		\$170.07	11,766	\$0	\$2,001,058	0.00%	\$0	\$0	\$0	\$0	\$0

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 FCI Report Avondale Elementary Weighted FCI Report

Report Date: 28 Jun 2011

Facility Name	Last Renovation	Cost Per Sq. Ft.	Gross Area (Sq. Ft.)	Repair Cost	Replacement Cost	Weighted FCI	Critical wt 1.25	Potentially Critical wt 1.1	Necessary wt 1	Recommended wt 0.75	Discretionary wt 0.5
Avondale Elementary\Site		\$95.98	71,567	\$6,454,826	\$6,869,262	93.97%	\$0	\$0	\$6,454,826	\$0	\$0
Avondale Elementary\1953, 1967, 1975	Jan 1975	\$187.05	44,882	\$3,470,891	\$8,395,071	38.35%	\$0	\$0	\$2,473,431	\$989,133	\$8,327
Building											
Avondale Elementary\2003 Gym		\$152.52	5,478	\$165,574	\$835,515	19.82%	\$0	\$0	\$165,574	\$0	\$0
Avondale Elementary\1988 Addition		\$162.32	9,450	\$135,274	\$1,533,949	6.61%	\$0	\$0	\$0	\$135,274	\$0
Avondale Elementary\Storage Building		\$71.43	100	\$0	\$7,143	0.00%	\$0	\$0	\$0	\$0	\$0
Avondale Elementary\1994 Addition		\$170.07	11,766	\$0	\$2,001,058	0.00%	\$0	\$0	\$0	\$0	\$0

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building Address: 10 Lakeshore Drive, Avondale Estates, GA 30002

Gross Area:	44,882 S.F.	Last Renovation:	1975
General Information: Function:	Elementary School	Year Built:	1953
Attributes: Building Codes Fire Sprinkler System	2010, 2011, 2012 Yes		

Facility Description:

The Avondale Elementary School main building is a one-story building located at 10 Lakeshore Drive in Avondale Estate, Georgia. Originally built in 1953, there have been four additions in 1967, 1975, 1988, and 1994, HVAC renovations in 2008, roof renovations in 2009, and lighting upgrades in 2008, 2009, and 2010. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Energy conservation opportunities for this building include: 1) Replacing exterior doors and windows; 2) Replacing the electrical service and distribution; 3) Replacing the exterior lighting; and 4) Replacing the plumbing fixtures in conjunction with domestic water distribution and sanitary sewer system upgrades.

Current Repair Cost: \$3,470,890.80



03-Dec-2010 West Elevation

Replacement Cost: \$8,395,071.41



03-Dec-2010 South Elevation



03-Dec-2010 Southeast Elevation

FCI: 41.34%



03-Dec-2010 East Elevation

DeKalb County School Sys	tem	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Avondale Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011
Facility: \Elementary Schools\	Avondale Elementary\1953, 1967, 1975 Building (continued)	

Building Condition:

System	Unit Price\$	Unit of Meas	Qty	Renewal%	Renewal\$	Life	Installed	Calc Next Renewal	Next Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$187.05	S.F.	44,882	108	\$9,062,452	39	1973	1961	2015		\$3,470,889	\$8,395,071	41
Substructure	\$13.21	S.F.	44,882	100	\$592,739	100	1953				**, ****	\$592,739	
Foundations	\$13.21	S.F.	44,882	100	\$592,739	100	1953					\$592,739	<u> </u>
Standard Foundations	\$6.49	S.F.	44,882	100	\$291,105	100	1953					\$291,105	
Special Foundations	\$4.14	S.F.	0	100	+,	100	1953						<u> </u>
Slab on Grade	\$6.72	S.F.	44,882	100	\$301,634	100	1953					\$301,634	
Basement Construction	¢0.72	0	0		\$001,001	0	0					\$001,001	
Basement Excavation		S.F.	0	100		100	1953						
Basement Walls		S.F.	0	100		100	1953						
	¢22.20				¢1 504 700			1002			\$202.00F	£1 444 000	20
Shell	\$32.20	S.F.	44,882	104	\$1,504,700	69	1962	1963			\$382,895	\$1,444,992	26
Superstructure	\$4.43	S.F.	44,882	100	\$198,818	100	1953					\$198,818	L
Floor Construction	-	S.F.	0	100		100	1953						
Roof Construction	\$4.43	S.F.	44,882	100	\$198,818	100	1953					\$198,818	
Exterior Enclosure	\$21.65	S.F.	44,882	103	\$1,004,062	75	1953	1983			\$354,961	\$971,793	37
Exterior Walls	\$14.46	S.F.	44,882	100	\$649,101	100	1953					\$649,101	
Exterior Windows	\$6.32	S.F.	44,882	110	\$312,039	30	1953	1983			\$312,039	\$283,672	110
Exterior Doors	\$0.87	S.F.	44,882	110	\$42,922	30	1953	1983			\$42,922	\$39,020	110
Roofing	\$6.11	S.F.	44,882	110	\$301,820	25	1978	1963			\$27,934	\$274,381	10
Roof Coverings - Asphal		S.F.	0	110		10	1953	1963					
Shingles													1
Roof Coverings - BUR	\$5.55	S.F.	44,882	110	\$273,886	25	2004	2029				\$248,987	
Roof Coverings - EPDM		S.F.	0	110	,	15	1953	1968					
Roof Coverings - Preformed		S.F.	0	110		30	1953	1983					
Metal			v										
		00	0	110		75	1052	2020					l
Roof Coverings - Standing		S.F.	0	110		75	1953	2028					1
Seam Metal													L
Roof Openings	\$0.57	S.F.	44,882	110	\$27,934	30	1953	1983			\$27,934	\$25,394	110
Interiors	\$40.49	S.F.	44,882	108	\$1,971,022	41	1960	1961	2018		\$1,108,112	\$1,817,345	61
Interior Construction	\$11.04	S.F.	44,882	104	\$516,989	70	1953	1973			\$200,862	\$495,497	41
Partitions	\$6.40	S.F.	44,882	110	\$316,127	100	1953					\$287,388	
Interior Doors	\$2.08	S.F.	44,882	80	\$74,820	30	1953	1983			\$74,820	\$93,525	80
Fittings	\$2.55	S.F.	44,882	110	\$126,042	20	1953	1973			\$126,042	\$114,584	110
Stairs			0			0	0						
Stair Construction		S.F.	0	100		100	1953						
Interior Finishes	\$29.45	S.F.	44,882	110	\$1,454,033	31	1968	1961	2018		\$907,250	\$1,321,848	69
Wall Finishes - Ceramic &	\$9.58	S.F.	8,976	110	\$94,561	30	1953	1983			\$94,561	\$85,965	110
Glazed		•	-,		+,						••••		
Wall Finishes - Paint	\$1.81	S.F.	35,906	110	\$71,402	10	2009	2019				\$64,911	l
	φ1.01	S.F.		110	\$71,402	10	1953	1963				\$04,911	I
Wall Finishes - Wall Coverings	¢7.07		0		¢77.000						¢77.000	\$70.005	
Floor Finishes - Carpet	\$7.87	S.F.	8,976	110	\$77,666	8	1953	1961			\$77,666	\$70,605	110
Floor Finishes - Ceramic &	\$13.40	S.F.	4,489	110	\$66,167	50	1953	2003			\$66,167	\$60,152	110
Quarry Tile													
Floor Finishes - Terrazzo	\$48.99	S.F.	8,976	110	\$483,708	50	1953	2003	2018	8	\$8,327	\$439,734	2
Floor Finishes - VCT	\$8.79	S.F.	22,441	110	\$216,997	20	1953	1973			\$216,997	\$197,270	110
Floor Finishes - Wood		S.F.	0	110		20	1953	1973					
Ceiling Finishes	\$8.98	S.F.	44,882	110	\$443,532	20	1953	1973			\$443,532	\$403,211	110
Services	\$87.73	S.F.	44,882	110	\$4,331,078	23	1987	1973	2015		\$1,771,402	\$3,937,346	45
Conveying			0			0	0						
Elevators and Lifts		S.F.	0	110		30	1953	1983					
Plumbing	\$24.01	S.F.	44,882	110	\$1,185,477	23	1968	1973	2015		\$1,122,796	\$1,077,707	104
Plumbing Fixtures	\$16.10	S.F.	44,882	110	\$795,087	20	1953	1973			\$795,087	\$722,807	110
Domestic Water Distribution	\$3.59	S.F.	44,882	110	\$177,140	30	1953	1983			\$177,140	\$161,037	110
Sanitary Waste	\$3.05	3.F. S.F.	44,882	110	\$177,140	30	1953	1983			\$150,569	\$136,881	110
-						30					\$15U,569		
Rain Water Drainage	\$0.88	S.F.	44,882	110	\$43,604		2004	2034				\$39,640	
Other Plumbing Systems -	\$0.39	S.F.	44,882	110	\$19,077	30	1975	2005	2015	5		\$17,342	1
Natural Gas													
HVAC	\$34.73	S.F.	44,882	110	\$1,714,853	22	1999	1983			\$230,282	\$1,558,960	15
Heat Generating Systems	\$4.15	S.F.	44,882	110	\$205,074	30	2008	2038				\$186,431	
Cooling Generating Systems	\$4.22	S.F.	44,882	110	\$208,480	30	2008	2038				\$189,528	
Distribution & Exhaust Systems	\$4.66	S.F.	44,882	110	\$230,282	30	1953	1983			\$230,282	\$209,348	110
Terminal & Package Units	\$17.29	S.F.	44,882	110	\$853,680	15	2008	2023				\$776,073	
Controls & Instrumentation	\$3.23	S.F.	44,882	110	\$159,426	20	2008	2028				\$144,933	
Other HVAC Systems/Equip -	\$1.17	S.F.	44,882	110	\$57,911	30	2008	2038				\$52,647	
Kitchen Hood													
Fire Protection	\$4.25	S.F.	44,882	110	\$209,843	30	1980	2038				\$190,766	
Sprinklers	\$4.25	5.F. S.F.	44,882	110	\$209,843	30	2008	2038				\$190,766	
	φ4.25				φ209,843			2038				\$ 19U,766	I
Standpipes		S.F.	44,882	110		30	1953				-		
Electrical	\$24.73	S.F.	44,882	110	\$1,220,905	24	1991	1983			\$418,324	\$1,109,913	38

1701 Mountain Industrial Blvd
Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Electrical Service/Distribution	\$1.95	S.F.	44,882	110	\$96,065	30	1953	1983			\$96,065	\$87,331	110
Branch Wiring	\$6.53	S.F.	44,882	110	\$322,259	30	1953	1983			\$322,259	\$292,963	110
Lighting	\$8.58	S.F.	44,882	110	\$423,774	30	2008	2038				\$385,249	
Communications and Security -	\$5.51	S.F.	44,882	110	\$271,842	10	2004	2014				\$247,129	
Clock & PA Systems													
Communications and Security -	\$1.20	S.F.	44,882	110	\$59,274	10	2004	2014				\$53,885	
Fire Alarm													
Communications and Security -	\$0.59	S.F.	44,882	110	\$29,296	10	2010	2020				\$26,633	
Security & CCTV													
Other Electrical Systems -	\$0.37	S.F.	44,882	110	\$18,395	20	2008	2028				\$16,723	
Emergency Generator													
Equipment & Furnishings	\$13.43	S.F.	44,882	110	\$662,913	20	1953	1973	2015		\$208,480	\$602,649	35
Equipment	\$9.20	S.F.	44,882	110	\$454,433	20	1953	1973	2015			\$413,121	
Commercial Equipment		S.F.	44,882	110		20	1953	1973					
Institutional Equipment	\$0.40	S.F.	44,882	110	\$19,758	20	1953	1973	2015	5		\$17,962	
Other Equipment - Kitchen	\$8.80	S.F.	44,882	110	\$434,675	20	1953	1973	2018	8		\$395,159	
Equipment													
Furnishings	\$4.22	S.F.	44,882	110	\$208,480	20	1953	1973			\$208,480	\$189,528	110
Fixed Furnishings	\$4.22	S.F.	44,882	110	\$208,480	20	1953	1973			\$208,480	\$189,528	110
Special Construction		S.F.	44,882			0	1953	1978					
Special Construction		S.F.	44,882			0	1953	1978					
Special Structures - Canopies		S.F.	44,882	100		25	1953	1978					

DeKalb County School System		
1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avon	COMET4 Facility Report Iale Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$3,470,889		\$372,674	\$45,020			\$1,261,764	\$93,163	\$39,372		
Substructure											
Foundations											
Standard Foundations											
Special Foundations											
Slab on Grade											
Basement Construction											
Basement Excavation											
Basement Walls	* ****										-
Shell	\$382,895										
Superstructure											
Floor Construction											
Roof Construction											
Exterior Enclosure	\$354,961										
Exterior Walls											
Exterior Windows	\$312,039										
Exterior Doors	\$42,922										
Roofing	\$27,934										-
Roof Coverings - Asphal Shingles	· · · · · · · · · · · · · · · · · · ·					1					+
Roof Coverings - BUR											+
Roof Coverings - EPDM							+				+
Roof Coverings - Preformed Metal											+
											+
Roof Coverings - Standing Seam											
Metal											
Roof Openings	\$27,934										
Interiors	\$1,108,112						\$711,131	\$93,163			
Interior Construction	\$200,862										
Partitions											
Interior Doors	\$74,820										
Fittings	\$126,042										
Stairs											-
Stair Construction											
Interior Finishes	\$907,250						\$711,131	\$93,163			
Wall Finishes - Ceramic & Glazed	\$94,561						•••••				
Wall Finishes - Paint	ψ04,001							\$93,163			
								\$95,105			
Wall Finishes - Wall Coverings	A77.000						6 00.005				
Floor Finishes - Carpet	\$77,666						\$98,385				
Floor Finishes - Ceramic & Quarry	\$66,167										
Tile											
Floor Finishes - Terrazzo	\$8,327						\$612,746				
Floor Finishes - VCT	\$216,997										
Floor Finishes - Wood											
Ceiling Finishes	\$443,532										
Services	\$1,771,402		\$372,674	\$22,115					\$39,372		-
Conveying											
Elevators and Lifts											+
Plumbing	\$1,122,796			\$22,115			+				+
Plumbing Fixtures	\$795,087			ψ22,110			+				+
											+
Domestic Water Distribution	\$177,140										
Sanitary Waste	\$150,569										
Rain Water Drainage											
Other Plumbing Systems - Natural				\$22,115							
Gas											
HVAC	\$230,282										
Heat Generating Systems											1
Cooling Generating Systems						1					1
Distribution & Exhaust Systems	\$230,282					1					1
Terminal & Package Units							+ +				+
Controls & Instrumentation							+				+
Other HVAC Systems/Equip -	-										+
Kitchen Hood	-										+
Fire Protection											<u> </u>
Sprinklers											
Standpipes											
Electrical	\$418,324		\$372,674						\$39,372		

DeKalb County School System COMET4 Facility Report 1701 Mountain Industrial Blvd Report Date: 28 Jun 2011 Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083 2010-12 2015 2016 2017 2019 Systems 2013 2014 2018 2020 2021 2022 Electrical Service/Distribution \$96,065 Branch Wiring \$322,259 Lighting Communications and Security -\$305,961 Clock & PA Systems \$66,713 Communications and Security - Fire Alarm Communications and Security -\$39,372 Security & CCTV Other Electrical Systems -Emergency Generator Equipment & Furnishings \$208,480 \$22,905 \$550,633 Equipment \$22,905 \$550,633 Commercial Equipment Institutional Equipment \$22,905 \$550,633 Other Equipment - Kitchen Equipment \$208,480 Furnishings

Fixed Furnishings

Special Construction Special Construction Special Structures - Canopies \$208,480

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	B2020	Priority:	3	
System:	Exterior Windows	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The original metal frame, single pan	e, operable windows are aged,	worn, and inefficient a	nd should be replaced.



Estimates:

Raw Cost	\$226,115.52
Plus or (Minus) Additional Cost	\$85,923.90
Total Estimated Amount	\$312,039.42

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	B2030	Priority:	4	
System:	Exterior Doors	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The original metal exterior doors are aged, i	rusted, and damaged, a	nd should be replaced.	



Estimates:

Raw Cost \$31,103.23 Plus or (Minus) Additional Cost \$11,819.23 Total Estimated Amount \$42,922.46

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	B3020	Priority:	4	
System:	Roof Openings	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The roof opening does not follow OSHA guideling	nes and should be i	replaced.	
Correction:	Renew System	nes and should be	replaced.	



Estimates:

Raw Cost	\$20,241.78
Plus or (Minus) Additional Cost	\$7,691.88
Total Estimated Amount	\$27,933.66

Fri, 24-Jun-2011

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

C1020Priority:4Interior DoorsQuantity:1SystemBeyond Service Life5Deferred MaintenanceFenew SystemThe original interior wood doors are aged and worn and should be replaced.

Surveyor/Update:

Walter Williams



Estimates:

Raw Cost\$54,217.46Plus or (Minus) Additional Cost\$20,602.63Total Estimated Amount\$74,820.09

COMET4 Facility Report 1701 Mountain Industrial Blvd Report Date: 28 Jun 2011 Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency:

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	C1030	Priority:	3	
System:	Fittings	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	Fittings, such as chalk and tack boards, damaged, and should be replaced.	toilet and bath accessories	s, toilet partitions, and	shelving, are aged and



Estimates:

Note:

Raw Cost	\$91,334.87
Plus or (Minus) Additional Cost	\$34,707.25
Total Estimated Amount	\$126,042.12

Deficiency:		Surveyor/Update:	Walter Williams	Sun, 26-Jun-2011
Assembly:	C3010	Priority:	3	
System:	Wall Finishes - Ceramic & Glazed	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			

The ceramic tile wall covering is aged, damaged, and cracked, and should be replaced



Estimates:

Raw Cost	\$68,522.78
Plus or (Minus) Additional Cost	\$26,038.66
Total Estimated Amount	\$94,561.44

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avondale

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

24-Jun-2011

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Fri, 2



Estimates:

Raw Cost	\$56,279.52
Plus or (Minus) Additional Cost	\$21,386.22
Total Estimated Amount	\$77,665.74

Tue, 01-Feb-2011

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

 C3020
 Priority:
 3

 Floor Finishes - Ceramic & Quarry Tile
 Quantity:
 1

 System
 Beyond Service Life
 5

 Deferred Maintenance
 Renew System
 5

 The ceramic tile is aged, worn, chipped, cracked, and patched, and should be replaced.
 5

Surveyor/Update:

Walter Williams



Estimates:

Raw Cost	\$47,947.01
Plus or (Minus) Additional Cost	\$18,219.86
Total Estimated Amount	\$66,166.87

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency:		Surveyor/Update:	Kate McPhillips	Fri, 01-Apr-2011
Assembly:	C3020	Priority:	5	
System:	Floor Finishes - Terrazzo	Quantity:	700	
Material:	Terrazzo, Flooring			
Distress:	Damaged			
Category:	Deferred Maintenance			
Correction:	Repair Terrazzo			
Note:	The terrazo is stained with water damage and is showing signs of possible seepage. It is suggested that the water barrier be replaced.			



Estimates:

Raw Cost	\$6,034.00
Plus or (Minus) Additional Cost	\$2,292.92
Total Estimated Amount	\$8,326.92

Deficiency:

Assembly: System: Material: Distress: Category: Correction: Note:

C3020 **Floor Finishes - VCT** System Beyond Service Life **Deferred Maintenance Renew System**

Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Priority:	3	
Quantity:	1	

The VCT flooring is stained, cracked, chipped, and patched, and should be replaced. In some areas of the building, the floor is still covered with the original 9x9 tile.



Estimates:

Raw Cost \$157,244.09 Plus or (Minus) Additional Cost \$59,752.75 **Total Estimated Amount** \$216,996.84

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 21-Jun-2011
Assembly:	C3030	Priority:	4	
System:	Ceiling Finishes	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The acoustical ceiling tile and grid sy	ystem is aged, rusted, and dam	naged, and should be r	eplaced.



Estimates:

Raw Cost	\$321,400.00
Plus or (Minus) Additional Cost	\$122,132.00
Total Estimated Amount	\$443,532.00

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

D2010 **Plumbing Fixtures** System Beyond Service Life **Deferred Maintenance** Renew System The original plumbing fixtures are chipped, stained, and showing signs of excessive wear, and should be replaced.

Surveyor/Update: Priority: 3 Quantity: 1

Walter Williams

Fri, 24-Jun-2011

Estimates:

Raw Cost	\$576,150.23
Plus or (Minus) Additional Cost	\$218,937.09
Total Estimated Amount	\$795,087.32

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	D2020	Priority:	3	
System:	Domestic Water Distribution	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The domestic water laterals are aged, co	orroded, have periodic outa	ges, and should be re	placed.



Estimates:

Raw Cost	\$128,362.52
Plus or (Minus) Additional Cost	\$48,777.76
Total Estimated Amount	\$177,140.28

Tue, 01-Feb-2011

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

Surveyor/Update: Walter Williams Priority: 3 D2030 Sanitary Waste Quantity: 1 System **Beyond Service Life Deferred Maintenance Renew System** The original cast iron sanitary waste system is aged, has reported odors, multiple stoppages, and should be replaced.



Estimates:

\$109,108.14 Raw Cost \$41,461.09 Plus or (Minus) Additional Cost Total Estimated Amount \$150,569.23

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Fri, 24-Jun-2011
Assembly:	D3040	Priority:	3	
System:	Distribution & Exhaust Systems	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The exhaust system is aged and inefficier	nt and should be replaced		



Estimates:

Raw Cost	\$166,871.28
Plus or (Minus) Additional Cost	\$63,411.08
Total Estimated Amount	\$230,282.36

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

Priority: 3 D5010 Quantity: 1 **Electrical Service/Distribution** System **Beyond Service Life Deferred Maintenance Renew System** The main electrical switchboard is aged, becoming logistically unsupportable, and should be replaced.



Estimates:

Raw Cost \$69,611.98 Plus or (Minus) Additional Cost \$26,452.55 Total Estimated Amount \$96,064.53

Surveyor/Update: Walter Williams Tue, 01-Feb-2011

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\1953, 1967, 1975 Building (continued)

D			
1 1011	CIO	nci	
Defi	CIC	1101	

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	D5020	Priority:	4	
System:	Branch Wiring	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The original branch wiring system is replaced.	operational, but is aged, neari	ng capacity, in poor c	ondition, and should be



Estimates:

Raw Cost	\$233,521.05
Plus or (Minus) Additional Cost	\$88,738.00
Total Estimated Amount	\$322,259.05

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

E2010 **Fixed Furnishings** System Beyond Service Life **Deferred Maintenance Renew System**

Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Priority:	3	
Quantity:	1	

Fixed furnishings, such as the base/wall cabinets, counter tops, window shades, and fixed seating, are worn, beyond service life, and should be replaced.



Estimates:

Raw Cost \$151,072.81 Plus or (Minus) Additional Cost \$57,407.67 **Total Estimated Amount** \$208,480.48

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\1988 Addition Address: 10 Lakeshore Drive, Avondale Estates, GA 30002

Attributes: Building Codes Fire Sprinkler System	2013 Yes		
General Information: Function: Gross Area:	Elementary School 9,450 S.F.	Year Built: Last Renovation:	1988

Facility Description:

The 1988 Classroom Addition at Avondale Elementary School is one-story building located at 10 Lakeshore Drive in Avondale Estate, Georgia. There have been HVAC renovations in 2008, roof renovations in 2009, and lighting upgrades in 2008, 2009, and 2010. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

There are no energy conservation opportunities for this building at this time.

Current Repair Cost: \$135,274.29

Replacement Cost: \$1,533,949.49



03-Dec-2010 Southwest Elevation



03-Dec-2010 West Elevation



03-Dec-2010 Northwest Elevation

FCI: 8.82%



03-Dec-2010 East Elevation

DeKalb County School System	DeKalb	County	School S	vstem
-----------------------------	--------	--------	----------	-------

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1988 Addition (continued)

Building Condition:

System	Unit Price\$	Unit of Meas	Qty	Renewal%	Renewal\$	Life	Installed	Calc Next Renewal	Next Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$162.32	S.F.	9,450	108	\$1,649,982	40	1994	1996	2015	ROL	\$135,274	\$1,533,952	9
Substructure	\$13.21	S.F.	9,450	100	\$124,803	100	1988		2010		\$100,211	\$124,803	
Foundations	\$13.21	S.F.	9,450	100	\$124,803	100	1988					\$124,803	-
Standard Foundations	\$6.49	S.F.	9,450	100	\$61,293	100	1988					\$61,293	-
Special Foundations	\$4.14	S.F.	0	100	••••	100	1988						-
Slab on Grade	\$6.72	S.F.	9,450	100	\$63,510	100	1988					\$63,510	
Basement Construction	• -	_	0		*	0	0						-
Basement Excavation		S.F.	0	100		100	1988						
Basement Walls		S.F.	0	100		100	1988						
Shell	\$32.20	S.F.	9,450	104	\$316,818	69	1991	1998				\$304,248	-
Superstructure	\$4.43	S.F.	9,450	100	\$41,862	100	1988					\$41,862	-
Floor Construction		S.F.	9,450	100		100	1988						
Roof Construction	\$4.43	S.F.	9,450	100	\$41,862	100	1988					\$41,862	
Exterior Enclosure	\$21.65	S.F.	9,450	103	\$211,408	75	1988	2018				\$204,614	-
Exterior Walls	\$14.46	S.F.	9,450	100	\$136,670	100	1988					\$136,670	
Exterior Windows	\$6.32	S.F.	9,450	110	\$65,701	30	1988	2018				\$59,728	-
Exterior Doors	\$0.87	S.F.	9,450	110	\$9,037	30	1988	2018				\$8,216	-
Roofing	\$6.11	S.F.	9,450	110	\$63,548	25	1998	1998				\$57,772	-
Roof Coverings - Asphal	• -	S.F.	0	110	*	10	1988	1998					
Shingles			5										
Roof Coverings - BUR	\$5.55	S.F.	9,450	110	\$57,667	25	2009	2034				\$52,425	+
Roof Coverings - EPDM	\$0.00	S.F.	0,400	110	101,001	15	1988	2004				, .LU	+
Roof Coverings - Preformed		S.F.	0	110		30	1988	2000					+
Metal		5	5					20.0					
Roof Coverings - Standing		S.F.	0	110		75	1988	2063				+	+
Seam Metal		0.1 .	0	110		10	1000	2000					
Roof Openings	\$0.57	S.F.	9,450	110	\$5,881	30	1988	2018				\$5,347	
Interiors	\$33.76	S.F.	9,450	108	\$345,047	38	1900	1996	2015		\$91,378	\$319,050	29
Interior Construction	\$11.04	S.F.	9,450	100	\$108,853	70	1994	2018	2013		491,570	\$104,328	23
Partitions	\$6.40	S.F.	9,450	110	\$66,561	100	1995	2010				\$60,510	
Interior Doors	\$2.08	S.F.	9,450	80	\$15,754	30	1900	2018				\$19,692	
	\$2.08	5.F. S.F.	9,450	110	\$15,754	20	2008	2018				\$19,692	
Fittings Stairs	\$2.55	э.г.	9,450	110	\$20,538	20	2008	2028				\$24,120	
		0.5		400									
Stair Construction Interior Finishes	\$22.72	S.F.	0	100 110	\$000 404	100 23	1988 1993	1996	0045		\$ 04.070	\$044.700	- 10
Wall Finishes - Ceramic &	\$22.72	S.F.	9,450	110	\$236,194 \$15,170	30		2018	2015		\$91,378	\$214,722 \$13,791	43
	\$9.56	S.F.	1,440	110	\$15,170	30	1988	2016				\$13,791	
Glazed Wall Finishes - Paint	6 4.04	S.F.	7 500	110	\$15,034	10	2008	2018				¢40.007	<u> </u>
	\$1.81	5.F. S.F.	7,560	110	\$15,034	10	1988	1998				\$13,667	
Wall Finishes - Wall Coverings		5.F. S.F.	0	110		10	1966	1998					
Floor Finishes - Carpet	\$13.40			110	\$21,225	8 50	1966	2038				\$19,296	
Floor Finishes - Ceramic & Quarry Tile	\$13.40	S.F.	1,440	110	\$21,225	50	1900	2036				\$19,290	
Floor Finishes - Terrazzo	£40.00	0.5	0	110		50	1988	2038					
	\$48.99	S.F.	0		¢04.070	50 20					\$ 04.070	¢00.074	- 110
Floor Finishes - VCT	\$8.79	S.F.	9,450	110	\$91,378		1988	2008			\$91,378	\$83,071	110
Floor Finishes - Wood	\$ 0.00	S.F.	0	110 110	\$00.007	20	1988	2008	0045	-		\$04.007	<u> </u>
Ceiling Finishes	\$8.98 \$77.75	S.F.	9,450	110	\$93,387 \$808,203	20 22	1988 1997	2008 2008	2015 2015	5		\$84,897	<u> </u>
Services	\$11.15	S.F.	9,450	110	\$606,203			2006	2015			\$734,731	<u> </u>
Conveying		0.5	0	110		0	0	0040					<u> </u>
Elevators and Lifts	6040	S.F.	0	110	\$0.10 00F	30	1988	2018	0045			\$000 0 fo	<u> </u>
Plumbing	\$24.01	S.F.	9,450	110	\$249,605	23	1988	2008	2015	-		\$226,913	<u> </u>
Plumbing Fixtures	\$16.10	S.F.	9,450	110	\$167,407	20	1988	2008	2015	5		\$152,188	<u> </u>
Domestic Water Distribution	\$3.59	S.F.	9,450	110	\$37,297	30	1988	2018				\$33,907	
Sanitary Waste	\$3.05	S.F.	9,450	110	\$31,703	30	1988	2018				\$28,821	
Rain Water Drainage	\$0.88	S.F.	9,450	110	\$9,181	30	1988	2018				\$8,346	
Other Plumbing Systems -	\$0.39	S.F.	9,450	110	\$4,017	30	1988	2018				\$3,651	
Natural Gas													
HVAC	\$24.32	S.F.	9,450	110	\$252,761	18	2003	2018				\$229,783	
Heat Generating Systems	\$4.15	S.F.	0	110		30	2008	2038					
Cooling Generating Systems	\$4.22	S.F.	0	110		30	2008	2038					
Distribution & Exhaust Systems	\$3.80	S.F.	9,450	110	\$39,449	30	2008	2038				\$35,863	
Terminal & Package Units	\$17.29	S.F.	9,450	110	\$179,744	15	2008	2023				\$163,404	1
Controls & Instrumentation	\$3.23	S.F.	9,450	110	\$33,568	20	2008	2028				\$30,516	1
Other HVAC Systems/Equip -		S.F.	9,450	110		30	1988	2018					1
Kitchen Hood													
Fire Protection	\$4.69	S.F.	9,450	110	\$48,773	30	1988	2018				\$44,339	1
Sprinklers	\$4.25	S.F.	9,450	110	\$44,183	30	1988	2018				\$40,166	1
Standpipes	\$0.44	S.F.	9,450	110	\$4,590	30	1988					\$4,173	1
Electrical	\$24.73	S.F.	9,450	110	\$257,064	24	2003	2018	1			\$233,696	+

1701 Mountain Industrial Blvd
Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Electrical Service/Distribution	\$1.95	S.F.	9,450	110	\$20,227	30	1988	2018				\$18,388	
Branch Wiring	\$6.53	S.F.	9,450	110	\$67,852	30	1988	2018				\$61,684	
Lighting	\$8.58	S.F.	9,450	110	\$89,227	30	2008	2038				\$81,115	
Communications and Security -	\$5.51	S.F.	9,450	110	\$57,237	10	2008	2018				\$52,034	
Clock & PA Systems													
Communications and Security -	\$1.20	S.F.	9,450	110	\$12,480	10	2010	2020				\$11,346	
Fire Alarm													
Communications and Security -	\$0.59	S.F.	9,450	110	\$6,168	10	2010	2020				\$5,608	
Security & CCTV													
Other Electrical Systems -	\$0.37	S.F.	9,450	110	\$3,873	15	2008	2023				\$3,521	
Emergency Generator													
Equipment & Furnishings	\$4.22	S.F.	9,450	110	\$43,896	20	1988	2008			\$43,896	\$39,905	110
Equipment		S.F.	9,450			0	1988	2008					
Commercial Equipment		S.F.	9,450	110		20	1988	2008					
Institutional Equipment		S.F.	9,450	110		20	1988	2008					
Other Equipment		S.F.	9,450	110		20	1988	2008					
Furnishings	\$4.22	S.F.	9,450	110	\$43,896	20	1988	2008			\$43,896	\$39,905	110
Fixed Furnishings	\$4.22	S.F.	9,450	110	\$43,896	20	1988	2008			\$43,896	\$39,905	110
Special Construction	\$1.19	S.F.	9,450	100	\$11,215	25	1988	2013				\$11,215	
Special Construction	\$1.19	S.F.	9,450	100	\$11,215	25	1988	2013				\$11,215	
Special Structures - Canopies	\$1.19	S.F.	9,450	100	\$11,215	25	1988	2013				\$11,215	

DeKalb County School Syste	m	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Avondale Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\1988 Addition (continued)

Renewal Schedule:

Teal 935.292 92.283 99.203 99.2030 99.2030 99.2030 99.2030 99.2030 Faundator	Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Sabarbai Docaling Torolation Social for electronic distance Social for electronic distan							-					-
FeasibleImageImageImageImageImageImageImageImageImageSparand FoundariaImageIma		\$100,211	¢12,200		¢002,002			\$66 1,6 16		\$20,00E		
Border Automation Booked Factoriant Booked Factoriant Booke												
Book of control Book of c												
Bits or Suis Bissener Cartany Bissener Cartany<												
Instrum Image: Second Sec												
Bacanan bisonation Image Image <td></td>												
Descent Valid Descent												
Self Self <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>												
Super-Structure Image: Structure Image: Structure </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td> <td></td>								-				
Find Communition Image Image <thimage< th=""> Image Image</thimage<>								\$102,126				
Red Construction Image												
Ensite relations Image: state in the state												
Energy Wals Image												
Enter Undos Mail Status Status Status Rofing Participation Participation Participation Participation Rofing Participation Participation Participation Participation Rof Covering - Ruft Participation Participation Participation Participation Rof Covering - Stating								\$94,676				
Entern Doos Image Image <thimage< th=""> Image Image</thimage<>												
Roofing Image <	Exterior Windows							\$83,228				
Red Coverge - shall singlesImage <thimage< th="">ImageImageImage<</thimage<>	Exterior Doors							\$11,448				
Roof Covings - BVM Image Image <td>Roofing</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>\$7,450</td> <td></td> <td></td> <td></td> <td></td>	Roofing							\$7,450				
Red Covering- PPM Image	Roof Coverings - Asphal Shingles											
Rod Coverings - Protomol Meal Meal No. No. No. Rod Coverings - Standing Seam No. 17.40 17.40 1 Meal Standing Seam 100.261 \$105.261 100.261 1 Interior Construction 100.261 \$105.261 \$105.261 1 1 Particina 1 \$105.261 \$105.261 1 1 1 Interior Construction 1 \$105.261 \$105.261 1	Roof Coverings - BUR											
Rod Convings - Standing Seam Medi Media Media Standing Seam Media Standing Seam Media Standing Seam Media Standing Seam Media Media <th< td=""><td>Roof Coverings - EPDM</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>	Roof Coverings - EPDM											
Rod Convings - Standing Seam Medi Media Media Standing Seam Media Standing Seam Media Standing Seam Media Standing Seam Media Media <th< td=""><td>Roof Coverings - Preformed Metal</td><td> </td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>1</td></th<>	Roof Coverings - Preformed Metal											1
Mead Reof OpeningsImage												
Interior \$91.376 \$108.261	Metal											
Interior \$91.376 \$108.261								\$7,450				
Instruction Image Image Still		\$91,378			\$108,261							
Proteinans Image Image <thimage< th=""> Image Image</thimage<>					, .							
Interor Dors Image												
Fittings Image								\$19 956				
Sins Image: Sins Sins Sins Sins Sins Sins Sins Sins								\$10,000				
Sair Construction P												
Interver \$91,378 \$108,261 \$83,821 Image: charmic & Glazed Wall Finishes - Paint Image: charmic & Glazed Image: charmic & G												
Wall Finishes - Caranic & Glazed Sig.217 Image: Comparison of the second of the secon		¢01.279			\$109.261			\$20.261				
Wall Finishes - Paint Image: Start Sta		\$91,378			\$106,201							
Wall Finishes - Wall Coverings Image: Control of the set of												
Floor Finishes - Carpet Image: Carpet Finishes - Carpet & Carp								\$19,044				
Floor Finishes - Ceramic & Quarry Tile Image: Constraint of the second sec												
Tile Image: Constraint of the set of												
Floor Finishes - VCT \$91,378 Image: Constraint of the second of the sec												
Floor Finishes - VCT \$91,378 Image: Section of Sectio												
Floor Finishes - Wood Image: State of the s												
Ceiling Finishes Image: Storage state		\$91,378										
Services \$194,071 \$344,176 \$25,062 Image: Concern and Lifts												
Conveying Image: Conveying Conveying Image: Conveying Conveying Image: Conveying Conveying Conveying Image: Conveying												
Elevators and Lifts Image Image <thimage< th=""> Image Image<td>Services</td><td></td><td></td><td></td><td>\$194,071</td><td></td><td></td><td>\$344,176</td><td></td><td>\$25,062</td><td></td><td></td></thimage<>	Services				\$194,071			\$344,176		\$25,062		
Plumbing\$194,071\$104,125Plumbing Fixtures\$194,071 </td <td></td>												
Plumbing Fixtures \$194,071 Image: Construction of the second of the												
Domestic Water DistributionSecond Second								\$104,125				
Sanitary WasteSanitary WasteSanita					\$194,071							
Rain Water Drainage \$11,630 Other Plumbing Systems - Natural Gas \$5,088 \$5,088 \$5,088 HVAC	Domestic Water Distribution											
Other Plumbing Systems - Natural Gas Image: Constraint of the systems of the sys												
Gas Image: Constraint of the second seco	Rain Water Drainage							\$11,630				
HVAC Image: Constraint of the systems Image: Constraint of the sy	Other Plumbing Systems - Natural							\$5,088				
Heat Generating Systems Image: Cooling G	Gas											
Cooling Generating Systems Image: Coolin	HVAC											
Cooling Generating Systems Image: Coolin	Heat Generating Systems											
Distribution & Exhaust Systems Image: Controls of the systems of		<u> </u>										
Terminal & Package Units Image: Controls & Instrumentation Image: Controls & Instrumentation Image: Control & Instrumentation Image		+										
Controls & Instrumentation Image: Control & Instrumentation Image: Control & Instrumentation Other HVAC Systems/Equip - Kitchen Hood Image: Control & Instrumentation Image: Control & Instrumentation Fire Protection Image: Control & Instrumentation Image: Control & Instrumentation Image: Control & Instrumentation Sprinklers Image: Control & Instrumentation Image: Control & Instrumentation Image: Control & Instrumentation Standpipes Image: Control & Instrumentation Image: Control & Instrumentation Image: Control & Instrumentation												-
Other HVAC Systems/Equip - Kitchen Hood Image: Constraint of the systems/Equip - Kitchen Hood Image: Constraint of the systems/Equip - Systems/Equip - Fire Protection Image: Constraint of the systems/Equip - Systems/Equip - Standpipes Image: Constraint of the systems/Equip - Standpipes Image: Constraint of the systems/ Standpipes Image: Constraint of the systems/ Sta												
Kitchen Hood Image: Constraint of the system Image: Constrainton of the system Image: Constraint of the system		<u> </u>										
Fire Protection Image: Constraint of the system Image: Constrated Image: Constraint of the system												
Sprinklers Image: Constraint of the system Standpipes Image: Constraint of the system Standpipes Image: Constraint of the system Standpipes Image: Constraint of the system		┥───┤						\$55 070				
Standpipes		<u> </u>										
		 						\$35,97U				
Elecuricar \$184,081 \$25,062		<u> </u>						£404.004		60F 000		
	Electrical							\$184,081		\$25,062		

DeKalb County School System COMET4 Facility Report 1701 Mountain Industrial Blvd Report Date: 28 Jun 2011 Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083 2010-12 2014 2015 2016 2017 2019 Systems 2013 2018 2020 2021 2022 Electrical Service/Distribution \$25,622 Branch Wiring \$85,953 Lighting Communications and Security -\$72,506 Clock & PA Systems \$16,772 Communications and Security - Fire Alarm Communications and Security -\$8,290 Security & CCTV Other Electrical Systems -Emergency Generator Equipment & Furnishings \$43,896 Equipment Commercial Equipment

Institutional Equipment Other Equipment Furnishings

Fixed Furnishings

Special Construction

Special Construction

Special Structures - Canopies

\$43,896

\$43,896

\$12,255

\$12,255

\$12,255

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1988 Addition (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	C3020	Priority:	4	
System:	Floor Finishes - VCT	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The VCT flooring is stained, cracked, chipped	, and patched, and sh	ould be replaced.	



Estimates:

Raw Cost	\$66,216.15
Plus or (Minus) Additional Cost	\$25,162.14
Total Estimated Amount	\$91,378.29

Deficiency:

Assembly: System: Material: Distress: Category: Correction: Note:

E2010 Fixed Furnishings System Beyond Service Life Deferred Maintenance Renew System Fixed furnishings, such as the ba beyond service life, and should b

Surveyor/Update: Walter Williams Priority: 4 Quantity: 1 Tue, 01-Feb-2011

Fixed furnishings, such as the base/wall cabinets, counter tops, window shades, and fixed seating, are worn, beyond service life, and should be replaced.



Estimates:

Raw Cost\$31,808.70Plus or (Minus) Additional Cost\$12,087.31Total Estimated Amount\$43,896.01

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1994 Addition Address: 10 Lakeshore Drive, Avondale Estates, GA 30002

Attributes: Building Codes Fire Sprinkler System	2014 Yes		
General Information: Function: Gross Area:	Elementary School 11,766 S.F.	Year Built: Last Renovation:	1994

Facility Description:

The 1994 Classroom Addition at Avondale Elementary School is a one-story building located at Lakeshore Drive in Avondale Estates, Georgia. There have been HVAC renovations in 2008 and lighting upgrades in 2008, 2009, and 2010. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

There are no energy conservation opportunities for this building at this time.

Current Repair Cost: \$0.00

Replacement Cost: \$2,001,057.74

FCI: 0.00%



03-Dec-2010 East Elevation



03-Dec-2010 North Elevation



03-Dec-2010 Northwest Elevation



03-Dec-2010 West Elevation

DeKalb County School System	
------------------------------------	--

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1994 Addition (continued)

Building Condition:

_		Unit of						Calc Next	Next				
System Total	Unit Price\$ \$170.07	Meas S.F.	Qty 11,766	Renewal% 108	Renewal\$ \$2,154,644	Life 41	Installed 1997	Renewal 2002	Renewal	RSL	Deficiency\$	Replacement Value \$2,001,056	FCI%
Substructure	\$170.07 \$13.21	5.F. S.F.	11,766	108	\$2,154,644	100	1997	2002			0	\$2,001,058	
Foundations	\$13.21	3.F. S.F.	11,766	100	\$155,389	100	1994					\$155,389	
Standard Foundations	\$6.49	S.F.	11,766	100	\$76,314	100	1994					\$76,314	
Special Foundations	φ0. 4 3	S.F.	11,766	100	\$70,514	100	1994					\$70,514	
Slab on Grade	\$6.72	S.F.	11,766	100	\$79,075	100	1994					\$79,075	
	\$0.72	5.F. S.F.	11,766	100	\$79,075	0	1994					\$79,075	
Basement Construction				100		100	1994						
Basement Excavation Basement Walls		S.F. S.F.	11,766 11,766	100 100		100	1994						
	\$ 00.00				\$004.400			000.4				\$070.044	
Shell	\$32.20	S.F.	11,766	104	\$394,463	69	1994	2004				\$378,811	
Superstructure	\$4.43	S.F.	11,766	100	\$52,121	100	1994					\$52,121	
Floor Construction	A 4.40	S.F.	11,766	100	\$50.101	100	1994					A50.101	
Roof Construction	\$4.43	S.F.	11,766	100	\$52,121	100	1994					\$52,121	
Exterior Enclosure	\$21.65	S.F.	11,766	103	\$263,219	75	1994	2024				\$254,760	
Exterior Walls	\$14.46	S.F.	11,766	100	\$170,165	100	1994					\$170,165	
Exterior Windows	\$6.32	S.F.	11,766	110	\$81,802	30	1994	2024				\$74,366	
Exterior Doors	\$0.87	S.F.	11,766	110	\$11,252	30	1994	2024				\$10,229	
Roofing	\$6.11	S.F.	11,766	110	\$79,123	25	1994	2004				\$71,930	
Roof Coverings - Asphal		S.F.	11,766	110		10	1994	2004					
Shingles													
Roof Coverings - BUR	\$5.55	S.F.	11,766	110	\$71,800	25	1994	2019				\$65,273	
Roof Coverings - EPDM		S.F.	11,766	110		15	1994	2009					
Roof Coverings - Preformed		S.F.	11,766	110		30	1994	2024					
Metal													
Roof Coverings - Standing		S.F.	11,766	110		75	1994	2069					
Seam Metal													
Roof Openings	\$0.57	S.F.	11,766	110	\$7,323	30	1994	2024				\$6,657	
Interiors	\$37.65	S.F.	11,766	108	\$479,887	36	1996	2002				\$442,947	
Interior Construction	\$8.49	S.F.	11,766	103	\$102,488	87	1994	2014				\$99,858	
Partitions	\$6.40	S.F.	11,766	110	\$82,874	100	1994					\$75,340	
Interior Doors	\$2.08	S.F.	11,766	80	\$19,614	30	1994	2024				\$24,518	
Fittings		S.F.	11,766	110		20	1994	2014					
Stairs		S.F.	11,766			0	1994						
Stair Construction		S.F.	11,766	100		100	1994						
Interior Finishes	\$29.16	S.F.	11,766	110	\$377,399	23	1998	2002				\$343,089	
Wall Finishes - Ceramic &	\$9.58	S.F.	11,766	110	\$123,954	30	1994	2024				\$112,685	
Glazed													
Wall Finishes - Paint	\$1.81	S.F.	11,766	110	\$23,398	10	2009	2019				\$21,271	
Wall Finishes - Wall Coverings		S.F.	0	110		10	1994	2004					
Floor Finishes - Carpet		S.F.	0	110		8	1994	2002					
Floor Finishes - Ceramic &	\$13.40	S.F.	0	110		50	1994	2044					
Quarry Tile													
Floor Finishes - Terrazzo	\$48.99	S.F.	0	110		50	1994	2044					
Floor Finishes - VCT	\$8.79	S.F.	11,766	110	\$113,773	20	1994	2014				\$103,430	
Floor Finishes - Wood	• • •	S.F.	0	110	, .	20	1994	2014					
Ceiling Finishes	\$8.98	S.F.	11,766	110	\$116,274	20	1994	2014				\$105,703	
Services	\$81.61	S.F.	11,766	110	\$1,056,287	25	2000	2014		+		\$960,260	
Conveying		S.F.	11,766		,,	0	1994	2024					
Elevators and Lifts		S.F.	11,766	110		30	1994	2024					
Plumbing	\$7.91	S.F.	11,766	110	\$102,342	30	1994	2024				\$93,038	+
Plumbing Fixtures	φ1.01	S.F.	11,766	110	¥102,042	20	1994	2014				\$00,000	+
Domestic Water Distribution	\$3.59	S.F.	11,766	110	\$46,438	30	1994	2014		+		\$42,216	+
Sanitary Waste	\$3.05	S.F.	11,766	110	\$39,472	30	1994	2024				\$35,884	
Rain Water Drainage	\$3.05	5.F. S.F.	11,766	110	\$11,431	30	1994	2024				\$35,684	
Other Plumbing Systems -	\$0.88	S.F.	11,766	110	\$5,001	30	1994	2024				\$4,546	
Natural Gas	QU.39	Э.г.	11,700	110	\$0,001	30	1994	2024				\$4,546	
Natural Gas HVAC	¢ / / 70	0-	11 700	110	¢570.000		2000	2023		1		\$500 0.4.4	1
HVAC Heat Generating Systems	\$44.73 \$4.15	S.F. S.F.	11,766 11,766	110 110	\$578,868 \$53,761	23 30	2006 2008	2023				\$526,244 \$48,874	1
Cooling Generating Systems	\$4.22	S.F.	11,766	110	\$54,654	30	2008	2038				\$49,685	
Distribution & Exhaust Systems	\$3.80	S.F.	11,766	110	\$49,117	30	2008	2038				\$44,652	
Terminal & Package Units	\$17.29	S.F.	11,766	110	\$223,796	15	2008	2023				\$203,451	1
Controls & Instrumentation	\$3.23	S.F.	11,766	110	\$41,794	20	2008	2028		1		\$37,995	
Other HVAC Systems/Equip -	\$12.03	S.F.	11,766	110	\$155,746	30	1994	2024				\$141,587	
Kitchen Hood													
Fire Protection	\$4.25	S.F.	11,766	110	\$55,011	30	1994	2024				\$50,010	
Sprinklers	\$4.25	S.F.	11,766	110	\$55,011	30	1994	2024				\$50,010	
Standpipes		S.F.	11,766	110		30	1994						
Electrical	\$24.73	S.F.	11,766	110	\$320,066	24	2003	2014		1		\$290,968	

1701 Mountain Industrial Blvd
Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

		Unit of						Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Electrical Service/Distribution	\$1.95	S.F.	11,766	110	\$25,184	30	1994	2024				\$22,894	
Branch Wiring	\$6.53	S.F.	11,766	110	\$84,482	30	1994	2024				\$76,801	
Lighting	\$8.58	S.F.	11,766	110	\$111,094	30	2008	2038				\$100,995	
Communications and Security -	\$5.51	S.F.	11,766	110	\$71,265	10	2004	2014				\$64,786	
Clock & PA Systems													
Communications and Security -	\$1.20	S.F.	11,766	110	\$15,539	10	2004	2014				\$14,126	
Fire Alarm													
Communications and Security -	\$0.59	S.F.	11,766	110	\$7,680	10	2010	2020				\$6,982	
Security & CCTV													
Other Electrical Systems -	\$0.37	S.F.	11,766	110	\$4,822	15	2008	2023				\$4,384	
Emergency Generator													
Equipment & Furnishings	\$4.22	S.F.	11,766	110	\$54,654	20	1994	2014				\$49,685	
Equipment		S.F.	11,766			0	1994	2014					
Commercial Equipment		S.F.	11,766	110		20	1994	2014					
Institutional Equipment		S.F.	11,766	110		20	1994	2014					
Other Equipment		S.F.	11,766	110		20	1994	2014					
Furnishings	\$4.22	S.F.	11,766	110	\$54,654	20	1994	2014				\$49,685	
Fixed Furnishings	\$4.22	S.F.	11,766	110	\$54,654	20	1994	2014				\$49,685	
Special Construction	\$1.19	S.F.	11,766	100	\$13,964	25	1994	2019				\$13,964	
Special Construction	\$1.19	S.F.	11,766	100	\$13,964	25	1994	2019				\$13,964	
Special Structures - Canopies	\$1.19	S.F.	11,766	100	\$13,964	25	1994	2019				\$13,964	

DeKalb County School System	
	~ ~ · · ·

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1994 Addition (continued)

Renewal Schedule:

1701 Mountain Industrial Blvd

Stone Mountain, GA 30083

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total			\$418,132					\$142,432	\$10,321		
Substructure											
Foundations											
Standard Foundations											
Special Foundations											
Slab on Grade											
Basement Construction											
Basement Excavation											
Basement Walls								A 00.000			
Shell								\$93,683			
Superstructure											
Floor Construction											
Roof Construction											
Exterior Enclosure											
Exterior Walls											
Exterior Windows											
Exterior Doors											
Roofing	1		1				1	\$93,683			
Roof Coverings - Asphal Shingles											t
Roof Coverings - BUR	1		1				1	\$93,683			
Roof Coverings - EPDM	1		1								
Roof Coverings - Preformed Metal											
Roof Coverings - Standing Seam							+				
Metal											
Roof Openings											
Interiors			\$258,920					\$30,529			
Interior Construction			\$250,320					\$30,323			
Partitions											
Interior Doors											
Fittings											
Stairs											
Stair Construction											
Interior Finishes			\$258,920					\$30,529			
Wall Finishes - Ceramic & Glazed											
Wall Finishes - Paint								\$30,529			
Wall Finishes - Wall Coverings											
Floor Finishes - Carpet											
Floor Finishes - Ceramic & Quarry											
Tile											
Floor Finishes - Terrazzo											
Floor Finishes - VCT			\$128,053								
Floor Finishes - Wood											
Ceiling Finishes			\$130,867								
Services			\$97,698						\$10,321		-
Conveying			+,								
Elevators and Lifts											
Plumbing											
Plumbing Fixtures											
Domestic Water Distribution					L						
Sanitary Waste											
Rain Water Drainage											
Other Plumbing Systems - Natural											
Gas											
HVAC											
Heat Generating Systems											
Cooling Generating Systems											
Distribution & Exhaust Systems											
Terminal & Package Units	1		1				1				
Controls & Instrumentation			1				1				
Other HVAC Systems/Equip -			1								
Kitchen Hood											
Fire Protection											
Sprinklers											
Standpipes											
Electrical			\$97,698						\$10,321		
	1	Ì	431,030		1	Ì	1	1	ψ10,321	1	1

DeKalb County School System COMET4 Facility Report 1701 Mountain Industrial Blvd Report Date: 28 Jun 2011 Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083 2010-12 2015 2016 2017 2019 Systems 2013 2014 2018 2020 2021 2022 Electrical Service/Distribution Branch Wiring Lighting Communications and Security -\$80,209 Clock & PA Systems \$17,489 Communications and Security - Fire Alarm \$10,321 Communications and Security -Security & CCTV Other Electrical Systems -Emergency Generator Equipment & Furnishings \$61,514 Equipment Commercial Equipment Institutional Equipment Other Equipment Furnishings \$61,514 Fixed Furnishings \$61,514 Special Construction \$18,220

\$18,220

\$18,220

Special Construction

Special Structures - Canopies

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\1994 Addition (continued)

Deficiency Sheet:

*** No Deficiencies Found ***

DeKalb County School Sys	stem		
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COME Avondale Elementary Fa	Report Date: 28 Jun 2011	
Facility: \Elementary Schools\ Address: 10 Lakeshore Drive,	Avondale Elementary\ 2003 Gyr Avondale Estates, GA 30002	n	
Attributes: Building Codes Fire Sprinkler System	2020 No		
General Information: Function: Gross Area:	Elementary School 5,478 S.F.	Year Built: Last Renovation:	2003

Facility Description:

The 2003 Gymnasium Addition at Avondale Elementary School is a one-story building located at 10 Lakeshore Drive in Avondale Estates, Georgia. There have been no additions and no major renovations. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

An energy conservation opportunity for this building is to select and install an energy efficient cooling system.

Current Repair Cost: \$165,574.42

Replacement Cost: \$835,515.31

FCI: 19.82%



03-Dec-2010 West Elevation



03-Dec-2010 South Elevation



03-Dec-2010 East Elevation



03-Dec-2010 North Elevation

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\2003 Gym (continued)

Building Condition:

		Unit of	-					Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$152.52	S.F.	5,478	106	\$885,808	61	2003	2011	2010		\$109,420	\$835,518	13
Substructure	\$17.07	S.F.	5,478	100	\$93,513	100	2003					\$93,513	
Foundations	\$17.07	S.F.	5,478	100	\$93,513	100	2003					\$93,513	
Standard Foundations	\$10.57	S.F.	5,478	100	\$57,907	100	2003					\$57,907	
Slab on Grade	\$6.50	S.F.	5,478	100	\$35,606	100	2003					\$35,606	
Shell	\$45.06	S.F.	5,478	103	\$254,585	89	2003	2033				\$246,822	
Superstructure	\$14.21	S.F.	5,478	100	\$77,864	100	2003					\$77,864	
Roof Construction	\$14.21	S.F.	5,478	100	\$77,864	100	2003					\$77,864	
Exterior Enclosure	\$18.96	S.F.	5,478	101	\$105,124	91	2003	2033				\$103,869	
Exterior Walls	\$16.67	S.F.	5,478	100	\$91,320	100	2003					\$91,320	
Exterior Doors	\$2.29	S.F.	5,478	110	\$13,804	30	2003	2033				\$12,549	
Roofing	\$11.88	S.F.	5,478	110	\$71,597	75	2003	2078				\$65,089	
Roof Coverings - Standing	\$11.88	S.F.	5,478	110	\$71,597	75	2003	2078				\$65,089	
Seam Metal													
Interiors	\$45.28	S.F.	5,478	107	\$265,876	57	2003	2011	2010		\$103,350	\$248,056	42
Interior Construction	\$21.51	S.F.	5,478	104	\$122,655	76	2003	2023			,,	\$117,855	+
Partitions	\$13.57	S.F.	5,478	110	\$81,742	100	2003					\$74,311	
Interior Doors	\$4.25	S.F.	5,478	80	\$18,627	40	2003	2043				\$23,284	
Fittings	\$3.70	S.F.	5,478	110	\$22,286	20	2003	2040				\$20,260	
Interior Finishes	\$23.77	S.F.	5,478	110	\$143.221	41	2003	2020	2010		\$103.350	\$130,201	79
Wall Finishes - Ceramic	\$23.77	S.F.	0	110	\$143,221	30	2003	2011	2010		\$103,330	\$130,201	73
Wall Finishes - Ceramic Wall Finishes - Paint				110	\$9.147		2003	2033				* 0.010	
	\$1.52	S.F.	5,478	-	4 - 7	10						\$8,316	
Floor Finishes - Ceramic Tile	\$7.16	S.F.	274	110	\$2,159	8	2003	2011	2014	4		\$1,962	
Floor Finishes - Neoprene	\$19.06	S.F.	4,930	110	\$103,350	50	2003	2053	2010		\$103,350	\$93,955	110
Floor Finishes - VCT	\$5.38	S.F.	274	110	\$1,622	15	2003	2018				\$1,475	
Ceiling Finishes	\$4.47	S.F.	5,478	110	\$26,943	20	2003	2023				\$24,493	
Services	\$45.11	S.F.	5,478	110	\$271,834	26	2003	2013	2010		\$6,070	\$247,127	2
Plumbing	\$14.59	S.F.	5,478	110	\$87,895	30	2003	2033				\$79,906	
Plumbing Fixtures	\$7.20	S.F.	5,478	110	\$43,407	30	2003	2033				\$39,461	
Domestic Water Distribution	\$5.96	S.F.	5,478	110	\$35,923	30	2003	2033				\$32,658	
Sanitary Waste	\$0.87	S.F.	5,478	110	\$5,239	30	2003	2033				\$4,763	
Rain Water Drainage	\$0.22	S.F.	5,478	110	\$1,330	30	2003	2033				\$1,210	
Other Plumbing Systems -	\$0.33	S.F.	5,478	110	\$1,996	30	2003	2033				\$1,814	
Natural Gas													
HVAC	\$12.79	S.F.	5,478	110	\$77,085	28	2003	2018				\$70,078	
Distribution Systems & Exhaust	\$10.39	S.F.	5,478	110	\$62,616	30	2003	2033				\$56,924	
Systems													
Terminal & Package Units	\$0.81	S.F.	5,478	110	\$4,906	15	2003	2018				\$4,460	
Controls & Instrumentation	\$1.59	S.F.	5,478	110	\$9,563	20	2003	2023				\$8,694	
Fire Protection			0			0	0						
Sprinklers	\$3.91	S.F.	0	110		30	2003	2033					
Electrical	\$17.73	S.F.	5,478	110	\$106,854	22	2003	2000	2010		\$6,070	\$97,143	6
Electrical Service/Distribution	\$1.34	S.F.	5,478	110	\$8,066	30	2003	2013	20.0		\$5,570	\$7,333	``
Branch Wiring	\$5.96	S.F.	5,478	110	\$35,923	30	2003	2033				\$32,658	
Lighting	\$5.96	S.F. S.F.	5,478	110	\$35,923	20	2003	2033				\$32,658	
Communications and Security -	\$5.96	S.F. S.F.	5,478	110	\$35,923	10	2003	2023				\$32,658	
Fire Alarm	φ2.40	э.г.	5,476	110	φ14,oUZ	10	2003	2013				\$13,40b	
	64 6 4	0.5	E 470	446	\$0.070	00	0000	00000				AF 510	
Communications and Security -	\$1.01	S.F.	5,478	110	\$6,070	20	2003	2023				\$5,519	
Public Address & Clock System	.										<u> </u>	±	
Communications and Security -	\$1.01	S.F.	5,478	110	\$6,070	10	2003	2013	2010	1	\$6,070	\$5,519	110

DeKalb	County	School	System
--------	--------	--------	--------

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\2003 Gym (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$109,420	\$26,169	\$2,430			1	\$8,270		\$8,158		\$3,078
Substructure											
Foundations											
Standard Foundations											
Slab on Grade											
Shell											
Superstructure											
Roof Construction											
Exterior Enclosure											
Exterior Walls											
Exterior Doors											
Roofing											
Roof Coverings - Standing Seam											
Metal											
Interiors	\$103,350	\$9,995	\$2,430				\$2,055				\$3,078
Interior Construction		,	. =, . = =			+	,				<i>t</i> ,
Partitions					+	-					+
Interior Doors											
Fittings	+ +										
Interior Finishes	\$103,350	\$9,995	\$2,430				\$2,055				\$3,078
Wall Finishes - Ceramic	\$100,000	\$0,000	<i>42,100</i>				φ2,000				\$0,010
Wall Finishes - Paint		\$9,995									
Floor Finishes - Ceramic Tile		φ5,555	\$2,430								\$3,078
Floor Finishes - Neoprene	\$103,350		φ2,400								\$0,070
Floor Finishes - VCT	\$100,000						\$2,055				
Ceiling Finishes							φ2,000				
Services	\$6,070	\$16,174					\$6,215		\$8,158		
Plumbing	\$0,070	\$10,174					ψ0,213		ψ0,100		
Plumbing Fixtures											
Domestic Water Distribution											
Sanitary Waste											
Rain Water Drainage											
Other Plumbing Systems - Natural											
Gas							A 0.015				
HVAC							\$6,215				
Distribution Systems & Exhaust											
Systems											
Terminal & Package Units							\$6,215				
Controls & Instrumentation											
Fire Protection											
Sprinklers											
Electrical	\$6,070	\$16,174							\$8,158		
Electrical Service/Distribution											
Branch Wiring											
Lighting											
Communications and Security - Fire		\$16,174									
Alarm											
Communications and Security -											
Public Address & Clock System											
Communications and Security -	\$6,070								\$8,158		
Security & CCTV											

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\2003 Gym (continued)

Deficiency Sheet:

Deficiency:		Surveyor/Update:	Kate McPhillips	Tue, 01-Feb-2011
Assembly:	C3020	Priority:	3	
System:	Floor Finishes - Neoprene	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The Neoprene flooring in the gym is bu	bbling and a tripping hazard	I, and should be replace	ced.



Estimates:

Raw Cost \$74,891.63 Plus or (Minus) Additional Cost \$28,458.82 Total Estimated Amount \$103,350.45

Thu, 26-May-2011

Deficiency:

Deficiency:		Surveyor/Update:	Chuck Gulley
Assembly:	D3050	Priority:	3
System:	Terminal & Package Units	Quantity:	1
Material:	Packaged A/C, Elec. Ht., Const. Volume		
Distress:	Missing		
Category:	Capital Improvement		
Correction:	Install Package A/C - 20 ton		
Note:	An air conditioning system is missing in the g	ymnasium and shoul	d be installed.



Estimates:

Raw Cost \$40,691.00 Plus or (Minus) Additional Cost \$15,462.58 Total Estimated Amount \$56,153.58

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\2003 Gym (continued)

Deficiency:

Deficiency: Assembly: System:	D5030 Communications and Security - Security & CCTV	Surveyor/Update: Priority: Quantity:	Kate McPhillips 3 1	Tue, 01-Feb-2011
Material:	System			
Distress:	Damaged			
Category:	Safety			
Correction:	Renew System			
Note:	The security alarm in the gym is damaged and	currently not workin	g. The alarm should b	be repaired or replaced.



Estimates:

Raw Cost \$4,398.83 Plus or (Minus) Additional Cost \$1,671.56 **Total Estimated Amount** \$6,070.39

COME	Report Date: 28 Jun 2011		
1040			
Elementary School 71,567 S.F.	Year Built: Last Renovation:	1953	
	Avondale Elementary Fa Avondale Elementary\Site Avondale Estates, GA 30002 1040 Elementary School	COMET4 Facility Report Avondale Elementary Facility Executive Summary Re- Avondale Elementary\Site Avondale Estates, GA 30002 1040 Elementary School Year Built:	COMET4 Facility Report Avondale Elementary Facility Executive Summary Report \Avondale Elementary\Site Avondale Estates, GA 30002 1040 Elementary School Year Built: 1953

The Avondale Elementary School site was originally constructed in 1953, has a total area of 6.7 acres, and is occupied by approximately 71,576 square feet of permanent building space. Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report for the site features.

Current Repair Cost: \$6,454,826.48

Replacement Cost: \$6,869,262.15

FCI: 93.97%



04-Nov-2010 Aerial Image of Avondale Elementary School

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Building Condition:

		Unit of				r		Calc Next	Next				1
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$95.98	S.F.	71,567	109	\$7,498,455	35	1953	1963			\$6,454,827	\$6,869,261	94
Building Sitework	\$95.98	S.F.	71,567	109	\$7,498,455	35	1953	1963			\$6,454,827	\$6,869,261	94
Site Improvements	\$48.40	S.F.	71,567	108	\$3,752,721	22	1953	1963			\$2,709,093	\$3,464,049	78
Roadways	\$3.25	S.F.	291,852	110	\$1,043,628	25	1953	1978			\$1,043,628	\$948,752	110
Parking Lots	\$1.47	S.F.	291,852	110	\$473,273	25	1953	1978			\$473,273	\$430,248	110
Pedestrian Paving	\$1.65	S.F.	291,852	110	\$529,904	30	1953	1983			\$529,904	\$481,731	110
Site Development	\$0.26	S.F.	291,852	110	\$84,946	10	1953	1963			\$84,946	\$77,224	110
Site Development 2	\$8.07	S.F.	71,567	100	\$577,342	30	1953	1983			\$577,342	\$577,342	100
Fence & Guardrails	\$1.98	S.F.	291,852	100	\$577,342	30	1953	1983			\$577,342	\$577,342	100
Landscaping	\$3.25	S.F.	291,852	110	\$1,043,628	10	1953					\$948,752	
Site Mechanical Utilities	\$42.65	S.F.	71,567	110	\$3,357,407	50	1953	1983			\$3,357,407	\$3,052,188	110
Water Supply	\$2.38	S.F.	291,852	110	\$764,518	50	1953	2003			\$764,518	\$695,016	110
Sanitary Sewer	\$2.36	S.F.	291,852	110	\$756,428	50	1953	2003			\$756,428	\$687,662	110
Storm Sewer	\$5.51	S.F.	291,852	110	\$1,767,695	50	1953	2003			\$1,767,695	\$1,606,995	110
Fuel Distribution - Gas	\$0.21	S.F.	291,852	110	\$68,766	30	1953	1983			\$68,766	\$62,515	110
Site Electrical Utilities	\$4.93	S.F.	71,567	110	\$388,327	30	1953	1983			\$388,327	\$353,024	110
Electrical Distribution	\$0.52	S.F.	291,852	110	\$165,848	30	1953	1983			\$165,848	\$150,771	110
Site Lighting	\$0.69	S.F.	291,852	110	\$222,479	30	1953	1983			\$222,479	\$202,253	110

DeKalb County School Syste	m	
1701 Mountain Industrial Blvd Stone Mountain, GA 30083	COMET4 Facility Report Avondale Elementary Facility Executive Summary Report	Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total	\$6,454,827								\$114,161		
Building Sitework	\$6,454,827								\$114,161		
Site Improvements	\$2,709,093								\$114,161		
Roadways	\$1,043,628										
Parking Lots	\$473,273										
Pedestrian Paving	\$529,904										
Site Development	\$84,946								\$114,161		
Site Development 2	\$577,342										
Fence & Guardrails	\$577,342										
Landscaping											1
Site Mechanical Utilities	\$3,357,407										
Water Supply	\$764,518										1
Sanitary Sewer	\$756,428										1
Storm Sewer	\$1,767,695										
Fuel Distribution - Gas	\$68,766										
Site Electrical Utilities	\$388,327										1
Electrical Distribution	\$165,848		1								1
Site Lighting	\$222,479										1

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Deficiency Sheet:

Assembly: G2010 Priority: 3 System: Roadways Quantity: 1 Material: System Distress: Beyond Service Life Category: Deferred Maintenance I	
Material: System Distress: Beyond Service Life	
Distress: Beyond Service Life	
Category: Deferred Maintenance	
Correction: Renew System	
Note: The asphaltic roadways are cracked and have pot holes, and should be resurfaced.	



Estimates:

Note:

Raw Cost	\$828,275.98
Plus or (Minus) Additional Cost	\$215,351.75
Total Estimated Amount	\$1,043,627.73

Deficiency: Assembly: System:	G2020 Parking Lots	Surveyor/Update: Priority: Quantity:	Walter Williams 3 1	Fri, 24-Jun-2011
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			

The asphaltic parking lots are aged, have cuts and repairs, and should be resurfaced and restriped, including the side gravel parking lot.



Estimates:

\$375,613.52	Raw Cost
\$97,659.52	Plus or (Minus) Additional Cost
\$473,273.04	Total Estimated Amount

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 COMET4 Facility Report Report Report

Report Date: 28 Jun 2011

Tue, 01-Feb-2011

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Deficiency:		Surveyor/Update:	Walter Williams
Assembly:	G2030	Priority:	3
System:	Pedestrian Paving	Quantity:	1
Material:	System		
Distress:	Beyond Service Life		
Category:	Deferred Maintenance		
Correction:	Renew System		
Note:	The pedestrian paving is aged beyond it	ts service life and should be	e replaced.



Estimates:

Raw Cost	\$420,558.73
Plus or (Minus) Additional Cost	\$109,345.27
Total Estimated Amount	\$529,904.00

Deficiency:

G2040 Site Development System Beyond Service Life Deferred Maintenance Renew System The grass is damaged and should be reseeded.

Estimates:

.

Surveyor/Update: Walter Williams Priority: 3 Quantity: 1 Thu, 30-Dec-2010

Raw Cost	\$67,417.81
Plus or (Minus) Additional Cost	\$17,528.63
Total Estimated Amount	\$84,946.44

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	G2040105	Priority:	3	
System:	Fence & Guardrails	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The fencing is aged, rusted, and damaged, and	should be replaced		

Estimates:

Raw Cost \$458,207.64 Plus or (Minus) Additional Cost \$119,133.99 **Total Estimated Amount** \$577,341.63

Tue, 01-Feb-2011

Walter Williams

Deficiency:

Assembly: System: Material: Distress: Category: Correction: Note:

Surveyor/Update: Priority: G3010 3 Water Supply Quantity: 1 System **Beyond Service Life Deferred Maintenance Renew System** The original water distribution system is beyond its service life and should be replaced.



Estimates:

Raw Cost \$606,760.31 Plus or (Minus) Additional Cost \$157,757.68 Total Estimated Amount \$764,517.99

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avondale Elementary Facility Executive Summary Report Report

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	G3020	Priority:	3	
System:	Sanitary Sewer	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	The original sanitary sewer laterals are aged, h	nave periodic outage	s, and should be replaced	



Estimates:

Raw Cost	\$600,339.56
Plus or (Minus) Additional Cost	\$156,088.29
Total Estimated Amount	\$756,427.85

Tue, 01-Feb-2011

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

 G3030
 Priority:
 3

 Storm Sewer
 Quantity:
 1

 System
 1

 Beyond Service Life
 1

 Deferred Maintenance
 1

 Renew System
 1

 The storm sewer system is aged, has reported drainage problems, and should be replaced.

Surveyor/Update:

Walter Williams



Estimates:

 Raw Cost
 \$1,402,932.56

 Plus or (Minus) Additional Cost
 \$364,762.47

 Total Estimated Amount
 \$1,767,695.03

COMET4 Facility Report 1701 Mountain Industrial Blvd Avondale Elementary Facility Executive Summary Report Stone Mountain, GA 30083

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Deficiency:		Surveyor/Update:	Walter Williams	Tue, 01-Feb-2011
Assembly:	G3060	Priority:	3	
System:	Fuel Distribution - Gas	Quantity:	1	
Material:	System			
Distress:	Beyond Service Life			
Category:	Deferred Maintenance			
Correction:	Renew System			
Note:	Fuel distribution system is beyond its s	service life and should be sh	eduled for replacement	nt.



Estimates:

Raw Cost	\$54,576.32
Plus or (Minus) Additional Cost	\$14,189.84
Total Estimated Amount	\$68,766.16

Tue, 01-Feb-2011

Deficiency:

Assembly:
System:
Material:
Distress:
Category:
Correction:
Note:

Surveyor/Update: Walter Williams Priority: 3 G4010 **Electrical Distribution** Quantity: 1 System **Beyond Service Life Deferred Maintenance Renew System** The electrical distribution system is aged, becoming logistically unsupportable, and should be replaced.



Estimates:

Raw Cost \$131,625.25 Plus or (Minus) Additional Cost \$34,222.57 \$165,847.82 Total Estimated Amount

 1701 Mountain Industrial Blvd
 COMET4 Facility Report
 Report

 Stone Mountain, GA 30083
 Avondale Elementary Facility Executive Summary Report
 Report

Report Date: 28 Jun 2011

Tue, 01-Feb-2011

Facility: \Elementary Schools\Avondale Elementary\Site (continued)

Deficiency:		Surveyor/Update:	Walter Williams
Assembly:	G4020	Priority:	3
System:	Site Lighting	Quantity:	1
Material:	System		
Distress:	Beyond Service Life		
Category:	Deferred Maintenance		
Correction:	Renew System		
Note:	The original site lighting system is aged,	partially inoperable, and s	hould be replaced.



Estimates:

Raw Cost \$176,570.46 Plus or (Minus) Additional Cost \$45,908.32 Total Estimated Amount \$222,478.78

COMET4 Facility Report 1701 Mountain Industrial Blvd **Avondale Elementary Facility Executive Summary Report** Stone Mountain, GA 30083

Report Date: 28 Jun 2011

Facility: \Elementary Schools\Avondale Elementary\Storage Building Address: 10 Lakeshore Drive, Avondale Estates, GA 30002

Attributes: ***None***

General Information: Function:

Gross Area:

Storage Building 100 S.F.

Year Built: Last Renovation: 1994

Facility Description:

The Storage Building at Shadow Rock Elementary School is a one-story building located at 10 Lakeshore Drive in Avondale Estates, Georgia. There have been no additions and no renovations. This report contains condition and adequacy data collected during the 2010/2011 Facility Condition Assessment (FCA). The detailed condition and deficiency statements are contained in this report.

Current Repair Cost: \$0.00

Replacement Cost: \$7,142.88

FCI: 0.00%



03-Dec-2010 East Elevation



03-Dec-2010 North Elevation



03-Dec-2010 West Elevation



03-Dec-2010 South Elevation

DeKalb County School System	

1701 Mountain Industrial Blvd Stone Mountain, GA 30083

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\Storage Building (continued)

Building Condition:

		Unit of				Ì		Calc Next	Next				
System	Unit Price\$	Meas	Qty	Renewal%	Renewal\$	Life	Installed	Renewal	Renewal	RSL	Deficiency\$	Replacement Value	FCI%
Total	\$71.43	S.F.	100	102	\$7,293	82	1994	2014			0	\$7,143	
Substructure	\$7.89	S.F.	100	100	\$789	100	1994					\$789	
Foundations	\$7.89	S.F.	100	100	\$789	100	1994					\$789	
Standard Foundations	\$4.49	S.F.	100	100	\$448	100	1994					\$448	
Slab on Grade	\$3.41	S.F.	100	100	\$341	100	1994					\$341	
Basement Construction		S.F.	100			0	1994						
Basement Excavation		S.F.	100	100		100	1994						
Basement Walls		S.F.	100	100		100	1994						
Shell	\$63.54	S.F.	100	102	\$6,504	80	1994	2014				\$6,354	
Superstructure	\$13.57	S.F.	100	100	\$1,357	100	1994					\$1,357	
Roof Construction	\$13.57	S.F.	100	100	\$1,357	100	1994					\$1,357	
Exterior Enclosure	\$35.60	S.F.	100	100	\$3,567	98	1994	2024				\$3,560	
Exterior Walls	\$34.87	S.F.	100	100	\$3,487	100	1994					\$3,487	
Exterior Windows		S.F.	100	110		30	1994	2024					
Exterior Doors	\$0.73	S.F.	100	110	\$80	30	1994	2024				\$73	
Roofing	\$14.37	S.F.	100	110	\$1,580	20	1994	2014				\$1,437	
Roof Coverings	\$14.37	S.F.	100	110	\$1,580	20	1994	2014				\$1,437	
Interiors		S.F.	100			0	1994	2014					
Interior Construction		S.F.	100			0	1994	2014					
Partitions		S.F.	100	110		40	1994						
Interior Doors		S.F.	100	80		30	1994	2024					
Fittings		S.F.	100	110		20	1994	2014					
Interior Finishes		S.F.	100			0	1994	2014					
Wall Finishes		S.F.	100	110		20	1994	2014					
Floor Finishes		S.F.	100	110		20	1994	2014					
Ceiling Finishes		S.F.	100	110		20	1994	2014					
Services		S.F.	100			0	1994	2024					
Plumbing		S.F.	100			0	1994	2024		1			
Rain Water Drainage		S.F.	100	110		30	1994	2024		1			
Electrical		S.F.	100			0	1994	2024		1			
Electrical Service/Distribution		S.F.	100	110		30	1994	2024		1			
Lighting and Branch Wiring	1	S.F.	100	110		30	1994	2024					

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avo

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\Storage Building (continued)

Renewal Schedule:

Systems	2010-12	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Total			\$1,779								
Substructure											
Foundations											
Standard Foundations											
Slab on Grade											
Basement Construction											
Basement Excavation											
Basement Walls											
Shell			\$1,779								
Superstructure											
Roof Construction											
Exterior Enclosure											
Exterior Walls											
Exterior Windows											
Exterior Doors											
Roofing			\$1,779								
Roof Coverings			\$1,779								
Interiors											
Interior Construction											
Partitions											
Interior Doors											
Fittings											
Interior Finishes											
Wall Finishes											
Floor Finishes											
Ceiling Finishes											
Services			+ +								
Plumbing											
Rain Water Drainage			+ +								
Electrical			+ +								
Electrical Service/Distribution											
Lighting and Branch Wiring					+	1	1				+

1701 Mountain Industrial Blvd Stone Mountain, GA 30083 Avondale Elementa

COMET4 Facility Report Avondale Elementary Facility Executive Summary Report

Facility: \Elementary Schools\Avondale Elementary\Storage Building (continued)

Deficiency Sheet:

*** No Deficiencies Found ***

Educational Adequacy Report

BASYS Building Assessment System

Suitability Report - Full

Project #: 4469	County:	DeKalb		Site #: 5050				
Project: Assessments 2010	Region:	1		^{Site:} Avon	dale ES			
Grade Config: PK-5	Site Type:	Elementary		Site Size: 0.00				
Suitability			Rating	Score	Possible Score	Perc Sco		
Suitability - Elementary								
Site								
Traffic			Fair	1.34	2.00	6		
Pedestrian Traffic			Good	0.97	0.97	10		
Parking			Fair	0.54	0.81	6		
Playground			Good	2.34	2.34	10		
Safety and Security			-					
Fencing			Good	0.75	0.75	10		
Signage & Way Finding			Unsat	0.00	1.00			
Ease of Supervision			G/F	3.50	3.50	10		
Limited Entrances			G/F	0.50	0.50	10		
Interior Circulation			G/F	0.50	0.50	10		
Sprinkler System			Unsat	0.00	0.50			
School Climate								
Learning Style Variety			G/F	5.00	5.00	10		
School Environment			G/F	5.00	5.00	10		
Landscaping			G/F	1.00	1.00	10		
General Classrooms								
Size			Fair	11.02	16.45	6		
Adjacencies			Good	3.53	3.53	10		
Storage\Fixed Equip.			Good	3.53	3.53	10		
Remedial - Special Needs								
Size			Good	3.50	3.50	10		
Adjacencies			G/F	0.75	0.75	10		
Storage\Fixed Equip.			G/F	0.75	0.75	10		
Library								
Size			Fair	1.71	3.41	5		
Adjacencies			G/F	0.73	0.73	10		
Storage\Fixed Equip.			G/F	0.73	0.73	10		
P.E.			-			-		
Size			Good	6.72	6.72	10		
Adjacencies			G/F	1.44	1.44	10		
Storage\Fixed Equip.			P/U	0.00	1.44			
Music								
Size			Good	2.59	2.59	10		
Adjacencies			G/F	0.56	0.56	10		
Storage\Fixed Equip.			G/F	0.56	0.56	10		

Project #: 4469	^{County:} DeKalb	^{Site #:} 5050 ^{Site:} Avondale ES				
Project: Assessments 2010	^{Region:} 1					
Grade Config: PK-5	Site Type: Elementary		Site Size: 0.00			
Suitability		Rating	Score	Possible Score	Percent Score	
Art						
Size		Good	1.64	1.64	100.00	
Adjacencies		G/F	0.35	0.35	100.00	
Storage\Fixed Equip.		G/F	0.35	0.35	100.00	
Performing Arts\Auditorium						
Size		Good	2.12	2.12	100.00	
Adjacencies		Good	0.45	0.45	100.00	
Storage\Fixed Equip.		Good	0.45	0.45	100.00	
Computer Labs						
Size		Fair	0.60	1.19	50.00	
Adjacencies		G/F	0.26	0.26	100.00	
Storage\Fixed Equip.		G/F	0.26	0.26	100.00	
Kindergarten						
Size		Good	2.86	2.86	100.00	
Adjacencies		G/F	0.61	0.61	100.00	
Storage\Fixed Equip.		G/F	0.61	0.61	100.00	
Administration						
Size		Good	2.49	2.49	100.00	
Adjacencies		G/F	0.53	0.53	100.00	
Storage\Fixed Equip.		G/F	0.53	0.53	100.00	
Restrooms (Student)		Good	0.89	0.89	100.00	
Teacher Lounge and Work Room(s)		Fair	0.63	1.27	50.00	
Cafeteria		Fair	3.35	5.00	67.00	
Food Prep		Fair	4.16	6.20	67.00	
Counseling		Good	0.29	0.29	100.00	
Clinic		P/U	0.00	0.58	0.00	
Custodial & Maintenance		G/F	0.50	0.50	100.00	
Total For Site:			02.40	400.00	02.40	

Total For Site:

Comments

Suitability - Elementary

Avondale Elementary school serves students, grades PK-5. Many of their students are from outside its neighborhood due to the International Baccalaureate program. The original building was constructed in 1968 and the PK/kindergarten wing was added approximately 1980. The gym was constructed in 2002. There are two pods that were constructed as open-concept rooms. This is a Title 1 school for approximately 465 students.

Suitability - Elementary->Site-->Traffic

Buses load on a one-way street which conflicts with public usage. The parent circle is located behind the building.

Suitability - Elementary->Site-->Parking

There is some parking on the traffic circle and there is some on a gravel area adjacent to the parking lot. There is no visitor parking in front of the building.

- Suitability Elementary->Safety and Security-->Signage & Way Finding There is no large signage or wayfinding signs.
- Suitability Elementary->Safety and Security-->Sprinkler System There are no sprinklers at this site.

83.48

100.00

83.48

Project #: Project:	4469 Assessments 2010	County: Region:	DeKalb 1	^{Site #:} 5050 ^{Site:} Avondale ES					
Grade Config:		Site Type:	Elementary	Site Size: 0.00					
Suitability				Rating	Score	Possible Score	Percent Score		
•	Elementary->School Climate>	• •	•	ent learning experie	ences.				
-	Elementary->School Climate> an appealing learning environ		nent						
-	Elementary->General Classroor a few rooms that are too small,		en concept classr	poms.					
-	Elementary->General Classroor	-							
The library	Elementary->Library>Size is approximately 3,500 square ict guidelines for size.	feet in size, 2,40	0 square feet of v	vhich is available fo	or student us	e. This is			
-	Elementary->P.E>Storage\Fi> lack of adequate storage space		being provided.						
-	Elementary->Music>Size music classroom, but no music	program at this t	ime.						
-	Elementary->Computer Labs> uter lab is in a regular size clas		pelow district guid	elines for size.					
-	Elementary->Kindergarten>Stor garten room does not have a s		-						
A classroo	Elementary->Administration>S m adjacent to the office has bee a table in her office. The old offi	en converted to t			ough space to	o have a			
-	Elementary->Teacher Lounge a ers' lounge does not have water		3)						
-	Elementary->Cafeteria ria is 3,200 square feet in size,	which is below d	istrict size guideli	nes.					
Delivery is	Elementary->Food Prep not convenient. Deliveries veh n front of the building.	icles cross throu	gh the staff parki	ng area or items are	e hand-trucke	ed from			
	Elementary->Clinic restroom in the clinic.								

Technology Readiness Report

Technology Readiness Report - Full

Project #: 4469	County:	DeKalb		Site #:	5050		
Project: Assessments 2010	Region:	1			Avondale ES		
Technology Readiness			Rating		Score	Possible Score	Percent Score
Technology Readiness							
MDF\IT Equipment Environment			Good		15.00	15.00	100.00
Electrical Power			Good		10.00	10.00	100.00
Cooling			Good		10.00	10.00	100.00
Drops			Fair		6.70	10.00	67.00
Wireless			Unsat		0.00	5.00	0.00
WAN Backbone			Good		10.00	10.00	100.00
LAN-WAN Performance			Good		10.00	10.00	100.00
Video Distribution			Good		5.00	5.00	100.00
Voice Distribution			Unsat		0.00	5.00	0.00
Faculty & Staff Technology			Good		10.00	10.00	100.00
Emergency Alert			Good		5.00	5.00	100.00
Projectors			Unsat		0.00	5.00	0.00
Total For Site:					81.70	100.00	81.70

Comments

Technology Readiness->Drops Most classrooms have 2-3 computers and enough drops for more.

Technology Readiness->Wireless None of this building is wireless.

Technology Readiness->Video Distribution 90 percent of the classrooms have smartboards.

Technology Readiness->Voice Distribution This building does not have VOIP service.

Technology Readiness->Projectors There are no ceiling-mounted projectors in this building.