

School Name:	Avondale Middle	Facility			Grade Configuration: K-
Score:	82.54				
Category		Points Earned	Possible Points	Rating	Comment
Art					
Environmen	t	0.449	0.449	Excel	
Size		1.120	1.120	Excel	
Location		0.336	0.336	Excel	
Storage/Fixed Equip 0.26		0.269	0.336	Good	The art room does not have a kiln.
Career, Technie	cal and Agricultural	Education			
Environmen	t			N/A	
Size				N/A	
Location		N/A			
Storage/Fixed Equip			N/A		
Computer Labs	5				
Environmen	t	0.246	0.307	Good	
Size		0.499	0.767	Fair	The current space, room 905 is housing the computer lab for Fernbank Elementary School. Should the space remain as the designated computer lab, it will occupy sixty per cent of the adequate space standard
Location		0.150	0.230	Fair	It is located in a space that has 2 exterior walls. It lies distant from general education classroom
Storage/Fixe	ed Equip	0.150	0.230	Fair	The space has no motion sensor lighting or security cameras. Storage space is inadequate.
Early Childhoo	d Education				
Environmen	t			N/A	
Size				N/A	Space not yet determined, unable to assess.
Location				N/A	
Storage/Fixe	ed Equip			N/A	
General Classro	ooms				
Environmen	t	3.028	3.785	Good	



School Name: Avondale Middle F	acility			Grade Configuration: K-8
Score: 82.54				
Category	Points Earned	Possible Points	Rating	Comment
General Classrooms				
Size	7.570	9.463	Good	The kindergarten and first grade spaces will occupy 82% of the adequate space standard. The second through fifth grade will occupy 90% of the adequate space standard. The sixth through eighth grade will occupy 80% of the adequate spaces standard.
Location	2.271	2.839	Good	
Storage/Fixed Equip	2.271	2.839	Good	Classrooms do not have sinks or water bubblers
Instructional Resource Rooms				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
Kindergarten & Pre-Kindergarten				
Environment	0.276	0.344	Good	
Size	0.689	0.861	Good	Kindergarten classes meet 82% of the adequate space standard.
Location	0.207	0.258	Good	
Storage/Fixed Equip	0.168	0.258	Fair	There are no restrooms or sinks with bubblers that are specific to the kindergarten classrooms. Storage and casework are insufficient for these classrooms.
Learning Environment				
Learning Style Variety	5.115	5.115	Excel	
Interior Environment	2.046	2.046	Excel	
Exterior Environment	1.228	1.535	Good	
Environment	0.568	0.711	Good	A roof leak is damaging a small portion of the ceiling and carpet.
Media Center				
Size	1.421	1.776	Good	
Location	0.426	0.533	Good	

#### 2/23/2016



School Name: Avondale Middle	Facility		Grade Configuration: K-8
Score: 82.54			
Category	Points Possibl Earned Point		Comment
Media Center			
Storage/Fixed Equip	0.426 0.533	Good	
Music			
Environment	0.772 0.772	Excel	
Size	1.931 1.931	Excel	
Location	0.579 0.579	Excel	
Storage/Fixed Equip	0.463 0.579	Good	There is no raised platform in the music band room.
Performing Arts			
Environment	0.311 0.479	Fair	Dance and movement space for the performing arts school is lacking proper ventilation and climate control, as well as adequate lighting. The spaces lack appropriate acoustic materials.
Size	0.000 1.197	Unsat	An appropriate stage and performance seating do not exist. The facility lacks black box rooms.
Location	0.287 0.359	Good	
Storage/Fixed Equip	0.000 0.359	Unsat	Dressing rooms are inadequate. Lighting is inadequate for this level of performing arts. Dance and movement space for the performing arts school is lacking mirrored walls, dance flooring, warm-up routine bars, and a quality sound system.
Physical Education			
Environment	1.372 2.111	Fair	Current overhead lighting is dim. There is a roof leak that is damaging the gym floor & girls locker room.
Size	4.221 5.277	Good	
Location	1.266 1.583	Good	
Storage/Fixed Equip	1.266 1.583	Good	
Science			
Environment	0.630 0.788	Good	
Size	1.969 1.969	Excel	
Location	0.591 0.591	Excel	



School Name: Avondale Middle Fa	Grade Configuration:	K-8				
Score: 82.54						
Category	Points Earned	Possible Points	Rating	Comment		
Science						
Storage/Fixed Equip	0.473	0.591	Good			
Self-Contained Special Education						
Environment	0.460	0.575	Good			
Size	1.151	1.438	Good			
Location	0.345	0.432	Good			
Storage/Fixed Equip	0.345	0.432	Good			
Non-Instructional Spaces						
Administration	1.857	2.321	Good			
Cafeteria	4.092	5.115	Good	HVAC is poor.		
Food Service and Prep	5.215	8.022	Fair	The HVAC is poor in the kitchen work area.		
Clinic	0.278	0.348	Good			
Counseling	0.334	0.417	Good			
Custodial and Maintenance	0.409	0.512	Good			
Student Restrooms	0.741	0.927	Good	The stall doors in the girls restrooms lack latches.		
Faculty Work Space and Toilets	0.741	0.927	Good			
Outside Spaces						
Vehicular Traffic	3.069	3.069	Excel			
Pedestrian Traffic	0.818	1.023	Good			
Parking	1.105	1.382	Good			
Athletic Fields and Facilities	1.345	1.681	Good			
Safety and Security						
Fencing	0.997	1.246	Good			
Signage & Way Finding	0.125	0.156	Good			

#### 2/23/2016



School Name:	Avondale Middle Fac	ility			Grade Configuration: K-8
Score:	82.54				
Category		Points Earned	Possible Points	Rating	Comment
Safety and Sec	urity				
Ease of Supervision		1.637	2.046	Good	
Controlled Entrances		0.409	0.512	Good	
Technology Red	adiness				
IDF & MDF E	IDF & MDF Environment		1.500	Good	
Electrical Po	Electrical Power		1.000	Good	
Equity of Acc	cess, Wireless & Drops	1.000	1.000	Good	
LAN Connect	tivity	1.500	1.500	Good	
WAN Backbo	WAN Backbone		1.000	Good	
LAN-WAN Performance		1.000	1.000	Good	
Faculty & Staff Technology		1.000	1.000	Good	
Laptop Carts	5	1.000	1.000	Good	With the increase in staff and creation on more technology based classes, there will be a need for more carts and designated locking facilities for the carts.
Telephone/P	PA	1.000	1.000	Good	
Total		82.54 /	100.00 =	82.54	