

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pleasantdale ES

Grade Configuration:

PK-5

Score: 72.32

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.337	0.421	Good	
Size	0.684	1.053	Fair	The art room occupies 77% off the space requirement.
Location	0.253	0.316	Good	While located next to an ideal outdoor space, there is no access from the classroom.
Storage/Fixed Equip	0.253	0.316	Good	The space has one sink without a clay trap. Storage is not sufficient.
<i>Computer Labs</i>				
Environment	0.200	0.307	Fair	There is no HVAC in the computer lab. The room is quite warm.
Size	0.614	0.768	Good	The computer lab occupies 87% of the required space.
Location	0.184	0.230	Good	
Storage/Fixed Equip	0.150	0.230	Fair	The computer lab does not have motion lighting or cameras for security.
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>General Classrooms</i>				
Environment	3.528	4.410	Good	
Size	8.820	11.025	Good	Classroom spaces vary in size throughout the building from 84% to 95%
Location	2.646	3.307	Good	
Storage/Fixed Equip	2.150	3.307	Fair	The 1st through 5th grade classrooms have no sink or bubbler. Cubbies and coat hooks are not found in most classrooms.
<i>Instructional Resource Rooms</i>				
Environment	0.518	0.648	Good	
Size	1.620	1.620	Excel	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pleasantdale ES

Grade Configuration:

PK-5

Score: 72.32

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.389	0.486	Good	
Storage/Fixed Equip	0.316	0.486	Fair	Lockable storage and teacher material storage is not adequate.
<i>Kindergarten &amp; Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	
Size	0.751	0.938	Good	Kinder classrooms are 95% of the required adequate space.
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.141	0.282	Poor	Two of the six kindergarten rooms have restrooms, sinks and bubblers. Four of the six do not have these fixtures or facilities.
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	
Exterior Environment	0.675	1.350	Poor	Outdoor spaces are now supporting portable learning sites.
Environment	0.702	0.877	Good	The HVAC is inadequate.
<i>Media Center</i>				
Size	0.000	2.193	Unsat	The media center occupies 37% of the required space.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	
<i>Music</i>				
Environment	0.000	0.667	Unsat	
Size	0.000	1.667	Unsat	The music program takes place in a portable.
Location	0.000	0.500	Unsat	
Storage/Fixed Equip	0.000	0.500	Unsat	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pleasantdale ES

Grade Configuration:

PK-5

Score: 72.32

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.354	0.544	Fair	There is no ADA access to the stage.
Size	1.088	1.360	Good	
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.382	1.728	Good	
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	
<i>Science</i>				
Environment	0.000	0.450	Unsat	The science program takes place in a portable.
Size	0.000	1.125	Unsat	
Location	0.000	0.337	Unsat	
Storage/Fixed Equip	0.000	0.337	Unsat	
<i>Self-Contained Special Education</i>				
Environment	0.346	0.432	Good	
Size	0.864	1.080	Good	
Location	0.259	0.324	Good	
Storage/Fixed Equip	0.162	0.324	Poor	These spaces do not have their own restrooms, sinks with hot water, changing spaces or adequate storage.
<i>Non-Instructional Spaces</i>				
Administration	1.496	2.302	Fair	There is no conference space for up to 10 participants. The reception area is small and cannot accommodate more than one person deep. Teachers mailboxes are located on a wall that is within access to anyone who steps into the office.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pleasantdale ES

Grade Configuration:

PK-5

Score: 72.32

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Cafeteria	2.925	4.500	Fair	The cafeteria is undersized. There is no restroom with hot water nearby.
Food Service and Prep	4.467	5.584	Good	
Clinic	0.421	0.526	Good	
Counseling	0.211	0.263	Good	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.519	0.798	Fair	The restrooms are not vented and there are no windows to open for alternative ventilation.
Faculty Work Space and Toilets	0.912	1.140	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.440	1.800	Good	
Pedestrian Traffic	0.569	0.876	Fair	Pedestrian traffic routes are impeded by locations of portable classrooms, vehicle drop-off and on-site parking.
Parking	0.365	0.731	Poor	The number of parking spaces is insufficient. Portables are occupying former parking space.
Play Areas	1.369	2.107	Fair	There is no hard surface play area at this site. The field is dirt and uneven. There are also areas where standing water will exist during rains. The play equipment has no safety mulch or material to soften falls.
<i>Safety and Security</i>				
Fencing	0.440	0.677	Fair	There is no fencing around the site. This is contributing to student traffic//travel across school grounds at random points.
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	2.160	2.700	Good	The playground sets well below the grade of the building. The area is surrounded by trees and with no fencing.
Controlled Entrances	0.292	0.450	Fair	There is no vestibule. The camera system lacks full coverage at the front entrance and rear of school.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pleasantdale ES

Grade Configuration: PK-5

Score: 72.32

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	0.670	1.000	Fair	Wi-Fi is sometimes weak throughout the building.
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
<b>Total</b>	<b>72.32</b>	<b>100.00</b>	<b>=</b>	<b>72.32</b>