

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Princeton ES

Grade Configuration: PK-5

Score: 88.24

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.421	0.421	Excel	The art room contains display cases on an exterior wall. There is an exterior concrete pad and a kiln with ventilation.
Size	1.053	1.053	Excel	
Location	0.316	0.316	Excel	
Storage/Fixed Equip	0.253	0.316	Good	There is storage closet within the room. The kiln room is ventilated. There isn't a sink with a clay trap.
<i>Computer Labs</i>				
Environment	0.307	0.307	Excel	Princeton has several "Interactive Labs". The labs contain a room full of interactive Promethean tables.
Size	0.768	0.768	Excel	
Location	0.184	0.230	Good	Computer labs are located on the upper floor where are classrooms have exterior walls providing natural light.
Storage/Fixed Equip	0.150	0.230	Fair	Hard and wireless connections are available in all labs. There is little built in cabinetry in several of the rooms. Hallways contain security cameras, but they isn't one within the computer labs and the rooms do not have motion-sensor lighting.
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	1.125	1.125	Excel	
Location	0.337	0.337	Excel	
Storage/Fixed Equip	0.337	0.337	Excel	The classroom has access to warm water, an ADA accessible restroom with a shower, and permanent casework.
<i>General Classrooms</i>				
Environment	3.528	4.410	Good	
Size	11.025	11.025	Excel	
Location	3.307	3.307	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Princeton ES

Grade Configuration:

PK-5

Score: 88.24

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Storage/Fixed Equip	2.646	3.307	Good	
<i>Instructional Resource Rooms</i>				
Environment	0.518	0.648	Good	HVAC temperatures varied by classroom due to a leak on the second floor. Many general classrooms are utilized as instructional resource rooms.
Size	1.620	1.620	Excel	
Location	0.389	0.486	Good	Resource classes are located throughout the first and second floor.
Storage/Fixed Equip	0.486	0.486	Excel	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	A leak on the second floor is impacting HVAC temperatures throughout the school. Temperatures fluctuate by classroom.
Size	0.938	0.938	Excel	
Location	0.282	0.282	Excel	
Storage/Fixed Equip	0.225	0.282	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.170	1.800	Fair	There is currently an air conditioning leak that is impacting the HVAC temperatures throughout the building. Temperatures vary by space.
Exterior Environment	1.080	1.350	Good	
Environment	0.702	0.877	Good	
<i>Media Center</i>				
Size	1.097	2.193	Poor	The media center meets approximately 60% of the size requirements.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Princeton ES

Grade Configuration: PK-5

Score: 88.24

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Environment	0.433	0.667	Fair	There is a single music room at Princeton Elementary. The room has fixed risers.
Size	0.833	1.667	Poor	There is a single music room that meets approximately 80% of the size requirement. A second room/program is unavailable for band/orchestra.
Location	0.325	0.500	Fair	Only one room exists and opens to the commons area.
Storage/Fixed Equip	0.325	0.500	Fair	Only one music room exists and it contains a 120 square foot storage closet.
<i>Performing Arts</i>				
Environment	0.435	0.544	Good	The HVAC temperature is inconsistent throughout the building.
Size	1.088	1.360	Good	The stage is located in a multipurpose cafeteria/performing arts space with separate storage and dressing rooms.
Location	0.326	0.408	Good	The performing arts space is located on the ground floor of the facility and is conveniently located for public and after-school access.
Storage/Fixed Equip	0.326	0.408	Good	Lights on the stage?
<i>Physical Education</i>				
Environment	1.382	1.728	Good	The HVAC temperature was inconsistent throughout the building.
Size	4.320	4.320	Excel	
Location	1.296	1.296	Excel	The gym can be separated from additional portions of the facility.
Storage/Fixed Equip	1.037	1.296	Good	The gym has a storage closet. It does not have safety padding.
<i>Science</i>				
Environment	0.292	0.450	Fair	The STEM lab contains student science stations and a demonstration table for the teacher. There is hot and cold water available, but no eye wash station. The lab is located in a converted general education classroom.
Size	1.125	1.125	Excel	
Location	0.219	0.337	Fair	The lab is located at the end of the second floor fifth grade hallway.
Storage/Fixed Equip	0.219	0.337	Fair	The lab does not contain the required safety equipment. The room does not have a separate storage area.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Princeton ES

Grade Configuration: PK-5

Score: 88.24

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Environment	0.346	0.432	Good	Temperatures fluctuate by classroom due to a leak on the second floor of the facility. Dimmable lighting is unavailable.
Size	0.702	1.080	Fair	The individual self-contained classrooms are adequately sized for special education. Princeton does not have a family living center.
Location	0.211	0.324	Fair	One of the self-contained classrooms is located on the second floor of the facility. An elevator is available for ADA accessibility.
Storage/Fixed Equip	0.259	0.324	Good	
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	
Cafeteria	3.600	4.500	Good	
Food Service and Prep	5.584	5.584	Excel	
Clinic	0.421	0.526	Good	The clinic does not have a shower.
Counseling	0.263	0.263	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.639	0.798	Good	
Faculty Work Space and Toilets	1.140	1.140	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	1.800	1.800	Excel	The traffic flows well with designated bus and parent pick-up areas.
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.731	0.731	Excel	
Play Areas	2.107	2.107	Excel	There is an abundance of hard and soft surface play areas.
<i>Safety and Security</i>				
Fencing	0.677	0.677	Excel	
Signage & Way Finding	0.900	0.900	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Princeton ES

Grade Configuration: PK-5

Score: 88.24

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Ease of Supervision	2.700	2.700	Excel	
Controlled Entrances	0.450	0.450	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	Some IDF/MDF environments contain clutter and are in need of improved climate control.
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	88.24	100.00	=	