

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Ronald E. McNair, HS

Grade Configuration: 9-12

Score: 87.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.479	0.599	Good	
Size	1.496	1.496	Excel	
Location	0.449	0.449	Excel	
Storage/Fixed Equip	0.292	0.449	Fair	The art room sink does not have a clay trap.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.230	1.538	Good	
Size	3.845	3.845	Excel	The ROTC program does not have a drill pad.
Location	0.923	1.154	Good	
Storage/Fixed Equip	0.923	1.154	Good	
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	
Size	0.675	0.675	Excel	
Location	0.132	0.202	Fair	Four classrooms are being used to set up laptop labs. They are in an auxiliary building that has no secure entrance and the rooms have no camera or motion sensor lighting.
Storage/Fixed Equip	0.132	0.202	Fair	There are an insufficient number of power outlets to support computer equipment. None of the labs have motion sensor lighting or a security camera.
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	Classrooms have ceiling tiles and window blinds that are damaged.
Size	8.775	8.775	Excel	
Location	2.632	2.632	Excel	
Storage/Fixed Equip	2.106	2.632	Good	
<i>Instructional Resource Rooms</i>				
Environment	0.575	0.719	Good	
Size	1.797	1.797	Excel	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Ronald E. McNair, HS

Grade Configuration: 9-12

Score: 87.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.539	0.539	Excel	
Storage/Fixed Equip	0.431	0.539	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.170	1.800	Fair	The HVAC is not consistent throughout the building. There are some areas that are too hot and others that are too cold. Ceiling tiles need to be replaced in various spots throughout the building. Some rooms have window blinds that are damaged.
Exterior Environment	0.675	1.350	Poor	There are no outdoor learning labs or social gathering areas.
Environment	0.607	0.759	Good	
<i>Media Center</i>				
Size	1.897	1.897	Excel	
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.370	0.569	Fair	Bookcases are tall and in rows on one end of the media center. There are not enough outlets to support the computers in the area.
<i>Music</i>				
Environment	0.428	0.534	Good	
Size	1.336	1.336	Excel	
Location	0.321	0.401	Good	Practice rooms are not in line of sight for adequate supervision.
Storage/Fixed Equip	0.401	0.401	Excel	
<i>Performing Arts</i>				
Environment	0.231	0.289	Good	
Size	0.721	0.721	Excel	
Location	0.216	0.216	Excel	
Storage/Fixed Equip	0.173	0.216	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Ronald E. McNair, HS

Grade Configuration: 9-12

Score: 87.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Physical Education</i>				
Environment	1.728	2.160	Good	The locker rooms are not well ventilated.
Size	5.400	5.400	Excel	
Location	1.296	1.620	Good	
Storage/Fixed Equip	1.296	1.620	Good	There is no padding behind the backboard in the main gym area.
<i>Science</i>				
Environment	0.597	0.747	Good	
Size	1.867	1.867	Excel	
Location	0.364	0.560	Fair	Science classrooms do not have direct access to outdoor patio area.
Storage/Fixed Equip	0.280	0.560	Poor	The prep rooms do not have sinks. The sinks in most science classrooms have faucets that are broken and/or water does not come through the pipes. The gas does not work in the lab areas. There is one fume hood in one prep room, but it does not work. There is weak water pressure for the eye wash unit. There is no shower in any of the science lab areas. There are no dishwashers or refrigerators in the prep rooms. The cabinet for hazardous materials does not lock.
<i>Self-Contained Special Education</i>				
Environment	0.383	0.479	Good	
Size	1.198	1.198	Excel	
Location	0.359	0.359	Excel	
Storage/Fixed Equip	0.288	0.359	Good	
<i>Non-Instructional Spaces</i>				
Administration	2.349	2.349	Excel	
Cafeteria	2.880	3.600	Good	Ceiling tiles are damaged.
Food Service and Prep	3.676	4.595	Good	Ceiling tiles are damaged. There is no peep hole or window in the receiving dock door.
Clinic	0.000	0.214	Unsat	The school does not have a clinic

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Ronald E. McNair, HS

Grade Configuration: 9-12

Score: 87.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Counseling	0.681	0.681	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.411	0.821	Poor	Many stall doors in both the boys and girls bathroom are damaged. Fixtures for toilet paper and paper towels are missing or broken. There are no partitions between the urinals. There is poor ventilation in most of the restrooms.
Faculty Work Space and Toilets	0.513	0.641	Good	There are only three adult restrooms in the main building and one adjoins the staff workroom. There is a copier in the staff workroom.
<i>Outside Spaces</i>				
Vehicular Traffic	0.720	0.900	Good	There is no covered area for loading students onto buses.
Pedestrian Traffic	0.882	0.882	Excel	
Parking	1.897	1.897	Excel	
Athletic Fields and Facilities	1.618	2.488	Fair	There are no lights for the outdoor fields and courts. The area is not ADA accessible. The fields and fixed equipment are in poor condition.
<i>Safety and Security</i>				
Fencing	0.495	0.762	Fair	Six foot fencing does not surround the building.
Signage & Way Finding	0.900	0.900	Excel	
Ease of Supervision	1.350	2.700	Poor	Some security cameras inside and outside the building do not work. The picture quality as viewed on the monitors is poor. High vegetation around the back of the building obstructs the view of the playing fields
Controlled Entrances	0.292	0.450	Fair	There is no security vestibule. There are auxiliary buildings but not all have controlled entrances.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Ronald E. McNair, HS

Grade Configuration: 9-12

Score: 87.25

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

---

## *Technology Readiness*

WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
<b>Total</b>	<b>87.25</b>	<b>100.00</b>	<b>=</b>	<b>87.25</b>