

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Warren Technical School

Grade Configuration: 10-12

Score: 69.67

Category	Points Earned	Possible Points	Rating	Comment
<i>Computer Labs</i>				
Environment	0.000	0.498	Unsat	The computer lab is not operational at this time due to roof leaks. All equipment is wrapped in protective plastic to preserve it until the roof is repaired.
Size	0.995	1.244	Good	
Location	0.299	0.373	Good	
Storage/Fixed Equip	0.299	0.373	Good	
<i>General Classrooms</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Learning Environment</i>				
Learning Style Variety	4.976	6.220	Good	
Interior Environment	1.990	2.488	Good	
Exterior Environment	1.493	1.866	Good	
Environment			N/A	
<i>Media Center</i>				
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Physical Education</i>				
Environment			N/A	
Size			N/A	
Location			N/A	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Warren Technical School

Grade Configuration: 10-12

Score: 69.67

Category	Points Earned	Possible Points	Rating	Comment
<i>Physical Education</i>				
Storage/Fixed Equip			N/A	
<i>Non-Instructional Spaces</i>				
Administration	1.836	2.824	Fair	The administrative suite has a reception space appropriate for the size. Storage space is available for consumable materials. The principal's office has space for small meetings, but travels down the hall for use of a conference room.
Cafeteria	1.990	2.488	Good	The cafeteria exceeds the space requirement for an enrollment of 225 students. There is no hot water in the restrooms located closest to the cafeteria.
Food Service and Prep	2.986	3.732	Good	
Clinic	0.000	0.296	Unsat	Warren Technical does not have a clinic. Students who become ill are seen in the Healthcare lab.
Counseling	1.093	2.186	Poor	Student records are located in counselor's office. The files are fireproof. Once cabinet can be locked, but the other cannot. GA state testing is not required for the population enrolled at Warren Technology School, but space is provided for school psychologists when they are on campus.
Custodial and Maintenance	0.498	0.622	Good	There is no receiving area on campus. Custodial closets have sinks, but they are not floor sinks.
Student Restrooms	0.738	1.136	Fair	Since Warren Technical is located in a former elementary school, the toilets and urinals are designed for younger students. The boys restroom does not have privacy dividers between the urinals. There is a single ADA accessible restroom.
Faculty Work Space and Toilets	0.710	0.887	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	0.995	1.244	Good	
Pedestrian Traffic			N/A	None of the students walk to school.
Parking	1.990	2.488	Good	
Athletic Fields and Facilities			N/A	Warren Technical does not have an athletic program.
<i>Safety and Security</i>				
Fencing	1.053	1.053	Excel	Fencing is limited.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Warren Technical School

Grade Configuration: 10-12

Score: 69.67

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Signage & Way Finding	0.105	0.132	Good	Drug-Free and Weapons-Free signage is predominantly placed at the entrance to the bus/parking area. Subject to search and under surveillance signage was not present.
Ease of Supervision	1.990	2.488	Good	
Controlled Entrances	0.404	0.622	Fair	The secure door for deliveries to the food service area was left unlocked. Security cameras are in place, but they are not connected to monitors; therefore, they do not provide campus monitoring. A camera on the rear of the building facing a storage unit is ineffective due to its placement next to exterior lighting and break ins have occurred in the storage shed.
<i>Agriculture and Natural Resources</i>				
Environment	0.970	1.493	Fair	The greenhouse is currently not operational.
Size	0.000	3.732	Unsat	Agriculture is located in a small lab space with a greenhouse. The greenhouse space will be a productive area, but the site is still developing as they return to their campus.
Location	0.896	1.120	Good	
Storage/Fixed Equip	0.728	1.120	Fair	The agriculture classroom has a Promethean board, permanent cabinetry and tables where students work with plants and soil.
<i>Automotive Tech</i>				
Environment	0.871	1.742	Poor	
Size	2.177	4.354	Poor	The Automotive lab meets approximately 52% of the size standard.
Location	0.849	1.306	Fair	The location of the lab enable individuals to drive their vehicles up to a garage door for service. The facility's ceiling height is a detriment to the functionality of the lab.
Storage/Fixed Equip	0.849	1.306	Fair	Flammable storage, eyewash, fire extinguisher, MSDS, first aid kits, and safety posters are abundance in the automotive lab. There is a small storage closet available.
<i>Business, Management, and Admin</i>				
Environment	1.194	1.493	Good	The learning environment would be enhance if the two allocated spaces were available for student instruction.
Size	1.866	3.732	Poor	Although the total space allocation meets approximately 98% of the guidelines, only approximately 55% of the space is available for learning.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Warren Technical School

Grade Configuration: 10-12

Score: 69.67

Category	Points Earned	Possible Points	Rating	Comment
<i>Business, Management, and Admin</i>				
Location	0.728	1.120	Fair	The business lab and computer science labs are at opposite ends of the hallway.
Storage/Fixed Equip	0.896	1.120	Good	
<i>Construction Trades</i>				
Environment	1.132	1.742	Fair	The learning environment is impacted by the lack of equipment in the construction lab. For example, there is a dust collection unit that cannot be used since it does not meet code and students must travel outdoors to saw construction materials.
Size	2.177	4.354	Poor	The Construction lab meets approximately 59% of the guidelines.
Location	1.045	1.306	Good	
Storage/Fixed Equip	1.045	1.306	Good	Fixed and safety equipment are appropriate for the construction lab.
<i>Cosmetology</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Culinary</i>				
Environment	1.393	1.742	Good	The culinary arts area is located adjacent to the food service preparation area, enhancing the learning experience for students. The areas have lots of natural light, good air quality and lighting.
Size	2.177	4.354	Poor	The allocated space for Culinary Arts is in compliance with approximately 59% of the guidelines.
Location	1.045	1.306	Good	
Storage/Fixed Equip	0.849	1.306	Fair	Due to the upgrades provided this summer, an appropriately sized hood has not arrived and students are unable to use several pieces of equipment.
<i>Health Services</i>				
Environment	1.194	1.493	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Warren Technical School

Grade Configuration: 10-12

Score: 69.67

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

Health Services

Size	3.732	3.732	Excel	
Location	1.120	1.120	Excel	
Storage/Fixed Equip	0.896	1.120	Good	There is appropriate equipment for the Healthcare lab; however, updates in equipment would assist students as they transition to the world of work, utilizing the current equipment in real life settings.

Tech Ed and Communications

Environment	0.995	1.244	Good	
Size	1.555	3.110	Poor	The Graphic Communications lab meets approximately 60% of the size requirements.
Location	0.746	0.933	Good	
Storage/Fixed Equip	0.606	0.933	Fair	The required computers needed for a graphics class are older models and do not house current software programs. Permanent casework is adequate. Screen printing and safety equipment is available.

Technology Readiness

IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	The school does not meet electrical power requirements. They need quad outlets and a duplex in the ceiling.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	The PA system does not cover the exterior areas of the campus.

Total **69.67 / 100.00 = 69.67**