

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Allgood ES

Grade Configuration:

PK-5

Score: 71.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.000	0.432	Unsat	The art classroom is in a portable unit.
Size	0.000	1.080	Unsat	The art classroom is in a portable unit.
Location	0.000	0.324	Unsat	The art classroom is in a portable unit.
Storage/Fixed Equip	0.000	0.324	Unsat	The art classroom is in a portable unit.
<i>Computer Labs</i>				
Environment	0.205	0.315	Fair	The HVAC system leaks causing damage to ceiling tiles. They are discolored and stained. It also provides an inconsistent climate from day-to-day. The window blinds are aged and damaged.
Size	0.630	0.787	Good	
Location	0.189	0.236	Good	
Storage/Fixed Equip	0.154	0.236	Fair	The computer lab has no motion sensor lighting and no security camera.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment	2.940	4.523	Fair	The HVAC system leaks causing damage to ceiling tiles in many rooms. It also provides an inconsistent climate from room-to-room and day-to-day. The window blinds are aged and damaged.
Size	11.308	11.308	Excel	
Location	2.714	3.392	Good	
Storage/Fixed Equip	2.205	3.392	Fair	There is inadequate storage for instructional materials and no cubbies or other means for storage of student belongings. Fixed equipment is showing signs of wear and tear.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Allgood ES

Grade Configuration: PK-5

Score: 71.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.432	0.665	Fair	The HVAC system leaks causing damage to ceiling tiles. It also provides an inconsistent climate from day-to-day. The window blinds are aged and damaged.
Size	1.080	1.662	Fair	One room is in a portable.
Location	0.324	0.498	Fair	One resource classroom is in a portable unit.
Storage/Fixed Equip	0.324	0.498	Fair	There is no storage for resources or materials. Fixed equipment is showing signs of wear and tear.
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.250	0.385	Fair	The HVAC system leaks causing damage to ceiling tiles in many rooms. It also provides an inconsistent climate from rom-to-room and day-to-day. The window blinds are aged and damaged.
Size	0.625	0.962	Fair	Most kindergarten classrooms do not have a restroom or sink. The classrooms are approximately 84% of the size standard.
Location	0.231	0.289	Good	
Storage/Fixed Equip	0.144	0.289	Poor	There is inadequate storage for instructional materials and no cubbies for storage of student belongings. Fixed equipment is showing signs of wear and tear.
<i>Learning Environment</i>				
Learning Style Variety	2.308	4.615	Poor	The buildings traditional design does not allow for true flexible learning spaces within the building.
Interior Environment	1.200	1.846	Fair	The HVAC system leaks and has caused water damage particularly to ceiling tiles which are damaged or missing. It also provides an inconsistent climate from rom-to-room and day-to-day. The window blinds are aged and damaged.
Exterior Environment	1.108	1.385	Good	
Environment	0.720	0.900	Good	
<i>Media Center</i>				
Size	0.000	2.249	Unsat	The media center is approximately 38% of the size standard.
Location	0.540	0.675	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Allgood ES

Grade Configuration: PK-5

Score: 71.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Media Center</i>				
Storage/Fixed Equip	0.439	0.675	Fair	There is insufficient storage for equipment and materials.
<i>Music</i>				
Environment	0.444	0.684	Fair	The HVAC system leaks causing damage to ceiling tiles. They are discolored and stained. It also provides an inconsistent climate from day-to-day. The window blinds are aged and damaged.
Size	1.111	1.709	Fair	The general music room is approximately 76% of the size standard.
Location	0.256	0.513	Poor	The general music room neighbors the media center.
Storage/Fixed Equip	0.256	0.513	Poor	There is no sink or drinking fountain in the general music room. There is inadequate storage for equipment and materials. The room does not have acoustical wall coverings or high ceilings. The fixed equipment is showing wear and tear.
<i>Performing Arts</i>				
Environment	0.363	0.558	Fair	The stage is not ADA accessible.
Size	1.116	1.395	Good	
Location	0.335	0.418	Good	
Storage/Fixed Equip	0.272	0.418	Fair	There is no sound system for the performing arts area.
<i>Physical Education</i>				
Environment	1.152	1.772	Fair	There is inadequate ventilation in the gymnasium.
Size	4.431	4.431	Excel	
Location	1.063	1.329	Good	
Storage/Fixed Equip	0.665	1.329	Poor	The flooring has large gaps between the seams of the rubber surface. Fixed equipment is showing signs of wear and tear.
<i>Science</i>				
Environment	0.300	0.462	Fair	The HVAC system leaks causing damage to ceiling tiles. It also provides an inconsistent climate from day-to-day. The window blinds are aged and damaged. .
Size	0.750	1.154	Fair	The Science lab is approximately 77% of the size standard.
Location	0.225	0.346	Fair	There is no direct or nearby access to the outside.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Allgood ES

Grade Configuration: PK-5

Score: 71.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Science</i>				
Storage/Fixed Equip	0.173	0.346	Poor	There is inadequate storage for equipment and instructional materials. The lab has no eye wash station, shower, or fire blanket. Fixed equipment is showing signs of wear and tear.
<i>Self-Contained Special Education</i>				
Environment	0.288	0.443	Fair	The HVAC system leaks causing damage to ceiling tiles. It also provides an inconsistent climate from day-to-day. The window blinds are aged and damaged.
Size	0.554	1.108	Poor	The self-contained Special Education classrooms do not have a restroom, sink, or changing area. They do meet approximately 87% of the size standard.
Location	0.266	0.332	Good	
Storage/Fixed Equip	0.166	0.332	Poor	There is inadequate storage for instructional materials and the storage of student belongings. There is no family living center. Fixed equipment is showing signs of wear and tear.
<i>Non-Instructional Spaces</i>				
Administration	1.535	2.361	Fair	There is no conference room and the reception area is small. Fixed furnishings are showing wear and tear.
Cafeteria	3.000	4.615	Fair	The entire cafeteria area is showing wear and tear. Some ceiling tiles are damaged and discolored.
Food Service and Prep	3.722	5.727	Fair	The delivery door for the food service area has no peep hole, no bell or buzzer, and is narrow.
Clinic	0.432	0.540	Good	
Counseling	0.175	0.270	Fair	There is no reception area for the counseling program. The ceiling tiles are discolored and damaged from water.
Custodial and Maintenance	0.369	0.462	Good	
Student Restrooms	0.532	0.819	Fair	The restrooms have poor ventilation. Some of the boy's bathroom do not have privacy partitions between the urinals.
Faculty Work Space and Toilets	0.936	1.170	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.477	1.846	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Allgood ES

Grade Configuration: PK-5

Score: 71.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Outside Spaces</i>				
Pedestrian Traffic	0.449	0.898	Poor	The sidewalk is no longer a level surface. The unevenness of the sidewalk presents a safety hazard to pedestrians and is also a challenge for those using wheelchairs or walkers.
Parking	0.487	0.750	Fair	There is inadequate parking for staff and visitors and the lighting is insufficient.
Play Areas	1.404	2.161	Fair	The hard surface play area has grass growing through numerous cracks in the asphalt which becomes a safety hazard to students.
<i>Safety and Security</i>				
Fencing	0.451	0.694	Fair	The fence surrounding the school is approximately 4' high.
Signage & Way Finding	0.600	0.923	Fair	No signage for Weapon Free, Under Surveillance or Subject to Search.
Ease of Supervision	1.800	2.769	Fair	Lighting surrounding the school campus is inadequate. The lack of outdoor cameras leaves many blind spots and there is poor line of sight due to building design.
Controlled Entrances	0.300	0.462	Fair	There is no keypad system on the back door that leads to the play area.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	The internet is slow.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	71.59	100.00	=	71.59