

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Brockett ES

Grade Configuration: PK-5

Score: 77.61

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.216	0.432	Poor	Art instruction is held in a general classroom.
Size	0.702	1.080	Fair	The art classroom is only about 75% of the required size.
Location	0.211	0.324	Fair	The room has an exterior wall with windows looking into the courtyard, but no direct access to outside.
Storage/Fixed Equip	0.162	0.324	Poor	There is only one sink, no clay trap, little display space, and limited storage for supplies.
<i>Computer Labs</i>				
Environment	0.205	0.315	Fair	The computer lab is located in a reconfigured general classroom. There are no security coverings on the exterior windows.
Size	0.630	0.787	Good	The computer lab is about 85% of the size standard.
Location	0.154	0.236	Fair	The lab is located on the ground floor with a full wall of windows facing the exterior courtyard.
Storage/Fixed Equip	0.189	0.236	Good	There is no motion sensor in the room, but it has hallway cameras that cover the entrance to the computer lab. There is ample storage space.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment	3.618	4.523	Good	
Size	11.308	11.308	Excel	Nearly all classrooms meet or exceed at least 90% of the district's size standard.
Location	2.714	3.392	Good	
Storage/Fixed Equip	2.714	3.392	Good	Although classroom cabinetry and casework are older and worn, there is ample storage space.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Brockett ES

Grade Configuration: PK-5

Score: 77.61

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.432	0.665	Fair	Speech pullout instruction is held in a windowless room that doubles as a book storage room and work space.
Size	1.329	1.662	Good	
Location	0.399	0.498	Good	
Storage/Fixed Equip	0.324	0.498	Fair	The speech room has no appropriate fixtures, fixed equipment or storage appropriate for that purpose.
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.308	0.385	Good	
Size	0.770	0.962	Good	Kindergarten and prekindergarten classrooms are approximately 80% of the size standard.
Location	0.188	0.289	Fair	The four kindergarten classrooms are located at the end of a hallway that is the farthest point from the drop-off/pick-up location. The prekindergarten classroom is adjacent to the drop-off/pick-up area.
Storage/Fixed Equip	0.231	0.289	Good	There is no bathroom in the prekindergarten room.
<i>Learning Environment</i>				
Learning Style Variety	3.692	4.615	Good	
Interior Environment	1.477	1.846	Good	
Exterior Environment	0.900	1.385	Fair	The exterior appearance of the school shows its age and looks to need refurbishment. The spacious enclosed courtyard as well as a nature trail on the school property are overgrown, unkempt, and unusable in their current condition.
Environment	0.585	0.900	Fair	The media center lacks the required array of work space, and has little noise reduction treatments with a low ceiling.
<i>Media Center</i>				
Size	0.000	2.249	Unsat	The media center is less than half the size standard.
Location	0.540	0.675	Good	
Storage/Fixed Equip	0.337	0.675	Poor	There is limited storage and work/production areas, and no bathroom in the work area.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Brockett ES

Grade Configuration: PK-5

Score: 77.61

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Environment	0.342	0.684	Poor	Music instruction is delivered in a regular classroom.
Size	1.111	1.709	Fair	The music room is approximately 75% of the required size.
Location	0.410	0.513	Good	
Storage/Fixed Equip	0.256	0.513	Poor	There are no acoustical treatments, low ceilings, limited storage, and no water or sink in the room.
<i>Performing Arts</i>				
Environment	0.363	0.558	Fair	The performing arts space is a shared cafetorium. The stage has no fixed ADA access but the school has a portable lift. There are no acoustical treatments in this space.
Size	1.116	1.395	Good	
Location	0.272	0.418	Fair	The cafetorium cannot be isolated from other areas of the school for after-hours use.
Storage/Fixed Equip	0.209	0.418	Poor	There is little or no storage space available.
<i>Physical Education</i>				
Environment	1.152	1.772	Fair	The detached gym does not have HVAC. It has two large wall exhaust fans that create significant noise issues when in use.
Size	4.431	4.431	Excel	
Location	1.329	1.329	Excel	
Storage/Fixed Equip	1.063	1.329	Good	
<i>Science</i>				
Environment	0.300	0.462	Fair	There are no fixed work tables for students, just traditional classroom desks or moveable tables/chairs.
Size	0.750	1.154	Fair	These two original science rooms are approximately 75% of the size standard,
Location	0.277	0.346	Good	
Storage/Fixed Equip	0.173	0.346	Poor	Much of the required science related equipment, fixtures, safety components and storage space is not present.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Brockett ES

Grade Configuration: PK-5

Score: 77.61

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Environment	0.354	0.443	Good	
Size	0.720	1.108	Fair	There is no space for a family living center.
Location	0.216	0.332	Fair	The room is in a general classroom with small stairs at both ends of the hallway.
Storage/Fixed Equip	0.216	0.332	Fair	There is no family Living Center.
<i>Non-Instructional Spaces</i>				
Administration	1.535	2.361	Fair	The administration suite has limited storage, no conference room, and teacher mailboxes are in the public waiting area.
Cafeteria	3.692	4.615	Good	
Food Service and Prep	3.722	5.727	Fair	There is no HVAC in the kitchen areas, no staff lockers, and difficult loading dock location for large truck access.
Clinic	0.351	0.540	Fair	The clinic has limited space that serves as both a nurse station and patient area with only one cot. Restrooms are not ADA accessible.
Counseling	0.175	0.270	Fair	The counseling office has two small desks shared by two counselors and a part-time LTSE staff. There is no waiting area and no room for a private small group meeting.
Custodial and Maintenance	0.369	0.462	Good	
Student Restrooms	0.532	0.819	Fair	The boys restrooms do not have partitions between urinals.
Faculty Work Space and Toilets	0.936	1.170	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.477	1.846	Good	
Pedestrian Traffic	0.719	0.898	Good	
Parking	0.487	0.750	Fair	There are not enough parking spaces for all of the staff, faculty, administration, and visitors.
Play Areas	1.404	2.161	Fair	There is a hard surface court, but it is in disrepair, and could be unsafe for play.
<i>Safety and Security</i>				
Fencing	0.451	0.694	Fair	There are perimeter sections of the property that are accessible to adjacent homes, and a wooded ravine along the back of the property that does not appear to be fully fenced.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Brockett ES

Grade Configuration:

PK-5

Score: 77.61

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Signage & Way Finding	0.600	0.923	Fair	The required "under surveillance" and "subject to search" signs were not posted.
Ease of Supervision	2.215	2.769	Good	
Controlled Entrances	0.300	0.462	Fair	The school entry does not contain a secure vestibule space.
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	The MDF equipment is housed in the secure test storage room, which creates issues to access the network system equipment.
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	77.61	100.00	=	77.61