

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Browns Mill ES

Grade Configuration:

PK-5

Score: 75.87

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.274	0.421	Fair	There is a corner full of windows from floor to ceiling providing natural light in the art room. HVAC temperatures are inconsistent throughout the building.
Size	1.053	1.053	Excel	
Location	0.253	0.316	Good	There is direct access to an outdoor space, but it is small and it is connected to a stairwell.
Storage/Fixed Equip	0.205	0.316	Fair	The art room has sinks without clay traps, a kin with ventilation, and a storage closet. Student art work is hung around the room, but there is no display space.
<i>Computer Labs</i>				
Environment	0.200	0.307	Fair	HVAC temperature vary throughout the building. There are no motion sensors or security cameras in the lab.
Size	0.768	0.768	Excel	
Location	0.184	0.230	Good	
Storage/Fixed Equip	0.184	0.230	Good	There are no motion sensors or security cameras in the lab.
<i>Early Childhood Education</i>				
Environment	0.292	0.450	Fair	The environment is VERY warm. There hasn't been any air conditioning in the room for several weeks. Natural light shines through windows with blinds.
Size	1.125	1.125	Excel	
Location	0.337	0.337	Excel	
Storage/Fixed Equip	0.270	0.337	Good	There is a wall of built in cabinets supplemented by additional cubbies and storage units. The classroom has a restroom.
<i>General Classrooms</i>				
Environment	2.866	4.410	Fair	HVAC temperatures are exceptionally warm in some parts of the school. Inconsistent A/C temperatures negatively impact the learning environment. Natural lighting creates bright learning spaces. Acoustics are good.
Size	8.820	11.025	Good	
Location	2.646	3.307	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Browns Mill ES

Grade Configuration:

PK-5

Score: 75.87

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Storage/Fixed Equip	2.646	3.307	Good	Most general education classrooms have a bank of permanent casework along one wall that has a sink with a bubbler. Counters are set at an age-appropriate level.
<i>Instructional Resource Rooms</i>				
Environment	0.421	0.648	Fair	HVAC temperatures are inconsistent.
Size	1.296	1.620	Good	Small resource rooms meet approximately 75% of the standard and large resource rooms meet approximately 90% of the guidelines.
Location	0.389	0.486	Good	
Storage/Fixed Equip	0.389	0.486	Good	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.244	0.375	Fair	Kindergarten classrooms are clustered together and the HVAC temperatures vary by classroom. Natural lighting shines through window blinds. The acoustics are good.
Size	0.751	0.938	Good	
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.225	0.282	Good	There is a sink with bubbler in every classroom. Permanent cabinetry and additional storage cabinets provide an abundance of storage. Each class has a bathroom.
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	Space is available to provide differentiated instruction in most classrooms.
Interior Environment	1.170	1.800	Fair	The majority of the classroom have natural lighting. HVAC temperatures vary throughout the school. Some spaces on campus are very warm. Lighting levels and overall aesthetics are good.
Exterior Environment	1.080	1.350	Good	There are several commons areas where students garden and play.
Environment	0.570	0.877	Fair	HVAC temperatures are inconsistent throughout the facility.
<i>Media Center</i>				
Size	1.754	2.193	Good	
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Browns Mill ES

Grade Configuration:

PK-5

Score: 75.87

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Environment	0.333	0.667	Poor	The music room temperature is inconsistent. There is natural lighting, a storage room, and space for spatial configuration. Band is held in the cafeteria.
Size	0.833	1.667	Poor	The classroom identified as a music room meets approximately 90% of the standard. Band is held in the cafeteria.
Location	0.250	0.500	Poor	The one music room is located close to the auditorium. Band is held in the cafeteria.
Storage/Fixed Equip	0.250	0.500	Poor	The one music classroom has a 2500 SF storage closet. Band is held in the cafeteria.
<i>Performing Arts</i>				
Environment	0.435	0.544	Good	The HVAC temperatures are inconsistent. A ramp located to the side of the stage provides ADA accessibility.
Size	1.088	1.360	Good	The performing arts space is located in the cafeteria. There are no dressing rooms.
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.382	1.728	Good	There are attic fans, but no air conditioning in the gym.
Size	4.320	4.320	Excel	
Location	1.296	1.296	Excel	
Storage/Fixed Equip	1.037	1.296	Good	There is adequate storage space, restrooms, and a water fountain. There is no safety padding.
<i>Science</i>				
Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>Self-Contained Special Education</i>				
Environment	0.000	0.432	Unsat	There is no self-contained special education space.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Browns Mill ES

Grade Configuration:

PK-5

Score: 75.87

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Size	0.000	1.080	Unsat	There is no self-contained special education space.
Location	0.000	0.324	Unsat	There is no self-contained special education space.
Storage/Fixed Equip	0.000	0.324	Unsat	Browns Mill does not have self-contained special education space. Elementary Schools without self-contained programs are not required to have a family living center
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	
Cafeteria	2.925	4.500	Fair	There are several roof leaks in the cafeteria. Student restrooms closest to the cafeteria do not have hot and cold water.
Food Service and Prep	3.629	5.584	Fair	Equipment in the food service area needs to be repaired or replaced. There is a stove that does not work and a cooler that runs intermittently. The area lacks lockers and a changing area.
Clinic	0.421	0.526	Good	There is a clinic housed within the administrative suite with one cot, hot and cold water, a restroom, and secure storage for medication.
Counseling	0.171	0.263	Fair	There is a single counselor with a private office. The school does not have a reception area for guidance. A conference room is available in the administrative suite.
Custodial and Maintenance	0.292	0.450	Fair	There is no receiving area.
Student Restrooms	0.519	0.798	Fair	There are an appropriate number of restrooms located throughout the school. The boys bathrooms lack partitions between the urinals. Lighting in the hall area outside of two of the restrooms is inadequate.
Faculty Work Space and Toilets	0.741	1.140	Fair	The workrooms are adequately staffed with the necessary equipment. ADA accessible restrooms with hot and cold water are available near the front office, but no other restrooms are available in the facility for staff.
<i>Outside Spaces</i>				
Vehicular Traffic	1.440	1.800	Good	
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.585	0.731	Good	
Play Areas	1.685	2.107	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Browns Mill ES

Grade Configuration:

PK-5

Score: 75.87

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Fencing	0.542	0.677	Good	
Signage & Way Finding	0.720	0.900	Good	The Drug-Free and Weapons-Free signage is posted; however the surveillance and subject to search signage is unavailable.
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	All rooms do not have the required quad outlets and a duplex in the ceiling and front wall.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Access can be slow, especially when there is increased demand.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	There are three laptop computer carts available at Browns Mill. Storage is limited and one cart is housed in the media center for overnight charging. The remaining carts are housed in the computer lab storage closet under a security camera.
Telephone/PA	0.500	1.000	Fair	Telephones are available in classrooms and the PA system adequately serves the school. The PA system does not cover the external areas.
Total	75.87	100.00	=	75.87