

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lakeside HS

Grade Configuration: 9-12

Score: 83.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.599	0.599	Excel	
Size	1.496	1.496	Excel	
Location	0.449	0.449	Excel	
Storage/Fixed Equip	0.449	0.449	Excel	
<i>Career, Technical and Agricultural Education</i>				
Environment	1.230	1.538	Good	Some of the career, technology, and agriculture classrooms have a lot of open wall space, painted a bright white which creates a sterile and institutional atmosphere. The HVAC system does not provide a consistent climate from one classroom to another and can fluctuate between temperature extremes.
Size	3.076	3.845	Good	
Location	1.154	1.154	Excel	
Storage/Fixed Equip	1.154	1.154	Excel	
<i>Computer Labs</i>				
Environment	0.175	0.270	Fair	The computer labs are painted a bright white which creates a sterile and institutional atmosphere. The labs can fluctuate between temperature extremes.
Size	0.540	0.675	Good	
Location	0.132	0.202	Fair	There is only one computer lab in the school. It is located on the far corner of the upper level and not easily accessible by any classrooms.
Storage/Fixed Equip	0.132	0.202	Fair	There is no motion sensor lighting or security camera in the computer lab.
<i>General Classrooms</i>				
Environment	2.281	3.510	Fair	The classrooms are painted a bright white which creates a sterile and institutional atmosphere. The HVAC system does not provide a consistent climate from one classroom to another, and rooms can fluctuate between temperature extremes.
Size	8.775	8.775	Excel	
Location	2.106	2.632	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lakeside HS

Grade Configuration: 9-12

Score: 83.17

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Storage/Fixed Equip	1.711	2.632	Fair	Many classrooms are missing at least one of the following standard equipment items: a locked storage cabinet, a locked teacher cabinet, or bookcase.
<i>Instructional Resource Rooms</i>				
Environment	0.467	0.719	Fair	The resource rooms are painted a bright white which creates a sterile and institutional atmosphere. The HVAC system does not provide a consistent climate from one room to another, and they can fluctuate between temperature extremes.
Size	1.797	1.797	Excel	
Location	0.539	0.539	Excel	
Storage/Fixed Equip	0.350	0.539	Fair	Many resource rooms were missing at least one of the following standard fixed equipment items: a locked storage cabinet, a locked teacher cabinet, or bookcase.
<i>Learning Environment</i>				
Learning Style Variety	2.925	4.500	Fair	Lakeside High has a traditional design that does not provide sufficient flexible learning spaces or storage for ongoing projects.
Interior Environment	1.170	1.800	Fair	Most areas of the building are painted a bright white which creates a sterile and institutional atmosphere. The HVAC system does not provide a consistent climate from one area to another, and rooms fluctuate between temperature extremes.
Exterior Environment	1.080	1.350	Good	
Environment	0.607	0.759	Good	
<i>Media Center</i>				
Size	1.518	1.897	Good	
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.569	0.569	Excel	
<i>Music</i>				
Environment	0.534	0.534	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lakeside HS

Grade Configuration: 9-12

Score: 83.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Size	1.069	1.336	Good	There are only three practice rooms, and they are located in an area that is not in a direct line of sight.
Location	0.401	0.401	Excel	
Storage/Fixed Equip	0.321	0.401	Good	
<i>Performing Arts</i>				
Environment	0.289	0.289	Excel	
Size	0.721	0.721	Excel	
Location	0.216	0.216	Excel	
Storage/Fixed Equip	0.216	0.216	Excel	
<i>Physical Education</i>				
Environment	2.160	2.160	Excel	
Size	4.320	5.400	Good	
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.620	1.620	Excel	
<i>Science</i>				
Environment	0.485	0.747	Fair	The science labs are painted a bright white which creates a sterile and institutional atmosphere. The HVAC system does not provide a consistent climate in the labs and they can fluctuate between temperature extremes.
Size	1.867	1.867	Excel	
Location	0.448	0.560	Good	Science labs do not have access to any type of outdoor patio area.
Storage/Fixed Equip	0.448	0.560	Good	Almost all science labs have their own prep room, but they are not equipped with a dishwasher or a refrigerator.
<i>Self-Contained Special Education</i>				
Environment	0.383	0.479	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lakeside HS

Grade Configuration: 9-12

Score: 83.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Size	1.198	1.198	Excel	
Location	0.359	0.359	Excel	
Storage/Fixed Equip	0.359	0.359	Excel	
<i>Non-Instructional Spaces</i>				
Administration	2.349	2.349	Excel	
Cafeteria	1.800	3.600	Poor	The cafeteria is not large enough to accommodate seating for the number of students that are in a lunch period.
Food Service and Prep	3.676	4.595	Good	The delivery door does not have a peep hole, and it does not meet the 60" wide standard.
Clinic	0.000	0.214	Unsat	The school has no clinic.
Counseling	0.681	0.681	Excel	
Custodial and Maintenance	0.450	0.450	Excel	
Student Restrooms	0.534	0.821	Fair	The only ADA accessible restroom for students is in the special education suite.
Faculty Work Space and Toilets	0.641	0.641	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	0.585	0.900	Fair	Bus drop-off, and vehicular traffic from student drop-off and visitor parking, all flow into the same parking lot in front of the building.
Pedestrian Traffic	0.441	0.882	Poor	Some of the area on Briarcliff Road, the road directly in front of the school, does not have a sidewalk route, so walkers must travel along the side of the road.
Parking	1.518	1.897	Good	
Athletic Fields and Facilities	2.488	2.488	Excel	
<i>Safety and Security</i>				
Fencing	0.495	0.762	Fair	Fencing does not surround the sides and the back perimeters of the building. The fencing that is standing is not at the standard of 6'.
Signage & Way Finding	0.720	0.900	Good	The "Subject to search" sign is not visible.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lakeside HS

Grade Configuration: 9-12

Score: 83.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Ease of Supervision	1.755	2.700	Fair	There are an inadequate number of cameras on the exterior of the building so that there are multiple blind spots.
Controlled Entrances	0.450	0.450	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	Classrooms do not have the standard seven quad wall outlets and one ceiling outlet.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	There is limited storage space for laptop and iPad carts and insufficient power sources in these areas to charge the devices.
Telephone/PA	0.500	1.000	Fair	The PA system can not be heard outside.
Total	83.17 / 100.00 =		83.17	