

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Laurel Ridge ES

Grade Configuration:

PK-5

Score: 66.21

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.432	0.432	Excel	
Size	1.080	1.080	Excel	
Location	0.259	0.324	Good	
Storage/Fixed Equip	0.259	0.324	Good	There is no direct access to an outside patio from the art room.
<i>Computer Labs</i>				
Environment	0.252	0.315	Good	
Size	0.630	0.787	Good	The computer lab is approximately 85% of the size standard.
Location	0.118	0.236	Poor	The computer room has an outside wall with windows and no security covers.
Storage/Fixed Equip	0.154	0.236	Fair	There is little storage space in the room, and there is no motion sensor. A hall camera has view of room entry.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment	2.940	4.523	Fair	There are some HVAC issues in classrooms, and there is noise transfer between classrooms and outside.
Size	9.046	11.308	Good	
Location	2.714	3.392	Good	
Storage/Fixed Equip	2.205	3.392	Fair	Not all 1st grade rooms have access to bathrooms or sinks and bubblers in their room.
<i>Instructional Resource Rooms</i>				
Environment	0.532	0.665	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Laurel Ridge ES

Grade Configuration:

PK-5

Score: 66.21

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Size	1.329	1.662	Good	
Location	0.249	0.498	Poor	ESOL class is held in basement.
Storage/Fixed Equip	0.324	0.498	Fair	Most instructional resource rooms lack ample storage and casework.
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.250	0.385	Fair	There are HVAC issues in several rooms, and there is noise transfer between kindergarten rooms and adjacent hallways.
Size	0.770	0.962	Good	The kindergarten classrooms are approximately 85% of the size standard
Location	0.231	0.289	Good	
Storage/Fixed Equip	0.188	0.289	Fair	Not all kindergarten rooms have access to in-room bathrooms or sinks and bubblers.
<i>Learning Environment</i>				
Learning Style Variety	2.308	4.615	Poor	The school is old and shows its age. Windows allow noise transfer. There are no flexible spaces.
Interior Environment	1.200	1.846	Fair	Interior hallways are dim and reflect the age and design style of the of a building built in the 1950's and 60's.
Exterior Environment	1.108	1.385	Good	There is a large interior courtyard with a pond and fountain, as well as the newly refurbished playground/picnic area, and walking track.
Environment	0.585	0.900	Fair	Lighting is dim, and there are drop poles for power to computers in center of the main area.
<i>Media Center</i>				
Size	0.000	2.249	Unsat	The school's media center is less than 40% of the size standard. There are only three storage/workroom/office spaces in the media center.
Location	0.337	0.675	Poor	The media center is at the far back corner of the school.
Storage/Fixed Equip	0.337	0.675	Poor	There is inadequate storage and work space available in the media center.
<i>Music</i>				
Environment	0.000	0.684	Unsat	There are no acoustical treatments, and no fixed equipment in either room that support music instruction.
Size	0.855	1.709	Poor	The music room is about 75% of the size standard, but the band room size is unsatisfactory.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Laurel Ridge ES

Grade Configuration:

PK-5

Score: 66.21

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Location	0.256	0.513	Poor	The music room is near several classrooms, and resource rooms. The band room is on the stage.
Storage/Fixed Equip	0.000	0.513	Unsat	There are no fixed equipment in either room that support music instruction.
<i>Performing Arts</i>				
Environment	0.363	0.558	Fair	There are no acoustical treatments, and the stage is not ADA accessible.
Size	0.906	1.395	Fair	There is no dressing room or restrooms in the cafetorium or behind the stage.
Location	0.272	0.418	Fair	The cafetorium cannot be completely isolated from other parts of the school.
Storage/Fixed Equip	0.272	0.418	Fair	The stage is not ADA accessible.
<i>Physical Education</i>				
Environment	1.152	1.772	Fair	The gym does not have HVAC, and no sound reduction features. Exhaust fans create excessive noise.
Size	4.431	4.431	Excel	
Location	1.063	1.329	Good	The gym is a detached building from the main school facility.
Storage/Fixed Equip	0.864	1.329	Fair	Equipment is stored in general gym area due to lack of appropriate storage. No storage in field area.
<i>Science</i>				
Environment	0.000	0.462	Unsat	There is no science room.
Size	0.000	1.154	Unsat	There is no science room.
Location	0.000	0.346	Unsat	There is no science room.
Storage/Fixed Equip	0.000	0.346	Unsat	There is no science room.
<i>Self-Contained Special Education</i>				
Environment	0.288	0.443	Fair	There is an accordion style room divider between the two special education self-contained rooms, allowing for noise transfer.
Size	0.554	1.108	Poor	Rooms are approximately 90% of the required space, but there is no family living center. Access to an ADA bathroom with a changing table is down the hall and shared with other students. No hot water is available.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Laurel Ridge ES

Grade Configuration:

PK-5

Score: 66.21

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Location	0.216	0.332	Fair	The rooms are at the end of a hallway on the ground floor, but near the basement stairwell (safety issue).
Storage/Fixed Equip	0.216	0.332	Fair	There is inadequate storage space for the equipment required for student mobility needs.
<i>Non-Instructional Spaces</i>				
Administration	1.181	2.361	Poor	There is very little space for administrative staff, a small reception area, no conference room, and very limited storage.
Cafeteria	3.000	4.615	Fair	There is no storage space for tables and chairs, only one service line, and no access to water in the cafeteria.
Food Service and Prep	3.722	5.727	Fair	There is no HVAC in the kitchen, and no staff lockers.
Clinic	0.270	0.540	Poor	The clinic has one cot, an office, and access to restrooms and a sink. Hot water is not available.
Counseling	0.135	0.270	Poor	The counseling office is small, has no waiting area or confidential conference/meeting space.
Custodial and Maintenance	0.300	0.462	Fair	Some custodial closets are unlocked.
Student Restrooms	0.409	0.819	Poor	Some restrooms do not have partitions between urinals. Ventilation is an issue. There is an ADA bathroom stall with changing table, supplies and storage.
Faculty Work Space and Toilets	0.936	1.170	Good	The teacher workroom includes their mailboxes.
<i>Outside Spaces</i>				
Vehicular Traffic	0.000	1.846	Unsat	There is no room for parent pickup as buses use the single lane in front of school, thus traffic backs up into every street surrounding the front of the school at dismissal time.
Pedestrian Traffic	0.449	0.898	Poor	Pedestrians need to cross streets, the front parking lot, and bus/parent traffic patterns to enter of leave school during arrival and pick up times.
Parking	0.375	0.750	Poor	There is very limited parking in front of school, and overall not enough spaces to accommodate faculty and staff.
Play Areas	2.161	2.161	Excel	The new playground area and equipment has been recently upgraded and is ADA accessible.
<i>Safety and Security</i>				
Fencing	0.347	0.694	Poor	Areas behind the school need additional fencing to reduce public access to school grounds.
Signage & Way Finding	0.600	0.923	Fair	Only Drug-Free zone sign is visible along exterior.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Laurel Ridge ES

Grade Configuration: PK-5

Score: 66.21

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Ease of Supervision	1.385	2.769	Poor	Sight lines are good in hallways, but the basement and stairwell are hard to monitor. The large wooded picnic area and walking track are hard to monitor. There is an exterior half wall running along the front of the school that obstructs view from inside or out.
Controlled Entrances	0.231	0.462	Poor	The main entry uses card and camera access, but there is no visual point of view from the main office directly to the entry door.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	It is slow at times.
Faculty & Staff Technology	1.000	1.000	Good	All have access to desktops and interactive boards.
Laptop Carts	1.000	1.000	Good	
Telephone/PA	0.500	1.000	Fair	PA is not heard outside. Sound/clarity is inconsistent throughout the building. PA doesn't work in basement or kitchen.
Total	66.21	100.00	=	66.21