

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Margaret Harris Comprehensive School

Grade Configuration: K-12

Score: 58.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.528	0.660	Good	
Size	0.000	1.650	Unsat	The art room is approximately 42% of the size standard for a high school art room.
Location	0.396	0.495	Good	
Storage/Fixed Equip	0.322	0.495	Fair	There is no kiln.
<i>Career, Technical and Agricultural Education</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Computer Labs</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	The school was originally designed with early childhood education/prekindergarten facilities. These are currently being used as general education classrooms. The school does not have any early education programming.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment			N/A	
Size			N/A	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Margaret Harris Comprehensive School

Grade Configuration: K-12

Score: 58.51

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Instructional Resource Rooms</i>				
Environment	0.707	0.884	Good	
Size	2.210	2.210	Excel	
Location	0.530	0.663	Good	
Storage/Fixed Equip	0.530	0.663	Good	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Learning Environment</i>				
Learning Style Variety	4.991	6.239	Good	
Interior Environment	1.996	2.495	Good	
Exterior Environment	0.936	1.872	Poor	There is an area set aside as a social gathering point for students. However, it has not been maintained and the outdoor seating is weathered and worn. There is a dated greenhouse that is in disrepair.
Environment	0.450	0.901	Poor	The media center has little natural light and the artificial lighting is poor. The doorway is set at such an angle to the hallway that it makes it inaccessible to many of the students served by the school.
<i>Media Center</i>				
Size	0.000	2.252	Unsat	The media center has none of the auxiliary spaces indicated in the standard: office, conference room, work space, video/studio room, storage room. It meets approximately 12% of the elementary size standard for a media center.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Margaret Harris Comprehensive School

Grade Configuration: K-12

Score: 58.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Media Center</i>				
Location	0.541	0.676	Good	
Storage/Fixed Equip	0.338	0.676	Poor	The media center has no storage space. The fixed furnishings are aged.
<i>Music</i>				
Environment	0.000	0.849	Unsat	There is no space designated as a music classroom.
Size	0.000	2.124	Unsat	There is no space designated as a music classroom.
Location	0.000	0.637	Unsat	There is no space designated as a music classroom.
Storage/Fixed Equip	0.000	0.637	Unsat	There is no space designated as a music classroom.
<i>Performing Arts</i>				
Environment	0.000	1.128	Unsat	Margaret Harris Comprehensive School does not offer a performing arts program. Therefore, there are classrooms purposed for this.
Size	0.000	2.821	Unsat	Margaret Harris Comprehensive School does not offer a performing arts program. Therefore, there are classrooms purposed for this.
Location	0.000	0.846	Unsat	Margaret Harris Comprehensive School does not offer a performing arts program. Therefore, there are classrooms purposed for this.
Storage/Fixed Equip	0.000	0.846	Unsat	Margaret Harris Comprehensive School does not offer a performing arts program. Therefore, there are classrooms purposed for this.
<i>Physical Education</i>				
Environment	2.995	2.995	Excel	
Size	3.743	7.486	Poor	The gymnasium area is undersized for a high school.
Location	1.797	2.246	Good	
Storage/Fixed Equip	1.123	2.246	Poor	There is no padding behind one of the backboards, no water fountain, and no motorized seating.
<i>Science</i>				
Environment	0.000	0.722	Unsat	There is no space designed or designated as a Science classroom.
Size	0.000	1.805	Unsat	There is no space designed or designated as a Science classroom.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Margaret Harris Comprehensive School

Grade Configuration: K-12

Score: 58.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Science</i>				
Location	0.000	0.542	Unsat	There is no space designed or designated as a Science classroom.
Storage/Fixed Equip	0.000	0.542	Unsat	There is no space designed or designated as a Science classroom.
<i>Self-Contained Special Education</i>				
Environment	0.471	0.589	Good	The HVAC system works inconsistently.
Size	0.958	1.473	Fair	There is not a changing area in all the self-contained classrooms.
Location	0.354	0.442	Good	
Storage/Fixed Equip	0.221	0.442	Poor	There is very little area for storage of materials and supplies because of the large adaptive equipment needs of the students.
<i>Non-Instructional Spaces</i>				
Administration	1.731	2.164	Good	
Cafeteria	4.055	6.239	Fair	The cafeteria is well aged. There is no table storage area. They must be stored in the back of the room or along the walls when used for other events such as parent programs or music instruction.
Food Service and Prep	6.620	8.275	Good	
Clinic	0.255	0.319	Good	
Counseling	0.000	0.389	Unsat	Margaret Harris Comprehensive School does not offer a school counseling program and has no space designated for a counselor.
Custodial and Maintenance	0.406	0.624	Fair	There is no designated receiving area for supplies and limited storage and shelving for them.
Student Restrooms	0.719	1.106	Fair	The student restrooms have little ventilation. There are no privacy partitions between the urinals.
Faculty Work Space and Toilets	0.425	0.849	Poor	The staff lounge-workroom has no restroom in it or in close proximity. There is no work space and no counters or sink.
<i>Outside Spaces</i>				
Vehicular Traffic	2.995	3.743	Good	
Pedestrian Traffic	0.273	0.419	Fair	The front door is not ADA accessible.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Margaret Harris Comprehensive School

Grade Configuration: K-12

Score: 58.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Outside Spaces</i>				
Parking	1.592	3.184	Poor	There is limited parking. Teachers and visitors must park along the street.
Athletic Fields and Facilities	1.659	3.317	Poor	There are no athletic courts or fields at this school. There is a grass area at the bottom of a set of wood steps that are covered with pine needles. There are no restrooms or drinking fountain, and there is no lighting for the area. There is a play area for the elementary age students. However, the playground equipment is not ADA accessible and is only suitable in size for prekindergarten age students.
<i>Safety and Security</i>				
Fencing	0.890	1.780	Poor	There is no fencing around the perimeter of the building. There is a stonewall that is in need of repair.
Signage & Way Finding	0.178	0.222	Good	
Ease of Supervision	1.248	2.495	Poor	There are no security cameras around the building.
Controlled Entrances	0.499	0.624	Good	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.330	1.000	Poor	Wireless connectivity is unreliable in most parts of the building.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	The available storage and charging areas are inadequate for the laptop and iPad carts.
Telephone/PA	1.000	1.000	Good	
Total	58.51	100.00	=	58.51