

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Miller Grove HS

Grade Configuration: 9-12

Score: 87.74

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.389	0.599	Fair	One art room was designed for an art program and the other was designed as a Health Care Lab.
Size	1.496	1.496	Excel	The classroom designed for art meets approximately 85% of the size standard. The second art classroom.....
Location	0.224	0.449	Poor	One of the two art classrooms has access to an outdoor patio and the second art room is located on the second floor. Both rooms have an exterior wall with windows providing natural light.
Storage/Fixed Equip	0.224	0.449	Poor	In the art room originally designed as a Health Care Lab, office space is utilized to display student artwork. This room does not have a kiln, adequate storage or sinks with clay traps. The art room on the first floor with patio access is a Visual Arts program containing a kiln with ventilation. The room lacks a display case.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.230	1.538	Good	
Size	2.499	3.845	Fair	Career Tech includes the following student programs: ROTC, family consumer science, business education, marketing, culinary arts, and broadcasting. Most of the programs meet more than 90% of the requirements for size; however, marketing meets approximately 48% of the criteria since it does not provide adequate instructional, store, and storage space. An ROTC firing range is currently being used as a classroom.
Location	0.923	1.154	Good	
Storage/Fixed Equip	0.923	1.154	Good	
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	
Size	0.675	0.675	Excel	
Location	0.202	0.202	Excel	
Storage/Fixed Equip	0.162	0.202	Good	The computer labs have storage closets, teacher cabinets, and bookcases. Equipment is secured by cameras in the hallway, not within the classroom. The labs do not include motion-sensor lighting.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Miller Grove HS

Grade Configuration: 9-12

Score: 87.74

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	
Size	8.775	8.775	Excel	
Location	2.632	2.632	Excel	
Storage/Fixed Equip	2.106	2.632	Good	The majority of the classrooms contained lockable teacher's/wardrobe cabinets, bookcases, and appropriate technology.
<i>Instructional Resource Rooms</i>				
Environment	0.719	0.719	Excel	
Size	1.797	1.797	Excel	
Location	0.539	0.539	Excel	
Storage/Fixed Equip	0.539	0.539	Excel	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	
Exterior Environment	1.080	1.350	Good	There are several outdoor areas which can be used for instruction.
Environment	0.759	0.759	Excel	
<i>Media Center</i>				
Size	1.233	1.897	Fair	The media center is aesthetically pleasing with a bank of exterior windows donning the front wall; however, the space meets approximately 70% of the size standard.
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.455	0.569	Good	
<i>Music</i>				
Environment	0.428	0.534	Good	
Size	1.336	1.336	Excel	
Location	0.401	0.401	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Miller Grove HS

Grade Configuration: 9-12

Score: 87.74

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Storage/Fixed Equip	0.321	0.401	Good	Practice rooms are not easily supervised.
<i>Performing Arts</i>				
Environment	0.289	0.289	Excel	ADA accessible stage with access from the front and backstage areas.
Size	0.721	0.721	Excel	
Location	0.216	0.216	Excel	
Storage/Fixed Equip	0.216	0.216	Excel	
<i>Physical Education</i>				
Environment	1.728	2.160	Good	The wrestling room has well worn wrestling mats. The girls locker room is in disrepair with toilet stalls missing doors.
Size	5.400	5.400	Excel	
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.053	1.620	Fair	
<i>Science</i>				
Environment	0.747	0.747	Excel	Wing 900 is devoted to the science program and classrooms do not have direct access to outdoor patio areas. The wing is located on the second floor of the building.
Size	1.867	1.867	Excel	
Location	0.364	0.560	Fair	
Storage/Fixed Equip	0.560	0.560	Excel	
<i>Self-Contained Special Education</i>				
Environment	0.383	0.479	Good	The HVAC temperature varied by classroom.
Size	0.599	1.198	Poor	The self-contained classrooms met approximately 57% of the size requirements since the site lacks a family living center. Two classrooms have an ADA restroom located between the rooms containing a changing area and shower.
Location	0.288	0.359	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Miller Grove HS

Grade Configuration: 9-12

Score: 87.74

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Storage/Fixed Equip	0.180	0.359	Poor	Storage is adequate for the self-contained classrooms; however, Miller Grove High Schools does not have an identified family living center.
<i>Non-Instructional Spaces</i>				
Administration	2.349	2.349	Excel	
Cafeteria	3.600	3.600	Excel	
Food Service and Prep	4.595	4.595	Excel	
Clinic	0.000	0.214	Unsat	Miller Grove High Schools does not have a clinic.
Counseling	0.681	0.681	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.821	0.821	Excel	
Faculty Work Space and Toilets	0.641	0.641	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	0.720	0.900	Good	As visitors arrive, signage is available next to the parking lot.
Pedestrian Traffic	0.882	0.882	Excel	
Parking	1.518	1.897	Good	
Athletic Fields and Facilities	1.991	2.488	Good	Athletic fields are abundant; however, lighting is unavailable.
<i>Safety and Security</i>				
Fencing	0.610	0.762	Good	
Signage & Way Finding	0.585	0.900	Fair	Directional signs are available, but not well located.
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.450	0.450	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Miller Grove HS

Grade Configuration: 9-12

Score: 87.74

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Electrical Power	0.500	1.000	Fair	The school does not possess the required quad and ceiling mounted outlets.
Equity of Access, Wireless & Drops	0.670	1.000	Fair	The network access is not fully operational.
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	The system is slow.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	87.74	100.00	=	87.74