

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Montgomery ES

Grade Configuration:

PK-5

Score: 74.42

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.345	0.431	Good	
Size	0.701	1.079	Fair	The art classroom meets 69% of the adequate space standard.
Location	0.259	0.324	Good	There is no access to an outdoor learning space from the art room.
Storage/Fixed Equip	0.210	0.324	Fair	There is a kiln in a storage area that is reported as not working. There is no venting system to support the kiln. There is one sink without a clay trap. Storage and display spaces are inadequate for teacher/student work.
<i>Computer Labs</i>				
Environment	0.252	0.315	Good	
Size	0.393	0.786	Poor	The computer lab meets 60% of standard.
Location	0.189	0.236	Good	
Storage/Fixed Equip	0.189	0.236	Good	
<i>Early Childhood Education</i>				
Environment	0.369	0.461	Good	
Size	0.922	1.152	Good	
Location	0.277	0.346	Good	
Storage/Fixed Equip	0.277	0.346	Good	
<i>General Classrooms</i>				
Environment	3.615	4.518	Good	The HVAC is not effective in climate control.
Size	11.296	11.296	Excel	The general education rooms meet 95% of the adequate space standard.
Location	2.711	3.389	Good	
Storage/Fixed Equip	2.203	3.389	Fair	The fourth and fifth grade do not have a sink or bubbler. There are no cubbies or student storage spots.
<i>Instructional Resource Rooms</i>				
Environment	0.531	0.664	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Montgomery ES

Grade Configuration: PK-5

Score: 74.42

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Size	0.830	1.660	Poor	The space for Instructional Resource meets 55% of the adequate space standard.
Location	0.398	0.498	Good	
Storage/Fixed Equip	0.324	0.498	Fair	The casework and lockable storage is inadequate for this space.
<i>Kindergarten &amp; Pre-Kindergarten</i>				
Environment	0.308	0.385	Good	
Size	0.769	0.961	Good	The kindergarten classrooms meet 82% of the adequate space standard.
Location	0.231	0.288	Good	
Storage/Fixed Equip	0.231	0.288	Good	Two of the eight kindergarten classes do not have their own restroom. Storage for learning materials and manipulatives is not adequate.
<i>Learning Environment</i>				
Learning Style Variety	3.689	4.611	Good	
Interior Environment	1.475	1.844	Good	The HVAC is inconsistent in effective climate control. There are numerous ceiling leaks and damaged tiles throughout the building.
Exterior Environment	1.383	1.383	Excel	There are many good outdoor learning spaces
Environment	0.584	0.899	Fair	The HVAC is ineffective in climate control. The lighting is dim. Some ceiling tiles show water damage.
<i>Media Center</i>				
Size	0.000	2.247	Unsat	The media center meets 36% of the adequate space standard.
Location	0.539	0.674	Good	
Storage/Fixed Equip	0.539	0.674	Good	
<i>Music</i>				
Environment	0.000	0.683	Unsat	Music is taught in a portable.
Size	0.000	1.708	Unsat	Music is taught in a portable.
Location	0.000	0.512	Unsat	Music is taught in a portable.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Montgomery ES

Grade Configuration:

PK-5

Score: 74.42

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Storage/Fixed Equip	0.000	0.512	Unsat	Music is taught in a portable.
<i>Performing Arts</i>				
Environment	0.446	0.557	Good	There is no ADA access to the stage.
Size	1.115	1.393	Good	
Location	0.334	0.418	Good	Restrooms are located some distance from the stage.
Storage/Fixed Equip	0.334	0.418	Good	
<i>Physical Education</i>				
Environment	1.416	1.771	Good	
Size	3.541	4.426	Good	
Location	1.062	1.328	Good	
Storage/Fixed Equip	1.062	1.328	Good	
<i>Science</i>				
Environment	0.000	0.461	Unsat	
Size	0.000	1.153	Unsat	There are no additional science spaces beyond STEM rooms.
Location	0.000	0.346	Unsat	
Storage/Fixed Equip	0.000	0.346	Unsat	
<i>Self-Contained Special Education</i>				
Environment	0.354	0.443	Good	
Size	0.719	1.107	Fair	The space meets 70% of the adequate space.
Location	0.266	0.332	Good	
Storage/Fixed Equip	0.000	0.332	Unsat	The casework and lockable storage for this space is inadequate. There is no sink with hot water or ADA adaptive restroom.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Montgomery ES

Grade Configuration: PK-5

Score: 74.42

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Administration	1.887	2.359	Good	
Cafeteria	3.689	4.611	Good	The HVAC is ineffective in climate control.
Food Service and Prep	4.577	5.721	Good	
Clinic	0.431	0.539	Good	
Counseling	0.216	0.270	Good	
Custodial and Maintenance	0.369	0.461	Good	
Student Restrooms	0.532	0.818	Fair	The ventilation is poor in the restrooms. There are no urinal partitions.
Faculty Work Space and Toilets	0.935	1.168	Good	Staff mail boxes are located in the main office.
<i>Outside Spaces</i>				
Vehicular Traffic	1.199	1.844	Fair	The traffic pattern is a shared space with buses, day care vans and cars. There is no covered loading for buses or day care.
Pedestrian Traffic	0.583	0.897	Fair	An ADA ramp at an exit at the south and west front of the school 90% blocked by a bench that is cemented into the ground.
Parking	0.487	0.749	Fair	The parking is inadequate for staff and the large number of parent volunteers. The parking extends down to a place where there are three portables. This is a dead end with no flow out to the street. A four or five point turn is needed to exit this parking area. It is far from the school entrance.
Play Areas	1.403	2.159	Fair	There is no hard surface for play. There is not a grassy area. There are no adaptive swings.
<i>Safety and Security</i>				
Fencing	0.347	0.694	Poor	The school does not have appropriate fencing.
Signage & Way Finding	0.738	0.922	Good	
Ease of Supervision	2.213	2.766	Good	
Controlled Entrances	0.300	0.461	Fair	There is no vestibule at this site.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Montgomery ES

Grade Configuration: PK-5

Score: 74.42

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Bandwidth is insufficient to support laptops.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	Charging capacity is inadequate for laptop carts.
Telephone/PA	1.000	1.000	Good	
<b>Total</b>	<b>75.76</b>	<b>102.21</b>	<b>=</b>	<b>74.12</b>