

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Narvie J. Harris Theme ES

Grade Configuration: PK-5

Score: 76.62

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.274	0.421	Fair	The art classroom has some natural lighting in the classroom, but does not have outdoor access to enhance the learning environment.
Size	0.842	1.053	Good	
Location	0.205	0.316	Fair	The art room is located off the main corridor. It lacks outside access.
Storage/Fixed Equip	0.205	0.316	Fair	The art room has two sinks without clay traps. A small storage closet does not meet guidelines and there is no kiln or display space.
<i>Computer Labs</i>				
Environment	0.246	0.307	Good	The temperature within the computer labs is warm.
Size	0.614	0.768	Good	
Location	0.184	0.230	Good	
Storage/Fixed Equip	0.150	0.230	Fair	There are motion sensor lights, but no security cameras.
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	1.125	1.125	Excel	Both rooms have their own restrooms.
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>General Classrooms</i>				
Environment	3.528	4.410	Good	
Size	8.820	11.025	Good	
Location	2.646	3.307	Good	
Storage/Fixed Equip	2.646	3.307	Good	
<i>Instructional Resource Rooms</i>				
Environment	0.518	0.648	Good	There are seven instructional resource rooms housed in general classrooms.
Size	1.620	1.620	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Narvie J. Harris Theme ES

Grade Configuration: PK-5

Score: 76.62

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.389	0.486	Good	
Storage/Fixed Equip	0.389	0.486	Good	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	
Size	0.938	0.938	Excel	Each kindergarten class has its own restroom.
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.225	0.282	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	
Exterior Environment	0.877	1.350	Fair	The school does not have an art patio.
Environment	0.702	0.877	Good	
<i>Media Center</i>				
Size	1.425	2.193	Fair	The size of the media center meets approximately 78% of the criteria.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	
<i>Music</i>				
Environment	0.433	0.667	Fair	The general music environment is very crowded with materials and costumes. There is a small storage closet within the storage suite.
Size	0.833	1.667	Poor	The school has a general music room that meets the size standard; however, the school lacks a band/orchestra space. A second designed music space is used as general music storage.
Location	0.325	0.500	Fair	General music is housed off the main corridor. There isn't a band/orchestra space.
Storage/Fixed Equip	0.325	0.500	Fair	There is allocated storage space to meet guidelines. Fixed equipment does not include a drinking fountain, sink, or adequate technology equipment in the room.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Narvie J. Harris Theme ES

Grade Configuration: PK-5

Score: 76.62

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.354	0.544	Fair	The multipurpose cafeteria is used as a performing arts area. Air conditioning temperatures are warm. There is a single ramp to the rear of the stage for ADA accessibility.
Size	0.884	1.360	Fair	The performing arts multipurpose area does not have dressing rooms.
Location	0.265	0.408	Fair	The performing arts area is located off the main corridor. Public restrooms are not located in close proximity.
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.382	1.728	Good	
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	
<i>Science</i>				
Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	
Location	0.219	0.337	Fair	The science room is located off the main hallway with an exterior door.
Storage/Fixed Equip	0.270	0.337	Good	The science room has adequate storage for science materials and hazardous materials. The demonstration station has water, but not gas.
<i>Self-Contained Special Education</i>				
Environment	0.000	0.432	Unsat	The site does not have a self-contained special education space.
Size	0.000	1.080	Unsat	The site does not have a self-contained special education space.
Location	0.000	0.324	Unsat	The site does not have a self-contained special education space.
Storage/Fixed Equip	0.000	0.324	Unsat	The site does not have a self-contained special education space.
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Narvie J. Harris Theme ES

Grade Configuration: PK-5

Score: 76.62

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Cafeteria	2.925	4.500	Fair	The cafeteria does not have a restroom nearby with hot water. There isn't a storage area large enough to house all of the tables with fixed seating.
Food Service and Prep	4.467	5.584	Good	
Clinic	0.421	0.526	Good	The clinic is located within the administrative suite. It has two cots, lockable medicine storage, a sink with hot water, and an ADA restroom.
Counseling	0.171	0.263	Fair	The counseling suite does not have a conference room.
Custodial and Maintenance	0.292	0.450	Fair	There is no receiving area.
Student Restrooms	0.399	0.798	Poor	There is no hot water in the restrooms located close to the cafeteria. There is no ADA unisex restroom for students.
Faculty Work Space and Toilets	0.912	1.140	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.440	1.800	Good	
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.585	0.731	Good	
Play Areas	1.685	2.107	Good	A ramp leads down to the play area and playground equipment is accessible to the physically challenged.
<i>Safety and Security</i>				
Fencing	0.542	0.677	Good	
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	Card Access points are in the front and back of the building only.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	The school lacks sufficient electrical outlets including seven quad outlets in each classroom and a duplex in the ceiling and on the front wall.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Narvie J. Harris Theme ES

Grade Configuration: PK-5

Score: 76.62

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	Additional electrical outlets are needed to charge all laptop carts within the designated area of the media center.
Telephone/PA	0.500	1.000	Fair	The PA system works well within the interior of the school and has limited coverage externally.
Total	76.62	100.00	=	76.62