

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Oak Grove ES

Grade Configuration:

PK-5

Score: 68.29

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.347	0.434	Good	
Size	0.868	1.085	Good	
Location	0.260	0.325	Good	
Storage/Fixed Equip	0.260	0.325	Good	
<i>Computer Labs</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Early Childhood Education</i>				
Environment	0.301	0.464	Fair	The prekindergarten class is in need of refurbishment to accommodate spatial configurations and enhance aesthetics. Natural light is available and the air conditioning temperature is inconsistent throughout the facility.
Size	0.927	1.159	Good	
Location	0.278	0.348	Good	
Storage/Fixed Equip	0.226	0.348	Fair	Although the prekindergarten class has a sink, it does not have a bubbler.
<i>General Classrooms</i>				
Environment	2.954	4.545	Fair	The air temperature throughout the building is inconsistent. The classrooms are not designed for small group and spatially configured activities. Aesthetics are fair. HVAC is an issue.
Size	9.090	11.363	Good	
Location	2.727	3.409	Good	
Storage/Fixed Equip	2.216	3.409	Fair	All classrooms in grades 1-5 lack sinks and bubblers.
<i>Instructional Resource Rooms</i>				
Environment	0.534	0.668	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Oak Grove ES

Grade Configuration:

PK-5

Score: 68.29

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Size	1.336	1.670	Good	
Location	0.401	0.501	Good	Rooms are strategically placed throughout the school to meet student needs
Storage/Fixed Equip	0.401	0.501	Good	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.251	0.387	Fair	There are inconsistent HVAC temperatures in the kindergarten classes. The classrooms are not designed for spatially configured activities.
Size	0.774	0.967	Good	
Location	0.232	0.290	Good	
Storage/Fixed Equip	0.189	0.290	Fair	All kindergarten classes have sinks, but they lack bubblers.
<i>Learning Environment</i>				
Learning Style Variety	3.710	4.638	Good	
Interior Environment	1.206	1.855	Fair	HVAC is an issue.
Exterior Environment	1.113	1.391	Good	
Environment	0.723	0.904	Good	
<i>Media Center</i>				
Size	1.130	2.260	Poor	The media center meets approximately 54% of the standard criteria.
Location	0.542	0.678	Good	
Storage/Fixed Equip	0.441	0.678	Fair	Fixed equipment needs to be upgraded to provide routine use of security cameras and electrical outlets.
<i>Music</i>				
Environment	0.000	0.687	Unsat	The elementary music, band, and string programs are housed in portables.
Size	0.000	1.718	Unsat	The elementary music, band, and string programs are housed in portables.
Location	0.000	0.515	Unsat	The elementary music, band, and string programs are housed in portables.
Storage/Fixed Equip	0.000	0.515	Unsat	The elementary music, band, and string programs are housed in portables.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Oak Grove ES

Grade Configuration:

PK-5

Score: 68.29

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.364	0.561	Fair	The stage is not ADA accessible from the side. Individuals could access the stage off the main corridor. HVAC is an issue.
Size	1.121	1.401	Good	
Location	0.336	0.420	Good	
Storage/Fixed Equip	0.273	0.420	Fair	There is limited storage on the stage and in the general vicinity to accommodate a performing arts program in the multi-purpose cafeteria.
<i>Physical Education</i>				
Environment	1.425	1.781	Good	The lighting is good, HVAC temperatures are inconsistent, and there is some natural lighting. There is no A/C.
Size	4.453	4.453	Excel	
Location	0.868	1.336	Fair	The gym can be separated from the rest of the school facility, but there are no public restrooms available.
Storage/Fixed Equip	1.069	1.336	Good	
<i>Science</i>				
Environment	0.000	0.464	Unsat	There is no science room.
Size	0.000	1.159	Unsat	There is no science room.
Location	0.000	0.348	Unsat	No science room, but there is a closet of materials available to supplement classroom instruction.
Storage/Fixed Equip	0.000	0.348	Unsat	There is no science room at Oak Gove Elementary School.
<i>Self-Contained Special Education</i>				
Environment	0.289	0.445	Fair	The two self-contained classrooms were very warm in temperature and they do not have dimmable lights.
Size	0.557	1.113	Poor	The intermediate class meets approximately 59% of the size criteria. Both rooms lack hot water and changing areas. The school does not have a family living center.
Location	0.217	0.334	Fair	There is a small office in a closet off the self-contained classrooms where the bookkeeper and technology staff must travel through the classroom to access the room/IDF hub.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Oak Grove ES

Grade Configuration:

PK-5

Score: 68.29

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Storage/Fixed Equip	0.217	0.334	Fair	One of the self-contained special education classrooms has very little storage space to house equipment and supplies. Limited permanent casework is available in both rooms. The site does not have a family living center.
<i>Non-Instructional Spaces</i>				
Administration	1.186	2.373	Poor	The area has natural light, inconsistent HVAC temperatures, a testing room and card access at entry. The principal's office has a very small area to meet with staff and no conference room.
Cafeteria	3.015	4.638	Fair	Insufficient space to house tables/chairs, restroom does not have hot water. HVAC is an issue.
Food Service and Prep	3.741	5.755	Fair	The food service area lacks changing room/lockers. There is no A/C, so it makes for very warm working conditions.
Clinic	0.353	0.542	Fair	There is a single cot in the clinic and they lack an ADA accessible restroom.
Counseling	0.136	0.271	Poor	Counselors have an office, but lack a conference room and reception area. Student records are housed in the vault which is fireproof, but the filing cabinets are not fireproof.
Custodial and Maintenance	0.232	0.464	Poor	The custodial closets have sinks, but lack floor sinks. There is no identified receiving area.
Student Restrooms	0.411	0.823	Poor	The boys restroom lacks privacy partitions between urinals and there isn't an ADA unisex facility available. Ventilation is poor.
Faculty Work Space and Toilets			N/A	
<i>Outside Spaces</i>				
Vehicular Traffic	1.206	1.855	Fair	Buses and parent vehicles utilize the same drop off/pick up loop.
Pedestrian Traffic	0.587	0.903	Fair	Parents have a passageway from the neighborhood behind the school, but co-mingle with cars and buses at the front of the school.
Parking	0.377	0.753	Poor	There is inadequate parking for the number of staff employed at the site.
Play Areas	1.086	2.171	Poor	Hard surface cannot currently be used due to shrubbery hazard on the surface which is located at the bottom of a steep hill. The "grassy area" is a dust bowl with very little grass. The area floods easily.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Oak Grove ES

Grade Configuration:

PK-5

Score: 68.29

Category	Points Earned	Possible Points	Rating	Comment
<i>Safety and Security</i>				
Fencing	0.453	0.698	Fair	Adequate fencing, but it does not meet standard of 6' surrounding the school. Many room numbers are missing over the doors.
Signage & Way Finding	0.603	0.928	Fair	Signage regarding surveillance and search were not present. Directional signage regarding locations to park and traffic flow for vehicles and buses is limited.
Ease of Supervision	1.809	2.783	Fair	Quality/Quantity/Location of cameras poor.
Controlled Entrances	0.301	0.464	Fair	The schools lacks of vestibule at the main entrance.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	Electrical plugs in the media center are not grounded and this is a challenge when attempting to recharge laptop carts each evening. The school lacks seven quads in each classroom and a duplex in the ceiling and one on the front wall.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Wireless connections with iPads are not reliable.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	The Media Specialist is charging the carts in shifts as the outlets and security camera cannot be simultaneously operational . There are not a sufficient number of grounded outlets to charge the carts each evening.
Telephone/PA	0.500	1.000	Fair	The PA system is operational internally, but a megaphone is used for communication outside of the building.
Total	68.29	100.00	=	68.29