

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Robert Shaw Theme ES

Grade Configuration:

PK-5

Score: 70.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.274	0.421	Fair	The lighting both overhead and natural is poor. The HVAC is inconsistent throughout the building.
Size	0.684	1.053	Fair	The art room is 77% of the standard.
Location	0.253	0.316	Good	
Storage/Fixed Equip	0.205	0.316	Fair	There is inadequate space for storage for supplies and student projects. The space has one sink with no clay trap. The technology in the space is insufficient. There is no kiln or vent.
<i>Computer Labs</i>				
Environment	0.200	0.307	Fair	The HVAC is insufficient for the needs of this space. The lighting is dim.
Size	0.768	0.768	Excel	
Location	0.115	0.230	Poor	The space is not centrally located and exists at the end of a hallway next to an exit used for recess. The space is at the rear of the building with a potential break-in problem.
Storage/Fixed Equip	0.115	0.230	Poor	Storage is inadequate for books, teacher and student materials. The room has no motion sensor lighting or security cameras.
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	0.731	1.125	Fair	One of two rooms meets 76% of the standard.
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>General Classrooms</i>				
Environment	2.205	4.410	Poor	The HVAC is inconsistent throughout the building. The classrooms need to be refurbished with paint flooring and some ceiling tiles. Natural lighting is minimal while overhead lighting is good.
Size	8.820	11.025	Good	
Location	2.646	3.307	Good	
Storage/Fixed Equip	1.654	3.307	Poor	Classroom storage is inadequate for student materials and teacher storage. Cubbies and hooks for student materials is also in need of expansion and refurbishment.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Robert Shaw Theme ES

Grade Configuration:

PK-5

Score: 70.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.000	0.648	Unsat	The storage space is poorly vented and there is no natural light.
Size	0.000	1.620	Unsat	The instructional resource space is housed in an existing storage room.
Location	0.000	0.486	Unsat	The resource space is at the end of a hall, distant from the cluster of general education classes.
Storage/Fixed Equip	0.000	0.486	Unsat	There is not sufficient storage.
<i>Kindergarten &amp; Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	HVAC is inconsistent and natural light is low
Size	0.751	0.938	Good	The kindergarten space is 88% of the standard for adequacy.
Location	0.183	0.282	Fair	The kindergarten classrooms are located distant from the front entrance.
Storage/Fixed Equip	0.225	0.282	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.170	1.800	Fair	The HVAC throughout the building is inconsistent. The natural light is low and in some cases nonexistent. Rooms are in need of paint and refurbishment of floors and ceiling tiles.
Exterior Environment	0.675	1.350	Poor	While a social gathering space exists there are few spaces for outdoor learning labs and opportunities.
Environment	0.570	0.877	Fair	The HVAC is inconsistent in operation. There is no natural lighting in this space. The space needs to be refurbished with new flooring and paint.
<i>Media Center</i>				
Size	1.097	2.193	Poor	The media center meets 40% of the standard.
Location	0.658	0.658	Excel	
Storage/Fixed Equip	0.526	0.658	Good	
<i>Music</i>				
Environment	0.000	0.667	Unsat	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Robert Shaw Theme ES

Grade Configuration:

PK-5

Score: 70.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Size	0.000	1.667	Unsat	The music program is delivered schoolwide from a cart by the music teacher. There is no music room.
Location	0.000	0.500	Unsat	
Storage/Fixed Equip	0.000	0.500	Unsat	.
<i>Performing Arts</i>				
Environment	0.354	0.544	Fair	There is no ADA stage access.
Size	1.088	1.360	Good	
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.382	1.728	Good	
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	0.842	1.296	Fair	The gym flooring is pulling up from the concrete base creating tripping hazards.
<i>Science</i>				
Environment	0.225	0.450	Poor	The HVAC is inconsistent. The overhead lighting is poor as is the natural lighting.
Size	0.731	1.125	Fair	The science room meets 74% of the standard space for adequacy.
Location	0.270	0.337	Good	There is no outdoor access from the space.
Storage/Fixed Equip	0.169	0.337	Poor	The eye wash station is inoperable. Storage for equipment and supplies is inadequate.
<i>Self-Contained Special Education</i>				
Environment	0.432	0.432	Excel	
Size	1.080	1.080	Excel	
Location	0.324	0.324	Excel	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Robert Shaw Theme ES

Grade Configuration:

PK-5

Score: 70.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Storage/Fixed Equip	0.324	0.324	Excel	
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	The administration area lacks a conference space for meetings. Storage space is inadequate.
Cafeteria	3.600	4.500	Good	HVAC is inconsistent throughout the building.
Food Service and Prep	4.467	5.584	Good	The HVAC is poor in the kitchen.
Clinic	0.421	0.526	Good	The clinic has one cot. There is no restroom in the clinic.
Counseling	0.211	0.263	Good	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.399	0.798	Poor	Restrooms are in need of paint and flooring. The wall coverings need to be replaced. There are no urinal partitions in the boys restrooms.
Faculty Work Space and Toilets	0.912	1.140	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.440	1.800	Good	
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.365	0.731	Poor	The current parking is inadequate and spills onto a portion of the playground.
Play Areas	1.053	2.107	Poor	There is no existing hard surface. The area is small.
<i>Safety and Security</i>				
Fencing	0.542	0.677	Good	
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	The space does not have adequate climate control.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Robert Shaw Theme ES

Grade Configuration: PK-5

Score: 70.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Internet connectivity is inconsistent.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
<b>Total</b>	<b>70.16</b>	<b>100.00</b>	<b>=</b>	<b>70.16</b>