

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.274	0.421	Fair	The HVAC system is inconsistent. The lighting is dark and uninviting. The art room is showing its age.
Size	1.053	1.053	Excel	
Location	0.205	0.316	Fair	The art room does not have direct access to the outside.
Storage/Fixed Equip	0.205	0.316	Fair	The art room does not have a kiln. The sinks do not have hot water. There is no display case. There is not storage for 3D projects. There is limited storage.
<i>Computer Labs</i>				
Environment	0.153	0.307	Poor	The computer lab is extremely hot. The lightning does not minimize screen glare and eye strain. The computers are in rows so the configuration does not allow for small group work. The lab is showing its age.
Size	0.614	0.768	Good	
Location	0.184	0.230	Good	
Storage/Fixed Equip	0.000	0.230	Unsat	The computer lab does not have any casework, storage cabinets or bookcases. There are an insufficient number of power outlets. There is no security camera inside the classroom or outside in the hallway. There is no motion-sensor lighting.
<i>Early Childhood Education</i>				
Environment	0.225	0.450	Poor	The HVAC system is inconsistent. The lighting in the school is dark and uninviting. Doors have holes in them. Casework is broken and the finish has worn off the cabinets. Baseboards are missing. Blinds are either missing, bent or broken. The classroom is showing its age and is extremely worn and tired. The physical environment of the classroom is unappealing and uninviting.
Size	0.900	1.125	Good	
Location	0.219	0.337	Fair	The ECE classroom is not located close to the office or the parent drop-off or bus loading area.
Storage/Fixed Equip	0.219	0.337	Fair	There is no designed space in the classroom for the students personal belongings. The material storage space is insufficient. There are no designed spaces for learning stations. Much of the casework is damaged with the finish worn off. The restroom is not an ADA restroom.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Environment	2.205	4.410	Poor	The HVAC system is inconsistent and doesn't work at all in some of the classrooms. Many of the classrooms are very hot while a few are cold. The lighting is dark and uninviting. Doors have holes in them. Casework is broken and the finish has worn off the cabinets. Baseboards are missing. The classrooms are showing their age and are extremely worn and tired. The physical environment of the classrooms is unappealing and uninviting.
Size	8.820	11.025	Good	Most of the classrooms are between approximately 94% and 100% of the standard. Two classrooms are in portables.
Location	2.646	3.307	Good	Two classrooms are in portables.
Storage/Fixed Equip	1.654	3.307	Poor	Two classrooms are in portables. There are no cubbies in any of the classrooms. There are no coat hook areas but a rod with hangars to hang the students' jackets. Only one classroom has a sink with a drinking fountain. Much of the casework is damaged with the finish worn off. Computer stations have power strips with wires all around the desk and floor. One first grade classroom has access to a restroom directly off the classroom.
<i>Instructional Resource Rooms</i>				
Environment	0.324	0.648	Poor	The HVAC system is inconsistent. The lighting in the school is dark and uninviting. Doors have holes in them. Casework is broken and the finish has worn off the cabinets. Baseboards are missing. The classrooms are showing their age and are extremely worn and tired. The physical environment of the classrooms is unappealing and uninviting. The speech teacher is in a storage closet that has no windows.
Size	0.810	1.620	Poor	There are no specifically designed spaces for the social worker, occupational therapist and physical therapist to work. The speech teacher is in a storage closet.
Location	0.243	0.486	Poor	The speech teacher is in a storage closet.
Storage/Fixed Equip	0.243	0.486	Poor	The resource rooms do not have adequate permanent casework or storage space.
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.188	0.375	Poor	The HVAC system is inconsistent. The lighting in the school is dark and uninviting. Doors have holes in them. Casework is broken and the finish has worn off the cabinets. Baseboards are missing. The classrooms are showing their age and are extremely worn and tired. The physical environment of the classrooms is unappealing and uninviting.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
<i>Kindergarten & Pre-Kindergarten</i>				
Size	0.938	0.938	Excel	
Location	0.183	0.282	Fair	The kindergarten and prekindergarten classrooms are not close to the parent drop off and bus loading.
Storage/Fixed Equip	0.141	0.282	Poor	One of six kindergarten classrooms has no access to a restroom directly off the classroom or a sink. There is no designed space in the classroom for the students personal belongings. The storage is insufficient for the materials needed in a kindergarten classroom. There are no designed spaces for learning stations. Much of the casework is damaged with the finish worn off. Computer stations have power strips with wires all around the desk and floor. In some of the kindergarten classrooms the casework with the sink and drinking fountain are not at an age appropriate height.
<i>Learning Environment</i>				
Learning Style Variety	0.000	4.500	Unsat	The building has no designed spaces that support differentiated learning and a variety of learning styles. There are no designed spaces to allow for various group sizes, projects, or individual workstations. There is no project-based learning or spaces for storage of "in progress" student projects.
Interior Environment	0.900	1.800	Poor	The HVAC system is inconsistent. The lighting is dark and uninviting. Doors have holes in them. Carpeting is frayed and tearing. Casework is broken and the finish has worn off the cabinets. Some of the hallways are dark and uninviting. Baseboards are missing. Blinds are either missing, bent or broken. The building is showing its age and is extremely worn. The environment is unappealing and uninviting.
Exterior Environment	1.080	1.350	Good	
Environment	0.570	0.877	Fair	The configuration of the media center does not support multiple uses for the library. The lighting is dated. The carpet is torn and frayed creating a safety hazard. The media center looks worn and tired.
<i>Media Center</i>				
Size	1.097	2.193	Poor	The media center is approximately 50% of the standard.
Location	0.329	0.658	Poor	The media center is not centrally located.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
<i>Media Center</i>				
Storage/Fixed Equip	0.329	0.658	Poor	The casework is not on casters. There are no upholstered student chairs. There are not 32 computer stations. There is no sink. There is limited storage.
<i>Music</i>				
Environment	0.333	0.667	Poor	The music room is showing its age. The carpet is ripped and puckering. The room looks worn and tired. The HVAC system is inconsistent. The lighting is dark and uninviting. The band does not have a designed designated space so it is conducted on the stage in the cafeteria which does not have the proper acoustics for a band room.
Size	0.833	1.667	Poor	There is no designed designated space for band.
Location	0.250	0.500	Poor	There is no designed designated space for band.
Storage/Fixed Equip	0.250	0.500	Poor	The band teacher has no storage.
<i>Performing Arts</i>				
Environment	0.272	0.544	Poor	There is no ADA access to the gym. The multipurpose space is showing its age. The stage looks worn. The curtains are frayed and torn.
Size	1.360	1.360	Excel	
Location	0.265	0.408	Fair	The access to other parts of the building cannot be restricted for evening or weekend events.
Storage/Fixed Equip	0.265	0.408	Fair	There is no dressing room. There is no storage for props and equipment for a production.
<i>Physical Education</i>				
Environment	0.864	1.728	Poor	There is no HVAC system in the gym so it is extremely hot. The lighting is dim.
Size	4.320	4.320	Excel	
Location	1.296	1.296	Excel	
Storage/Fixed Equip	0.842	1.296	Fair	There is minimal storage in the gym.
<i>Science</i>				
Environment	0.000	0.450	Unsat	There is no science room.
Size	0.000	1.125	Unsat	There is no science room.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
<i>Science</i>				
Location	0.000	0.337	Unsat	There is no science room.
Storage/Fixed Equip	0.000	0.337	Unsat	There is no science room.
<i>Self-Contained Special Education</i>				
Environment	0.000	0.432	Unsat	There is no special education self-contained classroom.
Size	0.000	1.080	Unsat	There is no special education self-contained classroom.
Location	0.000	0.324	Unsat	There is no special education self-contained classroom.
Storage/Fixed Equip	0.000	0.324	Unsat	There is no special education self-contained classroom.
<i>Non-Instructional Spaces</i>				
Administration	1.151	2.302	Poor	The administration area is very small. There is no reception within the administration area. The principal's office is small with no meeting space. There is no conference room. The student records are stored in a room with a fireproof door and three of the four filing cabinets are fireproof. None of the filing cabinets for student records are water proof. There is no HVAC in the principal's office.
Cafeteria	2.925	4.500	Fair	There is no space to store the tables and chairs. There is little flexibility in the arrangement because of the number of tables needed to seat the students. The restrooms near the cafeteria do not have hot water.
Food Service and Prep	3.629	5.584	Fair	There is inadequate serving line space.
Clinic	0.342	0.526	Fair	There is only one cot in the clinic. There is no ADA restroom. There is no hot water. There is no sink in the clinic restroom. The clinic is not located near the office.
Counseling	0.132	0.263	Poor	The counselors' offices are situated in a space that has been divided into two spaces with a sheetrock wall. The lighting goes between the two rooms with holes in the wall. Sound travels easily between the two spaces. This is not conducive to private conversations. There is no reception area for parents or students. There is no conference room. The student records are in the administrative area which is not close to the counselors' offices.
Custodial and Maintenance	0.450	0.450	Excel	
Student Restrooms	0.519	0.798	Fair	There is one boys restroom that has urinal privacy panels and the other two do not.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Faculty Work Space and Toilets	0.570	1.140	Poor	The size of the workroom are not adequate for the number of the staff and faculty. There is only one copier. There is not adequate space for instructional materials' preparation.
<i>Outside Spaces</i>				
Vehicular Traffic	0.000	1.800	Unsat	There is no separation between the parent drop off and the bus lane. There is no covered bus loading area.
Pedestrian Traffic	0.438	0.876	Poor	There are no crosswalks from the parking lot to the sidewalk in front of the school entrance.
Parking	0.365	0.731	Poor	There is not adequate parking for the number of staff, leaving little or no parking for visitors.
Play Areas	1.369	2.107	Fair	The hard surface area has two portables on it. The surface is cracked and in disrepair.
<i>Safety and Security</i>				
Fencing	0.338	0.677	Poor	There is fencing but it is in disrepair so students and others can walk between the fencing. The play areas are not fenced.
Signage & Way Finding	0.450	0.900	Poor	There is little or no signage outside or inside to direct people to visitor parking or parents to the drop off. There is little or no signage outside or inside directing people to the entrance, office, gym, or multipurpose room. There are no "Under Surveillance" or "Subject to Search" signs.
Ease of Supervision	1.350	2.700	Poor	There are not enough cameras to have full views of all the outside areas. The security camera pictures are grainy so it is hard to identify people.
Controlled Entrances	0.292	0.450	Fair	There is no security vestibule.
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	Space is not properly climate-controlled.
Electrical Power	0.500	1.000	Fair	There are not seven quad outlets in each classroom.
Equity of Access, Wireless & Drops	0.330	1.000	Poor	There is not adequate access in all instructional spaces.
LAN Connectivity	0.495	1.500	Poor	Most instructional areas have LAN connectivity.
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.000	1.000	Unsat	Internet is not available and not reliable all of the time.
Faculty & Staff Technology	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Stoneview ES

Grade Configuration: PK-5

Score: 58.50

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

Technology Readiness

Laptop Carts	1.000	1.000	Good	
--------------	-------	-------	------	--

Telephone/PA	1.000	1.000	Good	
--------------	-------	-------	------	--

Total	58.50	/ 100.00 =	58.50	
--------------	--------------	-------------------	--------------	--