

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Tucker MS

Grade Configuration:

6-8

Score: 82.37

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.580	0.580	Excel	
Size	1.451	1.451	Excel	
Location	0.435	0.435	Excel	
Storage/Fixed Equip	0.283	0.435	Fair	There is limited storage and display space.
<i>Career, Technical and Agricultural Education</i>				
Environment	0.971	1.214	Good	
Size	2.428	3.035	Good	The career technical labs meet about 80-85% of their respective size standard.
Location	0.728	0.911	Good	
Storage/Fixed Equip	0.728	0.911	Good	The space used for a shop/materials production area of the technology lab is not adequately ventilated for dust and residue.
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	
Size	0.675	0.675	Excel	
Location	0.162	0.202	Good	The main computer lab is on the 2nd floor.
Storage/Fixed Equip	0.132	0.202	Fair	There is limited storage, no motion sensor and the security camera to view entryway is outside the room and down the hall.
<i>General Classrooms</i>				
Environment	3.510	3.510	Excel	
Size	8.775	8.775	Excel	Most general classrooms meet about 90% of the size standard.
Location	2.106	2.632	Good	One grade is located on each floor of the school.
Storage/Fixed Equip	2.106	2.632	Good	All classrooms have at minimum, a storage cabinet, four student computers, a promethean board, a white board, and a small book case. A number of rooms appear to need additional storage space.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Tucker MS

Grade Configuration:

6-8

Score: 82.37

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.590	0.737	Good	
Size	1.842	1.842	Excel	
Location	0.553	0.553	Excel	
Storage/Fixed Equip	0.442	0.553	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.800	1.800	Excel	
Exterior Environment	1.350	1.350	Excel	
Environment	0.668	0.835	Good	
<i>Media Center</i>				
Size	1.357	2.088	Fair	The combined space of the media center rooms is about 65% of the size standard for middle schools.
Location	0.501	0.626	Good	
Storage/Fixed Equip	0.501	0.626	Good	The computer cart storage room within the media center cannot charge all equipment at one time.
<i>Music</i>				
Environment	0.662	0.662	Excel	The school has music rooms for band, orchestra, chorus and a keyboard space, now used for individual tutoring/practice.
Size	1.655	1.655	Excel	
Location	0.497	0.497	Excel	
Storage/Fixed Equip	0.397	0.497	Good	There are no individual practice rooms, there is no natural light in the keyboard room, and access to water and bathrooms are in the adjacent hallway.
<i>Performing Arts</i>				
Environment	0.245	0.377	Fair	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Tucker MS

Grade Configuration:

6-8

Score: 82.37

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Size	0.612	0.942	Fair	There is area no dressing areas.
Location	0.184	0.283	Fair	The cafetorium cannot be closed off from other parts of the school, and there is no direct loading access.
Storage/Fixed Equip	0.184	0.283	Fair	There is limited storage space.
<i>Physical Education</i>				
Environment	2.160	2.160	Excel	
Size	3.510	5.400	Fair	The gym is about 65-70% of the size standard for middle schools. There is no auxiliary gym, but there is a multi-purpose room currently used as a weight room.
Location	1.296	1.620	Good	
Storage/Fixed Equip	1.296	1.620	Good	
<i>Science</i>				
Environment	0.859	0.859	Excel	
Size	2.147	2.147	Excel	
Location	0.515	0.644	Good	The science labs do not have direct access to outdoors.
Storage/Fixed Equip	0.515	0.644	Good	Student work tables are moveable in the center of the rooms. All safety equipment is present with the exception of a fire blanket.
<i>Self-Contained Special Education</i>				
Environment	0.393	0.491	Good	Rooms are located on first, second and third floor.
Size	0.798	1.228	Fair	Each room with bathroom and storage area meets the 800 SF classroom size, but the school does not have the appropriately-sized family living center.
Location	0.239	0.368	Fair	
Storage/Fixed Equip	0.239	0.368	Fair	There is no family living center and accompanying features.
<i>Non-Instructional Spaces</i>				
Administration	1.509	1.886	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Tucker MS

Grade Configuration:

6-8

Score: 82.37

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Cafeteria	2.880	3.600	Good	
Food Service and Prep	3.344	5.144	Fair	There are only two serving lines
Clinic	0.153	0.306	Poor	There is a designated clinic space, but it is no longer used that purpose, and it does not have all of the fixed features required.
Counseling	0.382	0.382	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.668	0.835	Good	
Faculty Work Space and Toilets	0.652	0.815	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.800	3.600	Poor	Parent pick-up creates considerable congestion and on the public street in front of school.
Pedestrian Traffic	0.253	0.389	Fair	There are a number of walking students who must cross the congested and busy street in front of school. There are crosswalks and two crossing guards, but parent cars and departing buses add to the congestion.
Parking	0.619	0.774	Good	
Athletic Fields and Facilities	0.612	0.942	Fair	There are no restrooms near athletic fields. There is an old hard-surfaced tennis courts.
<i>Safety and Security</i>				
Fencing	0.454	0.698	Fair	Not all of the playing field perimeter is fenced.
Signage & Way Finding	0.585	0.900	Fair	No required signs are visible,
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.292	0.450	Fair	There is a controlled entrance and a security desk inside, but there is no security vestibule..
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	The main MDF room is climate controlled, but several smaller IDF rooms have HVAC issues.
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Tucker MS

Grade Configuration: 6-8

Score: 82.37

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	The laptop cart storage room in the media center does not have enough electrical outlets to charge all carts at one time.
Telephone/PA	1.000	1.000	Good	
Total	82.37 / 100.00 =		82.37	