

| | Grade Configuration: 6-12 | | | |
|---------------------------------------|---------------------------|--------------------|--------|---|
| Score: 56.48 | | | | |
| Category | Points Earned | Possible Points | Rating | Comment |
| Art | | | | |
| Environment | 0.000 | 0.599 | Unsat | DeKalb Alternative School does not have an art space. |
| Size | 0.000 | 1.496 | Unsat | DeKalb Alternative School does not have an art space. |
| Location | 0.000 | 0.449 | Unsat | DeKalb Alternative School does not have an art space. |
| Storage/Fixed Equip | 0.000 | 0.449 | Unsat | DeKalb Alternative School does not have an art space. |
| Career, Technical and Agricultural Ed | ducation | | | |
| Environment | 1.000 | 1.538 | Fair | The CTAE program has noise transfer in from other areas and lacks natural lighting. |
| Size | 0.000 | 3.845 | Unsat | The only CTAE program that DeKalb Alternative School has at this time is a Graphics Arts program. That program is housed in a room of about 983 SF, which is only 41%of the standard for high schools. |
| Location | 0.923 | 1.154 | Good | The CTAE program is not shielded from noise producing activities and functions. |
| Storage/Fixed Equip | 0.750 | 1.154 | Fair | The CTAE program lacks appropriate storage space for projects and materials and lacks permanent casework. |
| Computer Labs | | | | |
| Environment | 0.216 | 0.270 | Good | The computer labs have noise transfer in from other areas. |
| Size | 0.675 | 0.675 | Excel | |
| Location | 0.202 | 0.202 | Excel | |
| Storage/Fixed Equip | 0.000 | 0.202 | Unsat | The computer labs lack adequate storage for the teacher and materials. They also lack book cases and motion sensor lighting. |
| General Classrooms | | | | |
| Environment | 2.281 | 3.510 | Fair | The general classrooms lack insulation in the walls and ceilings. There are no sound panels in the larger spaces with tile floors and bare walls. Consequently, there is a great deal of noise in various spaces and a great deal of noise transfer into the classrooms from several areas of the building. The HVAC is controlled in zones throughout the building which results in over and under heating sections of the zones. The classrooms also lack natural lighting. |
| Size | 7.020 | 8.775 | Good | |

Page 1 of 5



| School Name: | DeKalb Alternat | ive School | | | Grade Configuration: 6-12 |
|-----------------|-----------------|------------------|--------------------|--------|--|
| Score: | 56.48 | | | | |
| Category | | Points Earned | Possible Points | Rating | Comment |
| General Classi | rooms | | | | |
| Location | | 2.106 | 2.632 | Good | |
| Storage/Fix | ed Equip | 1.316 | 2.632 | Poor | Most of the general classrooms lack permanent casework for teaching materials and records. A majority of the general classrooms also lack a lockable teacher's wardrobe cabinet, lockable storage cabinets, and bookcases. |
| Instructional R | Resource Rooms | | | | |
| Environmer | nt | 0.467 | 0.719 | Fair | The resource rooms have noise transfer in from other areas and lack natural lighting. |
| Size | | 1.438 | 1.797 | Good | |
| Location | | 0.431 | 0.539 | Good | |
| Storage/Fixe | ed Equip | 0.350 | 0.539 | Fair | The Instructional Resource rooms lack adequate permanent casework and adequate teacher and student storage. |
| Learning Envir | ronment | | | | |
| Learning Sty | yle Variety | 3.600 | 4.500 | Good | |
| Interior Env | ironment | 1.170 | 1.800 | Fair | On the inside, the areas are freshly painted and very clean from clutter and any marks. However the facility has little or no insulation in the walls or ceiling. The main halls have crate-type ceiling panels that somewhat hide leaking skylights and higher drafty spaces. There are no sound panels anywhere. This construction leaves water leaks when it rains and a great deal of noise transfer from several areas of the building. Furthermore, the building lacks natural lighting. |
| Exterior Env | vironment | 0.000 | 1.350 | Unsat | The current design of the program and that of the facility does not allow for outside learning opportunities. |
| Environmer | nt | 0.607 | 0.759 | Good | The media center lacks natural lighting. |
| Media Center | | | | | |
| Size | | 0.000 | 1.897 | Unsat | The media center is about 2085 SF, which is 24% of the standard for high schools. |
| Location | | 0.455 | 0.569 | Good | |
| Storage/Fixe | ed Equip | 0.370 | 0.569 | Fair | The media center lacks a sink and adequate storage space for the technology carts. |



| School Name: DeKalb Altern | ative School | | Grade Configuration: 6-12 |
|----------------------------|----------------------------------|-------|--|
| Score: 56.48 | | | |
| Category | Points Possible Earned Points | | Comment |
| Music | | | |
| Environment | 0.347 0.534 | Fair | The music room has noise transfer in from other areas and lacks natural lighting. |
| Size | 0.000 1.336 | Unsat | The music program is housed in a 627 SF room that combines instrumental and vocal music. This is only 35% of the high school standard for size. |
| Location | 0.261 0.401 | Fair | Though the music room is somewhat isolated and near the multipurpose room for performances. However, the lack of insulation in the walls makes it too easy for the sounds to bleed into other rooms. The program does not have practice rooms with any related supervision issues. |
| Storage/Fixed Equip | 0.200 0.401 | Poor | The music room lacks adequate casework, a sink, practice rooms, offices for each program, access to portable risers, a drinking fountain, and a podium. |
| Performing Arts | | | |
| Environment | 0.144 0.289 | Poor | The multipurpose room is used as the performing arts area. It lacks sound boards and only has fixed bright lights in the ceiling. |
| Size | 0.000 0.721 | Unsat | The Performance Arts area lacks an auditorium, a dance room, and a black box. DeKalb Alternative School does have a drama program. |
| Location | 0.108 0.216 | Poor | The Performance Arts area is not acoustically isolated and cannot be isolated from other spaces. |
| Storage/Fixed Equip | 0.000 0.216 | Unsat | The Performance Arts area lacks any storage room or space, a curtain, appropriate lighting, a sound system, and technology appropriate to the program. DeKalb Alternative School does have a drama program. |
| Physical Education | | | |
| Environment | 0.000 2.160 | Unsat | DeKalb Alternative School does not have a PE program. |
| Size | 0.000 5.400 | Unsat | DeKalb Alternative School does not have a PE program. |
| Location | 0.000 1.620 | Unsat | DeKalb Alternative School does not have a PE program. |
| Storage/Fixed Equip | 0.000 1.620 | Unsat | DeKalb Alternative School does not have a PE program. |
| Science | | | |
| Environment | 0.485 0.747 | Fair | The science rooms have noise transfer in from other areas and lack natural lighting. |

Page 3 of 5



| School Name: DeKalb Alternative School | | | | Grade Configuration: 6-12 |
|--|------------------|--------------------|--------|--|
| Score: 56.48 | | | | |
| Category | Points Earned | Possible Points | Rating | Comment |
| Science | | | | |
| Size | 1.494 | 1.867 | Good | Although the science program is housed in various size rooms, the average is about 82% of the standard. |
| Location | 0.448 | 0.560 | Good | The science program does not have access to an outdoor patio. |
| Storage/Fixed Equip | 0.280 | 0.560 | Poor | The science program lacks adequate storage, a demo station in some classrooms, a fume hood, a dishwasher and refrigerator. |
| Self-Contained Special Education | | | | |
| Environment | 0.312 | 0.479 | Fair | The special education room has noise transfer in from other areas, lacks natural lighting, and dimmable lighting. |
| Size | 0.000 | 1.198 | Unsat | The special education room is only 39% of standard for size. The program lacks a family living center, a changing area, and storage. |
| Location | 0.288 | 0.359 | Good | |
| Storage/Fixed Equip | 0.180 | 0.359 | Poor | The special education program lacks adequate casework, a family living center with related equipment, and adequate storage space for special needs equipment. |
| Non-Instructional Spaces | | | | |
| Administration | 2.349 | 2.349 | Excel | |
| Cafeteria | 2.880 | 3.600 | Good | The cafeteria is about 3,022 SF in a school with a student population that averages in the low to mid hundreds. It also lacks storage space for the equipment. |
| Food Service and Prep | 3.676 | 4.595 | Good | The food services area lacks natural lighting |
| Clinic | 0.000 | 0.214 | Unsat | DeKalb Alternative School does not have a clinic. |
| Counseling | 0.545 | 0.681 | Good | |
| Custodial and Maintenance | 0.292 | 0.450 | Fair | Custodial lacks a receiving area other than through the main hall. It also lacks floor mop sinks in the closets. |
| Student Restrooms | 0.657 | 0.821 | Good | The program needs more restrooms available. |
| Faculty Work Space and Toilets | 0.513 | 0.641 | Good | |
| Outside Spaces | | | | |
| Vehicular Traffic | 0.720 | 0.900 | Good | |
| 2/23/2016 | | | | Page 4 of S |
| | | | | |



School Name: DeKalb Alternative School **Grade Configuration:** 6-12 56.48 Score: **Points** Possible Category Earned **Points** Rating Comment **Outside Spaces** Pedestrian Traffic 0.706 0.882 Good **Parking** 0.949 1.897 Poor The parking area lacks markings and sufficient lighting. It also has holes in the pavement. Athletic Fields and Facilities 0.000 2.488 DeKalb Alternative School does not have athletic fields or spaces. Unsat Safety and Security 0.495 0.762 Outside access points are not appropriately controlled with gates. This is a very concerning issue Fencing Fair at the DeKalb Alternative School. Signage & Way Finding 0.450 0.900 Exterior signage is unclear, the rooms have more than just numbers, and the school lacks the Poor "Under Surveillance" signage. Ease of Supervision 2.700 2.700 Excel Controlled Entrances 0.450 0.450 Excel Technology Readiness **IDF & MDF Environment** 1.500 1.500 Good **Flectrical Power** 1.000 1.000 Good Equity of Access, Wireless & Drops 1.000 1.000 Good LAN Connectivity 1.500 1.500 Good WAN Backbone 1.000 1.000 Good LAN-WAN Performance 0.670 1.000 Fair Faculty & Staff Technology 1.000 1.000 Good **Laptop Carts** 0.500 1.000 Fair Telephone/PA 1.000 1.000 Good **Total** 56.48 / 100.00 =56.48

2/23/2016 Page 5 of 5