

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody ES

Grade Configuration:

PK-5

Score: 84.39

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.421	0.421	Excel	
Size	0.842	1.053	Good	The art classroom meets 85% of the adequate space standard.
Location	0.253	0.316	Good	There are no patios off the art room.
Storage/Fixed Equip	0.316	0.316	Excel	
<i>Computer Labs</i>				
Environment	0.307	0.307	Excel	
Size	0.768	0.768	Excel	
Location	0.184	0.230	Good	
Storage/Fixed Equip	0.184	0.230	Good	
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	Classrooms are undersized.
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>General Classrooms</i>				
Environment	4.410	4.410	Excel	
Size	8.820	11.025	Good	Classrooms are undersized.
Location	2.646	3.307	Good	
Storage/Fixed Equip	2.646	3.307	Good	Some spaces do not have sinks or bubblers
<i>Instructional Resource Rooms</i>				
Environment	0.518	0.648	Good	
Size	1.296	1.620	Good	
Location	0.389	0.486	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody ES

Grade Configuration:

PK-5

Score: 84.39

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Storage/Fixed Equip	0.000	0.486	Unsat	The storage the space is inadequate.
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.375	0.375	Excel	
Size	0.751	0.938	Good	
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.225	0.282	Good	
<i>Learning Environment</i>				
Learning Style Variety	4.500	4.500	Excel	
Interior Environment	1.800	1.800	Excel	
Exterior Environment	1.350	1.350	Excel	The art room has a full patio.
Environment	0.877	0.877	Excel	
<i>Media Center</i>				
Size	1.425	2.193	Fair	The media center meets 71% of the adequate space standard.
Location	0.329	0.658	Poor	The Media is located across from the gym and next to the kitchen and cafeteria.
Storage/Fixed Equip	0.526	0.658	Good	
<i>Music</i>				
Environment	0.667	0.667	Excel	
Size	1.333	1.667	Good	Music space meets 85% of the adequate space standard.
Location	0.400	0.500	Good	
Storage/Fixed Equip	0.400	0.500	Good	
<i>Performing Arts</i>				
Environment	0.435	0.544	Good	The stage has ADA access in the rear only.
Size	1.088	1.360	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody ES

Grade Configuration:

PK-5

Score: 84.39

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.728	1.728	Excel	
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	
<i>Science</i>				
Environment	0.450	0.450	Excel	
Size	1.125	1.125	Excel	
Location	0.337	0.337	Excel	
Storage/Fixed Equip	0.270	0.337	Good	
<i>Self-Contained Special Education</i>				
Environment	0.346	0.432	Good	
Size	0.864	1.080	Good	
Location	0.211	0.324	Fair	One elevator transports students from the special education classes down to the lower level. For emergency egress, this is inadequate as it will take several trips and too much time.
Storage/Fixed Equip	0.211	0.324	Fair	Storage space is inadequate. There are no sinks or hot water. Restroom usage requires transport to general population restrooms.
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	
Cafeteria	3.600	4.500	Good	
Food Service and Prep	4.467	5.584	Good	
Clinic	0.421	0.526	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody ES

Grade Configuration:

PK-5

Score: 84.39

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Counseling	0.211	0.263	Good	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.639	0.798	Good	
Faculty Work Space and Toilets	0.912	1.140	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.170	1.800	Fair	Bus and car traffic are not separate.
Pedestrian Traffic	0.701	0.876	Good	There is no covered loading area.
Parking	0.475	0.731	Fair	There is not enough parking for daily operations.
Play Areas	1.685	2.107	Good	
<i>Safety and Security</i>				
Fencing	0.440	0.677	Fair	There is no fencing for the play area.
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	The office is to the side of the main doors. Visitors can enter the main foyer when someone is leaving the foyer without going through the office area.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody ES

Grade Configuration: PK-5

Score: 84.39

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

Technology Readiness

Telephone/PA	1.000	1.000	Good	
--------------	-------	-------	------	--

Total	84.39	/ 100.00 =	84.39	
--------------	--------------	-------------------	--------------	--