

					»
School Name:	Southwest DeKalb	HS			Grade Configuration: 9-12
Score:	86.70				
		Points	Possible		
Category		Earned	Points	Rating	Comment
Art					
Environment	t	0.599	0.599	Excel	
Size		1.496	1.496	Excel	
Location		0.449	0.449	Excel	
Storage/Fixe	Storage/Fixed Equip		0.449	Good	Kiln room is available, but no kiln installed yet.
Career, Technical and Agricultural Education					
Environment	Environment		1.538	Excel	
Size			3.845	Excel	
Location			1.154	Excel	
Storage/Fixed Equip		1.154	1.154	Excel	The engineering technology lab space is in final stages of renovation. Not all equipment is in place at this time. Score is based on what was finished or described as in progress.
Computer Labs	i				
Environment	t	0.216	0.270	Good	
Size		0.675	0.675	Excel	
Location		0.132	0.202	Fair	Several computer labs have exterior windows.
Storage/Fixe	d Equip	0.132	0.202	Fair	Rooms have limited storage space.
General Classro	ooms				
Environment	t	3.510	3.510	Excel	
Size		8.775	8.775	Excel	
Location	Location		2.632	Excel	
Storage/Fixe	Storage/Fixed Equip		2.632	Good	
Instructional Resource Rooms					
Environment	Environment		0.719	Good	
Size	Size		1.797	Excel	
		0.575 1.797			



School Name: Southwest DeKalb HS				Grade Configuration: 9-12
Score: 86.70				
	Points	Possible		
Category	Earned	Points	Rating	Comment
Instructional Resource Rooms				
Location	0.431	0.539	Good	
Storage/Fixed Equip	0.431	0.539	Good	
Learning Environment				
Learning Style Variety	4.500	4.500	Excel	
Interior Environment	1.800	1.800	Excel	
Exterior Environment	1.350	1.350	Excel	
Environment	0.493	0.759	Fair	The media center has low ceilings, limited acoustical features and drop poles for power to computer banks.
Media Center				
Size	1.897	1.897	Excel	
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.455	0.569	Good	
Music				
Environment	0.534	0.534	Excel	There is an old music chorus/orchestra suite of rooms that is no longer used for music instruction or practice. The new music space has all of the required features, fixtures and amenities to provide an inviting environment for the program.
Size	1.336	1.336	Excel	
Location	0.401	0.401	Excel	A new full set of music rooms/spaces are adjacent to the new auditorium.
Storage/Fixed Equip	0.401	0.401	Excel	
Performing Arts				
Environment	0.289	0.289	Excel	
Size	0.721	0.721	Excel	
Location	0.216	0.216	Excel	
Storage/Fixed Equip	0.216	0.216	Excel	



School Name: Southwest DeKalb HS	5			Grade Configuration: 9-12
Score: 86.70				
Category	Points Earned	Possible Points	Rating	Comment
Physical Education				
Environment	1.728	2.160	Good	
Size	2.700	5.400	Poor	The main gym is roughly half of the high school size standard and seats approximately 800. There is no dance room.
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.296	1.620	Good	
Science				
Environment	0.747	0.747	Excel	
Size	1.867	1.867	Excel	
Location	0.448	0.560	Good	Science labs do not have direct access to outdoor work areas.
Storage/Fixed Equip	0.364	0.560	Fair	Most labs have all safety equipment except fire extinguishers in the lab or adjacent preparation room.
Self-Contained Special Education				
Environment	0.383	0.479	Good	
Size	1.198	1.198	Excel	
Location	0.288	0.359	Good	
Storage/Fixed Equip	0.288	0.359	Good	
Non-Instructional Spaces				
Administration	2.349	2.349	Excel	
Cafeteria	2.880	3.600	Good	
Food Service and Prep	2.987	4.595	Fair	There are only two serving lines. The enrollment size would require three lines.
Clinic	0.000	0.214	Unsat	There is no clinic.
Counseling	0.681	0.681	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.657	0.821	Good	The restrooms on the 3100 hall are not working and have odor issues.



School Name: Southwest DeKalb HS				Crede Configurations 0.42
School Name. Southwest Devalors				Grade Configuration: 9-12
Score: 86.70				
Catagory		Possible		
Category	Earned	Points	Rating	Comment
Non-Instructional Spaces				
Faculty Work Space and Toilets	0.513	0.641	Good	
Outside Spaces				
Vehicular Traffic	0.720	0.900	Good	
Pedestrian Traffic	0.573	0.882	Fair	Students walking through or parking in the student parking lot, cross over the parent drop-off lane to enter the school. Student cross walk(s) from parking lot are not clearly designated.
Parking	1.518	1.897	Good	
Athletic Fields and Facilities	1.244	2.488	Poor	The is a football practice field with track, but no other field for soccer. There is a single combination baseball / softball field, with few useable bleachers. Athletic fields are not lighted. Restrooms and water are a distance from some fields.
Safety and Security				
Fencing	0.381	0.762	Poor	Some areas of the school perimeter need additional fencing.
Signage & Way Finding	0.450	0.900	Poor	Only two required warning signs (Drug-Free and No Weapons) are visible. Room numbers displayed on hallway directory signs as well as those on individual rooms, do not match up and none match the rooms on the floorplans. This could pose a safety problem for first responders.
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.360	0.450	Good	
Technology Readiness				
IDF & MDF Environment	0.750	1.500	Fair	Several server rooms are not adequately cooled.
Electrical Power	0.500	1.000	Fair	Some classrooms use power strips. Two classrooms in ROTC do not have electrical power.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	All have access to desktops and interactive boards.
Laptop Carts	1.000	1.000	Good	



School Name:	Southwest DeKalb HS				Grade Configuration: 9-12
Score:	86.70				
Category		Points Earned	Possible Points	Rating	Comment
Technology Re	adiness				
Telephone/F	PA	1.000	1.000	Good	
Total		86.70 /	100.00 =	86.70	