

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Chamblee MS

Grade Configuration: 6-8

Score: 80.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.464	0.580	Good	
Size	1.451	1.451	Excel	
Location	0.435	0.435	Excel	
Storage/Fixed Equip	0.348	0.435	Good	
<i>Career, Technical and Agricultural Education</i>				
Environment	0.971	1.214	Good	
Size	1.973	3.035	Fair	The business lab is approximately 56% of the size standard and the Engineering Technology lab is approximately 75% of the standard.
Location	0.911	0.911	Excel	
Storage/Fixed Equip	0.728	0.911	Good	
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	
Size	0.540	0.675	Good	
Location	0.162	0.202	Good	
Storage/Fixed Equip	0.132	0.202	Fair	There is insufficient storage space for the program. There is no motion sensor lighting and no security camera.
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	
Size	7.020	8.775	Good	
Location	2.106	2.632	Good	
Storage/Fixed Equip	2.632	2.632	Excel	
<i>Instructional Resource Rooms</i>				
Environment	0.590	0.737	Good	
Size	1.474	1.842	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Chamblee MS

Grade Configuration: 6-8

Score: 80.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.553	0.553	Excel	
Storage/Fixed Equip	0.359	0.553	Fair	Some Instructional Resource rooms do not have storage for teacher or student materials.
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	
Exterior Environment	1.350	1.350	Excel	
Environment	0.668	0.835	Good	
<i>Media Center</i>				
Size	1.044	2.088	Poor	The media center is approximately 57% of the size standard.
Location	0.501	0.626	Good	
Storage/Fixed Equip	0.407	0.626	Fair	There are not enough power sources to accommodate recharging laptop and iPad carts.
<i>Music</i>				
Environment	0.530	0.662	Good	
Size	1.076	1.655	Fair	While the mental health facility room slightly exceed the size standard, the choral room is approximately 62% of the standard.
Location	0.497	0.497	Excel	
Storage/Fixed Equip	0.323	0.497	Fair	There are no practice rooms for the choral or orchestra rooms.
<i>Performing Arts</i>				
Environment	0.301	0.377	Good	
Size	0.754	0.942	Good	
Location	0.283	0.283	Excel	
Storage/Fixed Equip	0.184	0.283	Fair	The stage is only ADA accessible from the back. There is no sound system.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Chamblee MS

Grade Configuration: 6-8

Score: 80.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Physical Education</i>				
Environment	1.728	2.160	Good	
Size	2.700	5.400	Poor	The standard calls for two gyms but the school has only one and it only meets approximately 64% of the standard. The standards also call for two additional areas. There is a weight room but no multipurpose space.
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.053	1.620	Fair	There is no padding under one of the backboards.
<i>Science</i>				
Environment	0.687	0.859	Good	
Size	1.718	2.147	Good	
Location	0.644	0.644	Excel	
Storage/Fixed Equip	0.644	0.644	Excel	
<i>Self-Contained Special Education</i>				
Environment	0.393	0.491	Good	
Size	0.614	1.228	Poor	The self-contained Special Education classrooms do not have a family living center and no ADA accessible restroom. One classroom exceeds the size standard and the second classroom is approximately 85% of the standard.
Location	0.184	0.368	Poor	Students have to use stairs to access any room located on the two other levels of the school. This includes the cafeteria, the media center, the gymnasium, and the main office.
Storage/Fixed Equip	0.239	0.368	Fair	There is inadequate storage for the specialized equipment needs of the students.
<i>Non-Instructional Spaces</i>				
Administration	1.886	1.886	Excel	
Cafeteria	2.880	3.600	Good	
Food Service and Prep	4.116	5.144	Good	
Clinic	0.244	0.306	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Chamblee MS

Grade Configuration: 6-8

Score: 80.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Counseling	0.382	0.382	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.835	0.835	Excel	
Faculty Work Space and Toilets	0.815	0.815	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	3.600	3.600	Excel	
Pedestrian Traffic	0.389	0.389	Excel	
Parking	0.619	0.774	Good	
Athletic Fields and Facilities	0.942	0.942	Excel	
<i>Safety and Security</i>				
Fencing	0.454	0.698	Fair	There is only one side of the building that has fencing.
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	1.755	2.700	Fair	There are several blind spots. There are not enough outside cameras to see all immediate areas outside the building and the camera system does not work consistently. There are no cameras in the parking lot or in the front office area.
Controlled Entrances	0.225	0.450	Poor	There is a security office as you enter but no card or camera system and no security vestibule.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Chamblee MS

Grade Configuration: 6-8

Score: 80.78

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Laptop Carts	0.500	1.000	Fair	Laptops are stored in the media center conference room. Many power strips are used to charge carts because there are not enough outlets.
Telephone/PA	1.000	1.000	Good	
Total	80.78	100.00	= 80.78	