

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Eagle Woods Facility

Grade Configuration:

6-12

Score: 56.02

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.767	0.767	Excel	The art room provides natural light for students, as well as adequate lighting levels. The spatial configuration, acoustics, HVAC/temperature, and aesthetics support the learning process.
Size	0.000	1.918	Unsat	The art room provides approximately 35% of the required space for high school art rooms.
Location	0.374	0.575	Fair	The art room is located in the building with the gym. It provides natural light and is located on an exterior wall, however, it does not have direct access to an outdoor patio.
Storage/Fixed Equip	0.288	0.575	Poor	Storage is limited in the art room and there isn't an area to display student art work. The instructor utilizes easels and wall space to display student work.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.577	1.971	Good	The business lab has an abundance of natural light and lighting levels. The lab is housed in the building with the gym and is spatially configured on a smaller scale than a high school. HVAC/Temperature, acoustics, and aesthetics are appropriate.
Size	0.000	4.929	Unsat	High school standards for a Business lab are much larger than the space at Eagle Wood. Eagle Woods meets approximately 30% of the standard.
Location	0.739	1.478	Poor	The Business lab is shielded from noise-producing activities; however, they do not have an appropriate material delivery area.
Storage/Fixed Equip	0.739	1.478	Poor	Storage is limited in the business lab.
<i>Computer Labs</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment			N/A	
Size			N/A	
Location			N/A	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Eagle Woods Facility

Grade Configuration:

6-12

Score: 56.02

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Storage/Fixed Equip			N/A	
<i>Instructional Resource Rooms</i>				
Environment	0.921	0.921	Excel	
Size	2.304	2.304	Excel	
Location	0.553	0.691	Good	The majority of the instructional resource rooms are located in the building housing the gym. There is a ramp for ADA access to this building.
Storage/Fixed Equip	0.553	0.691	Good	
<i>Learning Environment</i>				
Learning Style Variety	4.614	5.768	Good	
Interior Environment	1.846	2.307	Good	
Exterior Environment	1.384	1.730	Good	
Environment	0.778	0.973	Good	The environment within the media center, has positive lighting, acoustics, HVAC temperatures, and overall aesthetics.
<i>Media Center</i>				
Size	0.000	2.432	Unsat	The site meets approximately 30% of the standard.
Location	0.584	0.730	Good	The media center is centrally located between the middle and high school classrooms at Eagle Woods.
Storage/Fixed Equip	0.474	0.730	Fair	There is limited storage in the media center. There is a single closet where the laptop carts are housed/charged each evening. The closet is secure and a camera is located in the storage space. The area does not have a workroom with a sink.
<i>Music</i>				
Environment	0.000	0.685	Unsat	Music instruction is not provided at Eagle Woods.
Size	0.000	1.713	Unsat	A space is not provided for music instruction.
Location	0.000	0.514	Unsat	Music instruction is not provided at Eagle Woods.
Storage/Fixed Equip	0.000	0.514	Unsat	Music instruction is not provided at Eagle Woods.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Eagle Woods Facility

Grade Configuration:

6-12

Score: 56.02

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.000	0.370	Unsat	Eagle Woods does not have a performing arts space.
Size	0.000	0.925	Unsat	Eagle Woods does not have a performing arts space.
Location	0.000	0.277	Unsat	Eagle Woods does not have a performing arts space.
Storage/Fixed Equip	0.000	0.277	Unsat	Eagle Woods does not have a performing arts space.
<i>Physical Education</i>				
Environment	1.800	2.769	Fair	The P.E. environment in the gym provides adequate lighting, spatial configuration, acoustics. The ceiling is damaged and the HVAC system is inadequate.
Size	0.000	6.921	Unsat	High school standards require large competitive courts and motorized seating. Eagle Wood meets approximately 35% of the criteria for size and possesses permanent bleachers. Weight rooms, showers and locker rooms are unavailable. There is a single health classroom. A multi-purpose space is available in the media center.
Location	1.661	2.076	Good	The gymnasium is housed in a separate building from the classrooms and offices at Eagle Woods. It can be secured from the campus for evening and weekend events. There is access to public restrooms in the building.
Storage/Fixed Equip	1.661	2.076	Good	There is adequate storage for PE. Eagle Woods does not have motorized seating in the gym.
<i>Science</i>				
Environment	0.622	0.957	Fair	Classrooms are not designed specifically for science.
Size	1.555	2.393	Fair	Classroom size is approximately 70% of the requirement.
Location	0.359	0.718	Poor	Classrooms used for science instruction do not have direct access to outdoor patio areas.
Storage/Fixed Equip	0.359	0.718	Poor	Classrooms do not have blankets and eye wash stations. Water and gas, sinks, and fume hoods are not provided in classrooms where science instruction is delivered.
<i>Self-Contained Special Education</i>				
Environment	0.491	0.614	Good	
Size	0.768	1.536	Poor	Self-contained special education classrooms meet approximately 70% of the standard. The family living center met approximately 60% of the requirement.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Eagle Woods Facility

Grade Configuration:

6-12

Score: 56.02

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Location	0.461	0.461	Excel	All classrooms were located on the ground floor and contained doors which opened into auxiliary halls. The classroom doors have windows for viewing traffic.
Storage/Fixed Equip	0.369	0.461	Good	
<i>Non-Instructional Spaces</i>				
Administration	1.957	3.011	Fair	The administrative "suite" is very small. A receptionist is located just inside the main entrance and a short hallway connects her office to the principal's office. The principal does not have space for a small group meeting in the office. A conference room is located in close proximity, but it is not connected to the principal's office. A disjointed configuration of offices house the teacher's lounge with mailboxes, adult restrooms, secure records storage, and textbook storage. The largest book room is located in the lower level of the media center and is not on the ground level.
Cafeteria	3.691	4.614	Good	The cafeteria provides adequate space and traffic flow through the serving line to/from seating for the less than 100 students served in the facility.
Food Service and Prep	2.945	5.890	Poor	Food services are provided to Eagle Wood through a satellite program. Meals are delivered to the site from another school. There are hot and cold storage areas and a small prep area. Equipment is old and outdated. There isn't an exterior access door connected to the kitchen. An office is not provided for food service personnel.
Clinic	0.137	0.274	Poor	A designed clinic is located on the middle school side of the facility, but is not used as a clinic. Instead, it is an office. A second clinic space is identified on the main corridor. This clinic has no cots. Both locations have ADA-accessible restrooms and a sink.
Counseling	0.000	0.873	Unsat	Counseling services at Eagle Wood are provided by a counselor and itinerant staff. There is adequate space for the counselor, psychologist, school social worker, post-doctorate intern, and interns. The school does not have an individual guidance office, reception or conference rooms.
Custodial and Maintenance	0.461	0.577	Good	There is a classroom in the building with the gym that is used as a custodial office and receiving area. There is a ramp available for the delivery of materials to that area. Shelves are available in this space to hold supplies. Custodial closets are located strategically throughout the building. They contain floor mop sinks.
Student Restrooms	0.684	1.053	Fair	The group restrooms are not ADA accessible; however there are restrooms on each hallway that are ADA accessible.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Eagle Woods Facility

Grade Configuration: 6-12

Score: 56.02

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Faculty Work Space and Toilets	0.411	0.822	Poor	The staff work space does not have faculty restrooms available within the room. It does contain cabinets, a copier, mailboxes, a refrigerator, and microwave.
<i>Outside Spaces</i>				
Vehicular Traffic	0.923	1.154	Good	Vehicular traffic is off street. All students arrive by bus.
Pedestrian Traffic			N/A	None of the students enrolled at Eagle Wood Academy walk to school.
Parking	1.946	2.432	Good	Students do not drive to campus and student parking is not designated on site. Faculty, staff, and visitor parking is off-street in a paved parking lot. Enhanced signage is needed to delineate the designated parking for vehicles other than school buses.
Athletic Fields and Facilities	0.000	3.190	Unsat	The school lacks an all-weather track, grassed football field, grassed soccer field, softball field and tennis courts. Fields have no lighting or irrigation. The facility lacks fixed bleachers for basketball, batting cages, and softball fields. There are no drinking fountains or ADA restrooms at the concession building. Eagle Woods lacks the required athletic spaces for high school.
<i>Safety and Security</i>				
Fencing	0.977	0.977	Excel	
Signage & Way Finding	0.577	1.154	Poor	Vehicular signage is needed to clearly delineate bus entrances/exits and those for other vehicles. Classrooms, custodial closets, restrooms, etc. were not all clearly marked with room numbers. A posted sign regarding weapons was posted; however, the Drug-Free, surveillance, and subject to search were not present.
Ease of Supervision	2.249	3.461	Fair	Supervision is monitored by personnel and cameras at Eagle Wood. Additional cameras are needed at the front of the building and near the gym. Campus fencing assists with the elopement of students.
Controlled Entrances	0.461	0.577	Good	Eagle Wood utilizes a card entry system. Personnel are visible at the entrance and in the hallways.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Eagle Woods Facility

Grade Configuration: 6-12

Score: 56.02

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

Technology Readiness

LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	

Total **56.02 / 100.00 = 56.02**