

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Shadow Rock Facility

Grade Configuration: K-5

Score: 66.22

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.573	0.717	Good	HVAC temperatures are inconsistent throughout the building. There is natural light in the art room.
Size	1.165	1.792	Fair	The art room meets approximately 65% of the size criteria.
Location	0.349	0.538	Fair	The art room does not have direct access to an outdoor patio.
Storage/Fixed Equip	0.349	0.538	Fair	The art room does not have a sink with a clay trap. It does not have a kiln with ventilation. There is a storage closet within the room.
<i>Computer Labs</i>				
Environment	0.418	0.523	Good	The computer lab is a basic classroom with a built in wall of cabinetry that has a sink with bubbler.
Size	0.000	1.307	Unsat	The computer lab meets less than 50% of the standard for size.
Location	0.314	0.392	Good	
Storage/Fixed Equip	0.255	0.392	Fair	The computer lab does not have sufficient outlets and the equipment is not properly secured. The room lacks motion-sensor lighting and security cameras.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	The school was originally designed with early childhood education/prekindergarten facilities. These are currently being used as general education classrooms. The school does not have any early education programming.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Shadow Rock Facility

Grade Configuration: K-5

Score: 66.22

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.883	1.103	Good	HVAC temperatures vary by space.
Size	2.758	2.758	Excel	The majority of instructional resource spaces exceed the 150 SF for small groups.
Location	0.662	0.827	Good	
Storage/Fixed Equip	0.662	0.827	Good	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Learning Environment</i>				
Learning Style Variety	7.661	7.661	Excel	
Interior Environment	3.064	3.064	Excel	
Exterior Environment	1.839	2.298	Good	
Environment	1.195	1.493	Good	HVAC temperatures vary throughout the facility and the media center was warm.
<i>Media Center</i>				
Size	0.000	3.734	Unsat	The media center meets less than 10% of the size requirement.
Location	0.896	1.120	Good	
Storage/Fixed Equip	0.560	1.120	Poor	The main body of the media center does not contain a storage closet; however, there are several storage rooms along the hallway outside the media center doors. There is a restroom with a sink. Permanent casework surrounds the room and a single lower height bookcase divides two sections of the room.
<i>Music</i>				
Environment	0.568	1.135	Poor	The classroom does not have a high ceiling. HVAC temperatures vary by space. There is natural lighting in the music room.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Shadow Rock Facility

Grade Configuration: K-5

Score: 66.22

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Size	1.844	2.838	Fair	There is a single music room. The current room meets approximately 65% of the required standard.
Location	0.681	0.851	Good	
Storage/Fixed Equip	0.681	0.851	Good	There is a wall of built in cabinets with a sink and bubbler under the window.
<i>Performing Arts</i>				
Environment	0.463	0.926	Poor	The stage in the gym at the Shadow Rock Center could be used as a performing arts area, but the lighting is poor and the environment is not aesthetically appealing. The acoustics are poor in this location.
Size	1.157	2.315	Poor	The size of the stage in the gym is exceptionally small, but it has a dressing room.
Location	0.347	0.694	Poor	The performing arts area of the gym does not have public restrooms in close proximity.
Storage/Fixed Equip	0.347	0.694	Poor	The performing arts stage does not have curtains or adequate lighting.
<i>Physical Education</i>				
Environment	2.354	2.942	Good	
Size	0.000	7.355	Unsat	The gym meets less than 50% of the size standard.
Location	1.765	2.207	Good	
Storage/Fixed Equip	1.103	2.207	Poor	The gym's rubberized flooring releases a tar-like substance that adheres to clothing and cannot be removed with regular washing.
<i>Science</i>				
Environment	0.000	0.766	Unsat	There is no science room.
Size	0.000	1.915	Unsat	There is no science room.
Location	0.000	0.575	Unsat	There is no science room.
Storage/Fixed Equip	0.000	0.575	Unsat	There is no science room.
<i>Self-Contained Special Education</i>				
Environment	0.478	0.735	Fair	HVAC is inconsistent. There is natural light streaming through the windows of every classroom. The aesthetics and acoustics are excellent.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Shadow Rock Facility

Grade Configuration: K-5

Score: 66.22

Category	Points Earned	Possible Points	Rating	Comment
<i>Self-Contained Special Education</i>				
Size	0.919	1.839	Poor	Shadow Rock Center's self-contained classrooms meet approximately 78% of the standard. The school does not have a family living center.
Location	0.441	0.552	Good	Students are clustered according to primary and intermediate levels. The units are located some distance from one another.
Storage/Fixed Equip	0.441	0.552	Good	Each classroom has a bank of cabinets under the window. The counter has a sink with bubbler. Storage is abundant. Observation rooms are provided with every classrooms to facilitate observations by personnel and parents.
<i>Non-Instructional Spaces</i>				
Administration	3.136	3.919	Good	Student records are housed in the administrative suite in fireproof cabinets.
Cafeteria			N/A	
Food Service and Prep			N/A	
Clinic	0.717	0.896	Good	The clinic is comprised of two separate rooms that are down the hall from one another. One space is used as an office, containing locked medical cabinets and a refrigerator. the other room has a single cot, non-ADA-accessible restroom and sink. There is hot water in the clinic.
Counseling	0.291	0.448	Fair	Although the school has several counseling rooms identified on the blueprints, there is only one counselor. A psychologist uses one of the offices. There isn't a receptionist or conference room connected to the counselor's office.
Custodial and Maintenance	0.498	0.766	Fair	There are many storage closets on site. The custodial closets do not all have floor sinks. There is no receiving area.
Student Restrooms	0.883	1.359	Fair	Student restrooms located throughout the building are a combination of ADA accessible restrooms with tub/shower. Gang bathrooms have toilet partitions, but no privacy dividers between the urinals. Restrooms do not have hot water.
Faculty Work Space and Toilets	1.941	1.941	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	3.064	3.064	Excel	
Pedestrian Traffic			N/A	Shadow Rock Center does not have any walkers.
Parking	1.244	1.244	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: DeKalb Rockdale GNETS at Shadow Rock Facility

Grade Configuration: K-5

Score: 66.22

Category	Points Earned	Possible Points	Rating	Comment
<i>Outside Spaces</i>				
Play Areas	2.869	3.587	Good	There is a playground dedicated to the students at Shadow Rock Center. A 4' fence encloses the play area.
<i>Safety and Security</i>				
Fencing	0.576	1.152	Poor	The fence around the play area is 4' tall, enabling students to jump over it when they elope from staff/campus. Consideration should be given to a higher fence.
Signage & Way Finding	0.996	1.532	Fair	The parking area is not well marked. The weapons poster was noted; however, the Drug-Free , under surveillance, and subject to search signs were non-existent.
Ease of Supervision	3.677	4.597	Good	
Controlled Entrances	0.383	0.766	Poor	The school has card access and a buzzer at the main door. There is a vestibule at the main entrance; however, the second set of doors do not lock. This defeats the purpose of having a vestibule entryway.
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	The room is warm.
Electrical Power	0.500	1.000	Fair	The school does not have adequate number of quad outlets or a duplex in the ceiling.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	Laptops are not stored/charged in a secure environment with security cameras.
Telephone/PA	1.000	1.000	Good	The PA system does not service any outdoor areas.
Total	66.22	/ 100.00 =	66.22	