

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody HS

Grade Configuration: 9-12

Score: 77.81

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.599	0.599	Excel	
Size	1.496	1.496	Excel	
Location	0.292	0.449	Fair	The art rooms are located on the second floor, therefore, there is no access to an outdoor patio.
Storage/Fixed Equip	0.292	0.449	Fair	One art room has no sinks. There is a kiln, but it does not work. Neither sink in the other art room has a clay trap.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.538	1.538	Excel	
Size	2.499	3.845	Fair	The ROTC only has one classroom and no drill pad. The combined area for ROTC is approximately 61% of the standard. The broadcast/video production area is approximately 69% of the standard.
Location	1.154	1.154	Excel	
Storage/Fixed Equip	1.154	1.154	Excel	
<i>Computer Labs</i>				
Environment	0.270	0.270	Excel	
Size	0.675	0.675	Excel	
Location	0.202	0.202	Excel	
Storage/Fixed Equip	0.132	0.202	Fair	The computer labs do not have security cameras.
<i>General Classrooms</i>				
Environment	3.510	3.510	Excel	
Size	7.020	8.775	Good	General classrooms are approximately 81% of the standard.
Location	2.632	2.632	Excel	
Storage/Fixed Equip	2.632	2.632	Excel	
<i>Instructional Resource Rooms</i>				
Environment	0.467	0.719	Fair	Two resource spaces are in the main building and four are in portables.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody HS

Grade Configuration: 9-12

Score: 77.81

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Size	1.438	1.797	Good	The classrooms for the self-contained special education program slightly exceed the standard but the family living center is approximately 58% of the standard set for that space. The speech teacher is in a small storage closet.
Location	0.350	0.539	Fair	Pull out instruction for English Language Learners is held in four portable classrooms. Students must return to the main building to use the restroom. The school psychologist meets students in an office in the media center.
Storage/Fixed Equip	0.350	0.539	Fair	The portable classrooms lack adequate storage.
<i>Learning Environment</i>				
Learning Style Variety	2.925	4.500	Fair	The traditional design of the building does not allow for a great deal of flexibility with space. There are no large areas for group projects or small student meeting areas.
Interior Environment	1.440	1.800	Good	There are a few areas where the HVAC is inconsistent.
Exterior Environment	0.877	1.350	Fair	There are no outdoor instructional areas. There is an outdoor courtyard off the cafeteria and a outdoor student eating area.
Environment	0.759	0.759	Excel	
<i>Media Center</i>				
Size	0.949	1.897	Poor	The media center area is approximately 63% of the standard.
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.370	0.569	Fair	The media center lacks adequate storage for resources and equipment. One area designed for the media center is being used for a school counselor's office.
<i>Music</i>				
Environment	0.428	0.534	Good	
Size	0.668	1.336	Poor	The band room meets 78% of the standard. The orchestra room meets 55% of the standard. There is no choral classroom. Chorus is held on the stage one day a week and in lobby of the auditorium the other days of the week.
Location	0.321	0.401	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody HS

Grade Configuration:

9-12

Score: 77.81

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Storage/Fixed Equip	0.261	0.401	Fair	There are no practice rooms for the choral program. The chorus program does not have portable risers.
<i>Performing Arts</i>				
Environment	0.231	0.289	Good	The HVAC is inconsistent. The stage is only ADA accessible from the front of the stage.
Size	0.577	0.721	Good	
Location	0.108	0.216	Poor	The drama class is held in the lobby of the auditorium if chorus has a class the same period.
Storage/Fixed Equip	0.173	0.216	Good	
<i>Physical Education</i>				
Environment	2.160	2.160	Excel	
Size	3.510	5.400	Fair	The combined gym area meets approximately 72% of the standard. The gymnasium has seating for approximately 1,500. There is only one health classroom.
Location	0.810	1.620	Poor	The gymnasium can not be secured from other parts of the building.
Storage/Fixed Equip	1.053	1.620	Fair	There is inadequate storage for equipment.
<i>Science</i>				
Environment	0.747	0.747	Excel	
Size	1.867	1.867	Excel	
Location	0.448	0.560	Good	The science classrooms do not have access to an outdoor area.
Storage/Fixed Equip	0.560	0.560	Excel	
<i>Self-Contained Special Education</i>				
Environment	0.479	0.479	Excel	
Size	0.779	1.198	Fair	The classrooms for the self-contained special education slightly exceed the standard, but the family living center is approximately 58% of the standard.
Location	0.359	0.359	Excel	
Storage/Fixed Equip	0.359	0.359	Excel	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody HS

Grade Configuration: 9-12

Score: 77.81

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Administration	2.349	2.349	Excel	
Cafeteria	2.880	3.600	Good	Restrooms near cafeteria do not have hot water.
Food Service and Prep	2.987	4.595	Fair	There are several pieces of food preparation equipment that are aged and no longer work. There are two serving lines.
Clinic	0.000	0.214	Unsat	The school does not have a clinic.
Counseling	0.443	0.681	Fair	The counseling suite does not have enough space to accommodate all counselors. One counselor is located in a media center office.
Custodial and Maintenance	0.360	0.450	Good	There is no dedicated receiving area for custodial deliveries.
Student Restrooms	0.411	0.821	Poor	Many stall doors in the boys and girls bathrooms are missing or are broken. There are no partitions between the urinals. There is no hot water in the restroom faucets.
Faculty Work Space and Toilets	0.641	0.641	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	0.585	0.900	Fair	There is no covered bus loading area.
Pedestrian Traffic	0.882	0.882	Excel	
Parking	1.233	1.897	Fair	There is inadequate parking for students.
Athletic Fields and Facilities	1.618	2.488	Fair	There are sink holes on the football/soccer/lacrosse field.
<i>Safety and Security</i>				
Fencing	0.000	0.762	Unsat	There is no 6 foot fencing that goes around the perimeter of the building.
Signage & Way Finding	0.585	0.900	Fair	Two of the four required signs are not visible: Under Surveillance, and Subject to Search.
Ease of Supervision	2.700	2.700	Excel	
Controlled Entrances	0.225	0.450	Poor	There is no secured vestibule.
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	There are items stored in the areas housing MDF equipment. The areas are set at an appropriate room temperature.
Electrical Power	0.500	1.000	Fair	No classrooms have a duplex outlet in the ceiling.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Dunwoody HS

Grade Configuration: 9-12

Score: 77.81

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Internet connectivity is sometimes unreliable and/or slow.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.000	1.000	Unsat	Some carts are stored in unsecure areas due to lack of storage space.
Telephone/PA	1.000	1.000	Good	
<b>Total</b>	<b>77.81 / 100.00 =</b>		<b>77.81</b>	