

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: E.L. Bouie ES

Grade Configuration:

PK-5

Score: 77.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.281	0.432	Fair	The art classroom does not have a consistent HVAC system so the classroom can be too warm or too cold. The classroom is showing wear. The fixtures are showing their age
Size	1.080	1.080	Excel	
Location	0.259	0.324	Good	There is an outside access but there is no outdoor patio.
Storage/Fixed Equip	0.211	0.324	Fair	There is only one sink. The access to the area under the sink is permanently closed off so the clary trap was inaccessible. Non-flammable shelving is lacking. The kiln does not have a hood. There is no space for student art display.
<i>Computer Labs</i>				
Environment	0.205	0.315	Fair	The computer lab does not have a consistent HVAC system so the lab can be too warm or too cold. The classroom is showing wear. The fixtures are showing their age. The lab has windows with blinds.
Size	0.630	0.787	Good	
Location	0.154	0.236	Fair	The computer lab is not located in a central part of the buildings and is distant from the classrooms. The lab is located next to the stage which houses the band and orchestra. The lab is located on an outside wall with windows.
Storage/Fixed Equip	0.154	0.236	Fair	There is no security camera in the lab or directly outside the lab door. There is a security camera on the outside of the building. There is a motion sensor for security in the lab. There is no motion sensor lighting.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: E.L. Bouie ES

Grade Configuration:

PK-5

Score: 77.16

Category	Points Earned	Possible Points	Rating	Comment
<i>General Classrooms</i>				
Environment	2.940	4.523	Fair	The classrooms do not have a consistent HVAC system so many of the classrooms are too warm or too cold. The classrooms are showing wear. The fixtures are showing their age.
Size	11.308	11.308	Excel	
Location	3.392	3.392	Excel	
Storage/Fixed Equip	2.205	3.392	Fair	The general classrooms lack permanent casework. Most grade 3-5 classrooms do not have a wall of cabinets or cubbies. Some of the classrooms do not have storage for student jackets. In the classrooms that do have coat storage, hangars are used to accommodate all the students' jackets. Grade 1 does not have shared restrooms. Students use the regular student restrooms.
<i>Instructional Resource Rooms</i>				
Environment	0.432	0.665	Fair	The classrooms do not have a consistent HVAC system so many of the classrooms are too warm or too cold. The classrooms are showing wear. The fixtures are showing their age.
Size	1.662	1.662	Excel	
Location	0.498	0.498	Excel	
Storage/Fixed Equip	0.498	0.498	Excel	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.250	0.385	Fair	The kindergarten classrooms do not have a consistent HVAC system so many of the classrooms are too warm or too cold. The classrooms are showing wear. The fixtures are showing their age.
Size	0.962	0.962	Excel	
Location	0.289	0.289	Excel	
Storage/Fixed Equip	0.231	0.289	Good	There is a unisex restroom off each of the kindergarten and prekindergarten classrooms.
<i>Learning Environment</i>				
Learning Style Variety	0.000	4.615	Unsat	There are no designed spaces that support small group learning, individualized learning or shared learning spaces for two classrooms. There are no flexible spaces.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: E.L. Bouie ES

Grade Configuration:

PK-5

Score: 77.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Learning Environment</i>				
Interior Environment	1.200	1.846	Fair	Walls and carpet look worn. Lighting is inadequate in some rooms. Ventilation is inconsistent throughout the building so some rooms are hot and others very cold. Most of the rooms have ceiling tile. The lighting has not been updated in most of the learning spaces. The school is showing wear and tear due to its age.
Exterior Environment	0.900	1.385	Fair	There is one outdoor learning space that is used by the science teacher.
Environment	0.720	0.900	Good	The carpet and paint is showing their age. There are no upholstered student chairs.
<i>Media Center</i>				
Size	1.462	2.249	Fair	The media center is approximately 70% of the standard.
Location	0.337	0.675	Poor	The media center is not centrally located in the school building.
Storage/Fixed Equip	0.439	0.675	Fair	The computers are fixed in rows based on the electrical outlets and wiring. The casework is not on casters. There is no lockable display space near the entrance to the media center. There are not 32 computer stations.
<i>Music</i>				
Environment	0.444	0.684	Fair	The music room does not have a consistent HVAC system so it is very warm. The classrooms are showing wear. The fixtures are showing their age. New tile has been installed.
Size	0.855	1.709	Poor	There is a music room but there is no specified band/orchestra room.
Location	0.410	0.513	Good	There is no dedicated band/orchestra room.
Storage/Fixed Equip	0.333	0.513	Fair	There is no sink or drinking fountain in the music room.
<i>Performing Arts</i>				
Environment	0.446	0.558	Good	
Size	1.395	1.395	Excel	
Location	0.418	0.418	Excel	
Storage/Fixed Equip	0.272	0.418	Fair	There is no dressing room and limited storage space.
<i>Physical Education</i>				
Environment	1.418	1.772	Good	The gym does not have a consistent HVAC system so it is very warm.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: E.L. Bouie ES

Grade Configuration:

PK-5

Score: 77.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Physical Education</i>				
Size	4.431	4.431	Excel	
Location	1.329	1.329	Excel	
Storage/Fixed Equip	0.864	1.329	Fair	There is no padding under the backboards. There is no drinking fountain in the gym.
<i>Science</i>				
Environment	0.300	0.462	Fair	The science classroom does not have a consistent HVAC system so the classroom can be too warm or too cold. The classroom is showing wear. The fixtures are showing their age.
Size	1.154	1.154	Excel	
Location	0.225	0.346	Fair	The outdoor classroom space is not adjacent to the science lab.
Storage/Fixed Equip	0.225	0.346	Fair	The science lab lacks permanent casework. There was not a secured storage area for chemicals and cleaning agents. There was no eye shower, fire extinguisher, blanket. There was no demonstration station.
<i>Self-Contained Special Education</i>				
Environment	0.000	0.443	Unsat	There is no self-contained classroom.
Size	0.000	1.108	Unsat	There is no self-contained classroom.
Location	0.000	0.332	Unsat	There is no self-contained classroom.
Storage/Fixed Equip	0.000	0.332	Unsat	There is no self-contained classroom.
<i>Non-Instructional Spaces</i>				
Administration	1.535	2.361	Fair	Staff/faculty mailboxes are accessed through the public area. The student records are housed in a room that does not have a fireproof door and in file cabinets that are not fire or water proof.
Cafeteria	3.000	4.615	Fair	There is no designed storage space for storing the tables when there is a program using the stage.
Food Service and Prep	4.581	5.727	Good	The food service and prep area have a secured door with a peephole and buzzer.
Clinic	0.432	0.540	Good	There is no sink other than the sink in the restroom.
Counseling	0.175	0.270	Fair	There is no reception area by either of the counselors' offices.
Custodial and Maintenance	0.369	0.462	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: E.L. Bouie ES

Grade Configuration:

PK-5

Score: 77.16

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Student Restrooms	0.532	0.819	Fair	There is no hot water in the student restrooms.
Faculty Work Space and Toilets	1.170	1.170	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	1.477	1.846	Good	There is no covered bus loading area.
Pedestrian Traffic	0.719	0.898	Good	There were no marked crosswalks.
Parking	0.600	0.750	Good	
Play Areas	1.729	2.161	Good	The playground equipment have ADA access but no ADA adapted equipment.
<i>Safety and Security</i>				
Fencing	0.451	0.694	Fair	The school is not appropriately fenced.
Signage & Way Finding	0.600	0.923	Fair	There was no signage directing people to the major spaces. There were class lists outside several of the classrooms. There were no Under Surveillance and Subject to search signs.
Ease of Supervision	2.769	2.769	Excel	
Controlled Entrances	0.462	0.462	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	0.670	1.000	Fair	Wireless is inconsistent in the classrooms.
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Internet is not reliable.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: E.L. Bouie ES

Grade Configuration: PK-5

Score: 77.16

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

Total	77.16	/ 100.00	= 77.16	
--------------	--------------	-----------------	----------------	--