

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Elizabeth Andrews HS

Grade Configuration: 10-12

Score: 65.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.479	0.599	Good	The HVAC does not provide a consistent climate. There is insufficient ventilation.
Size	1.197	1.496	Good	
Location	0.359	0.449	Good	
Storage/Fixed Equip	0.292	0.449	Fair	There is not enough space for storage or displaying of student work. The kiln is not properly vented.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.000	1.538	Fair	The HVAC does not provide a consistent climate in the classrooms.
Size	0.000	3.845	Unsat	The CTAE rooms meet approximately 39% of the size standard.
Location	0.923	1.154	Good	
Storage/Fixed Equip	0.923	1.154	Good	
<i>Computer Labs</i>				
Environment	0.175	0.270	Fair	The HVAC system does not provide a consistent climate in the classrooms and there is poor ventilation.
Size	0.675	0.675	Excel	
Location	0.202	0.202	Excel	
Storage/Fixed Equip	0.162	0.202	Good	
<i>General Classrooms</i>				
Environment	2.281	3.510	Fair	The HVAC system is inconsistent. Classroom climate varies from one part of the building to the next. Many areas lack proper ventilation. There is an institutional feel to the classrooms.
Size	7.020	8.775	Good	
Location	2.632	2.632	Excel	
Storage/Fixed Equip	2.632	2.632	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Elizabeth Andrews HS

Grade Configuration: 10-12

Score: 65.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.467	0.719	Fair	The HVAC system is inconsistent. Classroom climate varies from one part of the building to the next. Rooms lack proper ventilation. There is no natural light in any of these areas. There is an institutional feel to these rooms.
Size	1.438	1.797	Good	The classrooms for larger groups meet approximately 87% of the standard. The small group rooms are twice the standard for small group instruction spaces.
Location	0.539	0.539	Excel	
Storage/Fixed Equip	0.539	0.539	Excel	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.170	1.800	Fair	The HVAC system does not provide a consistent climate throughout the building. There are areas that have extremes in temperature. There is no natural light in any part of the building. There is an institutional feel to the school as a whole.
Exterior Environment	1.080	1.350	Good	There are no outdoor learning spaces or social gathering areas.
Environment	0.493	0.759	Fair	The HVAC system does not provide a consistent climate. There is poor ventilation in the media center
<i>Media Center</i>				
Size	0.949	1.897	Poor	The media center meets approximately 52% of the size standard.
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.455	0.569	Good	
<i>Music</i>				
Environment	0.000	0.534	Unsat	Elizabeth Andrews High School does not have a music program.
Size	0.000	1.336	Unsat	Elizabeth Andrews High School does not have a music program.
Location	0.000	0.401	Unsat	Elizabeth Andrews High School does not have a music program.
Storage/Fixed Equip	0.000	0.401	Unsat	Elizabeth Andrews High School does not have a music program.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Elizabeth Andrews HS

Grade Configuration: 10-12

Score: 65.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.000	0.289	Unsat	Elizabeth Andrews High School does not have a performing arts program.
Size	0.000	0.721	Unsat	Elizabeth Andrews High School does not have a performing arts program.
Location	0.000	0.216	Unsat	Elizabeth Andrews High School does not have a performing arts program.
Storage/Fixed Equip	0.000	0.216	Unsat	Elizabeth Andrews High School does not have a performing arts program.
<i>Physical Education</i>				
Environment	2.160	2.160	Excel	
Size	0.000	5.400	Unsat	The size of the gymnasium area is approximately 16% of the size standard.
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.053	1.620	Fair	There is no seating in the gymnasium. There is only one backboard.
<i>Science</i>				
Environment	0.597	0.747	Good	The HVAC system does not provide a consistent climate in the science classrooms. Ventilation is poor.
Size	1.867	1.867	Excel	
Location	0.448	0.560	Good	There is no outdoor access.
Storage/Fixed Equip	0.364	0.560	Fair	There is no dishwasher or refrigerator in the prep room. There is no fume hood.
<i>Self-Contained Special Education</i>				
Environment	0.000	0.479	Unsat	Elizabeth Andrews High School does not have a self-contained special education program.
Size	0.000	1.198	Unsat	Elizabeth Andrews High School does not have a self-contained special education program.
Location	0.000	0.359	Unsat	Elizabeth Andrews High School does not have a self-contained special education program.
Storage/Fixed Equip	0.000	0.359	Unsat	Elizabeth Andrews High School does not have a self-contained special education program.
<i>Non-Instructional Spaces</i>				
Administration	1.879	2.349	Good	The HVAC system does not provide a consistent climate in this area.
Cafeteria	3.600	3.600	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Elizabeth Andrews HS

Grade Configuration: 10-12

Score: 65.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Food Service and Prep	4.595	4.595	Excel	
Clinic	0.000	0.214	Unsat	Elizabeth Andrews High School has no clinic
Counseling	0.545	0.681	Good	The HVAC system does not provide a consistent climate in this area.
Custodial and Maintenance	0.450	0.450	Excel	
Student Restrooms	0.657	0.821	Good	There is no hot water in some of the restrooms.
Faculty Work Space and Toilets	0.641	0.641	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	0.450	0.900	Poor	The district uses parking areas surrounding the school as a bus lot. This causes significant congestion at certain parts of the day. The building that houses this school is also home to another school and many district offices, so there is a great deal of traffic flowing through the parking lot.
Pedestrian Traffic	0.882	0.882	Excel	New sidewalks are available for students to use when walking from AIC/EAHS to the main street.
Parking	1.233	1.897	Fair	There is no signage or markings that indicate designated parking areas for students, staff, or visitors.
Athletic Fields and Facilities	0.000	2.488	Unsat	There are no athletic fields or outdoor athletic areas for this school. The parking lot is used by physical education classes. This area is now being used as a bus lot creating a safety issue due to the buses flowing in and out of the same area.
<i>Safety and Security</i>				
Fencing	0.000	0.762	Unsat	There is no fencing around the school campus.
Signage & Way Finding	0.585	0.900	Fair	The outdoor signage is not easily noticed.
Ease of Supervision	1.350	2.700	Poor	There is no camera security in the parking area or around the parameter of the building.
Controlled Entrances	0.450	0.450	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Elizabeth Andrews HS

Grade Configuration: 10-12

Score: 65.51

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
Electrical Power	0.500	1.000	Fair	There are insufficient power outlets to accommodate needs in the classroom and many office areas.
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.330	1.000	Poor	Connectivity is unreliable and slow on a daily basis.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	There are insufficient power sources to charge laptop and iPad carts.
Telephone/PA	0.500	1.000	Fair	The PA system does not project outside. The system is actually tied into the district office area and the other school housed in the building.
Total	65.51	100.00	=	65.51