

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Flat Rock ES

Grade Configuration:

PK-5

Score: 79.99

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.421	0.421	Excel	
Size	1.053	1.053	Excel	
Location	0.316	0.316	Excel	
Storage/Fixed Equip	0.253	0.316	Good	The art room sinks do not have clay traps.
<i>Computer Labs</i>				
Environment	0.246	0.307	Good	
Size	0.768	0.768	Excel	
Location	0.184	0.230	Good	The computer lab is on the second floor of the school on an exterior wall.
Storage/Fixed Equip	0.150	0.230	Fair	The computer lab lacks motion-sensor lighting and security cameras required by the standard.
<i>Early Childhood Education</i>				
Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>General Classrooms</i>				
Environment	3.528	4.410	Good	
Size	8.820	11.025	Good	
Location	2.646	3.307	Good	
Storage/Fixed Equip	2.150	3.307	Fair	The general education classrooms are equipped with permanent case work for instructional materials. Counters in prekindergarten through grade 5 were constructed at age-appropriate heights. Sinks are available in classrooms, but not all classroom sinks have bubblers.
<i>Instructional Resource Rooms</i>				
Environment	0.518	0.648	Good	
Size	1.296	1.620	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Flat Rock ES

Grade Configuration:

PK-5

Score: 79.99

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.389	0.486	Good	
Storage/Fixed Equip	0.389	0.486	Good	
<i>Kindergarten &amp; Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	
Size	0.751	0.938	Good	
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.225	0.282	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	
Exterior Environment	1.080	1.350	Good	
Environment	0.702	0.877	Good	
<i>Media Center</i>				
Size	1.425	2.193	Fair	The allotted square footage in the media center is approximately 75% of the required standard.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.526	0.658	Good	
<i>Music</i>				
Environment	0.533	0.667	Good	
Size	1.083	1.667	Fair	The size of the single music room exceeds the size standard; however, a second music room is not available.
Location	0.400	0.500	Good	
Storage/Fixed Equip	0.325	0.500	Fair	Flat Rock does not have a sink or drinking fountain in their identified music room.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Flat Rock ES

Grade Configuration:

PK-5

Score: 79.99

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.435	0.544	Good	Flat Rock utilizes the stage in the cafeteria for student performances. The stage is ADA accessible from the back.
Size	1.088	1.360	Good	The stage does not have dressing rooms available for performances.
Location	0.326	0.408	Good	
Storage/Fixed Equip	0.326	0.408	Good	
<i>Physical Education</i>				
Environment	1.382	1.728	Good	
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	
<i>Science</i>				
Environment	0.450	0.450	Excel	
Size	1.125	1.125	Excel	
Location	0.337	0.337	Excel	
Storage/Fixed Equip	0.337	0.337	Excel	
<i>Self-Contained Special Education</i>				
Environment	0.346	0.432	Good	
Size	0.702	1.080	Fair	The self-contained classrooms meet approximately 90% of the standard for size; however, the school does not have a family living center.
Location	0.259	0.324	Good	
Storage/Fixed Equip	0.211	0.324	Fair	Permanent casework and storage for special needs equipment are available. Flat Rock does not have a Family Needs Center.
<i>Non-Instructional Spaces</i>				
Administration	1.842	2.302	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Flat Rock ES

Grade Configuration:

PK-5

Score: 79.99

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Cafeteria	2.925	4.500	Fair	The restrooms closest to the cafeteria do not have hot/cold water. There is a stage at the front of the cafeteria with a ramp available from the back.
Food Service and Prep	3.629	5.584	Fair	Flat Rock has two operational serving lines. Storage and fixed equipment meet all standards. The food service area has an A/C unit, but it is not currently operable.
Clinic	0.421	0.526	Good	An ADA accessible restroom is located across the hall from the clinic and it does not have a shower.
Counseling	0.263	0.263	Excel	
Custodial and Maintenance	0.450	0.450	Excel	
Student Restrooms	0.639	0.798	Good	
Faculty Work Space and Toilets	1.140	1.140	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	1.800	1.800	Excel	
Pedestrian Traffic	0.876	0.876	Excel	
Parking	0.731	0.731	Excel	
Play Areas	1.369	2.107	Fair	The designated play areas flood during inclement weather. There are multiple play areas available across campus.
<i>Safety and Security</i>				
Fencing	0.542	0.677	Good	
Signage & Way Finding	0.720	0.900	Good	The Under Surveillance, and Subject to search signs were not seen on campus.
Ease of Supervision	1.755	2.700	Fair	Throughout the school, not all panic buttons are operable.
Controlled Entrances	0.292	0.450	Fair	The school does not have a secure vestibule at the main entrance.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Flat Rock ES

Grade Configuration: PK-5

Score: 79.99

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

## *Technology Readiness*

LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	

**Total**      **79.99 / 100.00 = 79.99**