

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Freedom MS

Grade Configuration:

6-8

Score: 86.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.464	0.580	Good	
Size	1.451	1.451	Excel	
Location	0.435	0.435	Excel	
Storage/Fixed Equip	0.348	0.435	Good	The sinks in the art room need clay traps.
<i>Career, Technical and Agricultural Education</i>				
Environment	0.971	1.214	Good	There is a water leak in the ceiling.
Size	2.428	3.035	Good	
Location	0.728	0.911	Good	
Storage/Fixed Equip	0.728	0.911	Good	
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	
Size	0.540	0.675	Good	These labs meet 81% of the adequate space standard.
Location	0.202	0.202	Excel	
Storage/Fixed Equip	0.162	0.202	Good	
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	
Size	7.020	8.775	Good	
Location	2.106	2.632	Good	
Storage/Fixed Equip	2.106	2.632	Good	
<i>Instructional Resource Rooms</i>				
Environment	0.590	0.737	Good	
Size	1.842	1.842	Excel	
Location	0.442	0.553	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Freedom MS

Grade Configuration:

6-8

Score: 86.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Storage/Fixed Equip	0.442	0.553	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	There are active leaks throughout the building and at the back door entrance.
Exterior Environment	1.350	1.350	Excel	
Environment	0.668	0.835	Good	
<i>Media Center</i>				
Size	1.670	2.088	Good	The media center meets 80% of the adequate space standard
Location	0.501	0.626	Good	
Storage/Fixed Equip	0.501	0.626	Good	
<i>Music</i>				
Environment	0.530	0.662	Good	
Size	1.655	1.655	Excel	
Location	0.497	0.497	Excel	There is a beautiful outdoor patio accessible from the art room.
Storage/Fixed Equip	0.397	0.497	Good	
<i>Performing Arts</i>				
Environment	0.301	0.377	Good	There is no ADA access to the stage.
Size	0.754	0.942	Good	
Location	0.184	0.283	Fair	There are no nearby restrooms. Restrooms are located some distance from the performing arts space, compromising restricted access to other places.
Storage/Fixed Equip	0.226	0.283	Good	
<i>Physical Education</i>				
Environment	2.160	2.160	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Freedom MS

Grade Configuration:

6-8

Score: 86.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Physical Education</i>				
Size	5.400	5.400	Excel	
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.620	1.620	Excel	
<i>Science</i>				
Environment	0.687	0.859	Good	
Size	2.147	2.147	Excel	
Location	0.515	0.644	Good	The science classrooms/labs do not have access to outside patio as these rooms are housed in the interior of the building.
Storage/Fixed Equip	0.515	0.644	Good	
<i>Self-Contained Special Education</i>				
Environment	0.393	0.491	Good	
Size	1.228	1.228	Excel	
Location	0.295	0.368	Good	
Storage/Fixed Equip	0.295	0.368	Good	
<i>Non-Instructional Spaces</i>				
Administration	1.509	1.886	Good	
Cafeteria	2.880	3.600	Good	Storage for tables does not exist.
Food Service and Prep	5.144	5.144	Excel	
Clinic	0.000	0.306	Unsat	There currently no clinic that meets the required components of a clinic.
Counseling	0.306	0.382	Good	
Custodial and Maintenance	0.450	0.450	Excel	
Student Restrooms	0.668	0.835	Good	
Faculty Work Space and Toilets	0.652	0.815	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Freedom MS

Grade Configuration: 6-8

Score: 86.25

Category	Points Earned	Possible Points	Rating	Comment
<i>Outside Spaces</i>				
Vehicular Traffic	2.880	3.600	Good	
Pedestrian Traffic	0.311	0.389	Good	
Parking	0.619	0.774	Good	Parking slot lines are faint.
Athletic Fields and Facilities	0.612	0.942	Fair	There is no ADA restroom within 150 feet of the athletic fields. The tennis court needs refurbishing.
<i>Safety and Security</i>				
Fencing	0.559	0.698	Good	There are openings in the fence along the northwest tree line.
Signage & Way Finding	0.720	0.900	Good	The following exterior signs are missing: Drug-Free, Weapons-Free, Under Surveillance, Subject to Search.
Ease of Supervision	1.755	2.700	Fair	Cameras are not able to view all exterior areas of the facility.
Controlled Entrances	0.000	0.450	Unsat	There is no vestibule. No controlled entry system with remote access.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	
Total	86.25	100.00	=	86.25