

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Kittredge Magnet

Grade Configuration: 4-6

Score: 65.88

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.235	0.471	Poor	The HVAC unit is extremely loud and has to be shut down in order to conduct instruction. The room temperature and ventilation are poor. The classroom and fixed equipment are well aged.
Size	0.765	1.177	Fair	The art room meets approximately 70% of the standard.
Location	0.283	0.353	Good	There is no access to an outdoor area.
Storage/Fixed Equip	0.230	0.353	Fair	There is inadequate storage for instructional materials and display and storage of student work.
<i>Computer Labs</i>				
Environment	0.223	0.343	Fair	The computer lab is well-aged.
Size	0.429	0.858	Poor	The computer lab meets approximately 60% of the standard.
Location	0.167	0.258	Fair	The computer lab is located on the opposite end of the building from most classrooms.
Storage/Fixed Equip	0.129	0.258	Poor	There is no teacher cabinet or other fixed storage space in the lab. There are insufficient power outlets. There is no motion sensor lighting or no security cameras in the lab.
<i>Early Childhood Education</i>				
Environment			N/A	
Size			N/A	Preschool through grade 3 classrooms are scored under either the Kindergarten and Pre-Kindergarten category or the General Classroom category.
Location			N/A	
Storage/Fixed Equip			N/A	
<i>General Classrooms</i>				
Environment	2.466	4.932	Poor	Classrooms and fixed equipment are well-aged. Some classrooms are in rooms that were originally designed for a kindergarten program. These rooms are still furnished with sinks and classroom bathrooms that are kindergarten appropriate. Some rooms have HVAC units that are so loud they interfere with instruction.
Size	9.864	12.330	Good	
Location	2.959	3.699	Good	
Storage/Fixed Equip	1.850	3.699	Poor	Classroom fixed equipment is aged. There is inadequate storage for materials.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Kittredge Magnet

Grade Configuration: 4-6

Score: 65.88

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Learning Environment</i>				
Learning Style Variety	3.271	5.033	Fair	The traditional design of the building does not allow for flexible learning spaces. One room has been designated for small group and project construction.
Interior Environment	1.007	2.013	Poor	The building and fixed equipment are well-aged. The building design does not support the needs of the instructional program. The acoustics are poor in many classrooms due to the loudness of the classroom HVAC system.
Exterior Environment	0.000	1.510	Unsat	There are no outdoor areas specifically designed for learning opportunities.
Environment	0.491	0.981	Poor	The acoustics in the media center are poor. Noise transfer from a typical classroom and activity from the adjoining general classroom can be heard. Environment appears well-aged. The size and design of the space are not conducive to creating a flexible environment for learning.
<i>Media Center</i>				
Size	1.226	2.453	Poor	The media center area is approximately 32% of the standard.
Location	0.589	0.736	Good	
Storage/Fixed Equip	0.478	0.736	Fair	The media center has inadequate storage for resources and equipment. The area and its fixed equipment are well-aged.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Kittredge Magnet

Grade Configuration: 4-6

Score: 65.88

Category	Points Earned	Possible Points	Rating	Comment
<i>Music</i>				
Environment	0.373	0.746	Poor	The band class is held on the stage in the cafeteria. The strings class meets in a general classroom. The environment in terms of lighting, acoustics, and room configuration are inadequate for a music program.
Size	1.212	1.864	Fair	The music rooms meet approximately 77% of the standard.
Location	0.280	0.559	Poor	The band classroom is located on the stage of the cafeteria and the strings classroom is located directly across from a 6th grade classroom.
Storage/Fixed Equip	0.280	0.559	Poor	There is no sink or high ceiling in the strings classroom. The band class stores instruments in lockers located along the walls of the cafeteria.
<i>Performing Arts</i>				
Environment	0.304	0.608	Poor	The stage flooring is well aged as is entire stage area. The stage is not ADA accessible from any point.
Size	1.217	1.521	Good	The stage does not have a dressing room nor adequate storage.
Location	0.456	0.456	Excel	
Storage/Fixed Equip	0.297	0.456	Fair	The stage area and its fixed equipment are well-aged. There is inadequate storage.
<i>Physical Education</i>				
Environment	0.966	1.933	Poor	The gymnasium area, its fixed equipment, and flooring are well-aged.
Size	4.832	4.832	Excel	
Location	1.450	1.450	Excel	
Storage/Fixed Equip	0.725	1.450	Poor	The gymnasium has inadequate storage for equipment. The rubber flooring is buckling in many areas. The gymnasium and its fixed equipment are well-aged.
<i>Science</i>				
Environment	0.252	0.503	Poor	The science classrooms were originally designed as general classrooms and are not well suited for laboratory science instruction. Classroom fixed equipment well aged.
Size	1.007	1.258	Good	
Location	0.245	0.377	Fair	Science classrooms do not have any access to an outdoor patio area.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Kittredge Magnet

Grade Configuration: 4-6

Score: 65.88

Category	Points Earned	Possible Points	Rating	Comment
<i>Science</i>				
Storage/Fixed Equip	0.189	0.377	Poor	The Science labs do not have basic science classroom furnishings. There is no demonstration station, no appropriate storage for science equipment, no fire blanket, no eye wash, and no shower.
<i>Self-Contained Special Education</i>				
Environment			N/A	
Size			N/A	
Location			N/A	
Storage/Fixed Equip			N/A	
<i>Non-Instructional Spaces</i>				
Administration	1.674	2.575	Fair	The administrative spaces are not adequate. The reception area is small, there is no conference room space for small or large areas. There is a lack of storage throughout various offices of the suite and the fixtures and fixed equipment are well-aged.
Cafeteria	4.026	5.033	Good	There is not storage for chairs and tables when area is use for events.
Food Service and Prep	4.059	6.245	Fair	The HVAC in the food preparation area is inconsistent. There is no peep hole in the delivery door.
Clinic	0.471	0.589	Good	The clinic area and fixed equipment are well-aged. There are two cot areas but one is not positioned for easy supervision.
Counseling	0.191	0.294	Fair	There is no reception area and no conference room for the counseling program.
Custodial and Maintenance	0.403	0.503	Good	There is no custodial receiving area.
Student Restrooms	0.714	0.893	Good	
Faculty Work Space and Toilets	1.020	1.275	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.007	2.013	Poor	Due to the size of the parking lot, a safe vehicular traffic pattern during pick-up and drop-off times is a challenge.
Pedestrian Traffic	0.783	0.979	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Kittredge Magnet

Grade Configuration: 4-6

Score: 65.88

Category	Points Earned	Possible Points	Rating	Comment
<i>Outside Spaces</i>				
Parking	0.531	0.817	Fair	Parking is inadequate for staff and there is no visitor parking. There is inadequate lighting in the parking area and the building perimeter.
Play Areas	1.531	2.356	Fair	There is no play ground area but there is a playing field.
<i>Safety and Security</i>				
Fencing	0.000	0.757	Unsat	The school does not have 6' fencing around the perimeter. The school grounds are easily accessible.
Signage & Way Finding	0.503	1.007	Poor	There is a lack of signage to direct visitors. Only one of the required safety signs is displayed. Missing signs include Weapons-Free, Under Surveillance, and Subject to Search.
Ease of Supervision	1.963	3.020	Fair	The design of the building makes outdoor supervision difficult. Outside lighting is inadequate.
Controlled Entrances	0.503	0.503	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	0.750	1.500	Fair	There are two small rooms containing IDF/MDF. Both contain some clutter with various old supplies and old financial records. The temperature in one of the rooms is high.
Electrical Power	0.000	1.000	Unsat	No classroom meets the standard of seven quad outlets and one duplex ceiling outlet. The breaker frequently trips in the administrative office area.
Equity of Access, Wireless & Drops	0.670	1.000	Fair	Additional access points are needed.
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	0.670	1.000	Fair	Internet connectivity is sometimes unreliable. Connectivity is problematic at least once a week.
Faculty & Staff Technology	0.670	1.000	Fair	The IAB location is inefficient.
Laptop Carts	0.500	1.000	Fair	There is not sufficient power outlets in the media center storage areas to charge laptop carts
Telephone/PA	0.000	1.000	Unsat	The PA system does not work outside.
Total	65.88	100.00	=	65.88