

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia HS

Grade Configuration: 9-12

Score: 83.63

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.599	0.599	Excel	The HVAC system is inconsistent.
Size	1.496	1.496	Excel	
Location	0.449	0.449	Excel	
Storage/Fixed Equip	0.449	0.449	Excel	
<i>Career, Technical and Agricultural Education</i>				
Environment	1.230	1.538	Good	The HVAC system is inconsistent.
Size	3.076	3.845	Good	
Location	1.154	1.154	Excel	The ROTC program does not have a 25' by 25' drill pad. There was no fire blanket in the engineering labs or the family and consumer science programs.
Storage/Fixed Equip	0.923	1.154	Good	
<i>Computer Labs</i>				
Environment	0.270	0.270	Excel	The HVAC system is not consistent so the classrooms can be too cold or too hot.
Size	0.675	0.675	Excel	
Location	0.202	0.202	Excel	
Storage/Fixed Equip	0.202	0.202	Excel	
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	The HVAC system is inconsistent.
Size	7.020	8.775	Good	
Location	2.632	2.632	Excel	
Storage/Fixed Equip	2.106	2.632	Good	
<i>Instructional Resource Rooms</i>				
Environment	0.575	0.719	Good	The HVAC system is inconsistent.
Size	1.438	1.797	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia HS

Grade Configuration: 9-12

Score: 83.63

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.539	0.539	Excel	
Storage/Fixed Equip	0.539	0.539	Excel	
<i>Learning Environment</i>				
Learning Style Variety	2.250	4.500	Poor	There are a few flexible spaces to allow for differentiated instruction to accommodate multiple teaching and learning styles. There are a few spaces provided to allow for various group sizes, projects, individual workstations, as well as general classrooms. There are no spaces for project learning storage.
Interior Environment	1.440	1.800	Good	The HVAC system is inconsistent.
Exterior Environment	0.000	1.350	Unsat	There are no outdoor learning labs, art patios, covered or open instructional areas and social gathering spaces.
Environment	0.607	0.759	Good	There is no natural lighting in the media center. The HVAC system is inconsistent.
<i>Media Center</i>				
Size	1.897	1.897	Excel	
Location	0.569	0.569	Excel	
Storage/Fixed Equip	0.455	0.569	Good	
<i>Music</i>				
Environment	0.347	0.534	Fair	The HVAC system is inconsistent. There is no natural light. The carpet is very worn and torn, creating a safety hazard.
Size	1.336	1.336	Excel	
Location	0.321	0.401	Good	
Storage/Fixed Equip	0.401	0.401	Excel	
<i>Performing Arts</i>				
Environment	0.289	0.289	Excel	
Size	0.721	0.721	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia HS

Grade Configuration: 9-12

Score: 83.63

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Location	0.216	0.216	Excel	
Storage/Fixed Equip	0.216	0.216	Excel	
<i>Physical Education</i>				
Environment	1.404	2.160	Fair	The HVAC system is inconsistent. The stairs to the upper level are worn and many of the steps are missing the rubber backing. The restrooms in the locker rooms do not have locks on the doors. Some of the other areas were worn.
Size	5.400	5.400	Excel	
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.620	1.620	Excel	There is no drinking fountain in the gym area.
<i>Science</i>				
Environment	0.597	0.747	Good	The HVAC system is inconsistent.
Size	1.867	1.867	Excel	
Location	0.280	0.560	Poor	There is no direct access to outdoor patio areas. There are no outdoor patio areas.
Storage/Fixed Equip	0.448	0.560	Good	There is no fire blankets in any of the science. classrooms.
<i>Self-Contained Special Education</i>				
Environment	0.383	0.479	Good	The HVAC system is inconsistent.
Size	0.959	1.198	Good	
Location	0.359	0.359	Excel	
Storage/Fixed Equip	0.288	0.359	Good	There is no lift to transfer students from their wheel chair to the changing table.
<i>Non-Instructional Spaces</i>				
Administration	2.349	2.349	Excel	The HVAC system is inconsistent.
Cafeteria	3.600	3.600	Excel	
Food Service and Prep	4.595	4.595	Excel	
Clinic	0.000	0.214	Unsat	There is no clinic in the school.

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia HS

Grade Configuration: 9-12

Score: 83.63

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Counseling	0.545	0.681	Good	The HVAC system is inconsistent. The student records are housed in file cabinets that are neither fire or water proof.
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.657	0.821	Good	There are no locks on the restroom stalls.
Faculty Work Space and Toilets	0.641	0.641	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	0.900	0.900	Excel	
Pedestrian Traffic	0.573	0.882	Fair	There are no crosswalks from the parking lot to the front entrance.
Parking	1.233	1.897	Fair	Parking lot lighting is inadequate.
Athletic Fields and Facilities	1.618	2.488	Fair	There are no ADA restrooms within 150 feet. There is no drinking fountain. The athletic fields are not lit. The track is in disrepair with many cracks and uneven surfaces. The football/soccer field has patchy grass with dirt areas from use. The irrigation system does not work, preventing reseeding/resodding of the field.
<i>Safety and Security</i>				
Fencing	0.381	0.762	Poor	The fence goes around the back of the building only. There is no fencing on the front of the school so people cut across the school grounds regularly during school hours.
Signage & Way Finding	0.450	0.900	Poor	There is no signage directing cars to the parking lot, visitor parking, handicapped parking, front entrance, administration area or other indoor spaces. There are no "Under Surveillance" or "Subject to Search" signs on the campus.
Ease of Supervision	1.755	2.700	Fair	There are security cameras that are directed at the outside of the building. There are no security cameras that are directed to the parking areas, bus areas or the athletic fields.
Controlled Entrances	0.292	0.450	Fair	The cameras do not show the entrances to the school.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	0.500	1.000	Fair	Most classrooms have sufficient electrical outlets.
Equity of Access, Wireless & Drops	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia HS

Grade Configuration: 9-12

Score: 83.63

Category	Points Earned	Possible Points	Rating	Comment
<i>Technology Readiness</i>				
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	0.500	1.000	Fair	The PA system does not go outside.
Total	83.63	100.00	=	83.63