

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia MS

Grade Configuration:

6-8

Score: 84.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.464	0.580	Good	
Size	1.451	1.451	Excel	
Location	0.435	0.435	Excel	
Storage/Fixed Equip	0.283	0.435	Fair	More display space is needed for projects in progress and those completed. Student work stations are folding cafeteria tables.
<i>Career, Technical and Agricultural Education</i>				
Environment	1.214	1.214	Excel	
Size	3.035	3.035	Excel	
Location	0.728	0.911	Good	
Storage/Fixed Equip	0.592	0.911	Fair	There was no ventilation in the mechanical work materials processing room, and limited storage space for hazardous materials or dangerous equipment.
<i>Computer Labs</i>				
Environment	0.216	0.270	Good	
Size	0.675	0.675	Excel	
Location	0.162	0.202	Good	
Storage/Fixed Equip	0.132	0.202	Fair	There were no motions sensors, security cameras were in the hallways, and power outlets were limited, requiring power strips. There was little or no storage.
<i>General Classrooms</i>				
Environment	2.808	3.510	Good	
Size	7.020	8.775	Good	On average, classrooms are about 85% of the size standard. However, a number of science labs are currently being used for general instruction purposes, and these exceed the classroom size standard.
Location	2.632	2.632	Excel	
Storage/Fixed Equip	1.711	2.632	Fair	Some classrooms do not have adequate storage cabinets, and several do not have the required number of student computers.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia MS

Grade Configuration:

6-8

Score: 84.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Environment	0.590	0.737	Good	
Size	1.474	1.842	Good	
Location	0.442	0.553	Good	
Storage/Fixed Equip	0.442	0.553	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	
Exterior Environment	1.080	1.350	Good	There is an exterior open-air courtyard completely enclosed by the school building wings.
Environment	0.668	0.835	Good	
<i>Media Center</i>				
Size	1.670	2.088	Good	
Location	0.626	0.626	Excel	
Storage/Fixed Equip	0.501	0.626	Good	
<i>Music</i>				
Environment	0.530	0.662	Good	
Size	1.655	1.655	Excel	The individual and combined music instruction rooms meet the size standards.
Location	0.397	0.497	Good	
Storage/Fixed Equip	0.323	0.497	Fair	Sinks, bathrooms, and water fountains are in adjacent hallways. Two rooms have fixed concrete tiered risers.
<i>Performing Arts</i>				
Environment	0.301	0.377	Good	The cafetorium is noisy and has no acoustical treatments.
Size	0.754	0.942	Good	
Location	0.226	0.283	Good	The cafetorium cannot be isolated form other parts of the school.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia MS

Grade Configuration:

6-8

Score: 84.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Storage/Fixed Equip	0.184	0.283	Fair	There is limited storage space, and no dressing rooms.
<i>Physical Education</i>				
Environment	1.728	2.160	Good	Ceiling tiles old and dirty
Size	5.400	5.400	Excel	The combined main gym, auxiliary gym (wrestling), lobby and weight room (mezzanine) meet the size standard for middle schools.
Location	1.620	1.620	Excel	
Storage/Fixed Equip	1.296	1.620	Good	Storage space is available in the mezzanine, auxiliary gym, and in the locker room areas below the gym.
<i>Science</i>				
Environment	0.687	0.859	Good	
Size	2.147	2.147	Excel	
Location	0.644	0.644	Excel	
Storage/Fixed Equip	0.419	0.644	Fair	The science labs have moveable tables. On a room by room basis, some safety equipment is missing such as hazardous materials storage cabinets, fire blankets, or goggles.
<i>Self-Contained Special Education</i>				
Environment	0.393	0.491	Good	
Size	0.798	1.228	Fair	The special education programs are housed in regular classrooms. There is no specific family living space that meets the prescribed space standard.
Location	0.295	0.368	Good	
Storage/Fixed Equip	0.239	0.368	Fair	Although the room used for students with severe and profound needs has most of the fixed equipment and features and an ADA restroom access, there is no kitchenette with an island.
<i>Non-Instructional Spaces</i>				
Administration	1.886	1.886	Excel	
Cafeteria	2.880	3.600	Good	Nearby restrooms do not have hot water, and there is very limited storage near stage.
Food Service and Prep	4.116	5.144	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia MS

Grade Configuration:

6-8

Score: 84.17

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Clinic	0.000	0.306	Unsat	There is no designated clinic.
Counseling	0.382	0.382	Excel	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.418	0.835	Poor	Sinks, toilets and plumbing are in need of upgrades.
Faculty Work Space and Toilets	0.652	0.815	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	2.880	3.600	Good	
Pedestrian Traffic	0.311	0.389	Good	
Parking	0.619	0.774	Good	
Athletic Fields and Facilities	0.612	0.942	Fair	There is a hard surface area, but it is not fenced.
<i>Safety and Security</i>				
Fencing	0.454	0.698	Fair	Areas behind the school near athletic fields have driving and walking access through school property to neighborhood.
Signage & Way Finding	0.585	0.900	Fair	Drug and Weapons-Free signs are posted outside. No other required signs are visible.
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.225	0.450	Poor	There is a manned security desk in front lobby area outside main office, but no secure vestibule. Doors to the enclosed courtyard do not lock,
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Lithonia MS

Grade Configuration: 6-8

Score: 84.17

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

*Technology Readiness*

Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	0.500	1.000	Fair	There are not enough power outlets in cart storage room to charge all at one time.
Telephone/PA	1.000	1.000	Good	

**Total**      **84.17 / 100.00 = 84.17**