

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pine Ridge ES

Grade Configuration: PK-5

Score: 90.04

Category	Points Earned	Possible Points	Rating	Comment
<i>Art</i>				
Environment	0.421	0.421	Excel	
Size	0.842	1.053	Good	
Location	0.316	0.316	Excel	
Storage/Fixed Equip	0.316	0.316	Excel	
<i>Computer Labs</i>				
Environment	0.307	0.307	Excel	
Size	0.768	0.768	Excel	
Location	0.230	0.230	Excel	
Storage/Fixed Equip	0.230	0.230	Excel	
<i>Early Childhood Education</i>				
Environment	0.450	0.450	Excel	
Size	1.125	1.125	Excel	
Location	0.337	0.337	Excel	
Storage/Fixed Equip	0.337	0.337	Excel	
<i>General Classrooms</i>				
Environment	3.528	4.410	Good	
Size	8.820	11.025	Good	None of the classrooms met the standards, but all of the classrooms made 85% of the standards.
Location	3.307	3.307	Excel	
Storage/Fixed Equip	3.307	3.307	Excel	
<i>Instructional Resource Rooms</i>				
Environment	0.648	0.648	Excel	
Size	1.620	1.620	Excel	
Location	0.486	0.486	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pine Ridge ES

Grade Configuration: PK-5

Score: 90.04

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Storage/Fixed Equip	0.486	0.486	Excel	
<i>Kindergarten & Pre-Kindergarten</i>				
Environment	0.375	0.375	Excel	
Size	0.938	0.938	Excel	
Location	0.282	0.282	Excel	
Storage/Fixed Equip	0.282	0.282	Excel	
<i>Learning Environment</i>				
Learning Style Variety	4.500	4.500	Excel	
Interior Environment	1.440	1.800	Good	
Exterior Environment	1.080	1.350	Good	
Environment	0.877	0.877	Excel	
<i>Media Center</i>				
Size	0.000	2.193	Unsat	The size of the media center is less than half of the standard.
Location	0.658	0.658	Excel	
Storage/Fixed Equip	0.658	0.658	Excel	
<i>Music</i>				
Environment	0.667	0.667	Excel	
Size	1.667	1.667	Excel	
Location	0.500	0.500	Excel	
Storage/Fixed Equip	0.500	0.500	Excel	
<i>Performing Arts</i>				
Environment	0.544	0.544	Excel	
Size	1.360	1.360	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pine Ridge ES

Grade Configuration: PK-5

Score: 90.04

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Location	0.408	0.408	Excel	
Storage/Fixed Equip	0.326	0.408	Good	The stage is only handicapped accessible from the rear.
<i>Physical Education</i>				
Environment	1.728	1.728	Excel	
Size	2.160	4.320	Poor	The gym is less than 60% of the 8000 square feet standard.
Location	1.296	1.296	Excel	
Storage/Fixed Equip	1.296	1.296	Excel	
<i>Science</i>				
Environment	0.450	0.450	Excel	
Size	1.125	1.125	Excel	
Location	0.337	0.337	Excel	
Storage/Fixed Equip	0.337	0.337	Excel	
<i>Self-Contained Special Education</i>				
Environment	0.432	0.432	Excel	
Size	0.864	1.080	Good	
Location	0.324	0.324	Excel	
Storage/Fixed Equip	0.324	0.324	Excel	
<i>Non-Instructional Spaces</i>				
Administration	2.302	2.302	Excel	
Cafeteria	4.500	4.500	Excel	
Food Service and Prep	5.584	5.584	Excel	
Clinic	0.526	0.526	Excel	
Counseling	0.263	0.263	Excel	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pine Ridge ES

Grade Configuration: PK-5

Score: 90.04

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Custodial and Maintenance	0.450	0.450	Excel	
Student Restrooms	0.798	0.798	Excel	One of the boys bathrooms is missing a urinal due to a plumbing problem. A work order has been submitted to the school district, but the repair has not been made.
Faculty Work Space and Toilets	1.140	1.140	Excel	
<i>Outside Spaces</i>				
Vehicular Traffic	1.800	1.800	Excel	
Pedestrian Traffic	0.876	0.876	Excel	
Parking	0.731	0.731	Excel	
Play Areas	2.107	2.107	Excel	
<i>Safety and Security</i>				
Fencing	0.677	0.677	Excel	
Signage & Way Finding	0.720	0.900	Good	
Ease of Supervision	2.160	2.700	Good	
Controlled Entrances	0.450	0.450	Excel	
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	
WAN Backbone	0.670	1.000	Fair	Slow network speeds are reported as an issue especially during periods of heavy use.
LAN-WAN Performance	0.670	1.000	Fair	Internet connectivity is spotty in places throughout the building.
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	

Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Pine Ridge ES

Grade Configuration: PK-5

Score: 90.04

Category	Points Earned	Possible Points	Rating	Comment
Total	90.04	100.00	= 90.04	