

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Woodward ES

Grade Configuration:

PK-5

Score: 76.59

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

## Art

Environment	0.337	0.421	Good	
Size	1.053	1.053	Excel	
Location	0.253	0.316	Good	The space lacks access to an outdoor patio.
Storage/Fixed Equip	0.205	0.316	Fair	The room has two sinks neither of which have clay traps. There is no kiln and required venting hood.

## Computer Labs

Environment	0.246	0.307	Good	The HVAC is inconsistent in operation
Size	0.614	0.768	Good	The computer lab meets 85% of the adequate space standard.
Location	0.184	0.230	Good	
Storage/Fixed Equip	0.150	0.230	Fair	There are no security cameras or motion sensor lighting. This space has an exterior wall that faces south. As a result it is very warm.

## Early Childhood Education

Environment	0.360	0.450	Good	
Size	0.900	1.125	Good	
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	

## General Classrooms

Environment	3.528	4.410	Good	
Size	8.820	11.025	Good	General education classroom vary in size from 83% to 98% of the space standard.
Location	2.646	3.307	Good	
Storage/Fixed Equip	2.150	3.307	Fair	The classrooms do not contain adequate cubby space or sinks with bubblers

## Instructional Resource Rooms

Environment	0.518	0.648	Good	
Size	1.296	1.620	Good	The space meets 93% of the adequate space standard and is shared space with two teachers.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Woodward ES

Grade Configuration:

PK-5

Score: 76.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Instructional Resource Rooms</i>				
Location	0.389	0.486	Good	
Storage/Fixed Equip	0.316	0.486	Fair	Storage for this space is inadequate. There needs to be more locking cabinetry and open storage for student materials.
<i>Kindergarten &amp; Pre-Kindergarten</i>				
Environment	0.300	0.375	Good	HVAC is inconsistent in operation.
Size	0.751	0.938	Good	The kindergarten spaces meet 81% of the adequate space standard.
Location	0.225	0.282	Good	
Storage/Fixed Equip	0.225	0.282	Good	
<i>Learning Environment</i>				
Learning Style Variety	3.600	4.500	Good	
Interior Environment	1.440	1.800	Good	The HVAC is inconsistent.
Exterior Environment	0.877	1.350	Fair	There are no outdoor learning spaces. There is a new gazebo in the front of the building. It greets people and is inviting but limited in space.
Environment	0.702	0.877	Good	
<i>Media Center</i>				
Size	0.000	2.193	Unsat	The media center meets 35% of the adequate space standard.
Location	0.526	0.658	Good	
Storage/Fixed Equip	0.428	0.658	Fair	There is no sink and storage is insufficient.
<i>Music</i>				
Environment	0.533	0.667	Good	The HVAC is inconsistent in the music room.
Size	1.667	1.667	Excel	
Location	0.400	0.500	Good	
Storage/Fixed Equip	0.400	0.500	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Woodward ES

Grade Configuration:

PK-5

Score: 76.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Performing Arts</i>				
Environment	0.435	0.544	Good	There is no ADA access to the stage.
Size	1.088	1.360	Good	
Location	0.326	0.408	Good	Students must travel down to the lower level to use restrooms.. It is not near public restrooms.
Storage/Fixed Equip	0.265	0.408	Fair	The curtains are in need of repair. The sound system needs to be upgraded.
<i>Physical Education</i>				
Environment	1.123	1.728	Fair	The climate control for this space is inadequate. There is no natural lighting
Size	3.456	4.320	Good	
Location	1.037	1.296	Good	
Storage/Fixed Equip	1.037	1.296	Good	The flooring is pulling up from the base. It is a tripping hazard when students are running.
<i>Science</i>				
Environment	0.360	0.450	Good	
Size	0.731	1.125	Fair	The space meets 75% of the adequate space standard.
Location	0.270	0.337	Good	
Storage/Fixed Equip	0.270	0.337	Good	
<i>Self-Contained Special Education</i>				
Environment	0.346	0.432	Good	
Size	1.080	1.080	Excel	
Location	0.259	0.324	Good	
Storage/Fixed Equip	0.259	0.324	Good	
<i>Non-Instructional Spaces</i>				
Administration	1.151	2.302	Poor	Administration lacks a meeting room with spaces for 10 people. The teacher mailboxes are in a public space. The reception area is small and compromises confidentiality.
Cafeteria	2.925	4.500	Fair	The cafeteria has very good natural light. It has only 1 serving line. Students needed to travel to the lower level to use restrooms and wash.

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Woodward ES

Grade Configuration:

PK-5

Score: 76.59

Category	Points Earned	Possible Points	Rating	Comment
<i>Non-Instructional Spaces</i>				
Food Service and Prep	4.467	5.584	Good	
Clinic	0.263	0.526	Poor	The clinic has one cot and no ADA restroom. It is undersized and is frequently crowded with ill students. The HVAC is not efficient in this space. It does have hot water at the sink.
Counseling	0.211	0.263	Good	
Custodial and Maintenance	0.360	0.450	Good	
Student Restrooms	0.639	0.798	Good	There are no urinal partitions in the boys restroom.
Faculty Work Space and Toilets	0.912	1.140	Good	
<i>Outside Spaces</i>				
Vehicular Traffic	1.440	1.800	Good	
Pedestrian Traffic	0.701	0.876	Good	
Parking	0.475	0.731	Fair	Staff parking at Woodward is off site along the street that runs in front of Cross Keys High School.
Play Areas	1.053	2.107	Poor	Approximately 35% of the hard surface that was play area is now occupied by portables. There is no grassy area. The play equipment is placed up to the fenced area which is difficult to supervise.
<i>Safety and Security</i>				
Fencing	0.440	0.677	Fair	There are openings in various locations along the back of the school.
Signage & Way Finding	0.585	0.900	Fair	Under Surveillance and Subject To Search signs are missing.
Ease of Supervision	1.755	2.700	Fair	The site is built down a hillside using paved walks to access parts of the building outside. The exterior is somewhat difficult to supervise.
Controlled Entrances	0.292	0.450	Fair	There are no cameras that capture the portables outside.
<i>Technology Readiness</i>				
IDF & MDF Environment	1.500	1.500	Good	
Electrical Power	1.000	1.000	Good	
Equity of Access, Wireless & Drops	1.000	1.000	Good	
LAN Connectivity	1.500	1.500	Good	

# Building S.P.A.C.E.S Facility Educational Adequacy Report



School Name: Woodward ES

Grade Configuration: PK-5

Score: 76.59

Category	Points Earned	Possible Points	Rating	Comment
----------	---------------	-----------------	--------	---------

## *Technology Readiness*

WAN Backbone	1.000	1.000	Good	
LAN-WAN Performance	1.000	1.000	Good	
Faculty & Staff Technology	1.000	1.000	Good	
Laptop Carts	1.000	1.000	Good	
Telephone/PA	1.000	1.000	Good	

<b>Total</b>	<b>76.59</b>	<b>/ 100.00 =</b>	<b>76.59</b>	
--------------	--------------	-------------------	--------------	--